



Exterior View - Entrance of the building earlier.





Exterior View - Entrance of the building now marked by a pebbled court.





Courtyard and corridor.






Interior view - View of courtyard as existed.





The central court now.





The kadappah stoned and wooden rafter roofed corridor around the central court.





Window module as existing (left) and now restored (right).





Structural cracks in the arch, now revived.





Kadappah stone flooring in the corridor.



Wooden rafters and purlins for roof of corridor around court.





An interior view of the store.