



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0161, W0157, W0168, W0167, W0159, W0169	NA	MAX MILLER SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0161/S023925	205.49	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9968576859		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING DRAIN BS SLAB COVERING TO DRAIN AT 6TH CROSS BEHIND MAX MILLER SCHOOL AT KHB COLONY	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/67/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0072, W0096, W0083	NA	SHARADA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0072/S024437	190.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956475867		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND PROVIDING COVERIING SLAB AT 1ST L CROSS ROAD	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/54/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0129	NA	ASHTAGRAMA BADAVANE
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0129/S024727	197.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SURENDRA KUMAR J		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956473857		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING DRAIN AND COVERING SLAB ATB4TH MAIN ROAD FROM ASHTAGRAMA BADAVANE TO MAGADI MAIN ROAD	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		043-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/80/14-15	30/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0159	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0159/S025303	51.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9957685785		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
DEVELOPMENTS WORKS FOR DRAIN AND PROVIDING COVERING SLAB AT 3RD MAIN	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/68/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0096, W0083	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0096/S030024	138.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S H PURUSHOTHAM		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956475847		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN IN 3RD MAIN	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/99/14-15	02/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0155, W0165, W0163, W0174, W0157, W0159	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0155/S030313	232.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956574857		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND PROVIDING BS SLAB COVERING AT 2ND A MAIN	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND B S SLAB COVERING
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/64/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0154, W0143, W0152	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0154/S030629	139.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S H PURUSHOTHAM		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956475848		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN 3RD MAIN 3RD CROSS 3RD B CROSS AND 4TH MAIN	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/100/14-15	02/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0165, W0169	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0165/S030922	67.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967564567		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING DRAIN AND BS SLAB COVERINGS TO 4TH MAIN BETWEEN 6TH CROSS TO 1ST MAIN ROAD	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	0	101-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/66/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0165	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0165/S031206	72.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB AT 5TH MAIN AT KHB COLONY	2250000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/69/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0158, W0153, W0150	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0158/S031444	220.43	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956475857		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB TO DRAIN AT 6TH MAIN	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND COVERIN SLAB
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/71/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0170, W0171	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0170/S031718	53.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9946575849		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND PROVIDING B S SLAB COVERING AT 7TH C CROSS	500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND BS SLAB COVERING
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-15-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/60/14-15	29/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004, W0037, W0014, W0020, W0029	NA	BASAVESWARA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0004/S032033	218.81	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956574856		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO SIDE DRAIN AND FOOTPATH AT 7TH C MAIN 1ST B CROSS AND 1ST G CROSS IN 3RD STAGE 4TH BLOCK	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	SIDE DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/215/13-14	28/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0165, W0155, W0163, W0174	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0165/S034224	74.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S H PURUSHOTHAM		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956574859		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND FOOTPATH ON BOTH SIDES FROM 1ST MAIN ROAD 5TH CROSS KHB COLONY TO MAGADINAGAR MAIN ROAD	1900000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-13-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/120/13-14	02/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0118, W0089	NA	GOVT SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0118/S034959	117.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9956475847		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROAD IN AK COLONY N4TH TO 8TH CROSS AND SURROUNDINGS	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/392/12-13	08/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0093, W0120	15th Crs, NA	SRI RAMNAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0093/S035241	99.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586759		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND COVERING SLAB	1975000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	DRAIN AND COVERING SLAB
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/398/12-13	08/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0118, W0093, W0110	NA, 15th Crs	BASAVESWARA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0118/S035452	96.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FROM 6TH MAIN ROAD TILL BASAVESWARANAGAR MAIN ROAD IMPROVING TH DRAIN ON BOTH SIDE AND ALSO PROVIDING COVERING SLABS	1950000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-12-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/93/12-13	05/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Lakshmanappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 101	<b>WardName</b> Kamakshipalya
<b>StreetID</b> W0065, W0050, W0048	<b>StreetName</b> Om Shakthi Lyt 5th Crs, NA	<b>Significant LandMark</b> KHB COLONY
<b>SegmentNo</b> 101/C-W0065/S035752	<b>TotalLength</b> 110.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9946574857	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> KAMAKSHIPALYA 8TH CROSS ROAD AND SURROUNDINGS CROSS IMPROVING THE DRAIN ON BOTH SIDES AND ALSO PROVIDING SLABS RESPECTIVELY	<b>Sanctioned Amount</b> 1200000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 101-12-000015
<b>Work OrderNo</b> EE/MLP/TS/PR/92/12-13	<b>Work Order Date</b> 05/09/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 101	<b>WardName</b> Kamakshipalya
<b>StreetID</b> W0089, W0091, W0130, W0126, W0093	<b>StreetName</b> NA, Om Shakthi Lyt 3rd Crs, 15th Crs	<b>Significant LandMark</b> GOVT SCHOOL
<b>SegmentNo</b> 101/S-W0089/S040117	<b>TotalLength</b> 106.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9957685768	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING CC ROAD IN A K COLONY 1 TO 4TH CROSS ROAD	<b>Sanctioned Amount</b> 1900000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> CC ROAD
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 101-13-000029
<b>Work OrderNo</b> EE/MLP/TS/PR/396/12-13	<b>Work Order Date</b> 08/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0088, W0077, W0086, W0090, W0094, W0076, W0092, W	NA	MEENAKSHINAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0088/S040507	145.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S H PURUSHOTHAM		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVING TH DRAIN ON BOTH SIDES AND ALSO PROVIDING COVERING SLABS	1950000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-12-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/97/12-13	05/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148	NA	A K COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0148/S040805	27.13	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND COVERING SLAB 1ST MAIN ROAD SURROUNDINGS AKCOLONY	1950000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	DRAIN AND COVERING SLAB
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/393/12-13	08/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0011	NA	A K COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0011/S041152	85.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9966554567		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND COVERING SLAB AT KAREKALLU A K COLOONY	19750000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	DRAIN AND SLAB
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/397/12-13	08/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0110, W0106	NA	KAMAKSHIPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0110/S041843	93.09	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
UDAYKUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO RCC BOX TYPE DRAIN AT 8TH CROSS AND SURROUNDINGS	1800000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	RCC BOX TYPE DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-12-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/153/12-13	19/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0118, W0089, W0091	NA, Om Shakthi Lyt 3rd Crs	GOVT SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
101/C-W0118/S042656	71.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586756		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN AND COVERING SLAB AT AK COLONY	1700000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	DRAIN AND COVERING SLAB
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		101-13-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/391/12-13	08/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0059	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	BASAVESWARA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0059/S043006	31.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
MANJUNATHA CONSTRUCTIONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS FOOTPATH HUVANUR CIRCLE SHARADA COLONY BMTc BUS STOP	199000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Footpath Layering	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-12-000026/6
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/263/12-13	18/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0098	NA	STS COMPLEX
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0098/S043348	150.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
MANJUNATHA CONSTRUCTIONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO FOOTPATH HUVANUR CIRCLE STS COMPLEX KASTURI SWEETS	199000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Footpath Layering	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-12-000026/3
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/259/12-13	18/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	101	Kamakshipalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100	NA	NANDINI BOOK STORE
<b>SegmentNo</b>	<b>TotalLength</b>	
101/S-W0100/S043803	132.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
C LOKESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO FOOTPATH HAVANUR CIRCLE NANDINI BOOK STORE 1ST MAIN ROAD	199000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Footpath Layering	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		101-12-000026/12
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MLP/TS/PR/260/12-13	18/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

