



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0223	NA	VRUSHABHAVATHI VALLY
SegmentNo	TotalLength	
102/S-W0223/S102417	181.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448615567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF SWD VRUSHBHAVATHINAGARA IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	DESILTING OF SWD
Tender	WorkDetails	Job No Work Code
Not a Tender	DESILTING OF SWD VRUSHBHAVATHINAGARA IN WARD NO.102	102-15-000056
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/389/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0076	NA	NEAR SHANIMAHATHMA TEMPLE
SegmentNo	TotalLength	
102/S-W0076/S103310	50.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448615567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING KULLEGOWDA INDUSTRIAL LAYOUT AND SURORUNDINGS IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMENTS TO DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING KULLEGOWDA INDUSTRIAL LAYOUT AND SURORUNDINGS IN WARD NO.102	102-15-000057
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/PR/WO/390/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0127	NA	SHANIMATHMA TEMPLE ROAD
SegmentNo	TotalLength	
102/S-W0127/S104116	349.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448615567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING SANNAKKI BAILU GANESHA TEMPLE AND SURROUNDINGS IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMENTS TO DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING SANNAKKI BAILU GANESHA TEMPLE AND SURROUNDINGS IN WARD NO.102	102-15-000064
Work OrderNo	Work Order Date	Period of Extension
EE/MLP/PR/WO/397/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/02/2016	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0060, W0049, W0072, W0061, W0047, W0090, W0065, W	NA, Om Shakthi Lyt 7th Crs, Om Shakthi Lyt 5th Crs, Om Shakthi Lyt 8th Crs, Om Shakthi Lyt 6th Crs	VRUSHABHAVATHINAGAR AND SURROUNDING
SegmentNo	TotalLength	
102/C-W0060/S041349	585.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF DRAINS AT NGO'S COLONY MARUTHINAGARA SANNAKKI BAILU IN WARD NO.102	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	DESILT
Tender	WorkDetails	Job No Work Code
Not a Tender	DESILTING OF DRAINS AT NGO'S COLONY MARUTHINAGARA SANNAKKI BAILU IN WARD NO.102	102-15-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/181/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0024	NA	NGO's colony and surroundings
SegmentNo	TotalLength	
102/S-W0024/S055545	112.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING FIXING NAME BOARDS IN WARD NO.102	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	NAME BOARDS
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING FIXING NAME BOARDS IN WARD NO.102	102-16-000045
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/149/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0090	NA	Vrushabhavathinagar area
SegmentNo	TotalLength	
102/S-W0090/S060159	1003.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DRINKING AND FIXING DRIKING WATER PIPELINE IN WARD NO.102	1300000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	WATER SUPPLY
Tender	WorkDetails	Job No Work Code
Not a Tender	DRINKING AND FIXING DRIKING WATER PIPELINE IN WARD NO.102	102-16-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR179/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0162	NA	Sannakki bailu
SegmentNo	TotalLength	
102/S-W0162/S113745	173.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AND CC TO CROSS ROADS SANNAKKI BAILU IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS WORKS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AND CC TO CROSS ROADS SANNAKKI BAILU IN WARD NO.102	102-15-000076
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/443/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0132	NA	Sannakki bailu
SegmentNo	TotalLength	
102/S-W0132/S114856	75.74	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AT SANNAKKI BAILU CROSS ROADS AND SURROUNDINGS IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AT SANNAKKI BAILU CROSS ROADS AND SURROUNDINGS IN WARD NO.102	102-15-000043
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/329/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0164	NA	MANIVILAS GARDEN
SegmentNo	TotalLength	
102/S-W0164/S115304	165.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING TO 2ND CROSS MANIVILASA GARDEN IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING TO 2ND CROSS MANIVILASA GARDEN IN WARD NO.102	102-15-000078
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/444/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0161	NA	Maruthi layout
SegmentNo	TotalLength	
102/S-W0161/S123535	172.29	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and laying cc to roads at Andanappa layout and maruthi layout in ward no.102	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing and laying cc to roads at Andanappa layout and maruthi layout in ward no.102	102-15-000075
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/442/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0273, W0254	NA	CHANNIGAPPA LYT
SegmentNo	TotalLength	
102/C-W0273/S083502	240.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING AT CHANNIGAPPA LYT ABD SURROUNDINGS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/148/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0247, W0208, W0263, W0261, W0249	4th Crs, NA	RAGHAVENDRA SCHOOL
SegmentNo	TotalLength	
102/C-W0247/S104328	186.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956784567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT RAGHAVENDRA SCHOOL ROAD	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000035
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/166/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0051	Om Shakthi Lyt 8th Crs	MARUTHI NAGAR
SegmentNo	TotalLength	
102/S-W0051/S104806	94.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT 5TH CROSS	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/170/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0188, W0267, W0190, W0257, W0269, W0255	StreetName NA, Maheshwari Nagar Ambedkar Rd, Mahadevapura Village Rd	Significant LandMark VINAYAKANAGAR
SegmentNo 102/C-W0188/S105051	TotalLength 174.35	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 8967586758	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT 4TH E CROSS ROAD	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 102-15-000036
Work OrderNo EE/MLP/TS/PR/167/14-15	Work Order Date 22/12/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0182, W0161	NA	MOURYA SCHOOL
SegmentNo	TotalLength	
102/C-W0182/S105357	159.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475847		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT MOURYA SCHOOL AND SURROUNDINGS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/149/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0044	NA	NGOS COLONY
SegmentNo	TotalLength	
102/S-W0044/S105619	241.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB NGOS COLONY AND SURROUNDINGS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/182/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0119, W0125, W0127, W0129, W0137, W0114	StreetName NA, Veera Anjaneya Temple Rd	Significant LandMark SANNAKKI BAILU MAIN ROAD
SegmentNo 102/C-W0119/S105952	TotalLength 303.44	

ContractorDetails		
NameofContractor C MAHESH	ContractorRegNo	Expenditure 0.00
PhoneNo 9967586758	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT RIGHT SIDE	Sanctioned Amount 2000000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 102-15-000026
Work OrderNo EE/MLP/TS/PR/247/14-15	Work Order Date 12/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0012, W0014, W0015	NA	GOVT SCHOOL
SegmentNo	TotalLength	
102/C-W0012/S110239	207.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING @ 5TH MAIN ROAD	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/339/14-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0174	NA	4th K Cross
SegmentNo	TotalLength	
102/S-W0174/S062704	188.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING CONCRETE ROADS TO 4TH K CROSS ROAD AND SURROUNDING CROSS ROADS KAMAKSHIPALYA IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS TO DRAIN
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN AND PROVIDING CONCRETE ROADS TO 4TH K CROSS ROAD AND SURROUNDING CROSS ROADS KAMAKSHIPALYA IN WARD NO.102	102-16-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/38/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0192	NA	4TH D CROSS
SegmentNo	TotalLength	
102/S-W0192/S063252	344.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND LAYING CC TO 4TH E CROSS ROAD AND 4TH D CROSS VINAYAKANAGARA IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	LAYING CC
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING AND LAYING CC TO 4TH E CROSS ROAD AND 4TH D CROSS VINAYAKANAGARA IN WARD NO.102	102-16-000007
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/39/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0197	Vinayaka Lyt 1st Crs	ganesha temple road
SegmentNo	TotalLength	
102/S-W0197/S064338	200.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements to drains and construction of damaged culverts in ward no.102	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	
Tender	WorkDetails	Job No Work Code
	improvements to drains and construction of damaged culverts in ward no.102	102-17-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/200/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0174	NA	VRUSHABHAVATHINAGAR
SegmentNo	TotalLength	
102/S-W0174/S075235	188.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
0		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND LAYING CEMENT CONCRETE TO 4TH L CROSS ROAD KAMAKSHIPALYA (NEAR SHANIMAHATHMA TEMPLE) IN WARD NO.102	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING AND LAYING CEMENT CONCRETE TO 4TH L CROSS ROAD KAMAKSHIPALYA (NEAR SHANIMAHATHMA TEMPLE) IN WARD NO.102	102-16-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/45/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0245	NA	VINAYAKANAGAR
SegmentNo	TotalLength	
102/S-W0245/S075632	162.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
0		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 4th E Cross and surrounding cross roads at Vinayakanagara in ward no.102	1300000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain at 4th E Cross and surrounding cross roads at Vinayakanagara in ward no.102	102-16-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/46/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0104	NA	Shanimahathma temple
SegmentNo	TotalLength	
102/S-W0104/S043449	112.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROADS AT SHANIMAHATHMA TEMPLE ROAD (SOUTH SIDE) IN WARD NO.102	1500000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	PROVIDING CC ROADS AT SHANIMAHATHMA TEMPLE ROAD (SOUTH SIDE) IN WARD NO.102	102-15-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/153/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0040	NA	NGO COLONY
SegmentNo	TotalLength	
102/S-W0040/S022835	349.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY WORKS IN WARD NO.102	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	EMERGENCY WORKS IN WARD NO.102	102-15-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/408/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0090	1st Main Rd Maruthi Nagara	House
SegmentNo	TotalLength	
102/S-W0090/S123043	1003.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
raju	7688	0.00
PhoneNo	EmailId	
9342122429	rmn@gmail.com	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
gfrtg	124500	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender		6758
Work OrderNo	Work Order Date	Period of Extention
gt5666	12/11/2014	30
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	31/01/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0188, W0259, W0267, W0257, W0173	StreetName NA, Ambedkar Nagar Slum, Maheshwari Nagar Ambedkar Rd	Significant LandMark 6th Main
SegmentNo 102/C-W0188/S033946	TotalLength 95.84	

ContractorDetails		
NameofContractor KRISHNEGOWDA	ContractorRegNo	Expenditure 0.00
PhoneNo 9845003091	EmailId	

Work Details		
NameOfWork PROVIDING RCC DRAIN WITH COVERING IN VRUSHABHAVATHINAGARA IN WARD NO.102	Sanctioned Amount 20	Sanctioned Year 2013-14
Year 2013 - 2014	Type of Work Others	Other Work Type RCC DRAIN
Tender Tender	WorkDetails PROVIDING RCC DRAIN WITH COVERING IN VRUSHABHAVATHINAGARA IN WARD NO.102	Job No Work Code 102-13-000009
Work OrderNo EE/MLP/WO/JE/PR/15/2013-14	Work Order Date 14/05/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0264, W0258, W0266, W0281, W0262, W0256	NA, Ambedkar Nagar Slum	11TH MAIN CHANNIGAPPA BADAVANE
SegmentNo	TotalLength	
102/C-W0264/S034612	96.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9845003091		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING IN CHANNIGAPPA BADAVANE IN WARD NO.102	20	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING RCC DRAIN WITH COVERING IN CHANNIGAPPA BADAVANE IN WARD NO.102	102-13-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/13/2013-14	14/05/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0129, W0124, W0146, W0114	NA	SANNAKKI BAILU MAIN ROAD
SegmentNo	TotalLength	
102/C-W0129/S035224	141.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9845003091		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING IN SANNAKKI BAILU IN WARD NO.102	20	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING RCC DRAIN WITH COVERING IN SANNAKKI BAILU IN WARD NO.102	102-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/12/2013-14	14/05/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0259, W0184, W0163, W0182, W0186	Ambedkar Nagar Slum, NA	SHREYAS HIGH SCHOOL
SegmentNo	TotalLength	
102/C-W0259/S094719	161.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9845003091		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING IN VINAYAKA NAGARA IN WARD NO.102	20	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING RCC DRAIN WITH COVERING IN VINAYAKA NAGARA IN WARD NO.102	102-13-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/JE/WO/11/2013-14	13/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0094	NA	Near Maruthi temple
SegmentNo	TotalLength	
102/S-W0094/S085233	107.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9880398035		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain with B.S.Slab covering Maruthinagara and surroundings in ward no.102	20	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	Improvements drain
Tender	WorkDetails	Job No Work Code
Not a Tender	Improvements to drain with B.S.Slab covering Maruthinagara and surroundings in ward no.102	102-15-000058
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/PR/WO/391/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0151	NA	4TH CROSS MARUTHINAGARA
SegmentNo	TotalLength	
102/S-W0151/S065930	175.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN WITH COVERING SLAB AT 4TH CROSS MARUTHINAGARA IN WARD NO.102 VRUSHABHAVATHINAGAR	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF DRAIN WITH COVERING SLAB AT 4TH CROSS MARUTHINAGARA IN WARD NO.102 VRUSHABHAVATHINAGAR	102-14-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/272/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0190	NA	3RD MAIN ROAD
SegmentNo	TotalLength	
102/S-W0190/S070744	342.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN WITH COVERING SLAB AT LAKSHMI VALLABHA ROAD 3RD MAIN ROAD IN WARD NO.102 VRUSHABHAVATHINAGAR (CH:250.00 TO 500.00MTR)	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF DRAIN WITH COVERING SLAB AT LAKSHMI VALLABHA ROAD 3RD MAIN ROAD IN WARD NO.102 VRUSHABHAVATHINAGAR (CH:250.00 TO 500.00MTR)	102-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/271/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0112	NA	Sannakki bailu
SegmentNo	TotalLength	
102/S-W0112/S030456	126.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CULVERTS AND RCC ROADS AT SANNAKKIBAYALU IN WARD NO.102	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF CULVERTS AND RCC ROADS AT SANNAKKIBAYALU IN WARD NO.102	102-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/PR/606/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0141	NA	6TH MAIN GANGANNA LAYOUT
SegmentNo	TotalLength	
102/S-W0141/S030917	203.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 6TH MAIN GANGANNA LAYOUT IN WARD NO.102	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 6TH MAIN GANGANNA LAYOUT IN WARD NO.102	102-13-000032
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/605/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0126	NA	INFRONT OF KEMPEGOWDA SCHOOL
SegmentNo	TotalLength	
102/S-W0126/S031229	146.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB IN FRONT OF KEMPEGOWDA SCHOOL IN WARD NO.102	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB IN FRONT OF KEMPEGOWDA SCHOOL IN WARD NO.102	102-13-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/604/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0090	NA	SANNAKKI BAILU SURROUNDINGS
SegmentNo	TotalLength	
102/S-W0090/S113653	1003.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO SANNAKKI BAILU MAIN ROAD AND CROSS ROAD IN WARD NO.102	4900000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	PROVIDING ASPHALTING TO SANNAKKI BAILU MAIN ROAD AND CROSS ROAD IN WARD NO.102	102-14-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/314/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0034	NA	MOURYA SCHOOL AND SURROUNDINGS
SegmentNo	TotalLength	
102/S-W0034/S114403	543.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO MOURYA SCHOOL ROAD AND SURROUNDINGS IN WARD NO.102	4800000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
	PROVIDING ASPHALTING TO MOURYA SCHOOL ROAD AND SURROUNDINGS IN WARD NO.102	102-14-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/315		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0256	Ambedkar Nagar Slum	6th main road
SegmentNo	TotalLength	
102/S-W0256/S011021	276.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KUSHAL S.R		0.00
PhoneNo	EmailId	
9986666677		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT CHURCH ROAD IN WARD NO.102	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT CHURCH ROAD IN WARD NO.102	102-12-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/52/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0264	NA	3RD MAIN KAMAKSHIPALYA
SegmentNo	TotalLength	
102/S-W0264/S011444	161.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.KUSHAL		0.00
PhoneNo	EmailId	
9986666677		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 3RD MAIN ROAD ARALIMARA MAIN ROAD IN WARD NO.102	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 3RD MAIN ROAD ARALIMARA MAIN ROAD IN WARD NO.102	102-12-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/53/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0256	Ambedkar Nagar Slum	MOURYA SCHOOL ROAD
SegmentNo	TotalLength	
102/S-W0256/S011811	276.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.KUSHAL		0.00
PhoneNo	EmailId	
9986666677		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT MOURYA SCHOOL ROAD IN WARD NO.102	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT MOURYA SCHOOL ROAD IN WARD NO.102	102-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/51/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0009	NA	1ST CROSS SANNAKKI BAILU
SegmentNo	TotalLength	
102/S-W0009/S012813	109.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAMANNA		0.00
PhoneNo	EmailId	
9986666677		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 4TH 1ST CROSS SANNAKKI BAILU (TEMPLED OPPOSITE ROAD) IN WARD NO.102	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 4TH 1ST CROSS SANNAKKI BAILU (TEMPLED OPPOSITE ROAD) IN WARD NO.102	102-12-000032
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/444/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0270	2nd A Crs, Maheshwari Nagar	2ND MAIN
SegmentNo	TotalLength	
102/S-W0270/S013335	204.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 2ND MAIN ROAD IN WARD NO.102	2016	2016-17
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Not a Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 2ND MAIN ROAD IN WARD NO.102	102-16-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/36/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0262	Ambedkar Nagar Slum	6TH MAIN ROAD
SegmentNo	TotalLength	
102/S-W0262/S013730	256.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 6TH MAIN ROAD IN WARD NO.102	2000000	2000000.00
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Not a Tender	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 6TH MAIN ROAD IN WARD NO.102	102-16-000029
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/38/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0281	NA	2ND CROSS ROAD
SegmentNo	TotalLength	
102/S-W0281/S014116	132.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 2ND CROSS ROAD IN WARD NO.102	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF RCC DRAIN WITH COVERING SLAB AT 2ND CROSS ROAD IN WARD NO.102	102-16-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/37/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0270	2nd A Crs, Maheshwari Nagar	KAMAKSHIPALYA MAIN ROAD W/S
SegmentNo	TotalLength	
102/S-W0270/S014432	204.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of missing RCC drain with covering slab at Kamakshipalya mainroad western side and cross roads in ward no.102	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of missing RCC drain with covering slab at Kamakshipalya mainroad western side and cross roads in ward no.102	102-16-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/39/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0041	Om Shakthi Lyt, 9th Crs	NGO S COLONY
SegmentNo	TotalLength	
102/S-W0041/S010411	143.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIIDNG RETAINING WALL ARROUND ARALIKATTE AND CC TO NGO COLONY CROSS ROAD IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	PROVIIDNG RETAINING WALL ARROUND ARALIKATTE AND CC TO NGO COLONY CROSS ROAD IN WARD NO.102	102-15-000049
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/334/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0078	NA	near Maramma temple
SegmentNo	TotalLength	
102/S-W0078/S112307	54.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND LAYING CC TO VRUSHABHAVATHINAGARA IN WARD NO.102	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMETNS
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING AND LAYING CC TO VRUSHABHAVATHINAGARA IN WARD NO.102	102-15-000055
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/338/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		Ramakrishna
Date of Inspection	Remarks	
21/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0190	NA	Vrushabhavathinagar
SegmentNo	TotalLength	
102/S-W0190/S024349	342.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY WORK IN WARD NO.102	1500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	EMERGENCY
Tender	WorkDetails	Job No Work Code
Tender	EMERGENCY WORK IN WARD NO.102	102-16-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/37/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0044	NA	NGO'S COLONY
SegmentNo	TotalLength	
102/S-W0044/S040139	261.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY WORKS IN WARD NO.102 (DESILTING OF DRAINS AND PROVIDING AND LAYING CC TO ROADS IN WARD NO.102)	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	EMERGENCY WORKS
Tender	WorkDetails	Job No Work Code
Not a Tender	EMERGENCY WORKS IN WARD NO.102 (DESILTING OF DRAINS AND PROVIDING AND LAYING CC TO ROADS IN WARD NO.102)	102-15-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/408/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0129	NA	SANNAKKI BAILU
SegmentNo	TotalLength	
102/S-W0129/S104939	401.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AND PROVIDING CEMENT CONCRETE AT 1ST CROSS AND CROSS ROADS SANNAKKI BAILU IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS AND PROVIDING CEMENT CONCRETE AT 1ST CROSS AND CROSS ROADS SANNAKKI BAILU IN WARD NO.102	102-16-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/52/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0013	NA	NGO;S COLONY
SegmentNo	TotalLength	
102/S-W0013/S105329	291.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT NGO'S COLONY MAIN ROAD INFRONT OF GOVERMENT SCHOOL IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AT NGO'S COLONY MAIN ROAD INFRONT OF GOVERMENT SCHOOL IN WARD NO.102	102-16-000036
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/49/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0219	Chowdeshwari Temple Rd	VRUSHABHAVATHINAGAR
SegmentNo	TotalLength	
102/S-W0219/S105639	226.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND LAYING CONCRETE AND IMPROVEMENTS TO DRAIN AT CHURCH ROAD MANIVILAS GARDEN IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	PROVIDING AND LAYING CONCRETE AND IMPROVEMENTS TO DRAIN AT CHURCH ROAD MANIVILAS GARDEN IN WARD NO.102	102-16-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/47/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0076	NA	NGO'S COLONY
SegmentNo	TotalLength	
102/S-W0076/S105955	50.09	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING CEMENT CONCRETE TO CROSS ROADS AND LANES AT SANNAKKI BAILU NEAR VRUSHABHAVATHI VALLEY IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AND PROVIDING CEMENT CONCRETE TO CROSS ROADS AND LANES AT SANNAKKI BAILU NEAR VRUSHABHAVATHI VALLEY IN WARD NO.102	102-16-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/50/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0078	NA	1ST A CROSS
SegmentNo	TotalLength	
102/S-W0078/S110210	54.41	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND CROSS ROADS AT 1ST A CROSS ROAD AND ROADS AT SANNAKKI BAILU NEAR VRUSHABHAVATHI VALLEY IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AND CROSS ROADS AT 1ST A CROSS ROAD AND ROADS AT SANNAKKI BAILU NEAR VRUSHABHAVATHI VALLEY IN WARD NO.102	102-16-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/51/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0210	NA	VINAYAKANAGARA
SegmentNo	TotalLength	
102/S-W0210/S103346	157.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDNG CC TO ROAD AT VINAYAKANAGARA 4TH A CROSS AND SURROUNDINGS IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	PROVIDNG CC TO ROAD AT VINAYAKANAGARA 4TH A CROSS AND SURROUNDINGS IN WARD NO.102	102-15-000046
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/331/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0086	NA	Puttaiah layout
SegmentNo	TotalLength	
102/S-W0086/S043242	65.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 11TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS AT 11TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	102-17-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/234/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		N Ramakrishna
Date of Inspection	Remarks	
03/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0049	NA	AYYAPPA SWAMI TEMPLE
SegmentNo	TotalLength	
102/S-W0049/S070818	95.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AND PROVIDING CC ROAD AT MARUTHI NAGAR AYYAPPA SWAMI TEMPLE ROAD	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	DRAIN AND CC ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/150/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0216, W0212, W0239	NA	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/C-W0216/S071156	61.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N NAGARAJA		0.00
PhoneNo	EmailId	
9967586958		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO RAODS AT 2ND B MAIN ROAD OF VINAYAKANAGARA	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000032
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR230/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0175	NA	ANDANAPPA LYT
SegmentNo	TotalLength	
102/S-W0175/S071515	111.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9968775867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING LAYING TO CC ROADS AT ANDANAPPA LYT AND MARUTHI LYT	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	CC ROADS
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-0000075
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/442/14-15	24/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0048, W0047, W0043	NA	MANIVILASA GARDE
SegmentNo	TotalLength	
102/C-W0048/S071925	66.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9957683647		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B S SLAB COVERING AT CHURCH ROAD EASTERN SIDE AT MANIVILASA NAGAR	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000077
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/445/14-15	24/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0009, W0078	NA	SANNAKKIBAYALU
SegmentNo	TotalLength	
102/C-W0009/S072146	49.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9954756475		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender		102-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/12/13-14	14/05/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0194	NA	VINAYAKA NAGARA
SegmentNo	TotalLength	
102/S-W0194/S072433	185.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9967586958		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender		102-13-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/11/13-14	14/05/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0258, W0281	Ambedkar Nagar Slum, NA	CHANNIGAPPA BADAVANE
SegmentNo	TotalLength	
102/C-W0258/S072819	162.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN WITH COVERING IN CHANNIGAPPA BADAVANE	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender		102-13-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/13/13-14	14/05/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0105, W0036, W0111	NA	BEML LYT
SegmentNo	TotalLength	
102/S-W0105/S073213	185.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586788		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN @11TH AND 12TH CROSS ROADS	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-13-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/318/13-14	28/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0163, W0182	NA	MARUTHI NAGAR
SegmentNo	TotalLength	
102/C-W0163/S122905	160.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967567867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT H CROSS MARUTHINAGAR	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-13-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/323/13-14	28/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0097, W0089, W0034	16th Crs, NA	BEML LYT
SegmentNo	TotalLength	
102/S-W0097/S123313	173.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 9TH AND 10TH CROSS ROADS	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-13-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/317/13-14	28/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0235, W0196, W0190, W0192, W0194	StreetName NA	Significant LandMark VINAYAKA NAGARA
SegmentNo 102/C-W0235/S123837	TotalLength 139.65	

ContractorDetails		
NameofContractor S H PURUSHOTHAM	ContractorRegNo	Expenditure 0.00
PhoneNo 9967895678	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF DRAIN WITH COVERING SLAB	Sanctioned Amount 1500000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 102-14-000007
Work OrderNo EE/MLP/TS/PR/395/13-14	Work Order Date 04/03/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0216, W0212, W0239, W0249	NA	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/C-W0216/S124401	63.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9978675678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 2ND A MAIN ROAD	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000029
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/278/14-15	19/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0127, W0114	NA	SANNAKKI BAILU
SegmentNo	TotalLength	
102/C-W0127/S124658	64.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
8967895678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO 2ND A CROSS ROADS	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/273/14-15	19/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0229, W0212, W0237, W0210	StreetName NA	Significant LandMark VINAYAKANAGARA
SegmentNo 102/C-W0229/S125012	TotalLength 79.01	

ContractorDetails		
NameofContractor KRISHNEGOWDA	ContractorRegNo	Expenditure 0.00
PhoneNo 9967586958	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO ROADS AT2ND MAIN ROAD	Sanctioned Amount 1500000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Road	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 102-15-000031
Work OrderNo EE/MLP/TS/PR/280/14-15	Work Order Date 19/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0214	NA	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/S-W0214/S125300	106.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROADS AT 2ND B MAIN ROAD	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/279/14-15	19/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0041, W0022, W0037	Om Shakthi Lyt, 9th Crs, NA	NGOS COLONY
SegmentNo	TotalLength	
102/C-W0041/S125743	103.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9956475847		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH COVERING SLAB TO 1ST MAIN ROAD	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/276/14-15	19/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0032, W0023, W0026, W0010, W0014, W0024	StreetName NA	Significant LandMark NGOS COLONY
SegmentNo 102/C-W0032/S010143	TotalLength 184.50	

ContractorDetails		
NameofContractor KRISHNEGOWDA	ContractorRegNo	Expenditure 0.00
PhoneNo 9978675678	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN WITH COVERING SLAB TO 4TH MAIN ROAD	Sanctioned Amount 1000000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 102-15-000028
Work OrderNo EE/MLP/TS/PR/277/14-15	Work Order Date 19/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0032	NA	NGOS COLONY
SegmentNo	TotalLength	
102/S-W0032/S010523	109.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
9967584957		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH COVERING SLAB TO 5TH E CROSS OF 4TH MAIN ROAD	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-15-000025
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/274/14-15	19/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0141, W0135, W0137, W0094	StreetName NA	Significant LandMark SANNAKKI BAILU
SegmentNo 102/C-W0141/S010806	TotalLength 99.17	

ContractorDetails		
NameofContractor KRISHNEGOWDA	ContractorRegNo	Expenditure 0.00
PhoneNo 9957685768	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN WITH COVERING SLAB AT 2ND A CROSS ROADS	Sanctioned Amount 1000000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 102-15-000024
Work OrderNo EE/MLP/TS/PR/275/14-15	Work Order Date 19/01/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0264, W0275, W0274, W0268, W0258, W0266, W0240, W	NA, 2nd Crs, Maheshwari Nagar, Ambedkar Nagar Slum, 2nd Main Rd, 2nd A Crs, Maheshwari Nagar	VRUSHIBHAVANTHI NAGAR
SegmentNo	TotalLength	
102/C-W0264/S011154	500.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N VENKATAREDDY		0.00
PhoneNo	EmailId	
9957689553		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN WITH COVERING SLAB AT VALLABHA ROAD 3RD MAIN ROAD	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/271/13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0275, W0236, W0228	NA, 2nd Main Rd	VRUSHIBHAVANTHI NAGAR
SegmentNo	TotalLength	
102/C-W0275/S011539	153.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N VENKATAREDDY		0.00
PhoneNo	EmailId	
9978675678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
COONSTRUCTION OF DRAIN WITH COVERING SLAB AT LAKSHMI VALLABHA ROAD 3RD MAIN ROAD	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-14-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/270/13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0126	NA	VRUSHIBHAVANTHI NAGAR
SegmentNo	TotalLength	
102/S-W0126/S011836	71.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S H PURUSHOTHAM		0.00
PhoneNo	EmailId	
9978675678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN WITH COVERING SLAB	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-14-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/394/13-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 102	WardName Vrisabhavathi Nagar
StreetID W0023, W0025, W0072, W0035	StreetName NA	Significant LandMark SHANKARNAG BUS STAND
SegmentNo 102/C-W0023/S012242	TotalLength 158.13	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9956475847	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN AT SHANKARNAG BUS STAND ROAD	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 102-13-000025
Work OrderNo EE/MLP/TS/PR/325/13-14	Work Order Date 23/02/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name ramakrishna
Date of Inspection 01/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0188, W0190, W0257, W0255, W0192, W0269	NA, Mahadevapura Village Rd	VINAYAKA NAGARA
SegmentNo	TotalLength	
102/C-W0188/S012550	296.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475847		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 4TH C CROSS ROADS	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-13-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/319/13-14	28/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0183, W0275, W0185, W0254, W0281, W0256, W0246, W	NA, Ambedkar Nagar Slum, Vinayaka Lyt 1st Crs, 2nd Main Rd, Maheshwari Nagar Ambedkar Rd	sannakki bailu
SegmentNo	TotalLength	
102/C-W0183/S012535	304.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T INDRAKUMAR		0.00
PhoneNo	EmailId	
9845316262		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CULVERTS AT SANNAKKI BAILU IN WARD NO.17	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	CONSTRUCTION OF CULVERTS AT SANNAKKI BAILU IN WARD NO.17	R-102-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/312/2009-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0034	NA	4th main
SegmentNo	TotalLength	
102/S-W0034/S054735	543.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AND CULVERTS AT 4TH MAIN ROAD BEML LAYOUT IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS AND CULVERTS AT 4TH MAIN ROAD BEML LAYOUT IN WARD NO.102	102-16-000015
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/88/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0064	NA	14TH MAIN ROAD
SegmentNo	TotalLength	
102/S-W0064/S055110	291.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DARINS AND PROVIDING CC TO 14TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DARINS AND PROVIDING CC TO 14TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	102-16-000016
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/89/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0064	NA	14th main
SegmentNo	TotalLength	
102/S-W0064/S123022	291.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 14TH MAIN ROAD AND SURROUNDING AREA IN WARD NO.102	2000000	
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS AT 14TH MAIN ROAD AND SURROUNDING AREA IN WARD NO.102	102-17-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/295/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0070	NA	13TH MAIN
SegmentNo	TotalLength	
102/S-W0070/S123429	258.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 13TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	2000000	
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS AT 13TH MAIN ROAD PUTTAIAH LAYOUT IN WARD NO.102	102-17-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/000/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0217, W0164, W0153, W0184, W0159, W0182, W0161, W	NA	BEML LAYOUT
SegmentNo	TotalLength	
102/C-W0217/S063933	35.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.H.Purushotham		0.00
PhoneNo	EmailId	
9845063823		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CULVERTS IN WARD NO.102	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	CULVERT
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF CULVERTS IN WARD NO.102	102-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/396/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0275	NA	VRISHABHAVATHI NAGAR
SegmentNo	TotalLength	
102/S-W0275/S033744	523.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAVINDRA J.G		0.00
PhoneNo	EmailId	
9590281209		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DRILLING OF BOREWELLS PROVIDING PUMP AND MOTAR TO SUPPLY OF DRINKING WATER IN WARD NO.102	2500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	WATER SUPPLY
Tender	WorkDetails	Job No Work Code
Tender	DRILLING OF BOREWELLS PROVIDING PUMP AND MOTAR TO SUPPLY OF DRINKING WATER IN WARD NO.102	102-16-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/27/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0064	NA	14th A Cross
SegmentNo	TotalLength	
102/S-W0064/S122557	291.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and providing cc to 14th A cross at Nanjappa layout in ward no.102	2000000	
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	Improvements to drains and providing cc to 14th A cross at Nanjappa layout in ward no.102	102-17-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/300/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0013	NA	14th B Cross
SegmentNo	TotalLength	
102/S-W0013/S123045	291.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and laying cc to 14th B Cross and surroundings aeras in ward no.102	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	Providing and laying cc to 14th B Cross and surroundings aeras in ward no.102	102-17-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/288/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0164	NA	Manivilas garden
SegmentNo	TotalLength	
102/S-W0164/S013504	165.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING AND LAYING CC TO CHURCH ROAD AT MANIVILASA GARDEN IN WARD NO.102	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING AND LAYING CC TO CHURCH ROAD AT MANIVILASA GARDEN IN WARD NO.102	102-15-000079
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/441/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0012, W0014, W0015	NA	KAMALANAGARA
SegmentNo	TotalLength	
102/C-W0012/S094848	178.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
8865465746		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING KAMALANAGARA AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000062
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/395/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0025	NA	NGO COLONY
SegmentNo	TotalLength	
102/S-W0025/S095157	179.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9946574856		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AND NGO COLONY AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000063
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/396/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0059, W0038	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, NA	MANVILAS GARDEN
SegmentNo	TotalLength	
102/C-W0059/S095456	166.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING MANVIALS GARDEN AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000065
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/398/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0151, W0147	NA	MARUTHI NAGAR
SegmentNo	TotalLength	
102/S-W0151/S095733	328.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945364758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 3RD AND4TH CROSS	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/322/13-14	28/02/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0185, W0228, W0181	NA, Vinayaka Lyt 3rd Crs	NARASAMMA CHOULTRY
SegmentNo	TotalLength	
102/C-W0185/S100036	120.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967567856		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH BS SLAB COVERING AT VEERANNA NARASAMMA CHOULTRY OPP ROAD	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/159/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0165, W0163, W0171, W0178	NA	VRUSHABHAVATHI NAGAR
SegmentNo	TotalLength	
102/C-W0165/S100629	122.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N VENTAKATA REDDY		0.00
PhoneNo	EmailId	
9956784567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN WITH COVERING SLAB AT 4TH CROSS MARUTHI NAGAR	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-14-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/272/13-14	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0005	NA	KUVEMPU ROA
SegmentNo	TotalLength	
102/S-W0005/S101352	142.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475869		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROADS AT CHANDRAPPA ROAD AND KUVEMPU ROAD	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	CC ROADS
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/183/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0225, W0227, W0166	NA	RUDRE GOWDA KALYANA MANTAPA
SegmentNo	TotalLength	
102/C-W0225/S101712	205.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9965768478		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING RUDRAMMA AND RUDREGOWDA KALYANA MANTAPA AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000059
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/392/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0102, W0125	NA, Veera Anjaneya Temple Rd	SANNAKKIBAILU
SegmentNo	TotalLength	
102/C-W0102/S102020	70.53	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING SANNAKKIBAILU AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000060
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/393/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
02/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0235, W0194	NA	RAMAIAH COLLEGE BACK SIDE
SegmentNo	TotalLength	
102/C-W0235/S102422	58.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9978678956		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AT RAMAIAH COLLEGE BACK SIDE ROAD AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000051
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/336/14-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0102, W0130, W0100, W0127, W0114, W0096, W0124	NA	GANESHA TEMPLE
SegmentNo	TotalLength	
102/C-W0102/S102927	335.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967895678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING SANNAKKA BAILU GANESHA TEMPLE AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000064
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/397/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0052, W0083, W0071, W0087, W0085	NA	MARUTHI NAGAR
SegmentNo	TotalLength	
102/C-W0052/S103332	341.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475869		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AT MARUTHI NAGAR MOURYA SCHOOL ROAD	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/335/14-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0235, W0200	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/C-W0235/S104103	81.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586756		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AT VINAYAKA NAGAR 4TH A CROSS AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000045
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/330/14-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0235, W0196	NA	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/C-W0235/S105421	56.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586756		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING AT VINAYAKA NAGARA 4TH B CROSS AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000048
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/333/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0247, W0245, W0204	4th Crs, NA	VINAYAKA NAGARA
SegmentNo	TotalLength	
102/C-W0247/S105712	165.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AT VINAYAKANAGARA 1ST A CROSS AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000044
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/328/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0239, W0220	NA	VIINAYAKANAGAR
SegmentNo	TotalLength	
102/C-W0239/S110005	131.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING AND CONSTRUCTION OF CULVERTS AT GANESHA TEMPLE ROAD	1500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/165/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0235, W0200, W0245, W0253	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	VINAYAKA NAGAR
SegmentNo	TotalLength	
102/C-W0235/S110426	255.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING AT VINAYAKANAGARA CROSS ROADS AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000042
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/327/14-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0225, W0227, W0166	NA	CHOULTRY
SegmentNo	TotalLength	
102/C-W0225/S110802	45.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AND PROVIDING CC ROAD AT RUDRAMMA RUDREGOWDA CHOULTRY ROAD	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/154/14-15	29/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0227	NA	CALIFORNIYA SCHOOL
SegmentNo	TotalLength	
102/S-W0227/S111125	141.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967854623		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH BS SLAB COVERING FACTORY ROAD BEHIND CALIFORNIYA SCHOOL AND SURROUNDINGS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000061
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/394/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0137, W0106	NA	KAMALA NAGAR
SegmentNo	TotalLength	
102/C-W0137/S111600	108.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE ROADS	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	CEMENT CONCRETE ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000067
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/385/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0185, W0293, W0256, W0189	NA, Maheshwari Nagar Opp Police Station Rd, Ambedkar Nagar Slum	ANDANAPPA LYT
SegmentNo	TotalLength	
102/C-W0185/S112408	72.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AT ANDANAPPA LYT AND SURROUNDINGS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000002
Work OrderNo	Work Order Date	Period of Extention
v147/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0259, W0163, W0157, W0186, W0255, W0159, W0243	Ambedkar Nagar Slum, NA, Mahadevapura Village Rd, Chowdeshwari Temple Behind Rd	VINAYAKA NAGARA
SegmentNo	TotalLength	
102/C-W0259/S112705	249.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967586758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B S SLAB COVERING AND PROVIDING CC ROAD AT 4TH F CROSS ROAD VINAYAKANAGARA	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		102-15-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/168/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0196, W0245, W0194	NA	VINAYAKA NAGARA
SegmentNo	TotalLength	
102/S-W0196/S113137	301.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N NAGARAJA		0.00
PhoneNo	EmailId	
9956475648		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 4TH C AND B CROSS ROADS	4000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		102-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/108/14-15	08/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0030, W0040, W0007, W0028	NA	KAMALANAGAR
SegmentNo	TotalLength	
102/C-W0030/S113438	245.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B N NAVEEN KUMAR		0.00
PhoneNo	EmailId	
9956475647		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN AND COVERING SLAB TO KUMEPU ROAD IN KAMALANAGARA SLUM	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN AND COVERING SLAB
Tender	WorkDetails	Job No Work Code
Tender		102-11-000045
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/98/13-14	23/09/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0023, W0019, W0040	NA	GOVT SCHOOL
SegmentNo	TotalLength	
102/C-W0023/S075523	166.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING FENCING AND DEVELOPMENT IN FRONT OF GOVT SCHOOL 1ST MAIN NGO'S COLONY IN WARD NO.102	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	PROVIDING FENCING AND DEVELOPMENT IN FRONT OF GOVT SCHOOL 1ST MAIN NGO'S COLONY IN WARD NO.102	102-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/610/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0283	NA	AKKAMAHADEVI TEMPLE
SegmentNo	TotalLength	
102/S-W0283/S102837	258.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING AND IMPROVEMENTS TO 2ND MAIN ROAD (AKKAMAHADEVI TEMPLE ROAD) IN WARD NO.102	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
	DESILTING AND IMPROVEMENTS TO 2ND MAIN ROAD (AKKAMAHADEVI TEMPLE ROAD) IN WARD NO.102	102-13-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/607/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0129	NA	ESHWARA TEMPLE
SegmentNo	TotalLength	
102/S-W0129/S105041	401.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AT ESHWARA TEMPLE (SIDE CROSS) ROADS IN WARD NO.102	1500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AT ESHWARA TEMPLE (SIDE CROSS) ROADS IN WARD NO.102	102-15-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/149/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0090	NA	Vrushabhavathinagar
SegmentNo	TotalLength	
102/S-W0090/S090439	1003.73	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.102 VRUSHABHAVATHINAGAR	5000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	DEVELOPMENT AND IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
	DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.102 VRUSHABHAVATHINAGAR	102-16-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/45/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0060	NA	Vrushabhavathinagar
SegmentNo	TotalLength	
102/S-W0060/S040810	381.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING WATER SUPPLY (DRILLING OF BOREWELL) IN WARD NO.102	2500000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	WATER SUPPLY
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING WATER SUPPLY (DRILLING OF BOREWELL) IN WARD NO.102	102-16-000043
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/153/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0227	NA	Vrushabhavathrinagar
SegmentNo	TotalLength	
102/S-W0227/S074328	339.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of potholes in ward no.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	Filling of potholes in ward no.102	102-15-000021
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/409/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0229	NA	magadi main road
SegmentNo	TotalLength	
102/S-W0229/S074853	228.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting from Anjaneya temple and surroundings to Magadi road in ward no.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	Providing asphaltting from Anjaneya temple and surroundings to Magadi road in ward no.102	102-14-000018
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/313/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0046	NA	Vrushabhavathinagar
SegmentNo	TotalLength	
102/S-W0046/S075501	501.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 11th main and 2nd main road in ward no.102 (Shiva temple)		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	Asphalting to 11th main and 2nd main road in ward no.102 (Shiva temple)	102-13-000033
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/609/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0194	NA	Vinayakanagar
SegmentNo	TotalLength	
102/S-W0194/S075756	413.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Vinayakanagara main roads and cross roads in ward no.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	Providing asphaltting to Vinayakanagara main roads and cross roads in ward no.102	102-15-000066
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/384/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0204	NA	1st Main Vinayakanagara
SegmentNo	TotalLength	
102/S-W0204/S011331	278.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
FORMATION AND PROVIDING CC ROAD TO 1ST A MAIN VINAYAKANAGARA IN WARD NO.102	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	PROVIDING CC
Tender	WorkDetails	Job No Work Code
Not a Tender	FORMATION AND PROVIDING CC ROAD TO 1ST A MAIN VINAYAKANAGARA IN WARD NO.102	102-17-000053
Work OrderNo	Work Order Date	Period of Extention
EE/PR/WO/394/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
4	Name
Date of Inspection	Remarks
02/03/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0141, W0135, W0137, W0094, W0104	NA	Ganganna layout
SegmentNo	TotalLength	
102/C-W0141/S012415	208.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO 3RD MAIN AND RCC DRAIN AT 7TH MAIN ROAD OF GANGANNA LAYOUT IN WARD NO.102	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	PROVIDING CC
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING CEMENT CONCRETE TO 3RD MAIN AND RCC DRAIN AT 7TH MAIN ROAD OF GANGANNA LAYOUT IN WARD NO.102	102-17-000049
Work OrderNo	Work Order Date	Period of Extention
EE/PR/WO/397/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0047, W0090, W0060, W0049, W0051	NA, Om Shakthi Lyt 8th Crs	Maruthinagara
SegmentNo	TotalLength	
102/C-W0047/S014724	144.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO 5TH CROSS 11TH MAIN (NORTHEN SIDE) MARUTHINAGARA IN WARD NO.102	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	CC TO ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING CEMENT CONCRETE TO 5TH CROSS 11TH MAIN (NORTHEN SIDE) MARUTHINAGARA IN WARD NO.102	102-17-000046
Work OrderNo	Work Order Date	Period of Extention
EE/PR/WO/396/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0142, W0145, W0140, W0136, W0138	NA, 3rd Crs, 2nd Crs	St. Marry High school
SegmentNo	TotalLength	
102/C-W0142/S035737	169.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB AT JAVARAPPA MAIN ROAD AND CROSS ROAD MARUTHINAGARA IN WARD NO.102	1500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS WITH B.S.SLAB AT JAVARAPPA MAIN ROAD AND CROSS ROAD MARUTHINAGARA IN WARD NO.102	102-15-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/169/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0070, W0087, W0187, W0090, W0109, W0088, W0107, W	NA, Subhash Chandra Bose Lyt	BEML Layout, Sannakki bailu, Aralimara road
SegmentNo	TotalLength	
102/C-W0070/S060325	155.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	Emailld	
9448615567		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF DRAINS AT BEML LAYOUT, SANNAKKI BAYALU, ARALIMARADA ROAD AND MANIVILAS GARDEN IN WARD NO.102	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	DESILTING OF DRAINS
Tender	WorkDetails	Job No Work Code
	DESILTING OF DRAINS AT BEML LAYOUT, SANNAKKI BAYALU, ARALIMARADA ROAD AND MANIVILAS GARDEN IN WARD NO.102	102-15-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/171/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0174, W0159, W0180, W0033, W0090, W0049, W0031, W	NA, Om Shakthi Lyt 8th Crs, 16th Crs, Om Shakthi Lyt 2nd Crs, Om Shakthi Lyt 7th Crs, Veera Anjaneya	VRUSHABHAVATHINAGAR
SegmentNo	TotalLength	
102/C-W0174/S113439	1060.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.B.UMESHA		0.00
PhoneNo	EmailId	
9886213563		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
POTHOLES FILLING AND ROAD CUTTING FILLINGS IN WARD NO.102	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	POTHOLE FILLING
Tender	WorkDetails	Job No Work Code
Tender	POTHOLES FILLING AND ROAD CUTTING FILLINGS IN WARD NO.102	102-16-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/57/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0303	NA	Marappa Industrial are
SegmentNo	TotalLength	
102/S-W0303/S101415	50.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC road at Marappa industrial estate and surrounding cross roads in ward no.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	Providing CC road at Marappa industrial estate and surrounding cross roads in ward no.102	102-15-000010
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/155/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramakrishna
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0277	NA	GOVT SCHOOL
SegmentNo	TotalLength	
102/S-W0277/S102006	74.98	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AND CC ROAD AT GOVT SCHOOL OPP HUCHAPPA ROAD SURROUNDINGS IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AND CC ROAD AT GOVT SCHOOL OPP HUCHAPPA ROAD SURROUNDINGS IN WARD NO.102	102-15-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/178/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	102	Vrisabhavathi Nagar
StreetID	StreetName	Significant LandMark
W0176	NA	Maruthinagar
SegmentNo	TotalLength	
102/S-W0176/S102336	131.27	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AT MARUTHINAGARA AND SURROUNDINGS IN WARD NO.102		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING AT MARUTHINAGARA AND SURROUNDINGS IN WARD NO.102	102-15-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/340/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	