



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0258, W0261	Ambedkar Nagar Slum, NA	NEAR PURUSHOTTAM WINE SHOP
SegmentNo	TotalLength	
103/C-W0258/S123740	177.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PROJECT MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN 3RD MAIN ROAD IN SAMPIGE LYT	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000059
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/WO/460/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
08/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0317	NA	SRI ANAJANYA TEMPLE
SegmentNo	TotalLength	
103/S-W0317/S125313	137.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
E.PANDURANGA		0.00
PhoneNo	EmailId	
9880304277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRIAN AND PROVIDING COVERING SLAB AT 7TH CROSS SRINIVASA NAGAR	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-14-000023
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/204/2013-14	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhar
Date of Inspection	Remarks	
08/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0286, W0279, W0294, W0288, W0290	4th Crs, Maheshwari Nagar, Ambedkar Nagar Slum, NA	KANAKA NAGAR
SegmentNo	TotalLength	
103/C-W0286/S010328	149.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
E.PANDURANGA		0.00
PhoneNo	EmailId	
9880304277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB AT 1ST MAIN ROAD KANAKA NAGAR	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/205/2013-14	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0298, W0291, W0310, W0304, W0293	Manjunath Floor Mill Rd, NA, Chikkanna Lyt 4th Crs, Maheshwari Nagar Opp Police Station Rd	BBMP HOSPITAL
SegmentNo	TotalLength	
103/C-W0298/S011013	156.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
E.PANDURANGA		0.00
PhoneNo	EmailId	
9880304277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT TO DRAIN AND PROVIDING COVERING SLAB AT PANCHASHEELA NAGAR MAIN ROADS	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-14-000024
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/203/2013-14	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0139, W0197, W0176, W0268, W0172, W0143	NA, Vinayaka Lyt 1st Crs	GUDDANNA GOVT SCHOOL
SegmentNo	TotalLength	
103/C-W0139/S011638	207.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GRAJESH		0.00
PhoneNo	EmailId	
9845532977		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRIAN AND PROVIDING COVERING SLAB SURROUNDING GEDDANNA SCHOOL ROAD	1900000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-14-000025
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/467/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0110, W0112, W0075, W0106, W0114, W0108	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	SRI RAMA TEMPLE
SegmentNo	TotalLength	
103/C-W0110/S012631	167.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
E.PANDURANGA		0.00
PhoneNo	EmailId	
9880304277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB IN 3RD MAIN ROAD KAVERIPURA	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-14-000022
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/202/2013-14	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 103	WardName Kaveripura
StreetID W0119, W0072, W0052, W0109, W0078, W0074	StreetName NA	Significant LandMark ST LAWRENCE PRIMARY SCHOOL
SegmentNo 103/C-W0119/S013111	TotalLength 105.51	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9945867208	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF RCC DRAIN TO GADDEKHAN ROAD	Sanctioned Amount 2160000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 103-13-000037
Work OrderNo EE/GRN/AE/WO/433/2012-13	Work Order Date 20/03/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name chandrashekhhar
Date of Inspection 03/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0213	NA	SWD
SegmentNo	TotalLength	
103/S-W0213/S014100	95.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN TO SHARAVATHI NAGARA CROSS ROADS	1940000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-13-000034
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/WO/430/2012-13	20/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
22/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0367, W0348, W0350, W0387, W0381	NA, 1st Crs, Mani Lyt 1st Main Rd	BBMP WARD OFFICE
SegmentNo	TotalLength	
103/C-W0367/S014617	205.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN TO SAMPIGE LYT CROSS ROADS	2400000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/WO/59/2013-14	07/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 103	WardName Kaveripura
StreetID W0280, W0201, W0102, W0282	StreetName 2nd Crs, Lakshmi Sagar Lyt, NA, 3rd A Crs Maheshwari Nagar	Significant LandMark PRASANTHI NAGAR
SegmentNo 103/S-W0280/S015326	TotalLength 79.76	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9945867208	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF RCC DRAIN TO HVR LYT	Sanctioned Amount 3500000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 103-13-000036
Work OrderNo EE/GRN/AE/WO/432/2012-13	Work Order Date 20/03/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name chandrashekhar
Date of Inspection 03/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0302, W0301	Vidya Nursary School & Raj Colony Rd, Bimel Behind Rd	PANCHASHEELA NAGAR BUS STOP
SegmentNo	TotalLength	
103/C-W0302/S015847	180.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.GOVIDARAJU		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IIMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB AT 3RD MAIN ROAD PANCHASHEELANAGAR	1990000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-15-000024
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/236/2014-15	31/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0353, W0330, W0334, W0332, W0337	NA, R H B Colcny, 5th Crs	NEAR NAVEEMI APPARTMENTS
SegmentNo	TotalLength	
103/C-W0353/S020510	184.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.GOVIDARAJU		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB A 6TH ,6TH A 5TH AND 4TH A CROSS ROADS OF SVG NAGAR	2500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-15-000026
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/237/2014-15	31/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0322, W0363, W0361, W0320, W0343, W0345	R H B Colony, 2nd Crs, R H B Colony 1st Main Rd, Chikka Muniswammappa Lyt, 1st Crs, Chikkanna Lyt 1s	NEAR ANAJENYA TEMPLE
SegmentNo	TotalLength	
103/C-W0322/S021157	234.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.GOVIDARAJU		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING CIVERING SLAB AT 4TH CROSS ROAD PATTEGARPALYA	2500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-15-000025
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/234/2014-15	31/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0157, W0211, W0220, W0234, W0224, W0221, W0230	NA	NEAR MUNIESWARA TEMPLE
SegmentNo	TotalLength	
103/C-W0157/S021834	313.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.GOVIDARAJU		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING SLAB AT MINESHWARA NAGARA MAIN AND CROSS ROADS (BALANCE PORTION)	3000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-15-000027
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/TN/WO/264/2014-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0095, W0054, W0046, W0052, W0022, W0048, W0093, W	Om Shakthi Lyt 2nd Crs, NA, 15th Crs, 16th Crs, Subhash Chandra Bose Lyt	VEGETABLE MARKET
SegmentNo	TotalLength	
103/C-W0095/S014133	222.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.KRISHNA		0.00
PhoneNo	EmailId	
9848022180		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC BOX DRAIN AT 1ST MAIN ROAD KAVERIPURA	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-13-000010
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/59/2013-14	24/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0150, W0115, W0195, W0191, W0137, W0090, W0088, W	NA	MYURI TEXTILES
SegmentNo	TotalLength	
103/C-W0150/S014942	303.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.KRISHNA		0.00
PhoneNo	EmailId	
9848022150		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE AND RCC DRAIN AT 3 RD MAIN AND 4TH CROSS RANGANATHAPURA	1910000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	C C ROAD AND RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender		103-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/58/2013-14	24/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0322, W0363, W0361, W0320, W0343, W0318	R H B Colony, 2nd Crs, R H B Colony 1st Main Rd, Chikka Muniswammappa Lyt, 1st Crs, Chikkanna Lyt 1s	ANAJANEYA TEMPLE
SegmentNo	TotalLength	
103/C-W0322/S021619	334.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER		0.00
PhoneNo	EmailId	
9848022143		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF ROAD AND FOOTPATH IN PATTEGARAPALYA	4500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROADS AND FOOTPATH
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000050
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/406/2013-14	01/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0196, W0143	NA	ABOVE HITENTATION LINE
SegmentNo	TotalLength	
103/C-W0196/S023013	190.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
NARASIMHA MURTHY .R		0.00
PhoneNo	EmailId	
9980197783		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC BOX DRAIN AT 5TH MAIN ROAD IN BETWEEN 2ND CROSS HVR LAYOUT AND MAGADI MAIN ROAD	800000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	RCC BOX DRAIN AND CULVERT
Tender	WorkDetails	Job No Work Code
Tender		103-11-000043
Work OrderNo	Work Order Date	Period of Extention
EE(GNR)/AE/TN/WO/190/2014- 15	13/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 103	WardName Kaveripura
StreetID W0289, W0300, W0287, W0298, W0296, W0021	StreetName Chikkanna Lyt, 4th Crs Lakshmi Sagar Lyt, Maheshwari Nagar 4th Main Rd, Manjunath Floor Mill Rd, 1s	Significant LandMark 8TH CROSS PANCHASHEELA NAGAR
SegmentNo 103/C-W0289/S024226	TotalLength 148.95	


ContractorDetails		
NameofContractor TECHNICAL MANAGER	ContractorRegNo	Expenditure 0.00
PhoneNo 9848022150	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB TO PANCHASHEELANAGAR	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 103-14-000033
Work OrderNo EE(GRN)/AE/W0/24/2014-15	Work Order Date 03/07/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
03/09/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0371, W0383	Dr Ambekdar Govt Ashraya Colony Garudacharapalya, 1st Crs	NEAR 60 FEET ROAD
SegmentNo	TotalLength	
103/S-W0371/S030034	137.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9848022150		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAN AND PROVIDING COVERING SLAB TO SAMPIGE LAYOUT ROADS	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	0	103-14-000035
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/25/2014-15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0316, W0289, W0287, W0298, W0296, W0293, W0291, W	Chikkanna Lyt 2nd Crs, Maheshwari Nagar 4th Main Rd, Manjunath Floor Mill Rd, 1st Crs, Maheshwari Na	NEAR FRANCK PUBLIC SCHOOL
SegmentNo	TotalLength	
103/C-W0316/S031050	159.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CONCRETE CEMENT ROAD AND DRAIN AT PACHASHEELANAGAR	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000063
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/478/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0075, W0214, W0235, W0218, W0222, W0216, W0212	NA	NEAR SWD
SegmentNo	TotalLength	
103/C-W0075/S031848	311.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD AND SIDE DRAIN AT KAVERI PURA (BDA LAYOUT)	5000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000062
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/479/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 103	WardName Kaveripura
StreetID W0088, W0137, W0135, W0090	StreetName NA	Significant LandMark MAYURA TEXTILES
SegmentNo 103/C-W0088/S032603	TotalLength 72.45	

ContractorDetails		
NameofContractor C.MAHESH	ContractorRegNo	Expenditure 0.00
PhoneNo 8095016337	EmailId	

Work Details		
NameOfWork PROVIDING CEMENT CONCRETE ROAD FOR KALASAPPA ROAD	Sanctioned Amount 400000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 103-14-000028
Work OrderNo EE(GRN)AE/TN/WO/199/2013-14	Work Order Date 16/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name chandrashekhhar
Date of Inspection 03/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0150, W0158, W0154, W0195, W0186	NA	GANAPATHI TEMPLE
SegmentNo	TotalLength	
103/C-W0150/S033307	106.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.MAHESH		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT TO ROAD AND DRAIN AND PROVIDING COVERING SLAB AT 3RD MAIN ROAD RANGANATHAPURA (OPP. TO GANAPATHI TEMPLE ROAD)	600000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN AND ROAD
Tender	WorkDetails	Job No Work Code
Tender		103-14-000019
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/200/2013- 14	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
03/09/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0131, W0117, W0123, W0115, W0092	NA	GANAPATHI TEMPLE
SegmentNo	TotalLength	
103/C-W0131/S034104	67.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.TIRUMALESHA		0.00
PhoneNo	EmailId	
9848022151		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC BOX DRAIN AND CEMENT CONCRETE TO LANE IN CONTINUATION OF 3RD CROSS RANGANATHAPURA	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC BOX DRAIN
Tender	WorkDetails	Job No Work Code
Tender		103-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/2013-14	31/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0169, W0093, W0181, W0138, W0130, W0136, W0128	NA, 15th Crs, Vinayaka Lyt 3rd Crs, 2nd Crs	GURURAJA PRIMEARY SCHOOL
SegmentNo	TotalLength	
103/C-W0169/S051706	231.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE ROAD AND DRAINS TO KAVERIPURA CROSS ROADS	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	C.C ROADS AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000032
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/23/2013-14	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0093, W0126, W0185	15th Crs, NA	RES HIGH SCHOOL
SegmentNo	TotalLength	
103/C-W0093/S052414	116.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING C.C ROADS TO KAVERIPURA	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000034
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/243/2013-14	17/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0152, W0115, W0191, W0109, W0156	NA	GANAPATHI TEMPLE
SegmentNo	TotalLength	
103/C-W0152/S052959	101.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.KRISHNA		0.00
PhoneNo	EmailId	
9035489036		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN AND RE CONSTRUCTION OF CULVERTS AT 5TH CROSS FROM 3RD MAIN TO 7TH MAIN ROAD RANGANATHAPURA	1990000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC DRAIN AND CULVERTS
Tender	WorkDetails	Job No Work Code
Tender		103-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/60/2013-14	24/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0300, W0287, W0298, W0296, W0021, W0289	4th Crs Lakshmi Sagar Lyt, Maheshwari Nagar 4th Main Rd, Manjunath Floor Mill Rd, 1st Crs, 8th Crs,	8TH CROSS PANCHASHEELANAGAR
SegmentNo	TotalLength	
103/C-W0300/S053803	150.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER (KRIDL)		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO PANCHASHEELA NAGAR ROADS	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000031
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/WO/242/2013-14	17/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0287, W0298, W0296	Maheshwari Nagar 4th Main Rd, Manjunath Floor Mill Rd, 1st Crs	FRANK PUBLIC SCHOOL
SegmentNo	TotalLength	
103/C-W0287/S054256	90.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R.ANIL KUMAR		0.00
PhoneNo	EmailId	
9848022152		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
WORK OF FORMATION OF ROAD AT 4TH MAIN ROAD OF PANCHASHEELA NAGAR	900000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender		103-12-000053
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/157/2012-13	13/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0093, W0075, W0040, W0083, W0048, W0050	15th Crs, NA	ST MEERA HIGH SCHOOL
SegmentNo	TotalLength	
103/C-W0093/S054742	206.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.RAJESH		0.00
PhoneNo	EmailId	
9845532977		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING COVERING SLAB AT 2ND MAIN1ST CROSS KAVERI PURA	1900000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	103-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/468/2013- 14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0381, W0373, W0377, W0356, W0385	NA, East Park Reje Lyt, V S T Opposite, 5th Crs, 8th Crs Gramatana	PINEWOOD SCHOOL
SegmentNo	TotalLength	
103/C-W0381/S055454	299.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.GOVINDARAJU		0.00
PhoneNo	EmailId	
8095016337		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 6TH MAIN ROAD OF SAMPIGE LYT	1900000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		103-12-000061
Work OrderNo	Work Order Date	Period of Extention
EE(GRN)/AE/TN/WO/168/2012- 13	26/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0139, W0178, W0180	NA	water tank
SegmentNo	TotalLength	
103/C-W0139/S053458	74.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO ROAD NEAR WATER TANK RANAGANATHA PURA	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000056
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/W0/462/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0083, W0079, W0089, W0081, W0077, W0022, W0095, W	NA, Om Shakthi Lyt 4th Crs, 14th Crs, Om Shakthi Lyt 2nd Crs, 15th Crs	MARKET ROAD
SegmentNo	TotalLength	
103/C-W0083/S054035	148.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF VEGETABLE MARKET ROAD AND DRAIN KAVERIPURA	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND ONE SIDE DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000055
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/WO/464/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhar
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	103	Kaveripura
StreetID	StreetName	Significant LandMark
W0066, W0056, W0062, W0068, W0058, W0060, W0064, W	NA	SWD
SegmentNo	TotalLength	
103/C-W0066/S054625	197.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRDIL		0.00
PhoneNo	EmailId	
9945867208		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF SABARAPALYA ROAD AND DRAIN IN KAVERIPURA	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender		103-14-000054
Work OrderNo	Work Order Date	Period of Extention
EE/GRN/AE/WO/465/2013-14	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrashekhara
Date of Inspection	Remarks	
24/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition

