



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0007, W0008, W0013, W0025, W0017, W0019, W0010 | NA | RAJAJI NAGAR 4TH BLOCK |
| SegmentNo | TotalLength | |
| 108/C-W0007/S013042 | 388.21 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| R JAIKUMAR | | 414821.00 |
| PhoneNo | EmailId | |
| 9541252485 | | |

| Work Details | | |
|---|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS & PROVIDING FLAGGING COURSE IN 42ND CROSS IN 4TH BLOCK RAJAJI NAGAR | 415282 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Others | FLAGGING COURSE |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000044 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\RN\PR\158\12-13 | 19/11/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0103 | NA | RAJAJINAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0103/S045631 | 207.75 | |


| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KIRAN Y | | 395292.00 |
| PhoneNo | EmailId | |
| 9152416516 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROIDING SSM FLAGGING CVOURSE AND BS SLAB CVERING | 396442 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000063 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\RN\WO\214\2012-13 | 19/12/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|---|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|---|--|
| Zone WEST | WardNo 108 | WardName Srirammandir |
| StreetID W0107 | StreetName Subhash Chandra Bose Lyt | Significant LandMark VENKAT INTERNATIONAL PUBLIC SCHOOL |
| SegmentNo 108/S-W0107/S045935 | TotalLength 282.42 | |

| | | |
|---------------------------------------|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor J K SUKESH | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9854535456 | EmailId | |

| | | |
|--|--|--|
| Work Details | | |
| NameOfWork PROVIDING SSM FLAGGING COURSE AND BS SLAB COVERING TO DRAIN | Sanctioned Amount 415035 | Sanctioned Year 2012 |
| Year 2012 - 2013 | Type of Work Drain Maintenance | Other Work Type |
| Tender Tender | WorkDetails | Job No Work Code 108-12-000061 |
| Work OrderNo EE\RN\WO\213\2012-13 | Work Order Date | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|---------------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name vijaykumar |
| Date of Inspection 14/09/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0090, W0075 | NA | RAJAJINAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/C-W0090/S053815 | 140.34 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| A RAJA | | 0.00 |
| PhoneNo | EmailId | |
| 9451686468 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING SSM FLAGGING COURSE AND BS BS SLAB COVERING TO DRAIN | 516087 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000064 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\RN\WO\188\2012-13 | | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0143 | NA | CHAMUNDI SLUM |
| SegmentNo | TotalLength | |
| 108/S-W0143/S054956 | 149.12 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9521564165 | | |

| | | |
|--|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVODING CEMENT CONCRETE PAVING AND RCC COVERING TO DRAIN IN CHAMUNDI SLUM | 5000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-11-0000099 |
| Work OrderNo | Work Order Date | Period of Extention |
| WW\NR\WO\351\12-13 | | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---|------------------------------|--|
| Zone WEST | WardNo 108 | WardName Srirammandir |
| StreetID W0150 | StreetName NA | Significant LandMark JADERAHALLI |
| SegmentNo 108/S-W0150/S055326 | TotalLength 661.34 | |


| | | |
|----------------------------------|------------------------|----------------------------|
| ContractorDetails | | |
| NameofContractor KRIDL | ContractorRegNo | Expenditure 0.00 |
| PhoneNo 9546654654 | EmailId | |

| | | |
|---|--|--|
| Work Details | | |
| NameOfWork CONSTRUCTION OF RCC DRAINS WITH COVERING IN 72ND CROSS | Sanctioned Amount 2000000 | Sanctioned Year 2013 |
| Year 2013 - 2014 | Type of Work Drain Maintenance | Other Work Type |
| Tender Not a Tender | WorkDetails | Job No Work Code 108-11-000102 |
| Work OrderNo EE\RN\WO\356\2012-13 | Work Order Date | Period of Extention |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved No |

| | | |
|---|--------------------------|---------------------------|
| Field Inspection Details | | |
| Number of Trees 0 | Other Information | Name vijaykumar |
| Date of Inspection 14/09/2015 | Remarks | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|---|
| Road Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0053 | NA | YAMAHA SHOWROOM |
| SegmentNo | TotalLength | |
| 108/S-W0053/S060753 | 848.61 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9415115642 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN & FOOTPATH IN 1ST MAIN | 2000000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-12-000036 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\RN\WO\380\2012-13 | | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0120 | NA | RAJAJINAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0120/S062844 | 210.95 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9454862354 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING SSM DRAIN | 1500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-14-000026 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\99\14-15 | 05/09/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0110 | NA | RAJAJI NAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0110/S063109 | 673.59 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9654153056 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING SSM DRAIN IN 66TH CROSS | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-14-000024 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\102\14-15 | 12/09/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0094 | NA | RAJAJINAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0094/S063327 | 635.53 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 0.00 |
| PhoneNo | EmailId | |
| 9546348154 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING SSM DRAIN IN 65TH CROSS | 2000000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-14-000023 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\RN\WO\2014-15 | 12/09/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0182 | NA | GUBBANNA INDUSTRIAL AREA |
| SegmentNo | TotalLength | |
| 108/S-W0182/S063646 | 119.57 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| A RAJA | | 0.00 |
| PhoneNo | EmailId | |
| 9535416515 | | |

| | | |
|---------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO CC ROAD AT 10TH CROSS | 500000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Road | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-13-000008 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\148\14-15 | 17/12/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0015 | NA | WEST SIDE |
| SegmentNo | TotalLength | |
| 108/S-W0015/S064017 | 195.58 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KR NAGARAJ | | 0.00 |
| PhoneNo | EmailId | |
| 9651635146 | | |

| | | |
|---|---------------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| RESETTING OF FOOTPATH IN THE 10TH MAIN | 200000 | 2014 |
| Year | Type of Work | Other Work Type |
| 2014 - 2015 | Footpath Layering | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000054 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\03\14-15 | 12/05/2014 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0060 | NA | RAJAJI NAGAR |
| SegmentNo | TotalLength | |
| 108/S-W0060/S064431 | 122.99 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| R SUDARSHAN | | 0.00 |
| PhoneNo | EmailId | |
| 9643126465 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS AND PROVIDING BS SLAB DRAIN | 500000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000043 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\201\2012-13 | 19/12/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|------------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0063 | Om Shakthi Lyt 6th Crs | NATIONAL PUBLIC SCHOOL |
| SegmentNo | TotalLength | |
| 108/S-W0063/S064714 | 162.38 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| R SUDARSHAN | | 0.00 |
| PhoneNo | EmailId | |
| 9321556561 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING BS SLAB COVERING TO DRAIN | 200000 | 2012 |
| Year | Type of Work | Other Work Type |
| 2012 - 2013 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-12-000058 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\271\12-13 | 18/01/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0140 | 3rd Crs | RAJAJI NAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0140/S123053 | 114.18 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| C.NANJUDASWAMY | | 0.00 |
| PhoneNo | EmailId | |
| 9612365151 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN & FOOTPATH | 400000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-13-000014 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\53\13-14 | | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0148 | NA | RAJAJI NAGAR 5TH BLOCK |
| SegmentNo | TotalLength | |
| 108/S-W0148/S124543 | 211.76 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| C.NANJUNDASWAMY | | 0.00 |
| PhoneNo | EmailId | |
| 9156416135 | | |

| Work Details | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENTS TO DRAIN & FOOTPATH | 400000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Drain Maintenance | |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 108-13-000016 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\54\13-14 | 08/08/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | Yes |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|-------|
| Road Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0183 | NA | KB TEMPLE |
| SegmentNo | TotalLength | |
| 108/S-W0183/S020058 | 260.95 | |



| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 1585000.00 |
| PhoneNo | EmailId | |
| 9678346236 | | |

| | | |
|---|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING CULVERTS AND SSM DRAINS IN 10TH CROSS KB TEMPLE IN 10TH CROSS | 1500000 | 2011 |
| Year | Type of Work | Other Work Type |
| 2011 - 2012 | Others | DRAIN & CUVERTS |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-11-000050 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\322\2011-12 | 28/02/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | ganesh |
| Date of Inspection | Remarks | |
| 07/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|----------------|--|
| Road Condition |  |
| Road Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0185 | NA | KB TEMPLE |
| SegmentNo | TotalLength | |
| 108/S-W0185/S020535 | 161.98 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 1585000.00 |
| PhoneNo | EmailId | |
| 9738246327 | | |

| | | |
|--|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING CULVERTS & SSM DRAINS IN 9TH CROSS KB TEMPLE | 1500000 | 2011 |
| Year | Type of Work | Other Work Type |
| 2011 - 2012 | Others | DRAINS & CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-11-000049 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\W0\324\2011-12 | 28/02/2012 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0189 | NA | KB TEMPLE |
| SegmentNo | TotalLength | |
| 108/S-W0189/S021125 | 169.81 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| KRIDL | | 1082000.00 |
| PhoneNo | EmailId | |
| 9248368732 | | |

| | | |
|-------------------------------------|-----------------------------------|-------------------------------|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| PROVIDING CULVERTS & DRAINS | 1000000 | 2011 |
| Year | Type of Work | Other Work Type |
| 2011 - 2012 | Others | DRAIN & CULVERTS |
| Tender | WorkDetails | Job No Work Code |
| Not a Tender | | 108-11-000047 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE\NRN\WO\314\2011-12 | 02/06/2011 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | vijaykumar |
| Date of Inspection | Remarks | |
| 14/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|-------|
| Drain Condition | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|--|---|--------------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0101, W0099, W0061, W0105, W0073, W0107, W0095, W | Om Shakthi Lyt 1st Crs, NA, Om Shakthi Lyt 7th Crs, Subhash Chandra Bose Lyt, Om Shakthi Lyt 2nd Crs | VENKAT INTERNATIONAL SCHOOL |
| SegmentNo | TotalLength | |
| 108/C-W0101/S024452 | 431.30 | |

| ContractorDetails | | |
|-------------------------|------------------------|--------------------|
| NameofContractor | ContractorRegNo | Expenditure |
| T. RAJESH | | 1093465.00 |
| PhoneNo | EmailId | |
| 9923456785 | | |

| Work Details | | |
|--|---------------------------------------|-------------------------------|
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENT TO DRAIN AND PROVIDING FLAGGING | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | |
| Tender | WorkDetails | Job No Work Code |
| Tender | 0 | 108-13-000012 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/RNR/TS/PR/335/2012-13 | 03/09/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| Field Inspection Details | | |
|---------------------------|--------------------------|-------------|
| Number of Trees | Other Information | Name |
| 0 | | ganesh |
| Date of Inspection | Remarks | |
| 07/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| | | |
|---------------------|--------------------|-----------------------------|
| Zone | WardNo | WardName |
| WEST | 108 | Srirammandir |
| StreetID | StreetName | Significant LandMark |
| W0075 | NA | 65TH CROSS 18 TH MAIN |
| SegmentNo | TotalLength | |
| 108/S-W0075/S030428 | 436.89 | |

| | | |
|--------------------------|------------------------|--------------------|
| ContractorDetails | | |
| NameofContractor | ContractorRegNo | Expenditure |
| M.MANJUNATHSWAMY | | 0.00 |
| PhoneNo | EmailId | |
| 7090130655 | | |

| | | |
|---|-----------------------------------|---|
| Work Details | | |
| NameOfWork | Sanctioned Amount | Sanctioned Year |
| IMPROVEMENT TO DRAIN AND PROVIDING FLAGGING | 1500000 | 2013 |
| Year | Type of Work | Other Work Type |
| 2013 - 2014 | Others | IMPROVEMENT TO DRAIN AND PROVIDING FLAGGING |
| Tender | WorkDetails | Job No Work Code |
| Tender | | 109-13-000011 |
| Work OrderNo | Work Order Date | Period of Extention |
| EE/RNR/TS/PR/354/2012-13 | 03/09/2013 | |
| Defect Liability Period From | Defect Liability Period To | Multiple Road Involved |
| | | No |

| | | |
|---------------------------------|--------------------------|-------------|
| Field Inspection Details | | |
| Number of Trees | Other Information | Name |
| 0 | | ganesh |
| Date of Inspection | Remarks | |
| 07/09/2015 | | |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

| Category | Photo |
|-----------------|--|
| Drain Condition |  |
| Drain Condition |  |