ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0228	NA	singapura village
SegmentNo	**TotalLength**	
11/S-W0228/S054100	101.24	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH T		2237072.27
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Singapura village surrounding areas in ward no. 11 kuvempunagara	2500000	2015-15
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing concrete road	011-16-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/336/2015-16	30/03/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
1		suresh
Date of Inspection	**Remarks**	
10/11/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0252	NA	SINGAPURA VILLAGE
SegmentNo	**TotalLength**	
11/S-W0252/S055211	102.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH T		2237072.27
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Singapura village surrounding areas in ward no. 11	2500000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016		
Tender	**WorkDetails**	**Job No Work Code**
		011-16-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/336/2015-16	30/03/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
0		suresh
Date of Inspection	**Remarks**	
10/11/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0254	NA	SINGAPURA VILLAGE
SegmentNo	**TotalLength**	
11/S-W0254/S055816	82.20	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH T		2237072.27
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Singapura village surrounding areas in ward no. 11	2500000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016		
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-16-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/336/2015-16	30/03/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
2		suresh
Date of Inspection	**Remarks**	
10/11/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0238, W0228, W0323, W0240	NA, 10th Crs Lakshmi Sagar Lyt	SINGAPURA VILLAGE
SegmentNo	**TotalLength**	
11/C-W0238/S061326	27.55	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH T		2237072.27
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Singapura village surrounding areas in ward no. 11	2500000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016		
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-16-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/336/2015-16	30/03/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
3		suresh
Date of Inspection	**Remarks**	
10/11/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0600	2nd Crs	Near Durga shreyas Apartment
SegmentNo	**TotalLength**	
11/S-W0600/S113938	51.77	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), Ve		1692023.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	011-14-000069
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/276/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0574, W0677	NA	Near Durga shreyas Apartment
SegmentNo	**TotalLength**	
11/C-W0574/S115610	26.58	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), Ve		1692023.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	011-14-000069
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/276/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0576	NA	Near Durga shreyas Apartment
SegmentNo	**TotalLength**	
11/S-W0576/S115934	32.72	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), Ve		1692023.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	011-14-000069
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/276/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0578	NA	Near Durga shreyas Apartment
SegmentNo	**TotalLength**	
11/S-W0578/S120302	49.35	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), Ve		1692023.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Mariyamma Block Garden In Ward No-11	011-14-000069
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/276/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0528	NA	Near Kuvempu Nagar 2nd Stage Bmtc Bus Stop
SegmentNo	**TotalLength**	
11/S-W0528/S122526	85.51	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. K. Shankar Reddy, Contractor, No.03, 1St Main, Ramachanrappa Layout, Arabic College(P), Veerana		1262135.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	1500000	3014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Road And Construction Of Culver
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	011-14-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/270/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0532	1st Crs	Near Kuvempu Nagar 2nd Stage Bmtc Bus Stop
SegmentNo	**TotalLength**	
11/S-W0532/S123428	85.07	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. K. Shankar Reddy, Contractor, No.03, 1St Main, Ramachanrappa Layout, Arabic College(P), Veerana		1262135.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Road And Construction Of Culver
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	011-14-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/270/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0593, W0524	6th Crs, NA	Nar Govt School
SegmentNo	**TotalLength**	
11/C-W0593/S124324	57.07	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. K. Shankar Reddy, Contractor, No.03, 1St Main, Ramachanrappa Layout, Arabic College(P), Veerana		1262135.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Road And Construction Of Culver
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Construction Of Culverts And Road Patch Works At Kuvempu Nagar 2Nd Stage In Ward No-11	011-14-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/270/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0157	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0157/S020037	77.86	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		2429163.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroun	2500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads, Drains And Providing Coveri
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroundings In Ward No-11	011-14-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/274/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0094	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0094/S020812	65.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		2429163.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroun	2500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroundings In Ward No-11	011-14-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/274/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0092	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0092/S021211	34.97	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		2429163.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroun	2500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads, Drains And Providing Coveri
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads, Drains And Providing Covering Slab To Chikkabettahalli Village (Newly Added Area) At MS Palya 3Rd Stage Near Anganavadi Surroundings In Ward No-11	011-14-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/274/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0001	NA	Near Singapura Lake
SegmentNo	**TotalLength**	
11/S-W0001/S023337	124.40	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1630425.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Express Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Express Layout In Ward No-11	011-14-000071
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0003	NA	Near Singapura Lake
SegmentNo	**TotalLength**	
11/S-W0003/S024609	138.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1630425.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Express Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Express Layout In Ward No-11	011-14-000071
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0015, W0005, W0002	NA	Near Singapura Lake
SegmentNo	**TotalLength**	
11/C-W0015/S025757	149.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1630425.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Express Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Express Layout In Ward No-11	011-14-000071
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0002	NA	Near Singapura Lake
SegmentNo	**TotalLength**	
11/S-W0002/S030033	91.76	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1630425.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Express Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Express Layout In Ward No-11	011-14-000071
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2013-14	07/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
WA002	NA	Near Singapura Lake
SegmentNo	**TotalLength**	
11/S-WA002/S030359	76.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1630425.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Express Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Express Layout In Ward No-11	011-14-000071
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/267/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0658	NA	Near Rajarajeshwari High School
SegmentNo	**TotalLength**	
11/S-W0658/S032233	33.35	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1709545.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads, Drains And Providing Cov
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	11-14-000070
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRIDL/WO/481/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/03/2014	28/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0676	Vinayaka Lyt Rd	Near Rajarajeshwari High School
SegmentNo	**TotalLength**	
11/S-W0676/S032908	34.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1709545.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads, Drains And Providing Cov
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	11-14-000070
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRIDL/WO/481/2013-14	21/02/2014	90 Dyas
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/03/2014	28/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0644, W0777, W0676, W0775, W0658, W0779, W0690, W	2nd Crs, Mariyappa Lyt Rd, Vinayaka Lyt Rd, Gear College, NA, Munireddy Lyt Rd	Near Rajarajeshwari High School
SegmentNo	**TotalLength**	
11/C-W0644/S033339	168.76	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1709545.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads, Drains And Providing Cov
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To CC Roads, Drains And Providing Covering Slabs At Raghuram Layout In Ward No-11	11-14-000070
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRIDL/WO/481/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/03/2014	28/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0479	1st Crs	LAKSHMI SAGAR LAYOUT
SegmentNo	**TotalLength**	
11/S-W0479/S105818	181.97	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. E. Sudhakar Reddy (Swasthik Enterprises) Contractor, F3 A Block, SLS Silver Oak Apartment, Viru		1612859.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Dewappa Layout In Ward No.11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Dewappa Layout In Ward No.11	011-14-000067
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/530/2013-14	24/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/03/2015	08/03/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0382	Doddamuniswammppa Lyt, 1st Crs	DODDAMUNISWAMAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0382/S110334	161.90	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. E. Sudhakar Reddy (Swasthik Enterprises) Contractor, F3 A Block, SLS Silver Oak Apartment, Viru		1612859.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Dewappa Layout In Ward No.11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Dewappa Layout In Ward No.11	011-14-000067
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/530/2013-14	24/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/03/2015	08/03/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0390, W0471, W0475	5th Crs, NA, 2nd Crs	LAKSHMI SAGAR LAYOUT
SegmentNo	**TotalLength**	
11/C-W0390/S110604	30.20	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. E. Sudhakar Reddy (Swasthik Enterprises) Contractor, F3 A Block, SLS Silver Oak Apartment, Viru		1612859.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Dewappa Layout In Ward No.11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Dewappa Layout In Ward No.11	011-14-000067
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/530/2013-14	24/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/03/2015	08/03/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0473, W0471, W0477	NA	LAKSHMI SAGAR LAYOUT
SegmentNo	**TotalLength**	
11/C-W0473/S110844	11.95	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. E. Sudhakar Reddy (Swasthik Enterprises) Contractor, F3 A Block, SLS Silver Oak Apartment, Viru		1612859.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads & Drains At Dewappa Layout In Ward No.11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads & Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads & Drains At Dewappa Layout In Ward No.11	011-14-000067
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/530/2013-14	24/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/03/2015	08/03/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
5		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0416	5th Crs	NAGAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0416/S111258	58.46	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No. 03, 1St Main Ramachandrappa Layout, Arabic College(P), Veeranapalya,		2460261.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	3000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And BS Slab Drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	011-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/273/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/04/2014	27/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
5		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0418	7th Crs Gramatana	NAGAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0418/S112333	59.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No. 03, 1St Main Ramachandrappa Layout, Arabic College(P), Veeranapalya,		2460261.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	3000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And BS Slab Drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	011-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/273/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/04/2014	27/04/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
4		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0424	NA	NAGAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0424/S113651	60.47	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No. 03, 1St Main Ramachandrappa Layout, Arabic College(P), Veeranapalya,		2460261.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	3000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And BS Slab Drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	011-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/273/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/04/2014	27/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0430	Nagappa Lyt	NAGAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0430/S114306	63.10	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No. 03, 1St Main Ramachandrappa Layout, Arabic College(P), Veeranapalya,		2460261.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	3000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And BS Slab Drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	011-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/273/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/04/2014	27/04/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0434	NA	NAGAPPA LAYOUT
SegmentNo	**TotalLength**	
11/S-W0434/S114504	64.56	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopireddy, Contractor, No. 03, 1St Main Ramachandrappa Layout, Arabic College(P), Veeranapalya,		2460261.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	3000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And BS Slab Drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And BS Slab Drain At Asraya Badavane (Singapura) In Ward No.11	011-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/273/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/04/2014	27/04/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0052, W0056, W0054, W0060, W0079, W0099	NA, Om Shakthi Lyt 4th Crs	VARADARAJA NAGAR
SegmentNo	**TotalLength**	
11/C-W0052/S115251	165.38	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, No.26, Near Sunrise School, Kempapura, Hebbala, Bangalore-24		1679923.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Asphalting to MS Palya Grama Tana Roads At Ms Palya In Ward No.11	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Asphalting to MS Palya Grama Tana Roads At Ms Palya In Ward No.11	011-13-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/71/2013-14	04/07/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0056, W0079, W0099	NA, Om Shakthi Lyt 4th Crs	VARADARAJU LAYOUT
SegmentNo	**TotalLength**	
11/C-W0056/S115902	111.53	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, No.26, Near Sunrise School, Kempapura, Hebbala, Bangalore-24		1679923.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Asphalting to MS Palya Grama Tana Roads At Ms Palya In Ward No.11	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Asphalting to MS Palya Grama Tana Roads At Ms Palya In Ward No.11	011-13-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/71/2013-14	04/07/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0174, W0336, W0185, W0187	NA, R H B Colcny, 6th Crs	NEAR GOVT URDU SCHOOL
SegmentNo	**TotalLength**	
11/C-W0174/S120916	74.41	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Manjuegowda V Patel, Contractor, #1045, Sri. Raghavendra Nilaya, R.T. Nagar(P), Bangalore-32		919500.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads And Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	011-12-000023
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/185/2012-13	15/11/2012	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/08/2013	01/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
5		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0195, W0203, W0340, W0336, W0201, W0096, W0207, W	NA, Mariyappa Lyt, R H B Colcny, 6th Crs, Vinayaka Lyt 2nd Crs, 3rd Crs	NEAR GOVT URDU SCHOOL
SegmentNo	**TotalLength**	
11/C-W0195/S122416	141.86	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Manjuegowda V Patel, Contractor, #1045, Sri. Raghavendra Nilaya, R.T. Nagar(P), Bangalore-32		919500.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads And Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	011-12-000023
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/185/2012-13	15/11/2012	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/08/2013	01/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
4		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0195	NA	NEAR GOVT URDU SCHOOL
SegmentNo	**TotalLength**	
11/S-W0195/S122857	27.01	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Manjuegowda V Patel, Contractor, #1045, Sri. Raghavendra Nilaya, R.T. Nagar(P), Bangalore-32		919500.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads And Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads And Drains In Vinayakanagara Back Ward Areas In Ward No.11	011-12-000023
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/185/2012-13	15/11/2012	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/08/2014	01/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0435, W0159, W0441, W0163, W0453, W0425, W0096, W	NA, 6th Crs, 2nd Crs, Garudachar Palya Main Rd	M S Palya to Vidyaranyapura Main Road
SegmentNo	**TotalLength**	
11/C-W0435/S015228	486.80	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Comprehensive development of Road from M S Palya to Vidyaranyapura Main in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	10000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Comprehensive development of Road from M S Palya to Vidyaranyapura Main in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	304-14-000260
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/RI/RRN/WO/06/2014-15	02/07/2014	8 MONTHS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
22/08/2015	21/08/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
4		SUMANA L S
Date of Inspection	**Remarks**	
18/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0562	NA	Kuvempunagara 1st stage
SegmentNo	**TotalLength**	
11/S-W0562/S110131	183.84	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH		0.00
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance roads and drains at Kuvempunagara 1st Stage and surrounding roads in ward no. 11 (Kuvempunagara), Vidyaranyapura sub division	3000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000050
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/338/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
2		suresh
Date of Inspection	**Remarks**	
29/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0560	NA	Kuvempunagara 1st Stage
SegmentNo	**TotalLength**	
11/S-W0560/S111451	213.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH		0.00
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance roads and drains at Kuvempunagara 1st Stage and surrounding roads in ward no. 11 (Kuvempunagara), Vidyaranyapura sub division	3000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000050
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/338/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
4		suresh
Date of Inspection	**Remarks**	
29/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0611, W0633, W0516	NA, Muniswamy Shetty Lyt Rd	KUVEMPUNAGARA 2ND STAGE
SegmentNo	**TotalLength**	
11/C-W0611/S113654	70.30	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH		0.00
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance roads and drains at Kuvempunagara 2nd Stage and surrounding roads in ward no. 11 (Kuvempunagara), Vidyaranyapura sub division	3000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/337/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
5		suresh
Date of Inspection	**Remarks**	
29/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0558	NA	Kuvempunagara 2nd stage
SegmentNo	**TotalLength**	
11/S-W0558/S055808	220.50	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH		0.00
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance roads and drains at Kuvempunagara 2nd Stage and surrounding roads in ward no. 11 (Kuvempunagara), Vidyaranyapura sub division	3000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/337/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
3		suresh
Date of Inspection	**Remarks**	
29/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0560	NA	Kuvempunagara 2nd stage
SegmentNo	**TotalLength**	
11/S-W0560/S060531	213.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
JAYAPRAKASH		0.00
PhoneNo	**EmailId**	
9980377722		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Balance roads and drains at Kuvempunagara 2nd Stage and surrounding roads in ward no. 11 (Kuvempunagara), Vidyaranyapura sub division	3000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/337/2016-17		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
1		suresh
Date of Inspection	**Remarks**	
29/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0628	5th Crs	RAMACHANDRAPURA
SegmentNo	**TotalLength**	
11/S-W0628/S024556	87.74	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1877155.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	2000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	011-13-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./351/2012-13	28/02/2013	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/05/2014	27/05/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0634, W0769	NA	RAMACHANDRAPURA
SegmentNo	**TotalLength**	
11/C-W0634/S025435	82.08	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1877155.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	2000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	011-13-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./351/2012-13	28/02/2013	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/05/2014	27/05/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0644, W0775, W0781, W0771, W0769	2nd Crs, Gear College, NA	RAMACHANDRAPURA
SegmentNo	**TotalLength**	
11/C-W0644/S030138	84.74	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1877155.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	2000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads At Ward No.11 Kuvempunagar In Singapura Garden And Singapura Paradise	011-13-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./351/2012-13	28/02/2013	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/05/2014	27/05/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0474, W0563, W0553, W0555, W0507, W0525	4th Crs, Sathya Lyt, NA, I T P L Main Rd	SATHYA LAYOUT
SegmentNo	**TotalLength**	
11/C-W0474/S030750	108.09	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
M/s Shobha Enterprises, #09, Sri Venkateshwara Nilaya, 11Th Main, Shivanagara, Rajaji Nagara, Bangal		902118.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads and Drains in Kuvempu nagar 1St Stage Slum In Ward No.11	1000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements to Roads and Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Roads and Drains in Kuvempu nagar 1St Stage Slum In Ward No.11	011-12-000029
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-TND/437/2012-13	16/03/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/10/2014	20/10/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0520, W0518, W0474, W0476, W0591	NA, 4th Crs, 3rd Crs	NEAR GOVT SCHOOL
SegmentNo	**TotalLength**	
11/C-W0520/S031346	65.29	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
M/s Shobha Enterprises, #09, Sri Venkateshwara Nilaya, 11Th Main, Shivanagara, Rajaji Nagara, Bangal		902118.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads and Drains in Kuvempu nagar 1St Stage Slum In Ward No.11	1000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements to Roads and Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Roads and Drains in Kuvempu nagar 1St Stage Slum In Ward No.11	011-12-000029
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-TND/437/2012-13	16/03/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/10/2014	20/10/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0016	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0016/S031857	154.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0014	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0014/S032640	156.30	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0012	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0012/S032913	158.25	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0063	Om Shakthi Lyt 6th Crs	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0063/S033217	32.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0053	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0053/S033428	44.57	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0045	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0045/S033622	59.18	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0043	NA	OM SHAKTHI LAYOUT
SegmentNo	**TotalLength**	
11/S-W0043/S033822	70.83	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Hemadrireddy, Contractor, #15, Chinappa, Hebbala, Kempapura, Bangalore-24		1021555.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	1200000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Construction Of Culve
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Construction Of Culverts And Covering Slabs At Muniramaiah Colony In Ward No.11	011-13-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/09/2012-13	17/05/2013	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
17/03/2014	16/03/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0220, W0351, W0353, W0230, W0242	NA, S Krishnappa Lyt	A K COLONY Singapura
SegmentNo	**TotalLength**	
11/C-W0220/S044555	185.72	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL BANGALORE		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Estimate for Providing CC road at A K COLONY Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1911000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Estimate for Providing CC road at A K COLONY Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000049
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/97/2016-17	05/08/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/08/2016	04/08/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		SURESH
Date of Inspection	**Remarks**	
29/10/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0442	Own Use Rd	6th cross singapura
SegmentNo	**TotalLength**	
11/S-W0442/S070848	64.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/2132015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
10		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0446	Mani Lyt 5th Crs	5th Cross Kanakadas road
SegmentNo	**TotalLength**	
11/S-W0446/S071905	66.25	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
4		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0452	NA	singapura
SegmentNo	**TotalLength**	
11/S-W0452/S072214	66.25	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
1		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0456	NA	cross road
SegmentNo	**TotalLength**	
11/S-W0456/S072427	75.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
0		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0468	1st Crs	maside road
SegmentNo	**TotalLength**	
11/S-W0468/S072634	75.92	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
2		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0434	NA	link road
SegmentNo	**TotalLength**	
11/S-W0434/S072955	64.56	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
0		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0488	NA	singapura 4th main road
SegmentNo	**TotalLength**	
11/S-W0488/S073240	147.82	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
5		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0496	60 Feet Main Rd	sandya wood work opp road
SegmentNo	**TotalLength**	
11/S-W0496/S073512	110.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
1		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0623, W0304	NA	5th main road
SegmentNo	**TotalLength**	
11/C-W0623/S074217	147.99	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Ashraya layout main road and cross roads in ward no. 11 (Kuvempunagara vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	0	011-15-000026
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/213/2015-16	16/02/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
0		suresh
Date of Inspection	**Remarks**	
07/12/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0630	NA	Raghuramlayout main road
SegmentNo	**TotalLength**	
11/S-W0630/S064632	41.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.R. Santoshkumar		0.00
PhoneNo	**EmailId**	
9448123078		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and providing covering slabs to existing drains in ward no. 11 (Kuvempunagara) Vidyaranyapura sub division	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender		011-14-000076
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/66/2015-16		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
8		ranganath
Date of Inspection	**Remarks**	
01/02/2017		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0692	NA	Gangamma gudi road
SegmentNo	**TotalLength**	
11/S-W0692/S065749	54.64	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.R. Santoshkumar		0.00
PhoneNo	**EmailId**	
9448123078		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and providing covering slabs to exisitng drins in ward no. 11	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Road	
Tender	**WorkDetails**	**Job No Work Code**
		011-14-000076
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/66/2015-16		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
3		ranganath
Date of Inspection	**Remarks**	
01/02/2017		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0626	1st Crs	Raghuram layout main road
SegmentNo	**TotalLength**	
11/S-W0626/S070324	44.01	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.R. Santoshkumar		0.00
PhoneNo	**EmailId**	
9448123078		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and providing covering slabs to existing drains in ward no. 11 (Kuvempunagara)	5000000	2014-15
Year	**Type of Work**	**Other Work Type**
2014 - 2015		
Tender	**WorkDetails**	**Job No Work Code**
		011-14-000076
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/66/2015-16		
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		No

Field Inspection Details

Number of Trees	Other Information	Name
5		ranganath
Date of Inspection	**Remarks**	
01/02/2017		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0560	NA	Near Gandhi Statue Kuvempu Nagar
SegmentNo	**TotalLength**	
11/S-W0560/S034654	213.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. C. Narasaraju Contractor, #256, Church Road, Nagashettyhalli, Bangalore-94		858056.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads and Drains In Kuvempu Nagar 2Nd Stage Near Bangarappa House Gudda Sides In Ward No.11	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements to Roads and Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Roads and Drains In Kuvempu Nagar 2Nd Stage Near Bangarappa House Gudda Sides In Ward No.11	011-12-000028
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-TND/310/2012-13	28/02/2013	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/06/2014	02/06/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
5		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0150, W0100, W0116, W0134, W0128, W0189, W0144, W	NA, 1st Crs, 3rd Crs	Near Seven Hills Public Schol
SegmentNo	**TotalLength**	
11/C-W0150/S035859	391.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		9442075.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	9900000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads Drains And Footpath
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	011-13-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./380/2012-13	07/03/2012	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/04/2014	23/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0150	NA	Raghavendra Colony
SegmentNo	**TotalLength**	
11/S-W0150/S041229	216.38	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		9442075.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	9900000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads Drains And Footpath
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	011-13-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./380/2012-13	07/03/2012	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/04/2014	23/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0211, W0223, W0110, W0112, W0207, W0205, W0241	NA	Near Seven Hill Public School
SegmentNo	**TotalLength**	
11/C-W0211/S042839	252.35	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		9442075.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	9900000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads Drains And Footpath
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads Drains And Footpath At Ms Palya, Singapura Kuvempunagara, Gangamma Gudi Area And Ramachandrapura Area In Ward No.11	011-13-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/W.O./380/2012-13	07/03/2012	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/04/2014	23/04/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0723, W0745, I0721, W0660, W0743, W0741	NA, 2nd Main Rd, 3rd Main Rd	Doddachannappa layout Raghuram layout
SegmentNo	**TotalLength**	
11/C-W0723/S081508	234.77	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.SHANKAR REDDY		0.00
PhoneNo	**EmailId**	
8553121546		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000009
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/WO/192/2015-16	03/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/02/2016	02/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
3		SURESH
Date of Inspection	**Remarks**	
21/09/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0572, W0677, W0574, W0576, W0586, W0582, W0596, W	NA, 2nd Crs, 1st Main Rd	Devappa layout Mariyamma block
SegmentNo	**TotalLength**	
11/C-W0572/S082316	385.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.SHANKAR REDDY		0.00
PhoneNo	**EmailId**	
8553121546		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Devappa layout Mariyamma block Doddachannappa layout Raghuram layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000009
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/WO/192/2015-16	03/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/02/2016	02/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
3		SURESH
Date of Inspection	**Remarks**	
21/09/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0077	NA	ayyapa swamy temple
SegmentNo	**TotalLength**	
11/S-W0077/S052738	58.08	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K. Anil kumar		4398808.00
PhoneNo	**EmailId**	
9845818296		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads and Drains at Varadarajanagar and Surrounding Roads in Ward no 11 Vidyaranyapura Sub Division		
Year	**Type of Work**	**Other Work Type**
	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction of concrete roads	011-16-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/17824/W.O/33/16-17	20/05/2016	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		suresh devatharaja
Date of Inspection	**Remarks**	
26/09/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0034, W0036, W0077, W0040, W0079, W0099, W0046, W	NA, Om Shakthi Lyt 4th Crs, V S T Opposite, 4th Crs	Varadarajanagara and Surrounding Roads
SegmentNo	**TotalLength**	
11/C-W0034/S081711	654.72	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.ANIL KUMAR		0.00
PhoneNo	**EmailId**	
9845818296		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Varadarajanagara and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4900000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Varadarajanagara and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/33/2016-17	20/06/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/06/2016	04/06/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		SURESH
Date of Inspection	**Remarks**	
03/10/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0163, W0207, W0171, W0168, W0183, W0174, W0185, W	NA, R H B Colcny, 6th Crs, 3rd Crs, Mariyappa Lyt	MS PLAYA NEAR Vidyaranayapura
SegmentNo	**TotalLength**	
11/C-W0163/S034936	330.62	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Development and Improvements to Roads and Drains in main road and cross roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	5000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Development and Improvements to Roads and Drains in main road and cross roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-16-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/ WO/76/2016-17	20/07/2016	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/07/2016	19/07/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		SURESH
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0093, W0024, W0042, W0040, W0099, W0046, W0050, W	15th Crs, NA, Om Shakthi Lyt 4th Crs	Varadarajanagara Gangamma Temple Road
SegmentNo	**TotalLength**	
11/C-W0093/S071250	227.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
S M VARADHARAJAPPA		0.00
PhoneNo	**EmailId**	
9448734501		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road Construction of Culverts and Drains in Varadarajanagara Gangamma Temple Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Divi	1200000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road Construction of Culverts and Drains in Varadarajanagara Gangamma Temple Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-12-000036
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/WO/116/2012-13	03/08/2012	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/08/2012	02/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
4		RANGNATH
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0747, W0767, W0668, W0751, W0753, W0672, W0648, W	NA, Cauveramma Street, 2nd Crs, Sardar Rd	gangamma gudi behind Michel English school
SegmentNo	**TotalLength**	
11/C-W0747/S102413	577.34	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to main road and cross roads at gangamma gudi behind Michel English school in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division	1950000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to main road and cross roads at gangamma gudi behind Michel English school in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/WO/367/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
08/06/2015	07/06/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
1		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0755, W0695, W0751, W0749, W0614, W0763, W0691	NA, Cauveramma Street	devappa layout
SegmentNo	**TotalLength**	
11/S-W0755/S103446	401.30	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to main road and cross roads at devappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to main road and cross roads at devappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000023
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/WO/366/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/06/2015	01/06/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0695, W0608, W0683, W0602, W0606, W0689, W0693, W	NA, 2nd Crs	muniramaiah colony
SegmentNo	**TotalLength**	
11/C-W0695/S104313	452.24	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to main road and cross roads at muniramaiah colony in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to main road and cross roads at muniramaiah colony in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/WO/365/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/05/2015	27/05/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
1		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0642, W0723, W0638, W0648, W0686, W0743, W0696, W	4th Crs, NA, 2nd Main Rd, 3rd Main Rd	Umesh house Main Road at gangamma temple
SegmentNo	**TotalLength**	
11/C-W0642/S105211	378.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Umesh house main road and cross roads at gangamma gudi gangamma temple in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Y	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to Umesh house main road and cross roads at gangamma gudi gangamma temple in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/WO/364/2014-15	20/04/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/05/2015	27/05/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
3		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0642, W0723, W0735, I0721	4th Crs, NA, 4th Main Rd	Velangani lane
SegmentNo	**TotalLength**	
11/C-W0642/S110021	249.91	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9449863065		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads at Velangani lane in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	1550000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to Roads at Velangani lane in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-14-000022
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/KRIDL/WO/363/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		RANGANATH
Date of Inspection	**Remarks**	
09/03/2017	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0153	NA	Near Ms Palya Circle
SegmentNo	**TotalLength**	
11/S-W0153/S031730	65.59	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Shekar Gowda, Contractor, #152, 2Nd Block, 3Rd Stage, SG Halli, BS Nagar, Bangalore 79		910199.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads Construction And Repairs Of
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	011-12-00039
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/162/2012-13	01/10/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/07/2013	30/07/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0155	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0155/S032633	23.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Shekar Gowda, Contractor, #152, 2Nd Block, 3Rd Stage, SG Halli, BS Nagar, Bangalore 79		910199.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads Construction And Repairs Of
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	011-12-00039
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/162/2012-13	01/10/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/07/2013	30/07/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0155, W0086	NA	Noorani Masjid
SegmentNo	**TotalLength**	
11/C-W0155/S033202	53.94	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Shekar Gowda, Contractor, #152, 2Nd Block, 3Rd Stage, SG Halli, BS Nagar, Bangalore 79		910199.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	Improvements To Roads Construction And Repairs Of
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads Construction And Repairs Of CC Drain From Vinayakanagara Air force Compound 1St Cross To 9Th Cross In Ward No-11	011-12-00039
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/162/2012-13	01/10/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/07/2013	30/07/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0264	NA	Varadharajaswamy Temple
SegmentNo	**TotalLength**	
11/S-W0264/S025948	43.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		1690496.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	011-14-000054
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/277/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0268	NA	Varadharajaswamy Temple
SegmentNo	**TotalLength**	
11/S-W0268/S031742	61.17	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		1690496.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	011-14-000054
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/277/2013-14	07/02/2014	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0278	Lakshmi Sagar Lyt, 1st Crs	Varadharajaswamy Temple
SegmentNo	**TotalLength**	
11/S-W0278/S033004	118.83	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		1690496.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	011-14-000054
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/277/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0280	2nd Crs, Lakshmi Sagar Lyt	Varadharajaswamy Temple
SegmentNo	**TotalLength**	
11/S-W0280/S033218	17.77	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		1690496.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	2000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Road And Patch Works At Sngapura Grama Thana In Ward No-11	011-14-000054
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/277/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0560	NA	Near Gandhi Statue Kuvempu Nagar
SegmentNo	**TotalLength**	
11/S-W0560/S034627	213.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. K. Shankar Reddy, Contractor, No.03, 1St Main, Ramachanrappa Layout, Arabic College (P), Veeran		1361396.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Drains And Providing Covering Slabs At Kuvempu Nagara 1St Cross And 2Nd Cross In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Drains And Providing
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Drains And Providing Covering Slabs At Kuvempu Nagara 1St Cross And 2Nd Cross In Ward No-11	011-14-000050
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/268/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0558	NA	Near Gandhi Statue Kuvempu Nagar
SegmentNo	**TotalLength**	
11/S-W0558/S035343	220.50	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. K. Shankar Reddy, Contractor, No.03, 1St Main, Ramachanrappa Layout, Arabic College (P), Veeran		1361396.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To CC Roads And Drains And Providing Covering Slabs At Kuvempu Nagara 1St Cross And 2Nd Cross In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To CC Roads And Drains And Providing
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To CC Roads And Drains And Providing Covering Slabs At Kuvempu Nagara 1St Cross And 2Nd Cross In Ward No-11	011-14-000050
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/268/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0275	NA	Near Abbigere Lake
SegmentNo	**TotalLength**	
11/S-W0275/S040248	146.17	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	28/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0279	Ambedkar Nagar Slum	Near Abbigere Lake
SegmentNo	**TotalLength**	
11/S-W0279/S040754	135.54	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0283	NA	Near Abbigere Lake
SegmentNo	**TotalLength**	
11/S-W0283/S041016	130.68	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0285	NA	Near Abbigere Lake
SegmentNo	**TotalLength**	
11/S-W0285/S041708	64.87	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0289	Chikkanna Lyt	Near
SegmentNo	**TotalLength**	
11/S-W0289/S041955	66.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
4		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0291, W0196, W0293, W0299, W0303, W0305, W0309, W	NA, Maheshwari Nagar Opp Police Station Rd, Maheshwari Nagar Main Rd, Church Rd	Near Abbigere Lake
SegmentNo	**TotalLength**	
11/C-W0291/S043058	383.61	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. N Venkatesh, Contractor, N0. 272, Sumangali Sevashrama Road, Anandagiri Layout, R.T. Nagar, Ban		1233327.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Main Road And Cross Roads
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Main Road And Cross Roads At Simhadri Layout In Ward No-11	011-14-000052
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/271/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		ranganath
Date of Inspection	**Remarks**	
11/09/2015	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0633, W0516, W0518, W0520, W0498, W0490, W0627, W	NA, Muniswamy Shetty Lyt Rd, 2nd Crs, 1st Crs, N G E F Industrial Area	Kuvempunagara 2nd Stage
SegmentNo	**TotalLength**	
11/C-W0633/S011423	719.47	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B B UMESHA		0.00
PhoneNo	**EmailId**	
9886213563		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting to Roads Kuvempunagara 2nd Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements and Asphalting to Roads Kuvempunagara 2nd Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/219/2015-16	16/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
16/02/2016	15/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
15		Suresh
Date of Inspection	**Remarks**	
17/06/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0633, W0554, W0595, W0538, W0593, W0528, W0611, W	NA, 1st Crs, 5th Crs, 1st Main Rd, 6th Crs, 4th Crs	Kuvempunagara 1st Stage
SegmentNo	**TotalLength**	
11/C-W0633/S013654	972.82	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B B UMESHA		0.00
PhoneNo	**EmailId**	
9886213563		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting to Roads Kuvempunagara 1st Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements and Asphalting to Roads Kuvempunagara 1st Stage in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000001
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/222/2015-16	15/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
16/02/2016	15/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
12		Suresh
Date of Inspection	**Remarks**	
17/06/2016	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0343, W0351, W0339, W0345, W0396, W0521, W0422, W	NA, S Krishnappa Lyt, Narayanaswamy Rd 4th Crs, Rama Anjaneya Lyt, 1st Crs, Own Use Rd, Mani Lyt 4th	Ashraya layout
SegmentNo	**TotalLength**	
11/C-W0343/S015201	325.47	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B B UMESHA		0.00
PhoneNo	**EmailId**	
9886213563		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and Asphalting to Ashraya layout Main Road and Cross Road Ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	3500000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements and Asphalting to Ashraya layout Main Road and Cross Road Ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000006
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/221/2015-16	16/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
16/02/2016	15/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
15		Suresh
Date of Inspection	**Remarks**	
17/06/2016	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0154, W0134, W0207, W0132, W0167, W0191, W0126, W	NA, 1st Crs, Vinayaka Lyt 3rd Crs, Vinayaka Lyt 1st Crs, Chowdeshwari Temple Rd	M S PALYA and Surrounding Roads
SegmentNo	**TotalLength**	
11/S-W0154/S123040	1055.63	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K S CHOWDA REDDY		0.00
PhoneNo	**EmailId**	
9901855542		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drain at M S PALYA and Surrounding Roads in Ward NO 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	RCC ROAD OR CC ROAD
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drain at M S PALYA and Surrounding Roads in Ward NO 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000001
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/273/2015-16	01/03/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2016	28/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
15		Suresh
Date of Inspection	**Remarks**	
20/06/2016	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0218, W0335, W0349, W0347, W0224, W0333, W0214, W	NA, 7th Main Rd, G M Palya, R H B Colcny 2nd Main Rd, S Krishnappa Lyt, Chikka Muniswammappa Lyt, 2n	Singapura
SegmentNo	**TotalLength**	
11/C-W0218/S123024	593.14	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
ASHWATHNARAYA		0.00
PhoneNo	**EmailId**	
9448034435		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	RCC ROAD OR CC ROAD
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/322/2015-16	24/03/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2016	22/03/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
Date of Inspection	**Remarks**	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0218, W0335, W0347, W0027, W0349, W0333, W0214, W	NA, R H B Colcny 2nd Main Rd, 7th Main Rd, G M Palya, Chikka Muniswammappa Lyt, 2nd Crs, 11th Crs La	Singapura
SegmentNo	**TotalLength**	
11/C-W0218/S010100	585.64	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
ASHWATHNARAYA		0.00
PhoneNo	**EmailId**	
9448034435		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Singapura in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/322/2015-16	24/03/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2016	23/03/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
5		SURESH
Date of Inspection	**Remarks**	
27/06/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0161	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0161/S125956	89.64	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		2096238.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Drains at chikkabettahalli Village at M S Palya Connecting Roads In Ward NO 11	2500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads and Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads and Drains at chikkabettahalli Village at M S Palya Connecting Roads In Ward NO 11	011-14-000038
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/ 278/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0163	NA	Near MS Palya Circle
SegmentNo	**TotalLength**	
11/S-W0163/S011119	86.82	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri. Gopi Reddy, Contractor, No.03, 1St Cross, 1St Main, Ramachandrappa Layout, Arabic College(P), V		2096238.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Drains at chikkabettahalli Village at M S Palya Connecting Roads In Ward NO 11	2500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Improvements To Roads and Drains
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements To Roads and Drains at chikkabettahalli Village at M S Palya Connecting Roads In Ward NO 11	011-14-000038
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/ 278/2013-14	07/02/2014	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/02/2014	27/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0390, W0479	5th Crs, 1st Crs	Near Juice Factory
SegmentNo	**TotalLength**	
11/C-W0390/S020737	60.95	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1285078.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	011-14-000055
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRDL/WO/479/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/05/2014	30/05/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0479, W0471	1st Crs, NA	Near Juice Factory
SegmentNo	**TotalLength**	
11/C-W0479/S022801	67.30	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1285078.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	011-14-000055
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRDL/WO/479/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/05/2014	30/05/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0386	Doddamuniswammppa Lyt, 2nd Crs	Near Juice Factory
SegmentNo	**TotalLength**	
11/S-W0386/S023300	69.53	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1285078.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	011-14-000055
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRDL/WO/479/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/05/2014	30/05/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0384	Own Use Rd	Near Juice Factory
SegmentNo	**TotalLength**	
11/S-W0384/S023529	142.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		1285078.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	1500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements To Roads and Asphalting To Singapura Paradise And Varadarajanagara Cross Roads In Ward No 11	011-14-000055
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/KRDL/WO/479/2013-14	21/02/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/05/2014	30/05/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ranganath
Date of Inspection	**Remarks**	
10/09/2015	completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0198, W0261, W0259, I0263, I0066, W0289, W0279, W	NA, Ambedkar Nagar Slum, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Chikkanna Lyt, Ma	Parkruthi Layout and Simhadri Layout
SegmentNo	**TotalLength**	
11/C-W0198/S082628	752.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N. THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Parkruthi Layout and Simhadri Layout Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelah	2500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to roads at Parkruthi Layout and Simhadri Layout Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-15-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/354/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2015	23/03/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
11		SURESH
Date of Inspection	**Remarks**	
27/11/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0023, W0025, W0008, W0006, W0021, W0301, W0307, W	NA, 8th Crs, Bimel Behind Rd	Balaji Layout near Singapura Main Road
SegmentNo	**TotalLength**	
11/C-W0023/S083314	479.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N.THIRUNAGENDRA		0.00
PhoneNo	**EmailId**	
9845547072		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads at Balaji Layout near Singapura Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zon	2400000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to roads at Balaji Layout near Singapura Main Road and Cross Roads in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-15-000025
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/353/2014-15	24/03/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/03/2015	23/03/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
10		SURESH
Date of Inspection	**Remarks**	
27/11/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0417, W0411, W0232, W0415	NA	Navodaya School Road
SegmentNo	**TotalLength**	
11/C-W0417/S105958	221.39	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
GOPI REDDY		0.00
PhoneNo	**EmailId**	
7760405418		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culverts and Providing Covering Slab to Existing Drians and Kerb at Navodaya School Road in ward no 11 Kuvempunagara Vidyaranayapura S	2000000	2015
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction of Culverts and Providing Covering Slab to Existing Drians and Kerb at Navodaya School Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-15-000062
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/ EE/BTP/WO/29/2016-17	05/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/05/2016	04/05/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
12		SURESH
Date of Inspection	**Remarks**	
29/11/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0458, W0523, W0460, W0454, W0478, W0474, W0553, W	NA, Purva Parkridge G C Palya Gosala Rd, 14th Crs, I T P L Main Rd, Sathya Lyt, 1st Crs, 2nd Crs, 5t	Kuvempunagar IInd Stage
SegmentNo	**TotalLength**	
11/C-W0458/S111153	645.06	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
RAMESH ANAND		0.00
PhoneNo	**EmailId**	
7760405418		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains at Kuvempunagar IInd Stage in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	4000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to roads and drains at Kuvempunagar IInd Stage in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-16-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/ EE/BTP/WO/100/2016-17	05/08/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/08/2016	04/08/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		SURESH
Date of Inspection	**Remarks**	
29/11/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0620	3rd Crs	Kalathur layout
SegmentNo	**TotalLength**	
11/S-W0620/S120323	127.17	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
NATARAJ.R		0.00
PhoneNo	**EmailId**	
9880095123		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	960000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	011-12-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/193/2011-12	02/11/2011	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/11/2011	01/11/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		Ranganath
Date of Inspection	**Remarks**	
25/03/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0636	7th Crs	Kalathur layout
SegmentNo	**TotalLength**	
11/S-W0636/S120904	97.85	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
NATARAJ.R		0.00
PhoneNo	**EmailId**	
9880095123		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	960000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	011-12-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/193/2011-12	02/11/2011	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/11/2011	01/11/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		Ranganath
Date of Inspection	**Remarks**	
25/03/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0650	1st Crs	Kalathur layout
SegmentNo	**TotalLength**	
11/S-W0650/S121053	90.66	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
NATARAJ.R		0.00
PhoneNo	**EmailId**	
9880095123		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	960000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	011-12-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/193/2011-12	02/11/2011	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/11/2011	01/11/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
3		Ranganath
Date of Inspection	**Remarks**	
25/03/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0709	NA	Kalathur layout
SegmentNo	**TotalLength**	
11/S-W0709/S121300	217.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
NATARAJ.R		0.00
PhoneNo	**EmailId**	
9880095123		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	960000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Kalathur layout cross roads in kuvempunagara ward no 11 VIDYARANYAPURA SUB DIVISION	011-12-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-TND/193/2011-12	02/11/2011	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/11/2011	01/11/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
6		Ranganath
Date of Inspection	**Remarks**	
25/03/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0656, W0769, W0670, W0694, W0767, W0688, W0743, W	NA, 2nd Crs, 2nd Main Rd, 4th Main Rd	murail house behaind
SegmentNo	**TotalLength**	
11/C-W0656/S120353	539.72	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
ASWATHNARAYANA		0.00
PhoneNo	**EmailId**	
9448034435		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to CC road at murail house behaind road sommanna house road and near adbula;s house road in ward no 11 (Kuvempunagara) Vidyaranayapura	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to CC road at murail house behaind road sommanna house road and near adbula;s house road in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-15-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/WO/180/2015-16	07/12/2015	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/12/2015	03/12/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
3		SURESH
Date of Inspection	**Remarks**	
02/09/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0186, W0301, W0188, W0309, W0311, I0196, W0307, W	NA, Bimel Behind Rd	lakkappa layout
SegmentNo	**TotalLength**	
11/S-W0186/S121810	539.59	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
M.LAKSHMINARAYANA		0.00
PhoneNo	**EmailId**	
9448481324		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drain at lakkappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	2000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to roads and drain at lakkappa layout in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000006
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/280/2015-16	09/03/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/03/2016	08/03/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
5		SURESH
Date of Inspection	**Remarks**	
02/09/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0032, W0064, W0228, W0222, W0323, W0329, W0226, W	NA, 10th Crs Lakshmi Sagar Lyt, Lakshmi Sagar Lyt North Side, 1st Crs	Vinayak Nagar
SegmentNo	**TotalLength**	
11/S-W0032/S075536	288.85	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B B UMESHA		0.00
PhoneNo	**EmailId**	
9886213563		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Vinayak Nagar in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	4000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Vinayak Nagar in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/103/2016-17	09/08/2016	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
09/08/2016	08/08/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		SURESH
Date of Inspection	**Remarks**	
14/09/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	11	Kuvempu Nagar
StreetID	**StreetName**	**Significant LandMark**
W0387, W0383, W0232, W0385, W0093, W0024, W0095, W	Mani Lyt 1st Main Rd, 1st Crs, NA, 8th Crs Gramatana, 15th Crs, Om Shakthi Lyt 2nd Crs, 16th Crs, Om	Singapura Paradise and Surrounding Roads
SegmentNo	**TotalLength**	
11/C-W0387/S080640	819.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B B UMESHA		0.00
PhoneNo	**EmailId**	
9886213563		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road and Drains at Singapura Paradise and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zon	3000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Road and Drains at Singapura Paradise and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone	011-16-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/41/2016-17	26/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/05/2016	25/05/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		SURESH
Date of Inspection	**Remarks**	
14/09/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	