



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028, W0019, W0022, W0021, W0015, W0017	NA, 8th Crs	shankarappa garden
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0028/S051904	444.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
8954656425		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CHIPCARPETING THE SHANKARAPPA GARDEN CROSS AND MAIN ROADS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	CHIPCARPETING
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CHIPCARPETING	121-14-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/AE/WO/947/13-14	28/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
17/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0144	3rd Crs	gopalapura cross roads
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0144/S120036	94.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		999559.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916950205		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
REPAIRS TO GOPALAPURA CROSS ROADS AND SURROUNDINGS	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Others	REPAIRS WORK
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	REPAIRS WORK	121-15-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/186/14-15	18/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0011, W0008, I0059, W0009, W0013, W0014, W0007	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0011/S121229	151.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		999953.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916950205		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
REPAIRS TO ROAD CULVERTS AT MAGADI ROAD 6TH CROSS RIGHT SIDE SURROUNDINGS	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Others	REPAIRES WORK
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	REPAIRS WORK	121-15-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/183/14-15	18/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0017	NA	SHANKARAPPA GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0017/S121852	271.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		869560.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916950205		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
REPAIRS TO DRAIN AND ROAD AT 6TH CROSS SHANKARAPPA GARDEN SURROUNDINGS	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Others	REPAIRS DRAIN AND ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	REPAIRS DRAIN AND ROAD WORKS	121-15-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GMR)/AE/WO/184/14-15	18/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0071, I0059, W0061, W0081, W0065, I0089, W0077, W	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Om Shakthi Lyt 7th Crs, 14th Crs, Om S	gopalapura
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0071/S104157	307.91	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9463553736		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING GOPALAPURA CROSS ROADS	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	ASPHALTING WORK	121-13-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/538/12-13	09/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
18/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0263	NA	PUTTARAJU HOUSE
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0263/S033951	61.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1500000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9323220885		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FORMATION OF ROADS AND PROVIDING METALING AND CC ROAD TO PUTTARAJU HOUSE ROAD	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	METALING AND CC ROAD	121-11-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO189/12-13	10/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0247	4th Crs	MUTYAMMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0247/S034612	105.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1500000.00
<b>PhoneNo</b>	<b>Emailld</b>	
955880882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FORMATION OF NEW ROAD AND PROVIDING METALLING AND CC ROADS TO MUTYALAMMA TEMPLE ROAD	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	METALLING AND CC ROAD WORK	121-11-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/192/12-13	10/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		sachin
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0129, W0058, W0133	NA, Vinayaka Lyt 4th Crs	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0129/S094453	412.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9433556656		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING CONCRETE TO MAGADI ROAD CROSS ROADS	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	ASPHALTING WORK	121-13-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE./WO/540/13-14	09/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 121	<b>WardName</b> Binnipete
<b>StreetID</b> W0015, W0048, W0028, W0017	<b>StreetName</b> NA	<b>Significant LandMark</b> MAGADI ROAD
<b>SegmentNo</b> 121/C-W0015/S095151	<b>TotalLength</b> 400.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 2000000.00
<b>PhoneNo</b> 9455563267	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ASPHALTING SORROUNDING ROADS OF SHANKARAPPA GARDEN	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> ASPHALTING WORK	<b>Job No Work Code</b> 121-13-000030
<b>Work OrderNo</b> EE/(GNR)/AE/WO/539/13-14	<b>Work Order Date</b> 09/07/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> muniappa
<b>Date of Inspection</b> 26/05/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 121	<b>WardName</b> Binnipete
<b>StreetID</b> W0141, W0137, I0135, W0058, W0143, W0139, I0001	<b>StreetName</b> NA	<b>Significant LandMark</b> K P AGRAHARA
<b>SegmentNo</b> 121/C-W0141/S100119	<b>TotalLength</b> 110.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 2000000.00
<b>PhoneNo</b> 9475862324	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ASPHALTING SORROUNDING ROADS OF K P AGRAHARA	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> ASPHALTING WORK	<b>Job No Work Code</b> 121-13-000027
<b>Work OrderNo</b> EE/(GNR)/AE/WO/537/13-14	<b>Work Order Date</b> 09/07/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> muniappa
<b>Date of Inspection</b> 26/05/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0141, W0137, W0056, I0135, W0143, W0139, W0147, W	NA	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0141/S101150	216.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9485766278		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CHIP CARPETING 1ST CROSS MAGADI ROAD AND ESI CROSS ROAD	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CHIPCARPETING WORK	121-14-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/948/13-14	28/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0117, W0052, W0119	NA	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0117/S105706	215.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERES		2000000.00
<b>PhoneNo</b>	<b>Emailld</b>	
96232168		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENT AND OTHER CC WORKS TO 6TH CROSS MAGADI ROAD	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC WORK	121-14-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/762/13-14	06/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0042	NA	GOPALAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0042/S110357	161.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERES		1000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
7346772		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINS AND CULVERT AT A STREET GOPALAPURA	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	RCC WRK	121-14-000003
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/732/13-14	04/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028	NA	kalyani road
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0028/S022113	133.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1500000.00
<b>PhoneNo</b>	<b>EmailId</b>	
973522871		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENT AND OTHER CC WORKS 7TH CROSS (KALYANI ROAD)	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC WORK	121-14-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/766/13-14	06/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0207	NA	BUVANESHWARA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0207/S042550	72.32	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
973631772		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAIN AND CULVERTS AND OTHER CC WORKS TO 6TH MAIN ROAD BHUVANESHWARA NAGAR (KRISHNAPPA BAR ROAD)	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	RCC DRAIN WORK	121-14-000016
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/742/13-14	04/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0014	NA	gopalapura
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0014/S064959	287.15	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1600000.00
<b>PhoneNo</b>	<b>Emailld</b>	
975230862		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDIND AND FIXING COVERING SLAB AND KERB STONE AND OTHER CC WORKS AT A CROSS AT GOPALAPURA	1600000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC WORK	121-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/765/13-14	06/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		sachin
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0042	NA	GOPALAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0042/S065619	161.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1000000.00
<b>PhoneNo</b>	<b>Emailld</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING SAUCER DRAIN AND OTHER CC WORKS AND CULVERTS TO ROAD BEETWEN A CROSS GOPALAPURA TO B CROSS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC WORK	121-14-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/737/13-14	04/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028	NA	GOPALAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0028/S070229	133.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTUREAND DEVELOPERS		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CHIP CARPETING ROAD FROM GOPALAPURA MAIN ROAD TO SWD (A CROSS)	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CHIP CARPETING WORK	121-14-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/AE/WO/943/13-14	28/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
I0036	NA	GOPALAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-I0036/S070904	162.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1500000.00
<b>PhoneNo</b>	<b>EmailId</b>	
962617547		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC POVEMENT TO B CROSS GOPALAPURA	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC POVEMENT WORK	121-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/JE/WO/756/13-14	06/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028	NA	VEENUS BREVERY ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0028/S071402	133.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
98622016		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENTS AND OTHER CC WORKS AT VEENUS BREVERY ROAD	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC POVEMENT	121-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)/JE/VO/733/13-14	04/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
26/05/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0169, W0098, W0102, W0171, W0111	NA	BBMP WARD OFFICE 121 WARD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0169/S080243	102.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M JAYAPRAKASH		974762.00
<b>PhoneNo</b>	<b>EmailId</b>	
9741763956		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DRAIN BETWEEN 4TH AND 5TH MAIN OF BHUVANESWARI NAGAR	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	DRAIN WORK	121-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/JE/WO/156/14-15	07/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
04/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0122, W0181, W0126	NA, Vinayaka Lyt 3rd Crs	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0122/S090158	107.23	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
967458125		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC POVEMENT TO 7TH B AND 7 TH C CROSS	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC POVEMENT WORK	121-13-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)AE/WO/555/13-14	11/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/06/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0152	NA	BINNY LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0152/S090932	368.82	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		1500000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9739517567		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENT AND IMPROVEMENTSO DRAIN AT 1ST CROSS NEW BINNY LAYOUT	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC PAVEMENT WORK	121-13-000016
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)AE/WO/554/13-14	11/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0022, W0025, W0026, W0027	NA	MAGADI ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0022/S091608	263.92	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AISHWARYA INFRASTRUCTURE AND DEVELOPERS		15000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
984521557		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENT TO 7TH A CROSS	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC PAVEMENT WORK	121-13-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(GNR)AE/WO/553/13-14	11/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0094	NA	SOWMYA BAR
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0094/S010409	63.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.H.RAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8976567898		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING COBBLE STONE PAVEMENTS TO ROAD OPP TO SOWMYA BAR AT KP AGRAHARA	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-13-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/JE/W.O/627/13-14	08/10/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0141, W0137, W0058, W0143, W0139	NA	MARIYAMMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0141/S011705	62.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.H.RAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7896789876		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC PAVEMENTS TO MARIYAMMA TEMPLE	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	121-13-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/JE/W.O/593/13-14	17/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0201	NA	MUNIAPPANA PALYA MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0201/S012952	95.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRINIVAS V		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8798987688		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CLEANING OF SHOULDER DRAIN	500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-14-000001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/JE/W.O/788/13-14	06/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0095	Om Shakthi Lyt 2nd Crs	MAGADI MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0095/S014622	28.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.RAMESH RAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972784944		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF RCC DRAIN AND PROVIDING CC PAVMENTS TO ABC CROSS ROADS INFRONT OF ESI HOSPITAL	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-12-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)/JE/W.O/620/13-14	03/09/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0026	NA	KADIRIVEL ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0026/S015654	56.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.VIJAY KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9342839190		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF RCC DRAIN AND CULVERTS & CC PAVEMENTS AT KALYANI ROAD AND KADIRI VEL ROAD	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-12-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)AE/W.O/279/12-13	08/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0042	NA	GOPALAPURA MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0042/S021359	161.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.VIJAY KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9342839190		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN AND CC TO ROAD LANES AT GOPALAPURA	500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)AE/W.O/278/12-13	08/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		n r muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0051	Om Shakthi Lyt 8th Crs	MAGADI 5TH CROSS
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0051/S022144	243.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
C.H.RAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7896789876		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPTS TO DRAIN AT 5TH CROSS MAGADI ROAD	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-13-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)JE/W.O/592/13-14	17/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0059, W0006, W0007, W0011, W0008, W0009, W0013	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, NA	GOPALAPURA MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0059/S023235	174.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7612570323		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF RCC DRAIN AND CC PAVEMENTS FOR BC CROSS ROAD IN GOPALAPURA	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)AE/W.O/281/12-13	08/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0162, W0251, W0255, W0164	NA, Maheshwaramma Temple Behind Rd, Mahadevapura Village Rd	MUTHYALAMMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
121/C-W0162/S040224	33.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8616234856		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINAGE AND CC CROSS ROAD SURROUNDING MUTHALAMMA TEMPLE	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-11-000051
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)AE/W.O/280/12-13	08/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		muniyappa
<b>Date of Inspection</b>	<b>Remarks</b>	
30/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	121	Binnipete
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0158	NA	RAILWAY TRACK
<b>SegmentNo</b>	<b>TotalLength</b>	
121/S-W0158/S041436	109.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI GOKUL CONSTRUCTION		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9342839190		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ARCH AND IMPTS OF ROAD SIDE MARKANDESHWARA NAGAR	400000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		121-11-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(GNR)AE/W.O/285/12-13	08/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		MUNIAPPA
<b>Date of Inspection</b>	<b>Remarks</b>	
23/05/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 121	<b>WardName</b> Binnipete
<b>StreetID</b> W0112, W0122, W0114, W0124, W0126, W0110, W0121, W	<b>StreetName</b> NA	<b>Significant LandMark</b> K P AGRAHARA POLICE STATION
<b>SegmentNo</b> 121/C-W0112/S081147	<b>TotalLength</b> 120.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 4714412.00
<b>PhoneNo</b> 9916950205	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> RECONSTRUCTION OF SECONDARY DRAIN IN FRONT OF K P AGRAHARA POLICE STATION IN WARD NO-121	<b>Sanctioned Amount</b> 5000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> RECONSTRUCTION OF SECONDARY DRAIN IN WARD NO-121	<b>Job No Work Code</b> 121-15-000017
<b>Work OrderNo</b> EE/(GNR)/AE/WO/194/2014-15	<b>Work Order Date</b> 26/03/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
17/03/2017	

Category	Photo
Drain Condition	
Footpath Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 121	<b>WardName</b> Binnipete
<b>StreetID</b> W0112, W0122, W0114, W0124, W0126, W0110, W0121, W	<b>StreetName</b> NA	<b>Significant LandMark</b> K P AGRAHARA POLICE
<b>SegmentNo</b> 121/C-W0112/S084211	<b>TotalLength</b> 121.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 4714412.00
<b>PhoneNo</b> 9916950205	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> RECONSTRUCTION OF SECONDARY DRAIN IN FRONT OF K P AGRAHARA POLICE STATION IN WARD NO-121	<b>Sanctioned Amount</b> 5000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> RECONSTRUCTION OFSECONDARY DRAIN IN WARDNO-121	<b>Job No Work Code</b> 121-15-000017
<b>Work OrderNo</b> EE/(GNR)/AE/WO/194/2014-15	<b>Work Order Date</b> 26/03/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
17/03/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Footpath Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start

