ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0158	Kalyan Nagar 3rd Main Rd	New Baldwin Public School
SegmentNo	**TotalLength**	
127/S-W0158/S113442	61.04	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		86060.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to secondary drain &construction of drain of Kalyananagara and adarshnagar, moodalapalya (under emergency work) in ward -127	99800	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to secondary drain &construction of drain of Kalyananagara and adarshnagar, moodalapalya (under emergency work) in ward -127	127-11-000014(f)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/187/2011-12	14/07/2011	30 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
14/07/2011	14/07/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0109, W0078	1st Main Rd, 3rd Crs	Noah Interiors
SegmentNo	**TotalLength**	
127/C-W0109/S114449	70.10	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1211900.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 3rd cross road in s v g nagara in ward no-127	1300000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 3rd cross road in s v g nagara in ward no-127	127-11-000037
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/81/2011-12	11/03/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
11/03/2011	11/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0090, W0109	2nd Crs, 1st Main Rd	Sri Ashwa
SegmentNo	**TotalLength**	
127/C-W0090/S115224	72.66	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1126526.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 2nd A cross road in s v g nagara in ward no-127	1200000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 2nd A cross road in s v g nagara in ward no-127	127-11-000036
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/417/2011-12	13/10/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/10/2011	13/10/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0084, W0052, W0060, W0336, W0059, W0313, W0068	NA, 6th Main Rd, 5th Main Rd, 8th A Crs Huchappa Layout, 8th Crs, Sanjeevini Nagar, 4th Crs, 1st Ma	Vijayanagar School of Nursing
SegmentNo	**TotalLength**	
127/C-W0084/S121416	225.67	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		936300.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 8th cross road in s v g nagara in ward no-127	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 8th cross road in s v g nagara in ward no-127	127-11-000046
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/112/2011-12	31/03/2011	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0088, W0084, W0086, W0059, W0061, W0104	2nd Main Rd, Sanjeevini Nagar, NA, 3rd Main Rd, Sanjeevini Nagar, 8th Crs, Sanjeevini Nagar, 7th Crs	Manasa Gangotri Vidyalaya
SegmentNo	**TotalLength**	
127/C-W0088/S122225	127.84	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		936300.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 8th cross road in s v g nagara in ward no-127	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 8th cross road in s v g nagara in ward no-127	127-11-000046
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/112/2011-12	31/03/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0104	Manjunath Talkies Rd	Moodalpalya Market
SegmentNo	**TotalLength**	
127/S-W0104/S123717	60.34	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		465990.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 2nd cross road in s v g nagara in ward no-127	500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 2nd cross road in s v g nagara in ward no-127	127-11-000039
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/414/2011-12	13/10/2011	60 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/10/2011	13/10/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0166, W0231, W0190, W0237	NA, 4th Crs, 1st Main Rd, Baiyraveswara Nagar, 3rd Crs	Ravi Kashi Studio
SegmentNo	**TotalLength**	
127/C-W0166/S125047	236.07	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1787889.00
PhoneNo	**EmailId**	
9111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and footpath in Kalyananagara in ward no-127	1999000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and footpath in Kalyananagara in ward no-127	127-11-000063
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/194/2011-12	14/07/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
14/07/2011	14/07/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0225, W0223, W0188, W0231, W0190	5th Crs, 9th B Main Rd, 4th Crs, 1st Main Rd, Baiyraveswara Nagar	Sri Lakshmi Venkateshwara Fancy Stores
SegmentNo	**TotalLength**	
127/C-W0225/S010146	57.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		90920.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to damaged portion of drains at Kalyananagara in ward no-127	99800	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to damaged portion of drains at Kalyananagara in ward no-127	127-11-000014(d)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/191/2011-12	14/07/2011	30 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
14/07/2011	14/07/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0242, W0287	NA, Maheshwari Nagar 4th Main Rd	ward office
SegmentNo	**TotalLength**	
127/C-W0242/S024248	84.61	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Rajashekar, Contractor, Attiguppe, Vijayanagara		1850546.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	1800000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	127-12-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/141/2012-13	30/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/08/2012	31/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0287, W0244	Maheshwari Nagar 4th Main Rd, NA	ward office
SegmentNo	**TotalLength**	
127/C-W0287/S024643	78.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Rajashekar, Contractor, Attiguppe, Vijayanagara		1850546.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	1800000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	127-12-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/141/2012-13	30/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/08/2012	29/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0225, W0237, W0245, W0243, W0241, W0231, W0190	NA, Chowdeshwari Temple Behind Rd	Kvv school
SegmentNo	**TotalLength**	
127/C-W0225/S025354	240.88	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SIR B SUNIL KUMAR ,CONTRACTOR,NAGARBAVI,2ND STAGE ,BDA LAYOUT		1934588.00
PhoneNo	**EmailId**	
9111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and Footpath in kalayan nagar 1st main road in mooodalpalya in ward no -127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and Footpath in kalayan nagar 1st main road in mooodalpalya in ward no -127	127-12-000048
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/116/2012-13	22/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
22/08/2012	21/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0216, W0221, W0271, W0224, W0279	NA, Ambedkar Nagar Slum	New Pioneer School
SegmentNo	**TotalLength**	
127/C-W0216/S031232	173.83	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri BV Dharmendra Babu Contracter Basaweshwara Nagar		1961382.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward - 127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward -127	127-12-000044
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/120/2012-13	24/08/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/08/2012	23/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0277, W0224	NA	New Pioneers School
SegmentNo	**TotalLength**	
127/C-W0277/S031828	134.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri BV Dharmendra Babu Contracter Basaweshwara Nagar		1961382.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward - 127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward -127	127-12-000044
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/120/2012-13	24/08/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/08/2012	23/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0277, W0224	NA	New Pioneers School
SegmentNo	**TotalLength**	
127/C-W0277/S032055	85.66	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri BV Dharmendra Babu Contracter Basaweshwara Nagar		1961382.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward - 127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of drain and Footpath in Byraveshwaranagar 4th main road and cross roads in ward -127	127-12-000044
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/120/2012-13	24/08/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/08/2012	23/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0220, W0215, W0213	NA	Meternity Hospital
SegmentNo	**TotalLength**	
127/C-W0220/S032523	340.81	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5307469.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	127-13-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/380/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0206, W0220, W0186, W0209, W0211	NA	MEtarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0206/S033127	430.66	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5307469.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	127-13-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/380/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0253	NA	Om Sri Shiradi Sai Baba Temple
SegmentNo	**TotalLength**	
127/S-W0253/S033503	73.95	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5307469.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & other Impruments Works at Adharsha Nagara & Shakthi Garden in Ward No-127	127-13-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/380/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0224	NA	BBMP Help Center
SegmentNo	**TotalLength**	
127/S-W0224/S033750	337.75	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5401518.00
PhoneNo	**EmailId**	
8884693341		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	127-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/379/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0238, W0242, W0226, W0287, W0224, W0244, W0283	NA, Maheshwari Nagar 4th Main Rd	Shanimahathma Temple
SegmentNo	**TotalLength**	
127/C-W0238/S034522	441.37	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5401518.00
PhoneNo	**EmailId**	
8884693341		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	127-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/379/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0277, W0240, W0279, W0224, W0281	NA, Ambedkar Nagar Slum	Shanimahathma Temple
SegmentNo	**TotalLength**	
127/C-W0277/S034811	481.35	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5401518.00
PhoneNo	**EmailId**	
8884693341		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	127-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/379/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0273, W0224	NA	Shanimahathma Temple
SegmentNo	**TotalLength**	
127/C-W0273/S035024	131.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5401518.00
PhoneNo	**EmailId**	
8884693341		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	127-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/379/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0037, W0146, W0161	NA	Vishwa Bharathi School
SegmentNo	**TotalLength**	
127/C-W0037/S035349	66.74	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		5401518.00
PhoneNo	**EmailId**	
8884693341		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Aspalting & Tailaring Center Road & Kalyan Nagar Main Road & Cross Road in Ward No-127	127-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/379/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0051	9th Crs, Sanjeevini Nagar	BWSSB Mini Waer Tank
SegmentNo	**TotalLength**	
127/S-W0051/S6799	25.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		2900000.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing re-asphalting	3000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender		127-13-000001
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/2012-13dtd	03/06/2013	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/09/2013	31/08/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0084, W0067, W0104, W0065	NA, 6th Crs, Manjunath Talkies Rd, 7th Crs	BSNL RETAILER,S.L.V STORES
SegmentNo	**TotalLength**	
127/C-W0084/S110031	118.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1396900.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 7th cross road in sanjeevininagara in ward no-127	1500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 7th cross road in sanjeevininagara in ward no-127	127-11-000053
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/111/2011-12	31/03/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0084, W0093, W0069	NA, 2nd & 3rd Crs, 7th A Crs	Vijayanagar School of Nursing
SegmentNo	**TotalLength**	
127/C-W0084/S111006	210.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1396900.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 7th cross road in sanjeevininagara in ward no-127	1500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 7th cross road in sanjeevininagara in ward no-127	127-11-000053
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/111/2011-12	31/03/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0084, W0087, W0104	NA, 4th Crs, Manjunath Talkies Rd	NR Complex
SegmentNo	**TotalLength**	
127/C-W0084/S111511	84.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Teahnical manager (west) BBMP division, KRIDL bengalore		1206426.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and footpath at 3rd cross road in sanjeevininagara in ward no-127	1300000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and footpath at 3rd cross road in sanjeevininagara in ward no-127	127-11-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/416/2011-12	13/10/2011	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/10/2011	13/10/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesha
Date of Inspection	**Remarks**	
09/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0220, W0217	9th H Crs, 9th E Main Rd	Sri Lakshmi Venkateshwara Fancy Stores
SegmentNo	**TotalLength**	
127/C-W0220/S112347	54.18	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		89550.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to secondary drain &construction of drain at adarshnagar (Left side) near st . anns school in moodalapalya (under emergency work) in	99900	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to secondary drain &construction of drain at adarshnagar (Left side) near st . anns school in moodalapalya (under emergency work) in ward -127	127-11-000014(i)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/289/2011-12	19/08/2011	30 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/08/2011	19/08/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
03/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0273, W0224	NA	ward office
SegmentNo	**TotalLength**	
127/C-W0273/S014614	130.44	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B N Naveen kumar NO:22,M R Line, Akkipet , Bangalore-560053		2995000.00
PhoneNo	**EmailId**	
9611111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at Byraveshwara nagara 9th Main and 9th A Main roads and surrounding Area in Ward no - 127	3000000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain at Byraveshwara nagara 9th Main and 9th A Main roads and surrounding Area in Ward no - 127	127-15-000041
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/217/2014-15	22/01/2015	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
22/01/2015	21/01/2016	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0159, W0180, W0158	NA	Shiva Temple
SegmentNo	**TotalLength**	
127/C-W0159/S020200	167.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		4994294.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slabs to adarsh nagara main roads and cross roads and surrounding area in ward no-127	4990000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain and providing covering slabs to adarsh nagara main roads and cross roads and surrounding area in ward no-127	127-14-000042
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/393/2013-14	01/03/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesha
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0153, W0169, W0159, W0180, W0155	NA	Shiva Temple
SegmentNo	**TotalLength**	
127/C-W0153/S021207	115.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Tecnical Manager (KRIDL)		4994294.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slabs to adarsh nagara main roads and cross roads and surrounding area in ward no-127	4999000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain and providing covering slabs to adarsh nagara main roads and cross roads and surrounding area in ward no-127	127-14-000042
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/393/2013-14	01/03/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0211, W0259, W0228, W0220	NA, Ambedkar Nagar Slum	bbmp metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0211/S032029	104.57	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara construnction ,prop.sir M Rajesh, Contractor, no-28,1st main road, 3rd cross An		1956510.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	127-14-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/216/2013-14	27/12/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2013	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0259, W0228, W0267, W0265, W0217, W0271, W0263, W	Ambedkar Nagar Slum, NA, Maheshwari Nagar Ambedkar Rd, 8th Crs	bbmp Metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0259/S034035	149.40	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara construnction ,prop.sir M Rajesh, Contractor, no-28,1st main road, 3rd cross An		1956510.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Resurfacing	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	127-14-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/216/2013-14	27/12/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0228, W0263	NA	bbmp Metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0228/S034350	28.59	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara construnction ,prop.sir M Rajesh, Contractor, no-28,1st main road, 3rd cross An		1956510.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	127-14-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/216/2013-14	27/12/2013	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0228, W0217	NA	bbmp metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0228/S034643	28.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara construnction ,prop.sir M Rajesh, Contractor, no-28,1st main road, 3rd cross An		1956510.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of providing and asphalting to Byraveshwaranagara, D cross roads in ward no-127	127-14-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE (GRN)/AE/TN/WO/216/2013-14	27/12/2013	90 DAys
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0211, W0259, W0253, W0220, W0217, W0261, W0257, W	NA, Ambedkar Nagar Slum	BBmp Metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0211/S035102	185.76	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (KRIDL)		4900000.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of development of cement and concrete roads and improvements to drain at adarsh nagar , Kalyan Nagara, Sanjeevini Nagara and Shakthi Garden in wa	4900000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of development of cement and concrete roads and improvements to drain at adarsh nagar , Kalyan Nagara, Sanjeevini Nagara and Shakthi Garden in ward no 127	127-12-000056
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE(GRN)/AE/TN/WO/57/2012-13	30/07/2012	90 DAys
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/07/2012	29/07/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0216, W0220, W0217, W0173, W0188	NA	Bbmp Metanity Hospital
SegmentNo	**TotalLength**	
127/C-W0216/S035829	229.24	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (KRIDL)		4900000.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of development of cement and concrete roads and improvements to drain at adarsh nagar , Kalyan Nagara, Sanjeevini Nagara and Shakthi Garden in wa	4900000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of development of cement and concrete roads and improvements to drain at adarsh nagar , Kalyan Nagara, Sanjeevini Nagara and Shakthi Garden in ward no 127	127-12-000056
Work OrderNo	**Work Order Date**	**Period of Extention**
NO:EE(GRN)/AE/TN/WO/57/2012 -13	30/07/2012	90 daYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/07/2012	29/07/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0138, W0191	2nd Crs, NA	KVV School
SegmentNo	**TotalLength**	
127/C-W0138/S120202	85.78	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical manager(KRIDL)		2465100.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	2250000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	127-14-000036
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE//WO//2013-14	01/03/2014	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0189, W0138	NA, 2nd Crs	KVV School
SegmentNo	**TotalLength**	
127/C-W0189/S121540	85.49	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical manager(KRIDL)		2465100.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	2250000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	127-14-000036
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE//WO//2013-14	01/03/2014	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0187, W0138	NA, 2nd Crs	KVV School
SegmentNo	**TotalLength**	
127/C-W0187/S122221	79.72	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical manager(KRIDL)		2465100.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	2250000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of Improvements to drain and providing covering slab to kalyana Nagara main and cross roads and surrounding area in ward no-127	127-14-000036
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE//WO//2013-14	01/03/2014	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0211, W0012, W0259, W0228, W0220	NA, Ambedkar Nagar Slum	BBMP Metarnity Hospital
SegmentNo	**TotalLength**	
127/C-W0211/S012124	150.42	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SIR NANJUNDESHWARA CONSTRUCTION,CONTRACTOR,1ST MAIN ROAD,3RD CROSS ROADS, ANNAPOORNESHWARINAGAR,BANG		1961883.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of construction of drain and footpath in Byraveshwaranagara 9th G and 9th D main roads in moodalapalya in ward no -127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of construction of drain and footpath in Byraveshwaranagara 9th G and 9th D main roads in moodalapalya in ward no -127	127-12-000047
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/138/2012-13	30/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/08/2012	29/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0216, W0265	NA, Ambedkar Nagar Slum	TOILORING CENTER
SegmentNo	**TotalLength**	
127/C-W0216/S013652	128.70	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SIR NANJUNDESHWARA CONSTRUCTION,CONTRACTOR,1ST MAIN ROAD,3RD CROSS ROADS, ANNAPOORNESHWARINAGAR,BANG		1961883.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of construction of drain and footpath in Byraveshwaranagara 9th G and 9th D main roads in moodalapalya in ward no -127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of construction of drain and footpath in Byraveshwaranagara 9th G and 9th D main roads in moodalapalya in ward no -127	127-12-000047
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/138/2012-13	30/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/08/2012	29/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0138, W0183	2nd Crs, NA	KVV school
SegmentNo	**TotalLength**	
127/C-W0138/S111736	86.78	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANGER (KRIDL)		4870025.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing concrete roads and other improments to drain at kalyana nagar main and cross roads in ward no-127	5000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of providing concrete roads and other improments to drain at kalyana nagar main and cross roads in ward no-127	127-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/395/2013-14	01/03/2014	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0138, W0185	2nd Crs, NA	KVV SCHOOL
SegmentNo	**TotalLength**	
127/C-W0138/S113114	85.52	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANGER (KRIDL)		4870025.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of providing concrete roads and other improvements to drain at kalayan nagar main road and cross roads in ward no-127	5000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	work of providing concrete roads and other improvements to drain at kalayan nagar main road and cross roads in ward no-127	127-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/395/2013-14	01/03/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0152, W0140, W0144, W0167, W0169, W0146, W0158	NA, 3rd Crs	VISHWA bharathi school
SegmentNo	**TotalLength**	
127/C-W0152/S114108	126.22	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANGER (KRIDL)		4870025.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of providing concrete roads and other improvements to drain at kalyana nagar main and cross roads in ward no - 127	5000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Work of providing concrete roads and other improvements to drain at kalyana nagar main and cross roads in ward no -127	127-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/WO/395/2013-14	01/03/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0037, W0140, W0167	NA, 3rd Crs	VSWABHARATHI SCHOOL
SegmentNo	**TotalLength**	
127/C-W0037/S115357	129.40	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical manager (K R I D L)		4870025.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing concrete Road and other Improvements to drain at Kalyana Nagara Main and cross Roads in ward no 127	5000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing concrete Road and other Improvements to drain at Kalyana Nagara Main and cross Roads in ward no 127	127-14-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/WO/395/2013-14	01/03/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2014	28/02/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0149, W0146, W0136	NA	VISWABHARATHI SCHOOL
SegmentNo	**TotalLength**	
127/C-W0149/S121117	33.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Naveen, Contractor,No - 270,7thCross Road ,Bellary Road, Byatarayanapura, Bangalore -560092		971296.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	127-14-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/212/2013-14	27/12/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0055, W0138, W0045	NA, 2nd Crs	B B M P Quartres
SegmentNo	**TotalLength**	
127/C-W0055/S122940	53.85	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Naveen, Contractor,No - 270,7thCross Road ,Bellary Road, Byatarayanapura, Bangalore -560092		971296.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	127-14-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/212/2013-14	27/12/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0055, W0130, W0049, W0045	NA	B B M P Quartres
SegmentNo	**TotalLength**	
127/C-W0055/S123731	56.76	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Naveen, Contractor,No - 270,7thCross Road ,Bellary Road, Byatarayanapura, Bangalore -560092		971296.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drain and Providing Covering Slabs to Shakthi Gardens and Sanjiveeni nagar Surrounding Areas in ward no 127	127-14-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/212/2013-14	27/12/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/12/2013	26/12/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0118, W0061, W0081	NA, Om Shakthi Lyt 7th Crs, 14th Crs	B B M P Quatress
SegmentNo	**TotalLength**	
127/C-W0118/S124443	98.55	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara Construnction , prop. Sir M Rajesh, Contractor,		1396754.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of Construnction of Drain and Footpath in Sanjeevini nagar (Balance Work) 2nd Main road Surrounding Area roads in ward no-127	1500000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of Construnction of Drain and Footpath in Sanjeevini nagar (Balance Work) 2nd Main road Surrounding Area roads in ward no-127	127-13-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/407/2012-13	06/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/03/2013	05/03/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0170, W0178, W0166, W0167, W0169, W0174, W0188, W	NA	Sri Shiva Temple
SegmentNo	**TotalLength**	
127/C-W0170/S125824	207.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager(KRIDL)		5315273.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	127-13-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/381/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0166, W0169, W0173, W0170, W0174	NA	Sri Eshwara Temple
SegmentNo	**TotalLength**	
127/C-W0166/S010457	124.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager(KRIDL)		5315273.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	127-13-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/381/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/03/2013	28/02/2014	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0216, W0273, W0227, W0224, W0229, W0275	NA	B B M P Ward Office
SegmentNo	**TotalLength**	
127/C-W0216/S011420	167.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager(KRIDL)		5315273.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	4975000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Providing Asphalting to main and cross roads at Sanjeevini nagar and Kalyannagar in ward no-127	127-13-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/381/2012-13	01/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/03/2013	28/02/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0055, W0156, W0179	NA	Sri Eshwara Temple Kalyan nagar
SegmentNo	**TotalLength**	
127/C-W0055/S012411	91.58	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara Construnction , prop. Sir M Rajesh, Contractor,		1845572.00
PhoneNo	**EmailId**	
9111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of Construnction of Drain and Footpath in Kalyan nagar 12th and 13th cross and surrounding area roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of Construnction of Drain and Footpath in Kalyan nagar 12th and 13th cross and surrounding area roads in ward no-127	127-13-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/435/2012-13	20/03/2013	90 DAys
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/03/2013	19/03/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0063, W0055, W0061, W0128, W0179, W0138, W0181	Om Shakthi Lyt 6th Crs, NA, Om Shakthi Lyt 7th Crs, 2nd Crs, Vinayaka Lyt 3rd Crs	K V V school
SegmentNo	**TotalLength**	
127/C-W0063/S013754	152.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Shree Nanjundeshwara Construnction , prop. Sir M Rajesh, Contractor,		1845572.00
PhoneNo	**EmailId**	
9731111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of Construnction of Drain and Footpath in Kalyan nagar 12th and 13th cross and surrounding area roads in ward no-127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of Construnction of Drain and Footpath in Kalyan nagar 12th and 13th cross and surrounding area roads in ward no-127	127-13-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/435/2012-13	20/03/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/03/2013	19/03/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0240, W0224, W0281	NA	Sri Shanimahathma temple
SegmentNo	**TotalLength**	
127/C-W0240/S014608	247.94	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sinchana Construnction , Contractor. Govindaraja Nagara , Vijayanagara		2052516.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of Drain and Footpath in Byraveshwar nagar 6th main &7th main road in ward no-127	1985000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construnction of Drain and Footpath in Byraveshwar nagar 6th main &7th main road in ward no-127	127-12-000045
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)AE/TN/WO/124/2012-13	25/08/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/08/2012	24/08/2013	No

Field Inspection Details

Number of Trees	Other Information	Name
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0226, W0287, W0238	NA, Maheshwari Nagar 4th Main Rd	B B M O Ward office
SegmentNo	**TotalLength**	
127/C-W0226/S020602	176.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri S Rajashekar, Contractor, Attiguppe, Vijayanagara		1850546.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	1800000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction of drain and Footpath in Byraveshwara nagar 4th D main to 4th A main road in Mudalapalya in ward no-127	127-12-000043
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/141/2012-13	30/08/2012	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
30/08/2012	29/08/2013	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0220, W0217	9th H Crs, 9th E Main Rd	BBMP HOSPITAL
SegmentNo	**TotalLength**	
127/C-W0220/S124923	64.85	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		89530.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to secondary drain &construction of drain at adarshnagar (right side) near st . anns school in moodalapalya (under emergency work) i	99900	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	darshnagar (right side) near st . anns school in
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to secondary drain &construction of drain at adarshnagar (right side) near st . anns school in moodalapalya (under emergency work) in ward -127	127-11-000014(h)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/288/2011-12	19/08/2011	30days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/08/2011	19/08/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0109, W0104	1st Main Rd, Manjunath Talkies Rd	mudalpalaya market
SegmentNo	**TotalLength**	
127/C-W0109/S012316	38.67	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		175250.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain in sanjeevini nagara and construction of culvert in market road in moodalpalaya in ward-127	200000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	Improvements to drain in sanjeevini nagara and co
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain in sanjeevini nagara and construction of culvert in market road in moodalpalaya in ward-127	127-11-000014(k)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/290/2011-12	19/08/2011	30days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/08/2011	19/08/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0275, W0224	NA, 4th Main Rd	new pioneer english school
SegmentNo	**TotalLength**	
127/C-W0275/S021301	35.17	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sir manjunath , contractor,no -1/3 , 3RD CROSS road ,behind Minerva mill,magadi road , Bangalore 23		71710.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to damaged portion of drains and culverts at 9th d main road , byraveshwaranagar (under emergency work) in ward no - 127	80000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to damaged portion of drains and culverts at 9th d main road , byraveshwaranagar (under emergency work) in ward no - 127	127-11-000014(b)
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/189/2011-12	14/07/2011	30days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
14/07/2011	14/07/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0225, W0223, W0237, W0188, W0245, W0243, W0241, W	5th Crs, 9th B Main Rd, 3rd Crs, NA, 1st Crs, 2nd Crs, 4th Crs, 1st Main Rd, Baiyraveswara Nagar	sandeep apatment
SegmentNo	**TotalLength**	
127/C-W0225/S103300	237.33	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI. B sunil kumar contractor no- 1293 6th cross road 9th bolck nagarbhavi 2nd stage bda loyout baga		1648849.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of construction of drain and footpath in kalyanagar 1st main road in moodalapalya in ward no 127	1900000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of construction of drain and footpath in kalyanagar 1st main road in moodalapalya in ward no 127	127-12-000048
Work OrderNo	**Work Order Date**	**Period of Extention**
EE (GRN)/AE/ TN/ W0/116/ 2012-2013	22/08/2012	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
22/08/2012	22/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
09/09/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0063, W0055, W0061, W0081, W0128	NA, 8th Crs, Kalyan Nagar, 7th Crs, 4th Crs, 3rd Main Rd, Sanjeevini Nagar	temple
SegmentNo	**TotalLength**	
127/C-W0063/S105825	145.10	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI NAJUNADEWARA CONSTRUTION PROP SRI M RAJESH contractor no 28 1st main road 3rd cross rd annapoorn		1216714.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of constrution of drain and footpath in sanjivinagara 2nd main rd surrounding area roads in ward no -127	1500000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of constrution of drain and footpath in sanjivinagara 2nd main rd surrounding area roads in ward no -127	127-13-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/407/2012-13	06/03/2013	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/03/2013	06/03/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0145, W0152, W0149, W0139, W0150	NA, 1st Crs Rd, 2nd Main Rd, 1st Main Rd	Best choice
SegmentNo	**TotalLength**	
127/C-W0145/S114941	145.68	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI S NAVEEN contractor no 270 7th cross rd bellary rd byatarayanapura blr-560092		890163.00
PhoneNo	**EmailId**	
9111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of constrution of drain and improvement of footpath in kalyanagar 1st a main road in ward no 127	1000000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of constrution of drain and improvement of footpath in kalyanagar 1st a main road in ward no 127	127-12-000049
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/W0/122/2012-2013	25/08/2012	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/08/2012	25/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0099, W0114	1st Crs, Sanjeevini Nagar 1st Main Rd	manjunath swamy theatre
SegmentNo	**TotalLength**	
127/C-W0099/S120848	142.29	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI NANJUNDESHWARA CONSTRUCTION PROP SRI M RAJESH contractor no 28 1st main rd 3rd cross rd annapoor		1642414.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
work of construction of drain and footpath in 1st cross and 1st a main roads in ward no -127	2000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	work of construction of drain and footpath in 1st cross and 1st a main roads in ward no -127	127-13-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/W0/408/2012-13	06/03/2013	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/03/2013	06/03/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramesh
Date of Inspection	**Remarks**	
03/09/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	127	Mudalapalya
StreetID	**StreetName**	**Significant LandMark**
W0216, W0273, W0227, W0224, W0229, W0275	3rd Main Rd, 9th A Main Rd, 4th Crs, 4th Main Rd, 2nd B Main Rd, NA	Venkateshwara Swamy Temple
SegmentNo	**TotalLength**	
127/C-W0216/S122802	246.01	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
sri gangaraju contractor no - 1093 2nd cross rd, 2nd main rd NGOS colony kamalanagar blr 560079		1763443.00
PhoneNo	**EmailId**	
1111111111		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Work of construction of drain and footpath in byraveshwaranagara 8th ,9th and 9th a main rd in moodalapalya in ward no -127	1945000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Work of construction of drain and footpath in byraveshwaranagara 8th ,9th and 9th a main rd in moodalapalya in ward no -127	127-12-000046
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(GRN)/AE/TN/WO/123/2012-13	25/08/2012	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/08/2012	25/08/2013	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramesh
Date of Inspection	**Remarks**	
05/09/2015		

Category	Photo
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	