



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0012	NA	Gundopath Street
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0012/S091503	393.15	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R Suri		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Asphalting from Mysore road to Gundoparth Street in Ward No - 139	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-11-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/271/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0008	NA	Pedestrian Lane
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0008/S092050	162.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Nirmiti Kendra		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804401		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Pedestrian Lane Surrounding individual road in Ward No - 139	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-11-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/295/2011-12	20/03/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0189	NA	Masjid
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0189/S092640	106.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sayeed Ahmed		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593836		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to damaged CC Roads at Toppunagara in Ward No - 139	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	CC Roads
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-12-000054
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/81/2012-13	07/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0015	NA	Pedestrian Lane
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0015/S093010	87.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Suri		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements & Development of Pedestrian Lane & side drain of O.T.Pet Road in Ward No - 139	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	139-11
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/86/2011-11	24/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004	NA	AS Char Street
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0004/S093330	200.64	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Chamundeswari		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804402		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements & Development of side drain at AS Char Street Easterside in Ward No - 139	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-11-
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/2010-11	23/05/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		murti
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0253	NA	Toppu Nagar
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0253/S094114	118.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492801111		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of drain & providing CC Road to Babalane in Ward No - 139	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Others	CC Roads
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-11-00003
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0039	NA	Balash Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0039/S100342	144.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804564		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements & repairs to drain at Balash Garden in Ward No - 139		2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	139-11-000072
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/ /2011-12	30/05/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0079	Om Shakthi Lyt 4th Crs	Balash Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0079/S100700	29.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804564		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements & repairs to drain at Balash Garden in Ward No - 139		2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	139-11-000072
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/ /2011-12	30/05/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0056	NA	Balash Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0056/S100840	218.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804564		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements & repairs to drain at Balash Garden in Ward No - 139		2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-11-000072
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/ /2011-12	30/05/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0060	NA	Swamy Lane
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0060/S101119	40.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492802586		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC to Swamy Lane in Ward No - 139	9150000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	CC Roads
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/W0/235/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0150, W0152, W0146, W0148, W0117	NA	CRIME BRANCH
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0150/S090425	116.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S L SUNIL(MATHASHREE BANASHANKARAMMA ENTERPRISES)		865059.00
<b>PhoneNo</b>	<b>EmailId</b>	
982722587		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROADS AND OTHER WORKS AT WARD JURISDICTION	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC ROADS WORK	139-14-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CRP/WO/95/2013-2014	30/10/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
02/04/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0107, W0100, W0102, W0106, W0104, W0123, W0119	Subhash Chandra Bose Lyt, NA	BDG LANE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0107/S081918	118.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.L.ANJANAIAH		1556467.00
<b>PhoneNo</b>	<b>EmailId</b>	
9986637446		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CC ROAD & FOOTPATH AT BDG LANE	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Others	CC ROAD & FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/253/2015-16	07/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
07/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0114, W0119, W0113	NA, 3rd Crs	NEAR JOLLY MOHALA MASJID ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0114/S045453	61.59	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
GOPAL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9742887489		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO FOOTPATH AND PROVIDING CC TO DAMAGED ROAD AT WARD JURISDICTION	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	FOOT PATH AND CC ROAD MAINTAINANCE	139-13-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/105/2013-14	16/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Niagara
<b>Date of Inspection</b>	<b>Remarks</b>	
07/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0053, W0024, W0045	NA	venkataraman temple street
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0053/S060722	113.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
FRANCIS N		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343652178		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DAMAGED CC ROAD AT BAKSHI GARDEN VENKATARAMAN SWAMY TEMPLE STREET AND SURROUNDINGS AREA	800000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Routine Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	DAMAGED CC ROAD WORK	139-16-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/04/2016-17	28/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0072, W0097, W0068, W0077, W0081	NA, 16th Crs, 14th Crs	PEER BOUDBARY
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0072/S061236	140.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
FRANCIS M		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343652178		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO CC ROAD AND DEVELOPMENT TO TOILET AT PEER BOUNDARY	700000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Routine Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC ROAD DEVELOPMENT	139-16-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/50/2016-17	19/08/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
08/11/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0092, W0090, W0149	NA	RANASINGHPET PUTTANA GALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0092/S061848	90.11	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
FRANCIS M		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343652178		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DAMAGED CC ROAD AT RANASINGH PET PUTTANNA GALLI 9TH CROSS	1000000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC ROAD MAINTAINANCE	139-16-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/05/2016-17	28/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0117	NA	BABA LANE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0117/S062457	49.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
FRANCIS M		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343652178		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
RECONSTRUCTION OF DAMAGED SSM WALLS AND REPAIRS TO CULVERT AT BABA LANE MYSORE ROAD	500000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-16-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/101/2015-16	24/02/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
08/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0195, W0203, W0162, W0191, W0197, W0160, W0166, W	NA, Vinayaka Lyt 1st Crs, Vinayaka Lyt 2nd Crs	TIPPUNAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0195/S063254	148.34	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
FRANCIS M		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343652178		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC DRAIN AT TIPPUNAGAR 5TH MAIN ROAD	700000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC DRAIN WORK	139-16-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/03/2016-17	28/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
08/11/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 139	<b>WardName</b> K R Market
<b>StreetID</b> W0124	<b>StreetName</b> NA	<b>Significant LandMark</b> KR MOSQUE
<b>SegmentNo</b> 139/S-W0124/S042526	<b>TotalLength</b> 68.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 940447.00
<b>PhoneNo</b> 9632722527	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO CC TO SERVICE ROAD OF MARKET MAIN ROAD & IMPROVEMENTS TO SSM DRAIN OF SERVICE ROAD [CHAINAGES 0.00 MTRS TO 70.00 MTRS]	<b>Sanctioned Amount</b> 945000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Others	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> 0	<b>Job No Work Code</b> 139-14-000034
<b>Work OrderNo</b> EE/CMP/TEND/WO/234/2013-14	<b>Work Order Date</b> 22/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 21/09/2014	<b>Defect Liability Period To</b> 20/09/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Basavaraj
Date of Inspection	Remarks
13/03/2016	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0124	NA	KR MOSQUE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0124/S043138	29.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		370854.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CC TO SERVICE ROAD OF MARKET MAIN ROAD AND IMPROVEMENTS TO SSM DRAIN OF SERVICE ROAD [CHAINAGE:70 MTRS TO 100 MTRS]	372000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	SSM DRAIN & CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	SSM DRAIN & CC ROAD WORK WAS DONE FROM 70 MTRS TO 100 MTRS	139-14-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/233/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/09/2014	19/09/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Basavaraj
Date of Inspection	Remarks
13/03/2016	

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 139	<b>WardName</b> K R Market
<b>StreetID</b> W0142, W0167, W0118, W0100, I0080	<b>StreetName</b> NA	<b>Significant LandMark</b> SURROUNDING AREA OF AS CHAR STREET
<b>SegmentNo</b> 139/C-W0142/S044153	<b>TotalLength</b> 174.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 790320.00
<b>PhoneNo</b> 9632722527	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING CC TO SURROUNDING AREA OF A.S.CHAR STREET	<b>Sanctioned Amount</b> 916000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 139-14-000041
<b>Work OrderNo</b> EE/CMP/TEND/WO/229/2013-14	<b>Work Order Date</b> 22/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 30/05/2014	<b>Defect Liability Period To</b> 29/05/2015	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Basavaraj
<b>Date of Inspection</b> 13/03/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 139	<b>WardName</b> K R Market
<b>StreetID</b> W0165, W0163, W0161, W0100, W0151, W0155	<b>StreetName</b> NA	<b>Significant LandMark</b> PVR ROAD
<b>SegmentNo</b> 139/C-W0165/S044734	<b>TotalLength</b> 109.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 741934.00
<b>PhoneNo</b> 9632722527	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO DRAIN AT PVR ROAD,NORTHERN SIDE	<b>Sanctioned Amount</b> 745000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> DRAIN WORK WAS DONE ON RIGHT SIDE FROM BVK IYENGAR ROAD	<b>Job No Work Code</b> 139-14-000037
<b>Work OrderNo</b> EE/CMP/TEND/WO/230/2013-14	<b>Work Order Date</b> 22/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 26/07/2014	<b>Defect Liability Period To</b> 25/07/2015	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Basavaraj
<b>Date of Inspection</b> 13/03/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0143, W0100, W0151, W0147	NA	JOLLY MOHALLA
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0143/S045136	62.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		769910.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING BOREWELL & SANITARY LLINE TO JOLLY MOHALLA & SURROUNDING AREA	700000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	BOREWELL & SANITARY LINE
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		139-12-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/WO/28/2013-14	26/08/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0257	NA	ST MARY'S HOSPITAL
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0257/S045603	98.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		819734.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC TO SURROUNDING AREA OF RAGHAVENDRA SWAMY TEMPLE STREET,N.T. PET ROAD	830000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CC ROAD WORK WAS DONE	139-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/228/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
01/10/2014	30/09/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0056	NA	BAKSHI GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0056/S045955	218.38	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		718188.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAINS & CULVERTS AT BAKSHI GARDEN	720000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK WAS DONE ON LEFT SIDE FROM TCM ROYAN ROAD	139-14-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/232/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/09/2014	23/09/2015	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 139	<b>WardName</b> K R Market
<b>StreetID</b> W0054, W0055, W0042, W0049, W0041, W0048, W0051	<b>StreetName</b> NA, Om Shakthi Lyt, 9th Crs, Om Shakthi Lyt 8th Crs	<b>Significant LandMark</b> SWAMY LANE
<b>SegmentNo</b> 139/C-W0054/S050508	<b>TotalLength</b> 190.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 909222.00
<b>PhoneNo</b> 9632722527	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING CC TO SWAMY LANE	<b>Sanctioned Amount</b> 915000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 139-14-000043
<b>Work OrderNo</b> EE/CMP/TEND/WO/235/2013-14	<b>Work Order Date</b> 22/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 01/10/2014	<b>Defect Liability Period To</b> 30/09/2015	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Basavaraj
<b>Date of Inspection</b> 13/03/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0138	2nd Crs	CHURCH CIRCLE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0138/S072241	345.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		997918.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAINS FROM CHURCH CIRCLE TO BVK IYENGAR ROAD(SOUTH SIDE)	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK WAS DONE ON LEFT SIDE FROM BVK IYENGAR ROAD	139-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/238/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0138	2nd Crs	CHURCH CIRCLE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0138/S072657	345.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		995629.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN FROM CHURCH CIRCLE TO BVK IYENGAR ROAD(NORTH SIDE)	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK ON RIGHT SIDE FROM BVK IYENGAR ROAD	139-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0167	NA	BVK IYENGAR ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0167/S073434	147.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		915333.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AT BVK IYENGAR ROAD WESTERN SIDE	916000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK WAS DONE ON LEFT SIDE FROM MYSORE ROAD	139-14-000033
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/236/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0167	NA	BVK IYENGAR ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0167/S073026	147.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		915333.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AT BVK IYENGAR ROAD EASTERN SIDE	916000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK WAS DONE ON RIGHT SIDE FROM MYSORE ROAD	139-14-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/231/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Basavaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0154	NA	MINI BHAKSHI GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0154/S061549	74.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
GANGAMUTHAIAH		920434.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884976681		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF PRAYER HALL AT MINI BAKSHMI GARDEN	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	PRAYER HALL
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE\CMP\TEND\WO\32\2014-15	09/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narayani
<b>Date of Inspection</b>	<b>Remarks</b>	
22/02/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 139	<b>WardName</b> K R Market
<b>StreetID</b> W0160, W0162, W0166, W0193, W0189	<b>StreetName</b> NA, Vinayaka Lyt 2nd Crs	<b>Significant LandMark</b> TIPPUNAGAR
<b>SegmentNo</b> 139/C-W0160/S094029	<b>TotalLength</b> 83.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1864800.00
<b>PhoneNo</b> 9632722527	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENT OF DRAIN AND ROADS AT TIPPUNAGAR	<b>Sanctioned Amount</b> 1995000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Others	<b>Other Work Type</b> DRAIN AND ROADS
<b>Tender</b> Tender	<b>WorkDetails</b> ROAD AND DRAIN WORK	<b>Job No Work Code</b> 139-11-000034
<b>Work OrderNo</b> EE(CMP)WO/201/13-14	<b>Work Order Date</b> 15/03/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> baswaraj
<b>Date of Inspection</b> 14/03/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0126, W0108, W0151, W0112	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	CM LANE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0126/S094848	75.10	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
GOPAL		419360.00
<b>PhoneNo</b>	<b>EmailId</b>	
9632722527		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DAMAGED CC ROAD AT CM LANE	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	IMPROVEMENT TO DAMAGED CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	ROAD WORK	139-12-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/185B/2012-13	28/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Baswaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
14/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0074, W0089, W0078, W0076, W0073, W0099, W0059	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	TIPPUNAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0074/S013611	204.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SYED IBRAHIM		815274.00
<b>PhoneNo</b>	<b>EmailId</b>	
9863746722		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
REPAIRS TO DAMAGED CC ROAD AT TIPPUNAGAR CROSS ROADS	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	SYED IBRAHIM	139-13-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/91/2013- 2014	21/11/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivaraja
<b>Date of Inspection</b>	<b>Remarks</b>	
16/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100, W0132, W0169, W0120, W0014	NA	BARLANE MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0100/S014447	306.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AMINULLA K		808096.00
<b>PhoneNo</b>	<b>EmailId</b>	
9778567376		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND FOOTPATH PROVIDING SS SLABS AT BARLANE MASJID SURROUNDING ROADS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	DRAIN AND FOOTPATH	139-14-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/242/2013- 2014	26/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivaraja
<b>Date of Inspection</b>	<b>Remarks</b>	
16/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0115, W0146, W0150, W0152, W0148, W0117, W0125, W	NA, Veera Anjaneya Temple Rd	BABALINE
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0115/S015158	102.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
AMINULLA KHAN		848490.00
<b>PhoneNo</b>	<b>EmailId</b>	
9647587383		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND REPAIRS TO DAMAGED CC ROAD AND DRAIN AT BABLINE	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC ROAD WORK	139-13-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/94/2013- 2014	21/11/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivaraja
<b>Date of Inspection</b>	<b>Remarks</b>	
16/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0165, W0163, W0143, W0161, W0129, W0139, W0100, W	NA	MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0165/S015758	261.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
RUKSANA CONSTRUCTION		775581.00
<b>PhoneNo</b>	<b>EmailId</b>	
8896654566		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
WORK ORDER TO START THE WORK PROVIDING DIRECTION NAME BOARDS TO PUBLIC AT SKR MARKET	8000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		139-12-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/175//2012- 2013	31/01/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivaraja
<b>Date of Inspection</b>	<b>Remarks</b>	
16/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0053	NA	BAKSHI GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
139/S-W0053/S062348	77.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.L.ANJANAIAH		1469169.00
<b>PhoneNo</b>	<b>EmailId</b>	
9986637446		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
REPAIRS TO DRAINS & DAMAGES TO CC ROAD AT BAKSHI GARDEN MAIN ROAD	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	DRAIN WORK ON BOTH SIDE & DAMAGED CC ROAD	139-13-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EEVCMP\TEND\WO\17\2014-15	19/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narayana
<b>Date of Inspection</b>	<b>Remarks</b>	
04/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0195, W0193, W0191, W0189, W0162	NA, Vinayaka Lyt 2nd Crs	ADIMOOLAM COMPOUND
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0195/S074122	53.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.L.ANJANAIAH		983125.00
<b>PhoneNo</b>	<b>EmailId</b>	
9986637446		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
RECONSTRUCTION OF DRAIN AND PROVIDING CC ROAD TO ADIMOOLAM COMPOUND AND SURROUNDING	1004000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN & ROAD WORK FOR W0193 ROAD ON BOTH SIDES	139-13-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE\CMP\TEND\WO\16\2014-15	19/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/07/2014	23/07/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Umesh
<b>Date of Inspection</b>	<b>Remarks</b>	
05/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	139	K R Market
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0130, W0134, W0143, W0151, W0159	NA, 1st Crs	JOLLY MOHALLA ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
139/C-W0130/S010155	167.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SERVER BAIG		1556127.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845199339		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
WORK ORDER TO START THE WORK IMPROVEMENTS TO DAMAGED CC ROADS AT JOLLY MOHALLA ROAD	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	C C ROAD WORK	139-12-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/48/2012-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Baswaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start

