



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004	NA	Arundhati Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0004/S112548	94.18	




ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0078	NA	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0078/S113224	291.44	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0144	3rd Crs	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0144/S113414	121.87	




<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0008	NA	BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0008/S113628	109.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0078	NA	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0078/S113922	291.44	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0144	3rd Crs	BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0144/S114125	121.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of Damaged Cement in Ward No - 141	2000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	Cement Road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/39/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0016, W0019	NA	ARUNDATHI SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0016/S084825	30.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ANJANAIAH		1644000.00
<b>PhoneNo</b>	<b>Emailld</b>	
9986637446		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CEMENT CONCRETE ROAD BEHIND ARUNDATHI SCHOOL AND SURROUNDING CROSSES	1800000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC ROAD	141-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/AE/WO/193/14-15	09/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		umesh
<b>Date of Inspection</b>	<b>Remarks</b>	
07/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0002	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0002/S123230	246.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N. Dhanaraj		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980303043		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to main cross roads of K.B nagara Valmiki Nagara, Vital Nagara and other roads in Ward No - 141	1500000	2010
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	099-10-N-G-E-R-AS-001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/17/10-11	14/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0076	NA	Burial Ground
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0076/S124003	317.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N. Dhanaraj		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980303043		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to main cross roads of K.B nagara Valmiki Nagara, Vital Nagara and other roads in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		099-10-N-G-E-R-AS-001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/17/10-11	14/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0001	NA	Burial Ground
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0001/S124621	143.42	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N. Dhanaraj		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980303043		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to main cross roads of K.B nagara Valmiki Nagara, Vital Nagara and other roads in Ward No - 141	1500000	2010
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	099-10-N-G-E-R-AS-001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/17/10-11	14/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0066, W0025	NA	Ganesh Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0066/S125159	104.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Om Sai Construction		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concrete to Conserrancy Line and Improvements Juridistion in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0072, W0025, W0027	NA	Ganesh Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0072/S125822	63.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Om Sai Construction		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concrete to Conserrancy Line and Improvements Juridistion in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0056, W0025, W0027	NA	Ganesh Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0056/S010119	64.03	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Om Sai Construction		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concrete to Conserrancy Line and Improvements Juridistion in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	141-11-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0074	NA	Ayyappa Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0074/S010401	96.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Samruddi Construction		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804401		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC to Conservancy line in Azad Nagara in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /11-12	28/01/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0025, W0064, W0027	NA	Ayyappa Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0025/S011218	64.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Samruddi Construction		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804401		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC to Conservancy line in Azad Nagara in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /11-12	28/01/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0008	NA	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0008/S011515	109.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P. Kumaraswamy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804401		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to 2nd 3rd cross road drain at 1st main Valmiki nagara in Ward No - 141	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	SSM Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	MOD/T.S/CE(W)/AE/51/2011-12
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/134/11-12	30/11/2001	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0002, W0001, W0076	NA	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0002/S012447	129.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P. Kumaraswamy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9492804401		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to 2nd 3rd cross road drain at 1st main Valmiki nagara in Ward No - 141	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	MOD/T.S/CE(W)/AE/51/2011-12
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/134/11-12	30/11/2001	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0026	NA	Health Ward Office
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0026/S022053	116.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
C. Subramanam		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC Drain at Valmiki Nagara 10th Cross in Ward No - 141	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/44/12-13	29/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0025	NA	BBMP Library
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0025/S022619	329.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
C. Subramanam		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC Box drain at Azad Nagara 1st Main Road in Ward No - 141	1998000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/45/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0007	NA	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0007/S023158	43.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.R Krishna Gowda		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain in 1st to Mysure Road Near Gopalan mall in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /12-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0009	NA	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0009/S023853	46.50	




<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.R Krishna Gowda		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain in 1st to Mysure Road Near Gopalan mall in Ward No - 141	1500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-12-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /12-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ramakrishna
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0132	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0132/S024116	92.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Venkat		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9491687262		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Drain and Providing CC to Cross roads in Ward Juridistion in Ward No - 141	1900000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/268/11/12	03/07/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0126	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0126/S024819	50.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Venkat		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9491687262		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Drain and Providing CC to Cross roads in Ward Juridistion in Ward No - 141	1900000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/268/11/12	03/07/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004	NA	Arundhati School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0004/S025333	94.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Ramesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8845936787		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road suide drain at Bande Slum in Ward No - 141	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000051
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/71/11-12	08/05/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0152	NA	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0152/S025939	121.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hosakotappa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC Box Drain in Ashwath Katte Road 7th cross in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	RCC BOX Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		141-11-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/180/11-12	02/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0154	NA	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0154/S030353	115.08	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hosakotappa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC Box Drain in Ashwath Katte Road 7th cross in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	RCC BOX Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		141-11-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/180/11-12	02/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0025, W0108, W0116	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0025/S030638	141.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hosakotappa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC Box Drain in Ashwath Katte Road 7th cross in Ward No - 141	1995000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/180/11-12	02/11/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0232	NA	Mullukattamma Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0232/S030925	32.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Nimithikedra		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CC to Vishwanunava School Road in Ward No - 141	1050000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	CC Road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		141-11-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /11-12	31/03/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0011	NA	Gajanana bar
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0011/S032108	35.84	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Ramesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8845936787		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road side drain at Bande slum in Ward No - 141	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000051
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/71/11-12	08/05/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ramakrishna
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0150	NA	Graden School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0150/S032931	121.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads side cross drain(CB) in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0244	NA	Graden School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0244/S033617	44.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads side cross drain(CB) in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0078, W0128, W0080, W0126, W0130, W0063, W0082, W	NA, Om Shakthi Lyt 6th Crs	Graden School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0078/S034000	164.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads side cross drain(CB) in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0191	NA	Graden School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0191/S034232	65.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads side cross drain(CB) in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0025	NA	BBMP Library
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0025/S034626	329.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R. Suri		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Reasphalting to Azadnagara Rudrappa Graden and Surrounding cross Roads in Ward No - 141	1750000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/272/11-12	12/07/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0238	NA	BBMP Library
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0238/S035220	109.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R. Suri		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Reasphalting to Azadnagara Rudrappa Graden and Surrounding cross Roads in Ward No - 141	1750000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/272/11-12	12/07/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0132	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0132/S035542	85.82	




<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sree Sai Constructions		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593838		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC and Improvements to Drain 2nd and 3rd cross at Aswath area Graden in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/237/11-12	09/12/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0136	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0136/S040048	125.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sree Sai Constructions		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593838		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC and Improvements to Drain 2nd and 3rd cross at Aswath area Graden in Ward No - 141	1995000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/237/11-12	09/12/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0063	Om Shakthi Lyt 6th Crs	Near BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0063/S101414	236.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road side Cross Drain in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0084	NA	Near BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0084/S103349	69.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road side Cross Drain in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0075	NA	Near BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0075/S103520	21.33	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road side Cross Drain in Ward No - 141	1500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0240	NA	Near BBMP School
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0240/S103743	91.52	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G. Somashekar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884675461		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road side Cross Drain in Ward No - 141	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/ /10-11	31/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0142	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0142/S104203	92.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0214	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0214/S105736	145.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0126	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0126/S105938	92.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0132	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0132/S110102	92.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0240	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0240/S111514	91.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	SSN Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0136	NA	Masjid Road
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0136/S075718	125.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BV Sridhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Constrction of CC and Improvements to Drain 5th and 6th Cross of Ashwathappa Graden in Ward No - 141	1995000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	DRAIN & ROADS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		141-11-0000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/TEND/55/11-12	20/10/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
05/12/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0121	NA	VALMIKINAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0121/S062441	574.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1805734.00
<b>PhoneNo</b>	<b>EmailId</b>	
9538319882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DRAIN AT VALMIKINAGARA 2ND MAIN EASTERN SIDE	1850000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK	141-15-000015
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/07/15-16	09/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		umesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0121	NA	VALMIKINAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0121/S062842	574.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1970588.00
<b>PhoneNo</b>	<b>EmailId</b>	
9538319882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENT TO DRAIN AT VALMIKINAGARA 2ND MAIN WESTERN SIDE	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK	141-15-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/57\15-16	20/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		umesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0020	NA	RUDRAPPA GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0020/S063556	108.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1724413.00
<b>PhoneNo</b>	<b>EmailId</b>	
9538319882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING DRAIN AND CC ROAD 8TH CROSS AT RUDRAPPA GARDEN	1750000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND CC ROAD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN AND CC ROAD WORK	141-15-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/06/15-16	09/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		umesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0168	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0168/S112233	125.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hobakattapa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concreted Valmiki Nagara, Vital nagar and Rudrappa Garden Cross in	2000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	Cement Road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		141-11-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		narashimha
<b>Date of Inspection</b>	<b>Remarks</b>	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0006	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0006/S121914	108.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hobakattapa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concreted Valmiki Nagara, Vital Nagar and Rudrappa Garden Cross in Ward No - 141	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0020	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0020/S122115	108.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hobakattapa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concreted Valmiki Nagara, Vital Nagar and Rudrappa Garden Cross in Ward No - 141	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0018, W0019, W0015, W0017	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0018/S122340	94.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hobakattapa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concreted Valmiki Nagara, Vital Nagar and Rudrappa Garden Cross in Ward No - 141	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0022	NA	Gopalan Mall
<b>SegmentNo</b>	<b>TotalLength</b>	
141/S-W0022/S122733	112.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Hobakattapa		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8884593837		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Cement Concreted Valmiki Nagara, Vital Nagar and Rudrappa Garden Cross in Ward No - 141	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	141-11-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/W0/10/10-11	25/03/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Narasimha
<b>Date of Inspection</b>	<b>Remarks</b>	
30/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0187, W0199, W0195, W0226, W0197, W0157, W0230, W	NA, Vinayaka Lyt 1st Crs	Mulkattamma temple
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0187/S050928	94.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
PROJECT MANAGER		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9848022150		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
emergency works for the year 2013-14 in ward no 141	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	construction of ssm drain, covering with BS slab and RCC slab wherever necessary, construction of culvert.	136-14-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CMP/TEND/WO/87/2014-15	19/09/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
22/09/2014	21/09/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		umesh M.S
<b>Date of Inspection</b>	<b>Remarks</b>	
04/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
WEST	141	Azad Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0238, W0220, W0154, W0216, W0228, W0156, W0218, W	NA	KANAKA BHAVAN
<b>SegmentNo</b>	<b>TotalLength</b>	
141/C-W0238/S085553	159.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1709030.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886817582		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DAMAGED DRAIN AT KB NAGARA 1ST MAIN,2ND CROSS AND SURROUNDING 2ND MAIN CROSS AND SURROUNDING (EMERGENCY WORK)	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	DRAIN WORK DONE ON BOTH SIDE AND CULVERTS TO 6TH & 7TH CROSS ROADS	141-15-000001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE\CMP\TEND\WO\85\2014-15	11/09/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/09/2014	19/09/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Umesh M S
Date of Inspection	Remarks	
05/03/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> WEST	<b>WardNo</b> 141	<b>WardName</b> Azad Nagar
<b>StreetID</b> W0176, W0186, W0160, W0187, W0180, W0182, W0222, W	<b>StreetName</b> NA	<b>Significant LandMark</b> KASTURBA ROAD
<b>SegmentNo</b> 141/C-W0176/S071231	<b>TotalLength</b> 181.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1709736.00
<b>PhoneNo</b> 9481417582	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> EMERGENCY WORKS	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> REPAIRS TO DRAIN & CONSTRUCTION OF CULVERT
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 141-14-000006
<b>Work OrderNo</b> EE\CMP\TEND\WO\87\2014-15	<b>Work Order Date</b> 11/09/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 22/09/2014	<b>Defect Liability Period To</b> 21/09/2015	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Umesh MS
<b>Date of Inspection</b> 05/03/2016	<b>Remarks</b>	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition

