



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0096, W0120, W0100, W0108, W0104, W0121, W0106, W	12th Crs, 6th Crs, 11th Crs, 9th Crs, 10th Crs, 9th A Crs, 9th A Main Rd, 6th Crs, 8th Main Rd, Bair	Mazid
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0096/S8462	259.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.S.Anil		2084663.76
<b>PhoneNo</b>	<b>Emailld</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing RCC drain	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		144-11-000033
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
ee/ckp/wo/60/11-12		60 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kotresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0077	4th Crs 7th Main Rd	PWD Quarters side
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0077/S8464	438.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
C.Balraj		1459491.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing RCC drain	1800000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		144-12-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
ee/ckp/wo/21/12-13		120 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kotresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0052, W0050, W0062, W0077, W0075, W0054, W0048	<b>StreetName</b> NA, J C Colony, NA, 4th Crs 7th Main Rd, 4th Crs, NA, NA	<b>Significant LandMark</b> Mariyyamma temple
<b>SegmentNo</b> 144/S-W0052/S8468	<b>TotalLength</b> 199.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.Harish	<b>ContractorRegNo</b>	<b>Expenditure</b> 718667.96
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Imp of footpath	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2011
<b>Year</b> 2010 - 2011	<b>Type of Work</b> Footpath Layering	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 144-11-000055
<b>Work OrderNo</b> ee/ckp/wo/358/11-12	<b>Work Order Date</b> 11/02/2012	<b>Period of Extention</b> 60 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b> no	<b>Name</b> M santhosh kumar
<b>Date of Inspection</b> 20/03/2014	<b>Remarks</b> incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0041, W0035, W0026, W0043, W0037, W0033	NA, NA, Khb Colony Rd, NA, NA, NA	guttepalya
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0041/S8469	93.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.P.Raveen		1480725.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
imp to drain	1800000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		144-12-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
ee/ckp/wo/82/12-13	05/09/2012	120 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kotresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/11/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0077, W0075, W0048	<b>StreetName</b> 4th Crs 7th Main Rd, 4th Crs, NA	<b>Significant LandMark</b> Lalbagh
<b>SegmentNo</b> 144/S-W0077/S9974	<b>TotalLength</b> 0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri.Balaraj	<b>ContractorRegNo</b>	<b>Expenditure</b> 1455750.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing RCC box Drain at Siddapura Nursury Road	<b>Sanctioned Amount</b> 1800000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2011 - 2012	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Providing RCC box Drain at Siddapura Nursury Road	<b>Job No Work Code</b> 144-10-000018
<b>Work OrderNo</b> EE(CKP)WO/21/2011-12	<b>Work Order Date</b>	<b>Period of Extention</b> 120 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Kotresh
<b>Date of Inspection</b> 23/11/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0052, W0050, W0062, W0075, W0054	<b>StreetName</b> NA, J C Colony, NA, 4th Crs, NA	<b>Significant LandMark</b> Lalbagh
<b>SegmentNo</b> 144/S-W0052/S9975	<b>TotalLength</b> 0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri.Balaraj	<b>ContractorRegNo</b>	<b>Expenditure</b> 1455750.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing RCC box Drain at Siddapura Nursury Road	<b>Sanctioned Amount</b> 1800000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2011 - 2012	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Providing RCC box Drain at Siddapura Nursury Road	<b>Job No Work Code</b> 144-10-000018
<b>Work OrderNo</b> EE(CKP)WO/21/2011-12	<b>Work Order Date</b>	<b>Period of Extention</b> 120 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Kotresh
<b>Date of Inspection</b> 23/11/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0061, W0063	Om Shakthi Lyt 7th Crs, Om Shakthi Lyt 6th Crs	WIDSON MANNER APPARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
144/C-W0061/S020658	114.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL TECHNICAL MANAGER-3		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9986697126		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drain and footpath windson manner appartmnt road in ward no 144	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements to drain and footpath windson manner appartmnt road in ward no 144	144-14-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/27/14-15	04/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas murthy
<b>Date of Inspection</b>	<b>Remarks</b>	
16/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0061	Hosur Crs	SWD Someshanagara
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0061/S34685	89.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N K REDDY		0.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Cons of SWD from Someshwaranagara to Hosur Road Near Abhaya hospital in ward no- 60	2500000	2009-10
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2009 - 2010	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	Cons of SWD from Someshwaranagara to Hosur Road Near Abhaya hospital in ward no- 60	061-09-NGED-FO-001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE//178/09-10		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	Srinivas Murthy
<b>Date of Inspection</b>	<b>Remarks</b>	
25/03/2014	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0002, W0039, W0004	NA, NA, NA	Murall Slum
<b>SegmentNo</b>	<b>TotalLength</b>	
144/C-W0002/S35115	139.00	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
PRADEEP MP		0.00
<b>PhoneNo</b>	<b>EmailId</b>	

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Impts of footpath in Murali Slum in ward no - 144	1000000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Impts of footpath in Murali Slum in ward no - 144	144-13-0000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/18/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
22/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0095, W0097, W0088	NA, 2nd Main Rd, NA	Siddapura cross roads
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0095/S35127	22.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
PRADEEP M P		0.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Impts of roads and culverts in Siddapura cross road in ward no- 144	6000000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	culverts
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Impts of roads and culverts in Siddapura cross road in ward no- 144	144-13-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/19/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
22/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0126, W0075, W0150, W0148, W0115, W0163, W0122, W	5th Crs, 4th Crs, 1st Crs Someshwara Nagara, 2nd Crs Someshwara Nagara, 2nd A Main Rd, NA, 6th Crs,	SOMESHWARANAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
144/C-W0126/S35134	176.00	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ALMAS CONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONS OF RCC DRAIN IN SOMESHWARANGARA MAIN ROAD	500000	2011-12
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	CONS OF RCC DRAIN IN SOMESHWARANGARA MAIN ROAD	144-11-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/108/10-11		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/03/2014	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0136	1st Crs	Tippu School
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0136/S10762	0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. G. Govardhana		407625.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Cross roads in Dayananda slum from Yellamma Temple	500000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Providing CC Cross roads in Dayananda slum from Yellamma Temple.	144-11-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(CKP)WO/35/2011-12		45 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	mo	M Santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0078, W0077, W0080, W0089, W0074	NA, 4th Crs 7th Main Rd, 4th Crs, NA, 6th Crs	Dayananda Colony
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0078/S23466	196.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. S. Sathish		0.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Pot hole filling	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	Pothole filling
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Pot hole filling .	144-12-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(CKP)WO/349/11-12		30 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0075, W0341, W0335	4th Crs, M H Mariyappa Rd, NA	Allethamma Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0075/S26323	182.00	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M. Swamy		882110.00
<b>PhoneNo</b>	<b>EmailId</b>	

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements Of Footpath	2000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	Foothpath
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements Of Footpath	114-11-000051
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(CKP)WO/366/2011-12	01/02/2012	60 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
01/02/2012	01/02/2013	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
19/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0031, W0014, W0016, W0018, W0026, W0029, W0022	<b>StreetName</b> 2nd Crs, K M Colony, NA, NA, Khb Colony Rd, 2nd Crs, NA	<b>Significant LandMark</b> Dayananda Slum
<b>SegmentNo</b> 144/S-W0031/S27520	<b>TotalLength</b> 69.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> K P. Ravven	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to Roads Drain	<b>Sanctioned Amount</b> 1800000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2010 - 2011	<b>Type of Work</b> Others	<b>Other Work Type</b> Road And Drain
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to Roads Drain	<b>Job No Work Code</b> 144-12-000012
<b>Work OrderNo</b> EE(CKP)WO/2011-12	<b>Work Order Date</b>	<b>Period of Extention</b> 120 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b> no	<b>Name</b> M santhosh kumar
<b>Date of Inspection</b> 21/03/2014	<b>Remarks</b> incompleted	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0031, W0014, W0035, W0016, W0018, W0026, W0029, W	<b>StreetName</b> 2nd Crs, K M Colony, NA, NA, NA, Khb Colony Rd, 2nd Crs, NA	<b>Significant LandMark</b> 4th Cross
<b>SegmentNo</b> 144/S-W0031/S31460	<b>TotalLength</b> 92.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> D. C. Prashanth	<b>ContractorRegNo</b>	<b>Expenditure</b> 1137370.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing RCC Drain	<b>Sanctioned Amount</b> 1900000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2011 - 2012	<b>Type of Work</b> Others	<b>Other Work Type</b> Drain
<b>Tender</b> Tender	<b>WorkDetails</b> Providing RCC Drain	<b>Job No Work Code</b> 144-12-000014
<b>Work OrderNo</b> EE(CKP)/WO/72/2011-12	<b>Work Order Date</b> 05/09/2012	<b>Period of Extention</b> 120 Days
<b>Defect Liability Period From</b> 05/09/2012	<b>Defect Liability Period To</b> 05/09/2013	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b> no	<b>Name</b> M santhosh kumar
<b>Date of Inspection</b> 22/03/2014	<b>Remarks</b> completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0076, W0097	NA, 2nd Main Rd	SWD SIDDAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0076/S35130	0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S.SATISH		1805960.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONS OF RCC SWD IN WARD NO - 144	2000000	2011-12
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	RCC SWD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CONS OF RCC SWD IN WARD NO - 144	144-11-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/141/11-12	26/07/2011	60 Days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/07/2011	26/07/2012	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	M santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
12/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0078, W0099, W0097, W0110	<b>StreetName</b> NA, 3rd Main Rd, 2nd Main Rd, NA	<b>Significant LandMark</b> SIDDAPURA
<b>SegmentNo</b> 144/S-W0078/S35218	<b>TotalLength</b> 0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> S SATISH	<b>ContractorRegNo</b>	<b>Expenditure</b> 1830152.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> CONS OF RCC SWD IN WARD NO - 144	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2011
<b>Year</b> 2011 - 2012	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> CONS OF RCC SWD IN WARD NO - 144	<b>Job No Work Code</b> 144-11-000048
<b>Work OrderNo</b> EE/CKP/WO/120/11-12	<b>Work Order Date</b> 26/07/2011	<b>Period of Extention</b> 60 Days
<b>Defect Liability Period From</b> 26/07/2011	<b>Defect Liability Period To</b> 26/07/2012	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b> no	<b>Name</b> M santhosh kumar
<b>Date of Inspection</b> 12/03/2014	<b>Remarks</b> completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0116, W0097	7th Crs, 2nd Main Rd	Siddapura
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0116/S32477	0.00	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R SATISH		286585.00
<b>PhoneNo</b>	<b>EmailId</b>	

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Impts of drain in Siddapura in ward no - 144	400000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Impts of drain in Siddapura in ward no - 144	144-11-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CKP/WO/189/11-12	21/07/2011	45 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
21/07/2011	21/07/2012	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0	no	m santhosh kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
11/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 144	<b>WardName</b> Siddapura
<b>StreetID</b> W0114, W0099, W0107, W0097	<b>StreetName</b> NA, 3rd Main Rd, 7th A Crs, 2nd Main Rd	<b>Significant LandMark</b> Siddapura
<b>SegmentNo</b> 144/S-W0114/S35215	<b>TotalLength</b> 0.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B V SRIDHAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 1290000.00
<b>PhoneNo</b>	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Cons of RCC drain in Siddapura from 540 585	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2011
<b>Year</b> 2011 - 2012	<b>Type of Work</b> Others	<b>Other Work Type</b> Culvert
<b>Tender</b> Tender	<b>WorkDetails</b> Cons of RCC drain in Siddapura from 540 585	<b>Job No Work Code</b> 144-11-000017
<b>Work OrderNo</b> EE/CKP/WO/130/10-11	<b>Work Order Date</b> 16/03/2011	<b>Period of Extention</b> 90Days
<b>Defect Liability Period From</b> 16/03/2011	<b>Defect Liability Period To</b> 16/03/2012	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b> no	<b>Name</b> m santhosh kumar
<b>Date of Inspection</b> 11/03/2014	<b>Remarks</b> completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	144	Siddapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100, W0104, W0106, W0125	NA, Veera Anjaneya Temple Rd	nimhans compound
<b>SegmentNo</b>	<b>TotalLength</b>	
144/S-W0100/S053345	122.47	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SAMPANNA SATHISH		1875063.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448040740		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVMENTS TO CC ROAD AND DRAIN INN RIGHT SIDE CROSS ROADS OF SOMESHWARA NAGAR ADJACENT NIMHANS COMPOUND	200000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	CC ROAD AND DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC DRAIN AND DRAIN	144-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/(CKP)/WO/47/2014-2015	23/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
5		paramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
17/12/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start

