



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W1125, W0634, W1127, W1123, W1129	<b>StreetName</b> NA	<b>Significant LandMark</b> HALLASALLI JUNCTION
<b>SegmentNo</b> 149/C-W1125/S011648	<b>TotalLength</b> 99.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b> VENKATACHALAPATHI M	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988776655	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> DEVELOPMENTS OF ROAD	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-13-000024
<b>Work OrderNo</b> EE/MD/WO/51/13-14	<b>Work Order Date</b> 01/07/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0620, W1055	3rd Crs, NA	jcr layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0620/S034358	61.20	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M VENKATACHALAPATHI		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829456789		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
DEVELOPMENT OF ROADS	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-12-000060
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/72/13-14	08/06/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0959, W0850, W0842, W0846	<b>StreetName</b> NA	<b>Significant LandMark</b> PANATHUR VILLAGE
<b>SegmentNo</b> 149/C-W0959/S034722	<b>TotalLength</b> 79.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b> R.MANJUNATH REDDY	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9678564534	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & DRAINS	<b>Sanctioned Amount</b> 8000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROADS & DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-000032
<b>Work OrderNo</b> EE/MD/WO/25/12-13	<b>Work Order Date</b> 18/06/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0518, W0627, W0524, W0625, W0522	NA, Pattanduru Agrahara Rd	janatha colony
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0518/S042728	142.69	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S R VENUGOPAL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988778899		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/173/13-14	21/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0057, W0032, W0024, W0055	NA	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0057/S043116	211.42	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SAMPANGI RAMI REDDY		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788990099		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-12-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/374/11-12	20/03/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028, W0011, W0026	NA	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0028/S043534	198.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7867564534		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAIN	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/40/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0997	NA	BALAGARE VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0997/S043930	75.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776677		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RCC DRAIN	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/157/13-14	25/11/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0254, W0256, W0209	NA, Ambedkar Nagar Slum	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0254/S044507	100.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829574567		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/39/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0921, W1000	NA	PANATHUR DINNE VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0921/S044802	91.37	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.VENKATESHAPPA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829543623		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAIN	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	ROADS & DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/156/13-14	22/11/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0122, W0138, W0120, W0085, W0088, W0124	NA, 2nd Crs	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0122/S045256	139.43	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N ESHWARARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988786756		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF DRAIN	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/37/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0608, W1067	2nd Crs, 1st Crs	VARTHUR
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0608/S045631	43.70	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788996677		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS & DRAINS	2500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-11-000073
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/KRIIDL-1/12-13	07/06/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W1265, W0798	NA	Gowramma House at Gunjur
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W1265/S052340	64.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.B.Shivananda		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972837799		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improv ements to road and drain from Thayappa House to Gowramma House at Gunjur village in ward No:149	973092	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	CC Road and CC Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC Road and CC Drain	149-13-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND/29-86/WO/58/2013-14	04/07/2013	01/08/2016
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/09/2016	29/09/2017	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
07/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0075, W0136, W0001, W0071, W0118, W0134, W0148, W	NA, 1st Crs	Bhuvaneshwari latout in Munnekolala
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0075/S055820	380.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopalakrishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902103553		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drain and Asphalting to Bhuvaneshwari Layout in Munnekolala at ward No;149	2467984	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	Asphalting Road and CC Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting Road and CC Drain	149-16-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04- 63/WO/114/2016-17	06/06/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
06/06/2016	29/06/2017	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
07/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0803, W0968, W0791, W0940, W0783, W0942, W0952	NA, 5th Crs Panathur New Extenslon Kaverappa Lyt	Water Tank Panathur
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0803/S061725	336.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopalakrishna		0.00
<b>PhoneNo</b>	<b>Emailld</b>	
9902103553		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements road and Drain to water tank in Panathur in ward No:149	2893453	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	asphalting and CC drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	asphalting and CC drain	149-16-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04- 70/WO/32/2016-17	07/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
31/05/2016	30/05/2017	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
07/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0327, W0308	Lakshmi Sagar Lyt North Side, 2nd Crs, NA	Madhura Nagar near Tirumala Bakery
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0327/S063200	85.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopalakrishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902103553		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Asphalting to Varthur Prakash layout 2nd and 4th cross roads in Varthur ward No:149	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Road	149-13-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/98/2012-13	15/03/2013	14-06-2013 to 1
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/06/2015	24/06/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
07/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0574	NA	Divya Jyothi School
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0574/S072113	25.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.Amarappa		498601.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945200058		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to road and Drain from Divya Jyothi School To Krishnamurthy house ar Madhuranagara 2nd stage in ward No:149	499792	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	CC Road and RCC Drain,Slab two Sides
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CC Road and RCC Drain,Slab	149-13-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/09-16WO/254/2014-15	25/02/2015	01-03-2016 to 3
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
31/03/2016	30/03/2017	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
07/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0337, W0366, W0356, W0386, W1041	<b>StreetName</b> NA, S Krishnappa Lyt, Doddamuniswammppa Lyt, 2nd Crs, 4th Crs	<b>Significant LandMark</b> Patel Layout
<b>SegmentNo</b> 149/C-W0337/S064317	<b>TotalLength</b> 320.11	
<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902701649	<b>EmailId</b>	
<b>Work Details</b>		
<b>NameOfWork</b> Providindg and Laying Asphalting to Paltel Layout -left side(Two cross Roads ) in varthur ward no:149	<b>Sanctioned Amount</b> 900000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> Asphalting Roads	<b>Job No Work Code</b> 149-13-000042
<b>Work OrderNo</b> BBMP/EE/MD/WO/95/2012-13	<b>Work Order Date</b> 14/03/2013	<b>Period of Extention</b> 14.06.2013 to 0
<b>Defect Liability Period From</b> 26/10/2015	<b>Defect Liability Period To</b> 25/10/2016	<b>Multiple Road Involved</b> Yes
<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Srinivasa Gowda
<b>Date of Inspection</b> 20/12/2016	<b>Remarks</b>	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0992, W0917, W1000, W0913, W1006, W0915, W0994, W	NA	Panathur Dinne
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0992/S070356	310.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902701649		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Panathur Dinne Balance Roads in Varthur ward No:149	900000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/100/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0055, W0018, W0065	NA, Om Shakthi Lyt 5th Crs	Raghavendra Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0055/S072007	550.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to to Raghavendra Layout in Varthur ward No:149	1500000	201
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000052
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO//104/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	24/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0268	NA	Canara Bank opp
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0268/S073458	58.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Canara Bank Opp Road ( Shivaraji Photo studio road in varthur ward No:149	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Road	149-13-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/96/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2016	25/10/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0158, W0195, W0199, W0163, W0193, W0191, W0167, W	NA, Vinayaka Lyt 2nd Crs	Vasantha Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0158/S074940	299.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Vasanth Layout 3rd and 4th Cross in Varthur ward No:149	1200000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000056
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/108/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0030, W0038, W0043, W0041, W0058, W0031, W0037, W	NA, Om Shakthi Lyt, 9th Crs	Rajashree Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0030/S075950	738.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Rajashree Layout 1st to 9th Cross in Varthur ward No:149	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000053
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/105/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0729, W0494, W0743, W0584, W0580, W0518, W0735, W	NA, 2nd Main Rd, Whitefield Rd, 4th Main Rd, 3rd Main Rd	Madhuranagar 2nd stage life side
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0729/S081316	1347.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Madhuranagar 2nd stage (left side) roads in Varthur ward No:149	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/99/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W1281	NA	Gunjur Kote Beedi ,Dasara Beedi
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W1281/S082758	240.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Gunjur Kote Beedi ,Dasara Beedi in warthur ward No;149	800000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/97/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0653	NA	Sorahunase road
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0653/S092109	99.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Sorahunase road towards Burial ground in Varthur ward No:149	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Road	149-13-000058
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/110/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0441, W0262, W0264	NA, Ambedkar Nagar Slum	Nanjudappa Layouty
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0441/S093720	148.23	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Varthur Nanjudappa Layout cross roads in varthur ward NO;149	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000057
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/109/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0180, W0075, W0087, W0095, W0069, W0188	NA, Om Shakthi Lyt 2nd Crs	Maramma Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0180/S094733	200.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Munnekolala Maramma Temple to railway track in vathur ward No:149	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/94/2012-13	14/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0122, W0083, W0088, W0078, W0079, W0085, W0073, W	NA, Om Shakthi Lyt 4th Crs	Sathyam street Main Road
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0122/S095722	282.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and Laying Asphalting to Sathyam Street Main Roads in Varthur ward No:149	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Asphalting Roads	149-13-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/102/2012-13	14/03/2013	14.06-2013 to 0
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/10/2015	25/10/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasa Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
20/12/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0729, W0494, W0743, W0731, W0739, W0741	NA, 2nd Main Rd, 3rd Main Rd	Ashraya Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0729/S063819	382.47	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.Ranganath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901989027		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of roads and Drain to Ashraya Layout cross roads at Madhuranagara ward no:149	1492570	20161
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting of Roads	149-16-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04- 71/WO/17/2016-17	06/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
02/07/2016	03/07/2017	Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	 
Segment End	 



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0109, W0256, W0227, W0233, W0204, W0190, W0192	NA, Ambedkar Nagar Slum	Papaiah Reddy Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0109/S065608	302.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.Ranganath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901989027		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain in papaiah reddy Layout ar ward no 149	1988617	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting of Roads	149-16-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E- PMT//04/72/WO/12/2016-17	06/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
02/07/2016	01/07/2017	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0088, W0105, W0143, W0119, W0117, W0133, W0127, W	NA, Vinayaka Lyt 4th Crs, Subhash Chandra Bose Lyt, 3rd Crs	Venkateswara layout 1st main
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0088/S070719	516.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.Ranganath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901989027		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvmnts of road and drain at venkateswara layout 1st main and cross roads in Munnekolala at ward No:149	2489846	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting of Roads	149-16-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04- 77/WO/176/2015-16	28/03/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/06/2016	25/06/2017	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/12/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0881	NA	Panathur Buss stop
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0881/S071624	384.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.Ranganath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901989027		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement of road and drain from Panathur Bus stop to Burial ground and panathur colony at ward no:149	1991291	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting of Roads	149-16-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04-67/WO/13/2016-17	06/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
04/07/2016	03/07/2017	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0088, W0100, W0107, W0085, W0105	NA, Subhash Chandra Bose Lyt	Venkateshwar Lyt
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0088/S072638	190.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.Ranganath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901989027		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvment of road and Drains at Gunjurpalya main road of all cross roads in ward no:149	1988075	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting of Roads	149-16-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/04- 67/WO/10/2016-17	06/04/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
05/07/2016	04/07/2017	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0084, W0134, W0136, W0116	NA, 1st Crs	MUNESWARA LYT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0084/S113142	130.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
CHANDRAPPA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9642190806		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement roads and drian at muvaneswari layout munekolala	5000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	ROAD AND DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-11-000068
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND/29/WO/31-2011-12	16/04/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		SRINIVASA GOWDA
<b>Date of Inspection</b>	<b>Remarks</b>	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0015, W0040, W0013, W0002, W0019	<b>StreetName</b> NA	<b>Significant LandMark</b> LAKSHMI LYT
<b>SegmentNo</b> 149/C-W0015/S113952	<b>TotalLength</b> 441.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b> ESHWARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9642190806	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvement to roads and drian at laksmi layout	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROAD AND DRAIN
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-000034
<b>Work OrderNo</b> EE/MD/E-TND/55-01/WO64/2012 -13	<b>Work Order Date</b> 18/05/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> SRINIVASA GOWDA
<b>Date of Inspection</b> 29/02/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0199, W0158, W0179, W0197	<b>StreetName</b> NA, Vinayaka Lyt 1st Crs	<b>Significant LandMark</b> SHIRIDI SAI LYT
<b>SegmentNo</b> 149/C-W0199/S114809	<b>TotalLength</b> 390.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N ESHWARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9642190806	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> improvement to roads and drian at sai layout	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROAD AND DRAIN
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-000036
<b>Work OrderNo</b> EE/MD/E-TND-55-93/WO/66/2012-13	<b>Work Order Date</b> 18/06/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> SRINIVASA GOWDA
<b>Date of Inspection</b> 29/02/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0137, W0142, W0139, W0156, W0147	<b>StreetName</b> NA	<b>Significant LandMark</b> ISRO LYT
<b>SegmentNo</b> 149/S-W0137/S115421	<b>TotalLength</b> 132.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N ESHWARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9642190806	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> improvement to roads and drian at ISRO Layout	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROAD AND DRAIN
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-000033
<b>Work OrderNo</b> EE/MD/E-TND-57/WO/69/-2012- 13	<b>Work Order Date</b> 18/06/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> SRINIVASA GOWDA
<b>Date of Inspection</b> 29/02/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0083, W0068, W0078, W0072	<b>StreetName</b> NA	<b>Significant LandMark</b> BHUVANESWARA LYT
<b>SegmentNo</b> 149/C-W0083/S115927	<b>TotalLength</b> 246.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N ESHWARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9642190806	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvement to roads and drian at BHUVANSWARA LYT	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROAD AND DRAIN
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-000037
<b>Work OrderNo</b> EE/MD/E-TND-57/WO/47/-2012- 13	<b>Work Order Date</b> 18/06/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> SRINIVASA GOWDA
<b>Date of Inspection</b> 29/02/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0096	NA	BHUVANESWARA LYT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0096/S120515	118.07	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N ESHWARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9642190806		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement to roads and drian at Bhuvaneshawari layout	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	ROAD AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-12-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND-55-42/WO/65/-2012-13	18/06/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		SRINIVASA GOWDA
<b>Date of Inspection</b>	<b>Remarks</b>	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0879, W0875	NA	TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0879/S121342	110.68	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
NARAYANA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9642190806		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
improvement to roads and drian at temple road in ward no 149	950000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	road and drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-11-000099
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND-55-42/WO/93/-2012-13	02/06/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		SRINIVASA GOWDA
<b>Date of Inspection</b>	<b>Remarks</b>	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0670, W0654, W0674	NA	VINAYAKA LYT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0670/S124444	209.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K VENUGOPAL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9642190806		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement roads and drian at renuka temple road and vinayaka lyt in varthuru	2000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	ROAD AND DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-11-000070
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND-22/WO/258-2011-12	05/12/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		SRINIVASA GOWDA
<b>Date of Inspection</b>	<b>Remarks</b>	
29/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0121, W0120, W0135, W0129, W0142, W0147, W0128, W	NA	SLN Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0121/S113713	174.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SUNIL J		1986130.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980601235		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drains of SLN temple opposite cross roads at Munnekolala	2000000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	Road & Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-16-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/06- 09/WO/61/2016-17	17/05/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		S. Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
22/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0047, W0065	NA, Om Shakthi Lyt 5th Crs	KRISHNA APARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0047/S114239	349.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SUNIL J		987741.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980601235		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain to Sri Krishna Apartment road beside Muneshwara Temple at Munnekolala	1000000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	Road & Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-16-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/06-11/WO/63/2016-17	17/05/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		S. Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
22/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0055, W0018, W0059, W0024	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Victoria Meadows Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0055/S114857	184.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SUNIL J		1800683.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980601235		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain to Victorian Meadows Layout 1st and 2nd Main at Munnekolala	1900000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	Road & Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-16-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/06-10/WO/62/2016-17	17/05/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		S. Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
22/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0925, W1004	<b>StreetName</b> NA	<b>Significant LandMark</b> Panathur Dinne
<b>SegmentNo</b> 149/C-W0925/S050814	<b>TotalLength</b> 155.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b> K.Venugopal	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9900003271	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvmnts to roads and drains at Panathur Dinne in ward No:149	<b>Sanctioned Amount</b> 889753	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Others	<b>Other Work Type</b> RCC Drain
<b>Tender</b> Tender	<b>WorkDetails</b> RCC Drain	<b>Job No Work Code</b> 149-16-000038
<b>Work OrderNo</b> EE/MD/E-PMT/09-09/WO/187/2016-17	<b>Work Order Date</b> 26/12/2016	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 09/02/2017	<b>Defect Liability Period To</b> 08/02/2018	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> y r ramesh
<b>Date of Inspection</b> 22/02/2017	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0831	Panathur Colony Rd	Panathur AK Colony
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0831/S052013	62.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.venugopal		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9900003271		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains at Panathur AK Colony in ward No:149	327130	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	RCC Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	RCC Drain	149-16-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/09-11/WO/18/2016-17	26/12/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
09/02/2017	08/02/2018	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		y r ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
22/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0492, W0518, W0697, W0699, W0715	<b>StreetName</b> NA	<b>Significant LandMark</b> Janatha Colony
<b>SegmentNo</b> 149/C-W0492/S053151	<b>TotalLength</b> 228.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b> K.Venugopal	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9900003271	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to roads and drains at Madhuranagara Janatha Colony in ward No:149	<b>Sanctioned Amount</b> 554995	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Others	<b>Other Work Type</b> SSM Drains
<b>Tender</b> Tender	<b>WorkDetails</b> SSM Drains	<b>Job No Work Code</b> 149-16-000039
<b>Work OrderNo</b> EE/MD/E-PMT/09- 10/WO/188/2016-17	<b>Work Order Date</b> 26/12/2016	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 09/02/2017	<b>Defect Liability Period To</b> 08/02/2018	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> y r ramesh
<b>Date of Inspection</b> 22/02/2017	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0053, W0051, W0058	NA, Om Shakthi Lyt 8th Crs	munekolala
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0053/S042029	150.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.ESWARARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776688		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS AND DRAINS	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/38/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0143, W0119, W0088, W0117, W0133, W0127, W0107, W	<b>StreetName</b> NA, Vinayaka Lyt 4th Crs, Subhash Chandra Bose Lyt, 3rd Crs	<b>Significant LandMark</b> GOVT.HOSPITAL
<b>SegmentNo</b> 149/C-W0143/S042601	<b>TotalLength</b> 212.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N RAMESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 7829582141	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO ROADS AND DRAINS	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Others	<b>Other Work Type</b> ROADS AND DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-12-00024
<b>Work OrderNo</b> EE/MD/WO/86/12-13	<b>Work Order Date</b> 23/06/2012	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0122, W0114, W0001, W0120, W0085, W0124	NA	MUNNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0122/S043327	101.13	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N CHANDRASEKHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAIN	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/84/13-14	16/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0068	NA	BALAGARE LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0068/S043734	103.42	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS AND DRAIN	2500000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-11-000071
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/KRIDL-2/12-13	07/06/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0327	Lakshmi Sagar Lyt North Side, 2nd Crs	mastan house road
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0327/S044500	83.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N RAMESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788990099		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS & DRAINS	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-12-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/87/12-13	23/06/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0109, W0228, W0244	NA	munnekolala
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0109/S051820	51.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R.JAYANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/31/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0055, W0018, W0024	NA	MUNNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0055/S052156	235.73	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N ESHWARARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776677		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF CC ROADS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
N ESHWARARAJU	19/05/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W1024, W1026, W1187, W1183, W1189	<b>StreetName</b> NA	<b>Significant LandMark</b> MUNNEKOLALA
<b>SegmentNo</b> 149/C-W1024/S052606	<b>TotalLength</b> 200.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b> G ANIL KUMAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988667788	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO ROADS AND DRAINS	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> ROADS & DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 0149-14-000011
<b>Work OrderNo</b> EE/MD/WO/75/14-15	<b>Work Order Date</b> 26/08/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0072	NA	MUNNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0072/S052951	154.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R.JAYANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988667755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/30/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0376, W0383	7th Crs Lakshmi Sagar Lyt, 1st Crs	LAKSHMI GYM
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0376/S053345	72.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8899008899		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO LAKSHMI GYM ROAD	10000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	149-13-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/145/14-15	19/11/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
03/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0327, W0308	Lakshmi Sagar Lyt North Side, 2nd Crs, NA	RAMAGONDANAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0327/S053808	53.22	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G.ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/144/14-15	19/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0417, W0280, W0302, W0272, W0292, W0401, W0296, W	NA, 2nd Crs, Lakshmi Sagar Lyt, Vidya Nursary School & Raj Colony Rd, 1st Crs, Maheshwari Nagar, 3r	NAGARAJA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0417/S054147	247.09	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/148/14-15	19/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0687	NA	HARISH HOUSE
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0687/S054502	92.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.VENUGOPAL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9978675645		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF DRAIN	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/76/2013-14	11/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0572, W0713, W0723, W0719, W0574	NA	MADHURA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0572/S054804	66.46	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T.ANJANAPPA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776756		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAIN	500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/41/14-15	26/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0814, W1253	NA	NARAYANA HOUSE
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0814/S055127	37.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-13-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/146/14-15	19/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0120, W0154, W0111	NA	VASANTH LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0120/S055410	98.52	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
G ANIL KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7766998877		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-14-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
G ANIL KUMAR	19/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0627, W0647, W0524, W0528	NA, 1st Main Rd, Pattandur Agrah	MADHURANAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0627/S055712	178.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788996677		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS & DRAINS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/10/14-15	31/10/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0308, W0393	NA	IMPROVEMENTS OF ROADS & DRAINS
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0308/S060120	55.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776655		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS & DRAINS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/09/14-15	31/10/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0039, W0058, W0037	<b>StreetName</b> NA	<b>Significant LandMark</b> MANJUNATH LAYOUT
<b>SegmentNo</b> 149/C-W0039/S060450	<b>TotalLength</b> 387.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N ESHWARARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988778877	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF RCC DRAIN IN MANJUNATH DRAIN	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-14-000013
<b>Work OrderNo</b> EE/MD/WO/28/14-15	<b>Work Order Date</b> 24/05/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0449, W0467, W0499, W0459, W0457, W0362, W0358, W	3rd Crs, 4th Crs, NA, Shetty Lyt, 2nd Main Rd, R H B Colcny, 7th Crs, Shetty Lyt, 1st Main Rd	INDANE GAS FACTORY
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0449/S060758	162.16	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N ESHWARARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788997788		



Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF SSM DRAIN	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		149-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/207/14-15	24/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0278, W0284, W0268	Lakshmi Sagar Lyt, 1st Crs, NA	IMPROVEMENTS OF ROADS & DRAINS
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0278/S061502	175.51	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788997788		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS & DRAINS	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/43/14-15	31/10/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
27/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0905, W0992	NA	Panathur Dinne
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0905/S043820	53.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S.Aravinda Prasad		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449659478		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of roads and drains at BCM area in Panathur Dinne at ward No:149	336572	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Others	SSM Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	SSM Drain	149-16-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/09-22/WO/190/2016-17	26/12/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2017	27/02/2018	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Y R Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0608, W0558, W0583, W0587	<b>StreetName</b> 2nd Crs, NA, 3rd Crs	<b>Significant LandMark</b> Prakash lyt
<b>SegmentNo</b> 149/C-W0608/S080838	<b>TotalLength</b> 284.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Anil kumar G	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901652865	<b>EmailId</b>	



<b>Work Details</b>		
<b>NameOfWork</b> Improvements to roads & Drain to 2nd & 3rd cross roads of Prakash layout in varthur at ward no-149 Varthur	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2014-15
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> Road and drain
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to roads & Drain to 2nd & 3rd cross roads of Prakash layout in varthur at ward no-149 Varthur	<b>Job No Work Code</b> 149-15-000008
<b>Work OrderNo</b> EE/MD/E-PMT/09- 77/WO/248/2014-15	<b>Work Order Date</b> 24/02/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/06/2016	

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0593, W0568, W0599, W0590, W0604, W0612, W0610	<b>StreetName</b> 6th Crs, NA, 1st Main Rd, 1st Crs, 3rd Crs	<b>Significant LandMark</b> Prakash lyt
<b>SegmentNo</b> 149/C-W0593/S081829	<b>TotalLength</b> 182.80	



<b>ContractorDetails</b>		
<b>NameofContractor</b> Anil kumar G	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901652865	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to roads & Drain to Balance cross roads of Prakash layout in varthur at ward no-149 Varthur	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2014-15
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to roads & Drain to Balance cross roads of Prakash layout in varthur at ward no-149 Varthur	<b>Job No Work Code</b> 149-15-000009
<b>Work OrderNo</b> EE/MD/E-PMT/09- 78/WO/249/2014-15	<b>Work Order Date</b> 24/02/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/06/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0570, W0608, W0593, W0568, W0558, W0604, W0590, W	<b>StreetName</b> 16th Crs, 2nd Crs, NA, 1st Crs, 1st Main Rd, 3rd Crs, 5th Crs	<b>Significant LandMark</b> Madhuranagar main road
<b>SegmentNo</b> 149/C-W0570/S082600	<b>TotalLength</b> 571.40	



<b>ContractorDetails</b>		
<b>NameofContractor</b> Anil kumar G	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901652865	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of Roads From Prakash layout to Madhuranagar main road at ward no-149 Varthur	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2014-15
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Construction of Roads From Prakash layout to Madhuranagar main road at ward no-149 Varthur	<b>Job No Work Code</b> 149-15-000010
<b>Work OrderNo</b> EE/MD/E-PMT/09- 79/WO/250/2014-15	<b>Work Order Date</b> 24/02/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/06/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W1235, W1251, W0828	NA	gunjur
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W1235/S083916	83.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Anil kumar G		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9901652865		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads & Drains beside Basavanna temple in Gunjur at ward no-149 Varthur	1000000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Roads and Drains
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements to roads & Drains beside Basavanna temple in Gunjur at ward no-149 Varthur	149-15-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/09-86/WO/253/2014-15	26/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		SrinivasGowda
<b>Date of Inspection</b>	<b>Remarks</b>	
24/06/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W1235, W0786, W1227	<b>StreetName</b> NA	<b>Significant LandMark</b> muddanna house road
<b>SegmentNo</b> 149/C-W1235/S084554	<b>TotalLength</b> 70.63	



<b>ContractorDetails</b>		
<b>NameofContractor</b> Anil kumar G	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901652865	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to road & Drain from muddanna house to Maramma temple in Gunjur at ward no-149 Varthur	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2014-15
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> Road and Drain
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to road & Drain from muddanna house to Maramma temple in Gunjur at ward no-149 Varthur	<b>Job No Work Code</b> 149-15-000017
<b>Work OrderNo</b> EE/MD/E-PMT/09-85/WO/252/2014-15	<b>Work Order Date</b> 24/02/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/06/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0339, W0308, W0343, W0345, W0347, W0330, W0336, W	<b>StreetName</b> NA, S Krishnappa Lyt, R H B Colony 2nd Main Rd, R H B Colony, 6th Crs, Mariyappa Lyt	<b>Significant LandMark</b> canara bank
<b>SegmentNo</b> 149/C-W0339/S090232	<b>TotalLength</b> 298.79	



<b>ContractorDetails</b>		
<b>NameofContractor</b> Anil kumar G	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901652865	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to road & Drain beside Canara Bank in varthurat at ward no-149 Varthur	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014-15
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> Roads and Drains
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to road & Drain beside Canara Bank in varthurat at ward no-149 Varthur	<b>Job No Work Code</b> 149-15-000012
<b>Work OrderNo</b> EE/MD/E-PMT/09- 81/WO/251/2014-15	<b>Work Order Date</b> 24/02/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/06/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0079, W0085, W0073, W0083, W0088, W0077, W0001, W	Om Shakthi Lyt 4th Crs, NA	Satyam street
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0079/S091634	266.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishan		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988775611		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement to roads and drian to satyam street area in Munnekolala	1500000	2015-16
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement to roads and drian to satyam street area in Munnekolala	149-15-000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/11-107/WO/09/2015-16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasgowda
<b>Date of Inspection</b>	<b>Remarks</b>	
28/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0094, W0183, W0092	NA	Munnekolala area
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0094/S092456	75.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988661155		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvment to roads and drains to MUUnnekolala balace area	1500000	2015-16
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvment to roads and drains to MUUnnekolala balace area	149-15-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/11-111/WO/11/2015-16		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasgowda
<b>Date of Inspection</b>	<b>Remarks</b>	
28/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0199, W0195, W0191, W0179, W0167, W0158, W0173, W	<b>StreetName</b> NA, Vinayaka Lyt 2nd Crs	<b>Significant LandMark</b> Shiradi Sai Laout
<b>SegmentNo</b> 149/S-W0199/S094038	<b>TotalLength</b> 597.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Gopal Krishna	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988776611	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvement to road and drains to shiradi sai Layout	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015-16
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvement to road and drains to shiradi sai Layout	<b>Job No Work Code</b> 149-15-000041
<b>Work OrderNo</b> EE/MDE-PMT/11- 115/WO/13/2015-16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Srinivasgowda
<b>Date of Inspection</b> 28/06/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0080, W0074, W0061, W0090	NA, Om Shakthi Lyt 7th Crs	Spring Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0080/S095438	142.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishana		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776623		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement to roads silver spring layout in Munnekolala	1000000	2015-16
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement to roads silver spring layout in Munnekolala	149-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/11-12/WO/12/2015-16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasgowda
<b>Date of Inspection</b>	<b>Remarks</b>	
28/06/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0238, W0265, W0248, W0259, W0269	<b>StreetName</b> NA, Ambedkar Nagar Slum	<b>Significant LandMark</b> Vagdevi villa s Layout
<b>SegmentNo</b> 149/C-W0238/S100143	<b>TotalLength</b> 247.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Gopal Krishna	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988776655	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvement to road and drains to vagdevi Lay	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2015-16
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvement to road and drains to vagdevi Layout in Munnekolala	<b>Job No Work Code</b> 149-15-000035
<b>Work OrderNo</b> EE/MD/E-PMT/11- 109/WO/10/2015-16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Srinivasgowda
<b>Date of Inspection</b> 28/06/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0216, W0219, W0228, W0244	NA, Chowdeshwari Temple Rd	Yellamma Temeple
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0216/S101303	146.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Gopal Krishna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988667744		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement to roads and drains to Yellamma temeplearea in Mennekolla	1500000	2015-16
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement to roads and drains to Yellamma temeplearea in Mennekolla	149-15-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT11-116/WO/14/2015-16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Sinivasgowda
<b>Date of Inspection</b>	<b>Remarks</b>	
28/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0235, W0109, W0247, W0245, W0239, W0218, W0243, W	<b>StreetName</b> NA, 4th Crs, Chowdeshwari Temple Behind Rd, Veera Anjaneya Temple Rd	<b>Significant LandMark</b> SLN Temple
<b>SegmentNo</b> 149/C-W0235/S102111	<b>TotalLength</b> 453.39	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Gopal Krishna	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9977886677	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvement to road and drain opp to SLN Temple in MUnnekolala	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2015-16
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvement to road and drain opp to SLN Temple in MUnnekolala	<b>Job No Work Code</b> 149-15-000033
<b>Work OrderNo</b> EE/MD/E-PMT/11- 107/WO/08/2015-16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Srinivasgowda
<b>Date of Inspection</b> 28/06/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0168, W0164, W0075, W0176, W0150, W0136	<b>StreetName</b> NA	<b>Significant LandMark</b> Munnekolala Bus stop
<b>SegmentNo</b> 149/C-W0168/S103057	<b>TotalLength</b> 149.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRDIL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9988556655	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing and laying Asphalting to Munnekolala bus top Main road	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2012-13
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Providing and laying Asphalting to Munnekolala bus top Main road	<b>Job No Work Code</b> 149-13-000055
<b>Work OrderNo</b> EE/MD/wo/ 107/2012-13	<b>Work Order Date</b> 14/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Srinivasgowda
<b>Date of Inspection</b> 28/06/2016	<b>Remarks</b>	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0335, W0321, W0339, W0323, W0315, W0327, W0329, W	NA, 10th Crs Lakshmi Sagar Lyt, Lakshmi Sagar Lyt North Side, 2nd Crs, Lakshmi Sagar Lyt North Sid	Varthur road edgar
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0335/S110825	813.82	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776655		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Poviding and laying asphaltting to varthur edgar road	2000000	2012-13
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Poviding and laying asphaltting to varthur edgar road	149-13-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/MD/WO/91/2012-13	14/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivasgowda
<b>Date of Inspection</b>	<b>Remarks</b>	
28/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0075, W0136, W0071, W0148, W0134	<b>StreetName</b> NA, 1st Crs	<b>Significant LandMark</b> munekolala
<b>SegmentNo</b> 149/C-W0075/S102853	<b>TotalLength</b> 146.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b> K.R.I.D.L	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 7788990088	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMTS TO ROADS & DRAINS	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Others	<b>Other Work Type</b> ROAD & DRAIN
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 149-14-000040
<b>Work OrderNo</b> EE/MD/WO/39/13-14	<b>Work Order Date</b> 04/03/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Ramesh
<b>Date of Inspection</b> 24/10/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0043, W0049, W0058, W0051, W0052	NA, Om Shakthi Lyt 8th Crs	MUNNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0043/S103305	183.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988007767		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MDS/WO/31/13-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0122, W0120, W0085, W0088, W0124	NA	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0122/S103559	137.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988776787		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS & DRAINS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/37/13-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0068	NA	munekolala
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0068/S104510	80.30	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988678990		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS & DRAINS	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	ROADS & DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/36/13-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0137, W0142, W0141, W0139, W0147	NA	ISRO LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0137/S104754	78.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-13-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/101/13-12	14/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0088, W0105, W0113, W0107	NA, 3rd Crs, Subhash Chandra Bose Lyt	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0088/S105218	135.27	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829582131		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/32/13-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0005, W0003, W0004, W0013, W0002, W0008	NA	MUNEKOLALA
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0005/S105558	330.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988778899		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO ROADS	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		149-14-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/WO/38/13-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ramesh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W0617, W0412, W0406, W0408, W0641, W0410, W0637, W	<b>StreetName</b> 2nd Crs, 4th Crs Kanaka Lyt, NA, 6th Crs Gramatana, Vydhi Hospital Main Rd, Rama Anjaneya Lyt, 1st	<b>Significant LandMark</b> Sapatagiri Layout
<b>SegmentNo</b> 149/C-W0617/S093154	<b>TotalLength</b> 188.31	



<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9611508999	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing and Laying Asphalting to Saptagiri Layout Cross Road ain Varthur ward No-149	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> Providing and Laying Asphalting to Saptagiri Layout Cross Road ain Varthur ward No-149	<b>Job No Work Code</b> 149-13-000051
<b>Work OrderNo</b> BBMP/EE/MD/WO/03/2012-13	<b>Work Order Date</b> 14/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b> 30/01/2015	<b>Defect Liability Period To</b> 29/01/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/11/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0318, W0389, W0334, W0407	1st Crs, V S T Opposite, 4th Crs, R H B Colcny, 5th Crs, Mani Lyt 2nd Main Rd	Thigalara street (Edga Road)
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0318/S013249	86.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P.Damodhararaju		2042387.00
<b>PhoneNo</b>	<b>Emailld</b>	
9448461353		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvmnts to Road and drain in Thigalara street (edga road) in ward No:159	2070911	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	Asphalting & CC Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Asphalting & CC Drain	149-11-000072
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND/22/WO/259/2011-12	05/12/2011	30/09/2012 TO 3
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
07/07/2015	06/07/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
01/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0065, W0161, W0120, W0102, W0159, W0178, W0261, W	Om Shakthi Lyt 5th Crs, NA	Rajashree Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
149/S-W0065/S014552	440.23	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P.Damodhararaju		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9964422141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvemnts to Road and drain in Rajashree layout Munnekolala in ward no:149	2052402	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Others	CC Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvemnts to Road and drain in Rajashree layout Munnekolala in ward no:149	149-11-000074
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-TND/22/W0/265/2011- 12	05/12/2011	05/03/2012 TO 3
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
03/06/2015	02/06/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas Gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
01/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
MAHADEVAPURA	149	Varthuru
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0120, W0165, W0112	NA	Near police station
<b>SegmentNo</b>	<b>TotalLength</b>	
149/C-W0120/S023011	131.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.Nagarajan		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9964422141		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of SSM Drain OPP Police station in varthur ward No:149	998939	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	SSM Drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	SSM Drain	149-15-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/MD/E-PMT/08- 80/WO/223/2014-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
16/07/2015	15/07/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Srinivas gowda
<b>Date of Inspection</b>	<b>Remarks</b>	
01/12/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> MAHADEVAPURA	<b>WardNo</b> 149	<b>WardName</b> Varthuru
<b>StreetID</b> W1002, W0837, W0863, W0996, W0839	<b>StreetName</b> NA, Jcr Lyt	<b>Significant LandMark</b> JCR layout
<b>SegmentNo</b> 149/C-W1002/S122457	<b>TotalLength</b> 223.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b> G.R.Subramani	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902845063	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of Roads and drains at Panathur JCR Layout in ward No:149	<b>Sanctioned Amount</b> 943242	<b>Sanctioned Year</b> 2011
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Asphalting	<b>Job No Work Code</b> 149-11-000059
<b>Work OrderNo</b> EE/MD/E-TND/16/WO/62/2011- 12	<b>Work Order Date</b> 28/07/2011	<b>Period of Extention</b> 28/10/2011 To 3
<b>Defect Liability Period From</b> 24/11/2014	<b>Defect Liability Period To</b> 23/11/2015	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Y R Ramesh
<b>Date of Inspection</b> 09/03/2017	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start

