



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0198	NA	PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0198/S103247	136.21	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9445279917		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 3RD CROSS ROAD,4TH BLOCK AND SURROUNDING ROADS IN WARD 151 (KORAMANGALA)	4872000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTM/E/WO/219/2013/14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0267	10th Main	POST OFFICE PLAY GROUND
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0267/S013610	240.34	


ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 5th cross, ,3rd block, 16th B main, 4th B block, and surrounding roads in ward no. 151 (Koramangala)	4846000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/217/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0308	NA	OPP TO KENDRIYA SADAN
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0308/S103726	361.84	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 2ND BLOCK AND SURROUNDING AREAS IN WARD NO.151( KORAMANGALA)	4990000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/198/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0361	NA	OPP MASZID
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0361/S104531	179.39	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 2ND BLOCK AND SURROUNDING AREAS IN WARD NO.151( KORAMANGALA)	4990000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/198/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0177	16th A Main Rd	NEAR CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0177/S113612	112.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0175	15th Main Rd	NEAR CHINAMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0175/S114557	120.63	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 106.00 MTS	151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0173	16th C Main Rd	NEAR CHINAMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0173/S114758	268.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0212	NA	BEHIND OOTY CHACOLTE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0212/S115038	135.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0194	NA	NEAR CHINMAYASCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0194/S115618	129.79	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0192	NA	NEAR CHINMAYASCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0192/S115803	128.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040	dm3bbmpwest@kridl.net	


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 16TH A TO C ROADS 4TH BLOCK AND SURROUNDING CROSS ROADS IN WARD NO.151( KORAMANGALA)	2432000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/201/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0190	16th A Main 4th Block Rd	NEAR CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0190/S120217	193.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4203000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/200/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
06/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0182	5th Crs	NEAR CHINAMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0182/S120423	188.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4203000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/200/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
06/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0153	17th B Crs	OPP TO KRISHNA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0153/S120725	222.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4203000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/200/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0141	NA	OPP KRISHNA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0141/S121932	291.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4203000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/200/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0171	<b>StreetName</b> NA	<b>Significant LandMark</b> BEDIND SUKSAGAR
<b>SegmentNo</b> 151/S-W0171/S122352	<b>TotalLength</b> 302.14	


<b>ContractorDetails</b>		
<b>NameofContractor</b> TECHNICAL MANAGER KRID LTD	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 4203000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING 170.00MTS	<b>Job No Work Code</b> 151-13-000024
<b>Work OrderNo</b> EE (BTM)/ /W.O/200/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0169	NA	BEHIND SUKSAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0169/S122754	51.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 4TH & 5TH ROADS 4TH BLOCK AND 17TH B MAIN ROAD INDUSTRIAL AREA AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4203000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/200/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0160	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0160/S015257	126.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND 3RD,7TH CROSS ROADS 6TH BLOCK AND K.R.GARDEN 8TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	2950000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 180.00 MTS	151-13-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/199/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0072	NA	NEAR JUSTIVE SHIVAPPA HOUSE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0072/S015809	56.79	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND 3RD,7TH CROSS ROADS 6TH BLOCK AND K.R.GARDEN 8TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	2950000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/199/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0050	<b>StreetName</b> NA	<b>Significant LandMark</b> OPP KORAMANGALA POLICE STATION
<b>SegmentNo</b> 151/S-W0050/S042447	<b>TotalLength</b> 193.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b> TECHNICAL MANAGER KRID LTD	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 2ND 3RD,7TH CROSS ROADS 6TH BLOCK AND K.R.GARDEN 8TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 2950000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000023
<b>Work OrderNo</b> EE (BTM)/ /W.O/199/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0067	NA	JUSTICE SHIVAPPA HOUSE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0067/S042816	210.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND 3RD,7TH CROSS ROADS 6TH BLOCK AND K.R.GARDEN 8TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	2950000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/199/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0074	NA	OPP KALAYANNA MANTAPA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0074/S043203	77.62	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND 3RD,7TH CROSS ROADS 6TH BLOCK AND K.R.GARDEN 8TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	2950000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/199/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0280	2nd Crs	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0280/S044955	144.27	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0276	3rd Crs	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0276/S045243	318.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0286	1st Crs	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0286/S045442	282.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0343	1st A Main	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0343/S045714	258.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0347	1st B Main	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0347/S045833	253.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0286	1st Crs	JAKKASANDRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0286/S050039	282.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	BURIAL GROUND ROAD 80.00 MTS	151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0265	NA	3RD BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0265/S050316	179.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/191/2012-13	07/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0272	<b>StreetName</b> 5th Crs	<b>Significant LandMark</b> JAKKASANDRA HOUSE NO.350
<b>SegmentNo</b> 151/S-W0272/S050752	<b>TotalLength</b> 75.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b> TECHNICAL MANAGER KRID LTD	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO CROSS ROADS AT JAKKASANDRA EXTENSION 11TH 14TH MAIN 3RD BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 4995000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING 92.00 MTS	<b>Job No Work Code</b> 151-13-000020
<b>Work OrderNo</b> EE (BTM)/ W.O/191/2012-13	<b>Work Order Date</b> 07/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0144	<b>StreetName</b> 4th Crs	<b>Significant LandMark</b> INDIAN BANK
<b>SegmentNo</b> 151/S-W0144/S070120	<b>TotalLength</b> 257.86	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0148	<b>StreetName</b> 3rd Crs	<b>Significant LandMark</b> ACCURA
<b>SegmentNo</b> 151/S-W0148/S070316	<b>TotalLength</b> 305.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0138	<b>StreetName</b> 5th Crs	<b>Significant LandMark</b> CANARA BANK
<b>SegmentNo</b> 151/S-W0138/S071946	<b>TotalLength</b> 681.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0103	<b>StreetName</b> NA	<b>Significant LandMark</b> CLUB
<b>SegmentNo</b> 151/S-W0103/S072540	<b>TotalLength</b> 257.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0107	<b>StreetName</b> NA	<b>Significant LandMark</b> CLUB
<b>SegmentNo</b> 151/S-W0107/S072640	<b>TotalLength</b> 247.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0111	<b>StreetName</b> NA	<b>Significant LandMark</b> CLUB
<b>SegmentNo</b> 151/S-W0111/S072736	<b>TotalLength</b> 238.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0106	<b>StreetName</b> NA	<b>Significant LandMark</b> PARK
<b>SegmentNo</b> 151/S-W0106/S072903	<b>TotalLength</b> 117.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0102	<b>StreetName</b> NA	<b>Significant LandMark</b> PARK
<b>SegmentNo</b> 151/S-W0102/S073051	<b>TotalLength</b> 128.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0100	<b>StreetName</b> NA	<b>Significant LandMark</b> PARK 6TH BLOCK
<b>SegmentNo</b> 151/S-W0100/S073325	<b>TotalLength</b> 75.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Resurfacing	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0092	<b>StreetName</b> 6th Crs	<b>Significant LandMark</b> CLUB ROAD
<b>SegmentNo</b> 151/S-W0092/S073510	<b>TotalLength</b> 528.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0085	18th Main	BUS DEPOT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0085/S075718	651.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0058	<b>StreetName</b> 5th Crs	<b>Significant LandMark</b> TEMPLE
<b>SegmentNo</b> 151/S-W0058/S080208	<b>TotalLength</b> 409.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0071	<b>StreetName</b> NA	<b>Significant LandMark</b> BUS DEPOT
<b>SegmentNo</b> 151/S-W0071/S081719	<b>TotalLength</b> 634.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0090	<b>StreetName</b> NA	<b>Significant LandMark</b> CLUB
<b>SegmentNo</b> 151/S-W0090/S081907	<b>TotalLength</b> 163.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0105	17th D Main	NEAR CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0105/S082038	230.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0101	<b>StreetName</b> 17th F Main	<b>Significant LandMark</b> NEAR CLUB
<b>SegmentNo</b> 151/S-W0101/S082218	<b>TotalLength</b> 317.08	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0146	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR BBMP OFFICE
<b>SegmentNo</b> 151/S-W0146/S082605	<b>TotalLength</b> 250.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0248	2nd Crs	RJS
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0248/S083723	571.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0002	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0002/S042330	<b>TotalLength</b> 39.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0004	<b>StreetName</b> NA	<b>Significant LandMark</b> KORAMANGALA VILLAGE
<b>SegmentNo</b> 151/S-W0004/S042506	<b>TotalLength</b> 37.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0006	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0006/S043035	<b>TotalLength</b> 40.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0003	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0003/S043205	<b>TotalLength</b> 166.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0008	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0008/S043556	<b>TotalLength</b> 94.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0017	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0017/S043759	<b>TotalLength</b> 113.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0010	NA	NEAR BASAVA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0010/S044007	108.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0012	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0012/S044154	<b>TotalLength</b> 126.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0023	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0023/S044337	<b>TotalLength</b> 69.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0025	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0025/S044503	<b>TotalLength</b> 155.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0011	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0011/S044728	<b>TotalLength</b> 118.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0020	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0020/S050458	<b>TotalLength</b> 81.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0014	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0014/S050628	<b>TotalLength</b> 66.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ /W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0022	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0022/S050911	<b>TotalLength</b> 131.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0057	<b>StreetName</b> NA	<b>Significant LandMark</b> OPP NGV
<b>SegmentNo</b> 151/S-W0057/S052029	<b>TotalLength</b> 118.42	


<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0038	NA	K.R GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0038/S053302	95.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Shivalingappa
10/09/2015	Remarks
Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0036	<b>StreetName</b> NA	<b>Significant LandMark</b> K.R.GARDEN
<b>SegmentNo</b> 151/S-W0036/S053550	<b>TotalLength</b> 99.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0104	3rd Crs	6th BLOCK PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0104/S105035	136.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0114	<b>StreetName</b> 1st Crs	<b>Significant LandMark</b> PARK
<b>SegmentNo</b> 151/S-W0114/S105259	<b>TotalLength</b> 142.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0096	<b>StreetName</b> 4th Crs	<b>Significant LandMark</b> PARK
<b>SegmentNo</b> 151/S-W0096/S105358	<b>TotalLength</b> 141.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0068	NA	OPP PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0068/S105605	137.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Shivalingappa
10/09/2015	Remarks
Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0081	18th E Main	BEHIND POLICE STATION
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0081/S110543	130.12	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0234	NA	NEAR VEMANA INSTITUTE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0234/S075218	166.39	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 5th cross, ,3rd block, 16th B main, 4th B block, and surrounding roads in ward no. 151 (Koramangala)	4846000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 256 MTS.	151-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/217/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0229	NA	NEAR MASTRYPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0229/S080049	256.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 5th cross, ,3rd block, 16th B main, 4th B block, and surrounding roads in ward no. 151 (Koramangala)	4846000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/217/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0187	12th A Crs	NEAR CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0187/S082138	119.24	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd	151-14-000040	0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 8th A main, 4th block and surrounding roads in ward no. 151 (Koramangala)	4858000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0185	13th Crs	NEAR CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0185/S082606	119.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd	151-14-000040	0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 8th A main, 4th block and surrounding roads in ward no. 151 (Koramangala)	4858000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0211	NA	FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0211/S082902	181.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd	151-14-000040	0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 8th A main, 4th block and surrounding roads in ward no. 151 (Koramangala)	4858000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0225	NA	SWABHIMANA PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0225/S083046	104.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd	151-14-000040	0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 8th A main, 4th block and surrounding roads in ward no. 151 (Koramangala)	4858000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0219	NA	SWABHIMANA PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0219/S083310	146.27	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd	151-14-000040	0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 8th A main, 4th block and surrounding roads in ward no. 151 (Koramangala)	4858000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0263	12th Main	NEAR POST OFFICE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0263/S015351	382.82	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 3rd main , 1st block and surrounding roads in ward no. 151 (Koramangala)	4793000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/233/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0244	14th A Crs	VEMANNA INSTITUTE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0244/S015715	212.73	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 3rd main , 1st block and surrounding roads in ward no. 151 (Koramangala)	4793000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE/e/W.O/233/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0179	16th Crs	GAJANANA GAS (CHINMAYA SCHOOL)
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0179/S021640	295.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th C main, 5th block and surrounding roads in ward no. 151 (Koramangala)	4923000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0151	17th C Crs	KRISHNA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0151/S022431	337.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th C main, 5th block and surrounding roads in ward no. 151 (Koramangala)	4923000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 316.30 mts	151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0036	<b>StreetName</b> NA	<b>Significant LandMark</b> K.R.GARDEN
<b>SegmentNo</b> 151/S-W0036/S074132	<b>TotalLength</b> 99.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0001	2nd Main	SHIVA CHITR MANDIRA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0001/S074536	273.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0164	NA	5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0164/S075532	544.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0080	<b>StreetName</b> NA	<b>Significant LandMark</b> PIZZA HUT
<b>SegmentNo</b> 151/S-W0080/S080038	<b>TotalLength</b> 153.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0153	17th B Crs	B MONA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0153/S091853	222.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Pothole filling	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0018	NA	8th block
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0018/S100104	43.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0009	<b>StreetName</b> NA	<b>Significant LandMark</b> village
<b>SegmentNo</b> 151/S-W0009/S100622	<b>TotalLength</b> 79.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0015	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0015/S100946	<b>TotalLength</b> 58.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ /W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0016	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR BASAVA TEMPLE
<b>SegmentNo</b> 151/S-W0016/S102747	<b>TotalLength</b> 50.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0019	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0019/S102924	<b>TotalLength</b> 30.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Routine Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0021	NA	KORAMANGALA VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0021/S103145	62.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0037	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0037/S103640	<b>TotalLength</b> 62.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0040	<b>StreetName</b> NA	<b>Significant LandMark</b> VILLAGE
<b>SegmentNo</b> 151/S-W0040/S104315	<b>TotalLength</b> 91.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0062	NA	HOUSE 27
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0062/S113608	56.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0064	NA	KALAYANA MANTAPA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0064/S121806	73.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.NAGESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9902357755		


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-13-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/99/2013-14	05/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0066	<b>StreetName</b> 8th Block	<b>Significant LandMark</b> OPP KALAYANA MANTAPA
<b>SegmentNo</b> 151/S-W0066/S122526	<b>TotalLength</b> 145.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.NAGESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9902357755	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ENGAGING PRIVATE TRACTOR AND LABOURS FOR MAINTENANCE OF FOOTPATH ROADS AND ROAD SIDE DRAINS EMERAGENCY WORKS A 1ST 2ND 3RD 4TH BLOCK KUDUREMUKHA COLON	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-13-000002
<b>Work OrderNo</b> EE (BTM)/ W.O/99/2013-14	<b>Work Order Date</b> 05/12/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0123	17th Main	KATHALIPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0123/S123313	220.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0116	<b>StreetName</b> NA	<b>Significant LandMark</b> KUTEERS ARCADE
<b>SegmentNo</b> 151/S-W0116/S124440	<b>TotalLength</b> 77.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Pothole filling	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0120	<b>StreetName</b> NA	<b>Significant LandMark</b> KATHALAPALYA
<b>SegmentNo</b> 151/S-W0120/S124721	<b>TotalLength</b> 79.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0124	<b>StreetName</b> NA	<b>Significant LandMark</b> KATHAPALYA
<b>SegmentNo</b> 151/S-W0124/S125519	<b>TotalLength</b> 44.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b> N.MANJUNATH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000021
<b>Work OrderNo</b> EE (BTM)/ /W.O/150/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0119	NA	KATHALPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0119/S010228	56.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.MANJUNATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
FILLING OF POT HOLES AND ROAD CUT PORTIONS BY ASPHALT AND CONCRETE TO MAIN AND CROSS ROADS IN WARD No.151 (KORAMANGALA) FOR YEAR 2011-12		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/ /W.O/150/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0247	NA	NEAR LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0247/S081410	218.81	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916364289		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 17 C MAIM,5TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4923000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148	3rd Crs	ACURA HOSPITAL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0148/S082220	305.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916364289		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 17 C MAIM,5TH BLOCK AND SURROUNDING ROADS IN WARD NO.151( KORAMANGALA)	4923000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 193.60 MTS.	151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	14th Main	OPP TO LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0259/S082904	273.09	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9916364289		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT SARJAPURA MAIN ROAD,SBI COLONY IN WARD NO.151( KORAMANGALA)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 244.50 MTS	151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0214	NA	TELEPHONE EXCHANGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0214/S083139	367.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT SARJAPURA MAIN ROAD,SBI COLONY IN WARD NO.151( KORAMANGALA)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 149.50 MTS	151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/238/2013-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0027	Doddamma Temple St Rd	NEAR GOVERNMENT SCHOOL VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0027/S083636	1437.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 1ST MAIN ROAD, 8TH BLOCK AND SURROUNDING AREA IN WARD NO.151( KORAMANGALA)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 259.00 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028	NA	VENKATESWARA TEMPLE ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0028/S084305	62.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 1ST MAIN ROAD, 8TH BLOCK AND SURROUNDING AREA IN WARD NO.151( KORAMANGALA)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 32.90 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0030	NA	VENKATESHWARA TEMPLE ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0030/S084545	59.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 1ST MAIN ROAD, 8TH BLOCK AND SURROUNDING AREA IN WARD NO.151( KORAMANGALA)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 47.00 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0032	NA	VENKATESHWARA TEMPLE ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0032/S084731	58.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 1ST MAIN ROAD, 8TH BLOCK AND SURROUNDING AREA IN WARD NO.151( KORAMANGALA)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 34.80 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0176	NA	BISLERE SLUM
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0176/S081414	178.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 4th cross, JNC road, 5th block, 15th main, 4th block and surrounding area in ward no. 151 (Koramangala)	4962000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/234/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0098	NA	GRAPE GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0098/S082305	151.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th cross (Club road )and surrounding area in ward no. 151 (Koramangala)	4954000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 90.0 MTS	151-14-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/240/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0210	NA	NEAR 12TH MAIN ROAD 4TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0210/S082853	348.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 2nd main, 2nd cross, 1st block and surrounding roads in ward no. 151 (Koramangala)	4989000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 232.70 MTS	151-14-000048
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/220/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0260	NA	L.I.C.
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0260/S091957	122.16	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Sarjapura main road, SBI colony in ward no. 151 (Koramangala)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 110.00 MTS	151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/238/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0287	NA	OPP L.I.C. BUILDING
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0287/S092713	87.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Sarjapura main road, SBI colony in ward no. 151 (Koramangala)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 180.00 MTS	151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/238/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0283	NA	OPP TO L.I.C. BUILDING
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0283/S093039	86.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Sarjapura main road, SBI colony in ward no. 151 (Koramangala)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 135.00 MTS	151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/W.O/238/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0277	8th C Main	OAK WOOD APARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0277/S050434	237.63	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 5TH,6TH MAIN AND SURROUNDING AREA AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)	1920000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/185/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0249	NA	NEAR B.D.A.COMPLEX
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0249/S051150	152.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 5TH,6TH MAIN AND SURROUNDING AREA AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/185/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0094	<b>StreetName</b> NA	<b>Significant LandMark</b> SIPANI APARTMENT
<b>SegmentNo</b> 151/S-W0094/S052000	<b>TotalLength</b> 263.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1830000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000045
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/187/2012- 13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0089	5th Crs	NEAR SRI KRISHNA TOWERS
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0089/S052338	247.28	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1830000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/187/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100	NA	NEAR 6TH BLOCK PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0100/S052651	75.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1830000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/187/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0083	NA	NEAR BETHANY SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0083/S053020	130.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1830000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/187/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0075	<b>StreetName</b> 18th Main	<b>Significant LandMark</b> NEAR BETHANY PARK
<b>SegmentNo</b> 151/S-W0075/S054702	<b>TotalLength</b> 143.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1830000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000045
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/187/2012- 13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0079	18th C Main	NEAR BETHANY SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0079/S054958	171.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1830000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/187/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0073	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR BETHANY SCHOOL
<b>SegmentNo</b> 151/S-W0073/S055450	<b>TotalLength</b> 301.65	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 18TH A,B,C,& D MAIN ROADS AND SURROUNDING AREA AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1830000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000045
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/187/2012- 13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148	3rd Crs	OPP ACURA HOSPITAL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0148/S060114	305.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS TO POLICE STATION, K.R.GARDEN CROSS ROAD AND MAIN ROADS AND SURROUNDING AREAS AT 8TH BLOCK KML IN WARD NO.151( KORAMANG	181900	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/188/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Shivalingappa
10/09/2015	Remarks
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0147	NA	5TH BLOCK PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0147/S060516	124.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS TO POLICE STATION, K.R.GARDEN CROSS ROAD AND MAIN ROADS AND SURROUNDING AREAS AT 8TH BLOCK KML IN WARD NO.151( KORAMANG	1819000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/188/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0145	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR TRIANGLE PARK5TH BLOCK
<b>SegmentNo</b> 151/S-W0145/S060712	<b>TotalLength</b> 245.86	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO ROADS TO POLICE STATION, K.R.GARDEN CROSS ROAD AND MAIN ROADS AND SURROUNDING AREAS AT 8TH BLOCK KML IN WARD NO.151( KORAMANG	<b>Sanctioned Amount</b> 1819000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000046
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/188/2012- 13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0140	NA	NEAR SMALL PARK 5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0140/S061732	191.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS TO POLICE STATION, K.R.GARDEN CROSS ROAD AND MAIN ROADS AND SURROUNDING AREAS AT 8TH BLOCK KML IN WARD NO.151( KORAMANG		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/188/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0070	NA	OPP TO POST OFFICE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0070/S061909	69.48	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS TO POLICE STATION, K.R.GARDEN CROSS ROAD AND MAIN ROADS AND SURROUNDING AREAS AT 8TH BLOCK KML IN WARD NO.151( KORAMANG		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/188/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0115	17th A Main	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0115/S062352	74.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0145	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0145/S012648	245.86	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
N.SHIVALINGA GOWDA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROAD SIDE DRAINS AND FOOTPATH TO 17 E MAIN ROAD AND SURROUNDING AREAS 5TH BLOCK IN WARD 151 KORAMANGALA	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-11-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE(BTM)TEND/JE/W.O/56/2010-11		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0155	17th Crs	NEAR WARD OFFICE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0155/S022650	165.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th C main, 5th block and surrounding roads in ward no. 151 (Koramangala)	4923000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/237/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0242	NA	KODANDARAMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0242/S023323	218.52	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Sarjapura main road, SBI colony in ward no. 151 (Koramangala)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 117 mts.	151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/238/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0220	NA	NEAR NEW LAKE 4TH B BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0220/S024039	239.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Sarjapura main road, SBI colony in ward no. 151 (Koramangala)	4996000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/238/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0063	NA	NEAR BAJAJ SHOW ROOM
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0063/S054014	209.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 1st A main road, 8th block and surrounding roads in ward no. 151 (Koramangala)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0027	Doddamma Temple St Rd	NEAR BAJAJ SHOW ROOM
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0027/S054425	1437.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 1st A main road, 8th block and surrounding roads in ward no. 151 (Koramangala)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 198.70 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0066	8th Block	NEAR KALYANA MANTAPA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0066/S054747	145.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 1st A main road, 8th block and surrounding roads in ward no. 151 (Koramangala)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 132.70 MTS	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0029	NA	ARCH ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0029/S055242	218.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 1st A main road, 8th block and surrounding roads in ward no. 151 (Koramangala)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0041	NA	K.R.GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0041/S055446	209.10	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 1st A main road, 8th block and surrounding roads in ward no. 151 (Koramangala)	4419000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 190.40 mts.	151-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/235/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0027	Doddamma Temple St Rd	NEAR JYOTHI NIVAS COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0027/S060755	1437.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th HB main, 5th block and surrounding area in ward no. 151 (Koramangala)	4942000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/236/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0133	NA	KHB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0133/S061258	219.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th HB main, 5th block and surrounding area in ward no. 151 (Koramangala)	4942000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/236/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0101	17th F Main	KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0101/S061932	317.08	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 17th HB main, 5th block and surrounding area in ward no. 151 (Koramangala)	4942000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 297.80 mts.	151-14-000045
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/236/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0165	NA	JYOTHI NIVAS COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0165/S111159	399.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 4th cross, JNC road, 5th block, 15th main, 4th block and surrounding area in ward no. 151 (Koramangala)	4962000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/234/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0163	NA	NEAR JYOTHI NIVAS COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0163/S111550	386.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 4th cross, JNC road, 5th block, 15th main, 4th block and surrounding area in ward no. 151 (Koramangala)	4962000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/234/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0183	14th Crs	CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0183/S111749	118.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 4th cross, JNC road, 5th block, 15th main, 4th block and surrounding area in ward no. 151 (Koramangala)	4962000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-14-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/234/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0181	15th Crs	CHINMAYA SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0181/S111943	281.10	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 4th cross, JNC road, 5th block, 15th main, 4th block and surrounding area in ward no. 151 (Koramangala)	4962000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/234/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0092	6th Crs	KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0092/S112434	528.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th cross (Club road )and surrounding area in ward no. 151 (Koramangala)	4954000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/240/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0111	NA	KATALIPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0111/S112715	238.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th cross (Club road )and surrounding area in ward no. 151 (Koramangala)	4954000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000047
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/240/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0085	18th Main	DEVI EYE CLINIC
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0085/S113805	651.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 2nd main, 2nd cross, 1st block and surrounding roads in ward no. 151 (Koramangala)	4989000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000048
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/220/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
10/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0351	1st D Main	SARJAPUR ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0351/S114228	251.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th main, 1st block, 1st mian (bajaj service station road) 8th block and surrounding area in ward no. 151 (Koramang	4918000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/218/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0159	Industrial Layout Main Rd	BEHIND RAHEJA ARCADE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0159/S114715	375.45	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th main, 1st block, 1st mian (bajaj service station road) 8th block and surrounding area in ward no. 151 (Koramang	4918000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/218/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0047	NA	K.R.GARDEN
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0047/S115345	239.84	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRIDL Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th main, 1st block, 1st mian (bajaj service station road) 8th block and surrounding area in ward no. 151 (Koramang	4918000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 200.00 mts	151-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/218/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0053	NA	OPP TO NGV INDOOR STADIUM
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0053/S115718	221.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th main, 1st block, 1st mian (bajaj service station road) 8th block and surrounding area in ward no. 151 (Koramang	4918000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 82.50 mts	151-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/218/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0035	NA	BAJAJ SERVICE STATION
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0035/S120209	191.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRIDL Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 6th main, 1st block, 1st mian (bajaj service station road) 8th block and surrounding area in ward no. 151 (Koramang	4918000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 170.00 mts.	151-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/218/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
16/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0184	7th Crs	maharaja signal
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0184/S120928	712.67	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 3rd cross road, 4th block and surrounding roads in ward no. 151 (Koramangala)	487200	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING 1562.40 Mts.	151-14-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/219/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0193	NA	NEAR FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0193/S121912	79.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at 3rd cross road, 4th block and surrounding roads in ward no. 151 (Koramangala)	4872000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM) JE//W.O/219/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0206	NA	NEAR FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0206/S101741	612.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRID LTD		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7353333524		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT 3RD CROSS ROAD,4TH BLOCK AND SURROUNDING ROADS IN WARD No. 151 (KORAMANGALA)	4872000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000050
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTM/JE/W.O/219/2013-14	27/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingapp
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0256	2nd Crs	OAK Wood APPARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0256/S100423	130.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manager,KRIDL Ltd..		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains & footpath at 8th A,B,C Main road J bLOCK & 14th main road 3rd block and surrounding roads in ward no.151	4970000	2013/14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	Flagging course, Covering of drains and fixings of kerb stones etc..	151-14-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE.BTM/W/299/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0254	3rd Crs	OAK WOOD APPARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0254/S102447	132.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER,KRIDL Ltd.		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF DRAIN & FOOTPATH	4970000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No.EE (BTM)/W.O/299/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0252	4th Crs	OAK WOOD APPARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0252/S104041	136.47	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and Footpaths at 8th A,B,C main road, J block and 14th main road 3rd block surrounding roads in ward no. 151 Koramangala	4970000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	FLAGGING COURSE , COVERING OF DRAINS AND FIXING OF KERB STONE NORTH SIDE OF THE ROAD	151-14-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/W.O/299/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0250	<b>StreetName</b> 5th Crs	<b>Significant LandMark</b> OAK WOOD APPARTMENT
<b>SegmentNo</b> 151/S-W0250/S105511	<b>TotalLength</b> 230.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b> TECHNICAL MANAGER KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and Footpaths at 8th A,B,C main road, J block and 14th main road 3rd block surrounding roads in ward no. 151 Koramangala	<b>Sanctioned Amount</b> 4970000	<b>Sanctioned Year</b> 2013-14
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE , COVERING OF DRAINS AND FIXING OF KERB STONE SOUTH SIDE OF THE ROAD	<b>Job No Work Code</b> 151-14-000027
<b>Work OrderNo</b> EE (BTM)/W.O/299/2013-14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0275	8th B Main	OAK WOOD APPARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0275/S110421	143.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and Footpaths at 8th A,B,C main road, J block and 14th main road 3rd block surrounding roads in ward no. 151 Koramangala	4970000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/W.O/299/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0277	<b>StreetName</b> 8th C Main	<b>Significant LandMark</b> OAK WOOD APPARTMENT
<b>SegmentNo</b> 151/S-W0277/S110640	<b>TotalLength</b> 237.63	


<b>ContractorDetails</b>		
<b>NameofContractor</b> TECHNICAL MANAGER KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and Footpaths at 8th A,B,C main road, J block and 14th main road 3rd block surrounding roads in ward no. 151 Koramangala	<b>Sanctioned Amount</b> 4970000	<b>Sanctioned Year</b> 2013-14
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE , COVERING OF DRAINS AND FIXING OF KERB STONE WEST SIDE OF THE ROAD	<b>Job No Work Code</b> 151-14-000027
<b>Work OrderNo</b> EE (BTM)/W.O/299/2013-14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0209	NA	NEAR FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0209/S112332	177.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 9th A, 10th ,11th , 11th A Main roads and surrounding roads 4th Block ward No. 151 Koramangala.	4988000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-00-0028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/298/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0113	17th B Main	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0113/S063218	73.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0109	17th C Main	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0109/S063615	70.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Shivalingappa
10/09/2015	Remarks
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0105	17th D Main	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0105/S063807	230.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	Providing Asphalting to existing damaged surface	151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/09/2015	

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0090	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR KORAMANGALA CLUB
<b>SegmentNo</b> 151/S-W0090/S063945	<b>TotalLength</b> 163.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1815000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000039
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/186/2012- 13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0084	NA	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0084/S064120	185.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0082	NA	NEAR KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0082/S064258	160.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH A1 TO A3 MAIN ROADS 6TH A TO 6TH C CROSS ROADS AND SURROUNDING AREAS AT 6TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1815000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/186/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0129	NA	AIRTEL OFFICE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0129/S065154	94.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH E,F MAIN ROADS 3RD AND 4TH CROSS ROADS AND SURROUNDING AREAS AT 5TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1899000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/183/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0131	NA	PUNJAB NATIONAL BANK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0131/S065644	164.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 17TH E,F MAIN ROADS 3RD AND 4TH CROSS ROADS AND SURROUNDING AREAS AT 5TH BLOCK KML IN WARD NO.151( KORAMANGALA)	1899000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/183/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0243	NA	BEHIND NANDINI HOTEL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0243/S070846	139.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND, 3RD, & 4TH CROSS ROADAT 4TH BLOCK AND 8TH A &10TH MAIN ROAD AND SURROUNDING AREAS AT 4TH C BLOCK KML IN WARD NO.151( KOR	1614000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ASPHALTING	151-12-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/182/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0245	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR LAKE
<b>SegmentNo</b> 151/S-W0245/S071156	<b>TotalLength</b> 86.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 2ND, 3RD, & 4TH CROSS ROADAT 4TH BLOCK AND 8TH A &10TH MAIN ROAD AND SURROUNDING AREAS AT 4TH C BLOCK KML IN WARD NO.151( KOR	<b>Sanctioned Amount</b> 1614000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 151-12-000043
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/182/2012- 13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0224	NA	NEAR LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0224/S071403	132.09	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		


<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND, 3RD, & 4TH CROSS ROADAT 4TH BLOCK AND 8TH A &10TH MAIN ROAD AND SURROUNDING AREAS AT 4TH C BLOCK KML IN WARD NO.151( KOR	1614000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/182/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0222	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR LAKE
<b>SegmentNo</b> 151/S-W0222/S071525	<b>TotalLength</b> 175.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 2ND, 3RD, & 4TH CROSS ROADAT 4TH BLOCK AND 8TH A &10TH MAIN ROAD AND SURROUNDING AREAS AT 4TH C BLOCK KML IN WARD NO.151( KOR	<b>Sanctioned Amount</b> 1614000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000043
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/182/2012- 13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0136	7th Crs	KATHALPALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0136/S072319	236.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 2ND, 3RD, & 4TH CROSS ROADAT 4TH BLOCK AND 8TH A &10TH MAIN ROAD AND SURROUNDING AREAS AT 4TH C BLOCK KML IN WARD NO.151( KOR	1614000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/182/2012-13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0240	<b>StreetName</b> NA	<b>Significant LandMark</b> WATER TANK
<b>SegmentNo</b> 151/S-W0240/S074815	<b>TotalLength</b> 164.44	


<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 16TH A,B MAIN ROADS AND FROM 2ND TO 6TH B CROSS AT 3RD BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1900000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000042
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/181/2012-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0238	<b>StreetName</b> NA	<b>Significant LandMark</b> WATER TANK
<b>SegmentNo</b> 151/S-W0238/S075052	<b>TotalLength</b> 164.44	


<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 16TH A,B MAIN ROADS AND FROM 2ND TO 6TH B CROSS AT 3RD BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1900000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000042
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/181/2012- 13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0236	<b>StreetName</b> NA	<b>Significant LandMark</b> WATER TANK
<b>SegmentNo</b> 151/S-W0236/S075233	<b>TotalLength</b> 166.11	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 16TH A,B MAIN ROADS AND FROM 2ND TO 6TH B CROSS AT 3RD BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000042
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/181/2012- 13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0256	<b>StreetName</b> 2nd Crs	<b>Significant LandMark</b> J.BLOCK NEAR OAK APARTMENT
<b>SegmentNo</b> 151/S-W0256/S025647	<b>TotalLength</b> 130.96	
<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	
<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1755000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000041
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/184/2012-13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0254	<b>StreetName</b> 3rd Crs	<b>Significant LandMark</b> J.BLOCK NEAR OAK APARTMENT
<b>SegmentNo</b> 151/S-W0254/S030412	<b>TotalLength</b> 132.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000041
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/184/2012-13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	
Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0252	4th Crs	J.BLOCK NEAR OAK APARTMENT
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0252/S030526	136.47	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/184/2012-13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0250	5th Crs	151-12-000041
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0250/S032418	230.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENSION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/184/2012- 13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0275	<b>StreetName</b> 8th B Main	<b>Significant LandMark</b> J.BLOCK NEAR OAK APARTMENT
<b>SegmentNo</b> 151/S-W0275/S032817	<b>TotalLength</b> 143.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M.S.VENKATESH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886066040	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)	<b>Sanctioned Amount</b> 1755000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 151-12-000041
<b>Work OrderNo</b> EE (BTM)/JE/e/TEND/W.O/184/2012-13	<b>Work Order Date</b> 16/02/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0251	16th B Main	WATER TANK
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0251/S033001	234.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.S.VENKATESH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886066040		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO 1ST D MAIN ROAD OPP.TO WIPRO PARK JAKKASANDRA EXTENSION AND SURROUNDING AREAS AT 1ST BLOCK KML IN WARD NO.151( KORAMANGALA)	1755000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-12-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE (BTM)/JE/e/TEND/W.O/184/2012- 13	16/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0205	NA	FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0205/S124049	222.71	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 9th A, 10th ,11th , 11th A Main roads and surrounding roads 4th Block ward No. 151 Koramangala	4988000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-00-0028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/298/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0197	NA	FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0197/S124518	189.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 9th A, 10th ,11th , 11th A Main roads and surrounding roads 4th Block ward No. 151 Koramangala	4988000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-00-0028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/298/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0195	NA	FOOD MALL
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0195/S124752	82.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 9th A, 10th ,11th , 11th A Main roads and surrounding roads 4th Block ward No. 151 Koramangala.	4988000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		151-14-00-0028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/298/2013-14	13/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Shivalingappa
<b>Date of Inspection</b>	<b>Remarks</b>	
13/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0296	<b>StreetName</b> 3rd Crs	<b>Significant LandMark</b> NEAR BDA PARK
<b>SegmentNo</b> 151/S-W0296/S013100	<b>TotalLength</b> 181.86	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	


<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 3rd,4th ,5th Cross roads and surrounding roads 1st Block ward No. 151 Koramangala.	<b>Sanctioned Amount</b> 4986000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE SOUTH SIDE OF THE ROAD	<b>Job No Work Code</b> 151-14-000026
<b>Work OrderNo</b> No. EE (BTM)/W.O/297/2013-14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
16/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0294	<b>StreetName</b> 4th Crs	<b>Significant LandMark</b> NEAR BDA PARK
<b>SegmentNo</b> 151/S-W0294/S013902	<b>TotalLength</b> 249.81	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 3rd,4th ,5th Cross roads and surrounding roads 1st Block ward No. 151 Koramangala.	<b>Sanctioned Amount</b> 4986000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE OF THE ROAD	<b>Job No Work Code</b> 151-14-000026
<b>Work OrderNo</b> No. EE (BTM)/W.O/297/2013-14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0290	<b>StreetName</b> 5th Crs	<b>Significant LandMark</b> NEAR BDA PARK
<b>SegmentNo</b> 151/S-W0290/S014454	<b>TotalLength</b> 156.59	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 3rd,4th ,5th Cross roads and surrounding roads 1st Block ward No. 151 Koramangala	<b>Sanctioned Amount</b> 4986000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE SOUTH SIDE OF THE ROAD	<b>Job No Work Code</b> 151-14-000026
<b>Work OrderNo</b> No. EE (BTM)/W.O/297/2013-14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0214	NA	NEAR TELEPHONE EXCHANGE
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0214/S020758	367.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 1st cross road (Behind Sipani bhavan),1st A Cross roads and Park surrounding area ward No. 151 Koramangala	1997000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE OF THE ROAD	151-14-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/284/2013-14	12/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	151	Koramangala
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0097	NA	KORAMANGALA CLUB
<b>SegmentNo</b>	<b>TotalLength</b>	
151/S-W0097/S023501	175.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical Manage KRID Ltd		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917	dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to drains and footpaths at 17th F1,F2,F3, & F4 Main Roads and surrounding Roads 6th Block in ward No. 151 Koramangala	4969000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE WEST SIDE OF THE ROAD	151-14-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
No. EE (BTM)/W.O/287/2013-14	12/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0095	<b>StreetName</b> 17th F Main	<b>Significant LandMark</b> KORAMANGALA CLUB
<b>SegmentNo</b> 151/S-W0095/S024739	<b>TotalLength</b> 175.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 17th F1,F2,F3, & F4 Main Roads and surrounding Roads 6th Block in ward No. 151 Koramangala.	<b>Sanctioned Amount</b> 4969000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE OF THE ROAD	<b>Job No Work Code</b> 151-14-000029
<b>Work OrderNo</b> No. EE (BTM)/W.O/287/2013-14	<b>Work Order Date</b> 12/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0093	<b>StreetName</b> 17th Main	<b>Significant LandMark</b> KORAMANGALA CLUB
<b>SegmentNo</b> 151/S-W0093/S025047	<b>TotalLength</b> 173.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 17th F1,F2,F3, & F4 Main Roads and surrounding Roads 6th Block in ward No. 151 Koramangala.	<b>Sanctioned Amount</b> 4969000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE OF THE ROAD	<b>Job No Work Code</b> 151-14-000029
<b>Work OrderNo</b> No. EE (BTM)/W.O/287/2013-14	<b>Work Order Date</b> 12/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
13/09/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0091	<b>StreetName</b> 17/5 F 3 Main	<b>Significant LandMark</b> KORAMANGALA CLUB
<b>SegmentNo</b> 151/S-W0091/S025449	<b>TotalLength</b> 173.78	



<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 17th F1,F2,F3, & F4 Main Roads and surrounding Roads 6th Block in ward No. 151 Koramangala.	<b>Sanctioned Amount</b> 4969000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE EAST SIDE OF THE ROAD	<b>Job No Work Code</b> 151-14-000029
<b>Work OrderNo</b> No. EE (BTM)/W.O/287/2013-14	<b>Work Order Date</b> 12/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
10/09/2015	

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 151	<b>WardName</b> Koramangala
<b>StreetID</b> W0088	<b>StreetName</b> NA	<b>Significant LandMark</b> KORAMANGALA CLUB
<b>SegmentNo</b> 151/S-W0088/S030015	<b>TotalLength</b> 158.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Technical Manage KRID Ltd	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b> dm3bbmpwest@kridl.net	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains and footpaths at 17th F1,F2,F3, & F4 Main Roads and surrounding Roads 6th Block in ward No. 151 Koramangala	<b>Sanctioned Amount</b> 4969000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> FLAGGING COURSE, COVERING OF DRAINS AND FIXING OF KERB STONE OF THE ROAD	<b>Job No Work Code</b> 151-14-000029
<b>Work OrderNo</b> No. EE (BTM)/W.O/287/2013-14	<b>Work Order Date</b> 12/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Drain Condition	