



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0258	7th Crs Maruthi Nagar	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/S-W0258/S013458	300.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMACHANDRA		0.00
PhoneNo	EmailId	
9880959815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab and construction of Culverts at Maruthi Nagara, 4th, 5th, 7th & 8th and Surrounding area cross roads	1499000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/61/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		7 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0260, W0173	8th Crs Maruthi Nagar, Srinivasa Temple Street	srinivasa temple
SegmentNo	TotalLength	
152/C-W0260/S014338	192.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMACHANDRA		0.00
PhoneNo	EmailId	
9880959815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab and construction of Culverts at Maruthi Nagara, 4th, 5th, 7th & 8th and Surrounding area cross roads	1499000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/61/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0224, W0149, W0147, W0228, W0232	4th Crs, 2nd Crs, NA, 2nd Main Rd Chikka Adugodi	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/C-W0224/S015807	118.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0149, W0147, W0151	2nd Crs, NA, 3rd Crs Chikka Adugodi	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/C-W0149/S020522	33.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0159, W0232	4th Crs, 2nd Main Rd Chikka Adugodi	BURIAL GROUND
SegmentNo	TotalLength	
152/C-W0159/S021434	150.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		vidhya bhavan road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0230	3rd Crs	HEALTH INDIA
SegmentNo	TotalLength	
152/S-W0230/S021737	77.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3rd main
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0224	4th Crs	HEALTH INDIA
SegmentNo	TotalLength	
152/S-W0224/S022033	138.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		6th main chikka adugodi
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0135	4th A Crs	HEALTH INDIA
SegmentNo	TotalLength	
152/S-W0135/S022221	132.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th main chikka adugodi
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0194	2nd Main Rd	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/S-W0194/S022611	97.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Cross road and drains in Brundavana Nagara and Chikka Adugodi in ward No.152 Suddugunte Palya	4579000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2nd main road
Date of Inspection	Remarks	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0176, W0170, W0172, W0192, W0156, W0098, W0121, W	4th Crs, 1st Crs, Bhovi Colony, 2nd Crs, 1st Crs, Krishna Murthy Lyt, 7th Crs, 3rd Crs, 4th Main Rd	ANJANEYA TEMPLE
SegmentNo	TotalLength	
152/C-W0176/S024326	199.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. RAMACHANDRA		0.00
PhoneNo	EmailId	
9880959815		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culverts and Improvements to selected drains and roads at suddagunte palya village, Bhovi colony in Ward No.152.	1018000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000038
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/164/11-12	12/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		2nd cross
Date of Inspection	Remarks	
11/09/2015		

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0043	NA	ANJANEYA TEMPLE
SegmentNo	TotalLength	
152/S-W0043/S024632	79.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culverts and Improvements to selected drains and roads at suddagunte palya village, Bhovi colony in Ward No.152.	1018000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-0000030
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/168/11-12	18/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th main
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0148	8th Crs	christ school
SegmentNo	TotalLength	
152/S-W0148/S030234	44.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. SANTHOSH KUMAR		0.00
PhoneNo	EmailId	
9880443537		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Concreting to bad roads at Balaji nagar and surrounding cross roads in ward no. 152	1985000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000046
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/124/11-12	03/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0034	2nd Crs Venkateshwara Layout	GHOUSIA COLLEGE
SegmentNo	TotalLength	
152/S-W0034/S031925	68.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0038, W0027	3rd Crs Venkateshwara Layout, NA	GHOUSIA COLLEGE
SegmentNo	TotalLength	
152/C-W0038/S034012	61.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	1900000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishna nagar road
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0040	4th Crs Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0040/S034254	67.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0042	5th Crs Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0042/S034453	67.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0044, W0031	6th Crs, Venkateshwara Layout, 1st Main Rd Venkateshwara Layout	SRINIVASA THEARTRE
SegmentNo	TotalLength	
152/C-W0044/S034632	68.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		6 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0031, W0046	1st Main Rd Venkateshwara Layout, 7th Crs Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/C-W0031/S034812	68.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		9th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0048	8th Crs Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0048/S035012	66.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0024	Kishnanagar Main Rd	GHOUSIA COLLEGE
SegmentNo	TotalLength	
152/S-W0024/S035407	291.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHI CONSTRUCTIONS		0.00
PhoneNo	EmailId	
9845429695		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at S.G. Palya main road and surrounding cross roads in ward no. 152	2000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000050
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/178/11-12	19/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		krishna nagar road
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0042, W0053	5th Crs Venkateshwara Layout, 2nd Main Rd	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/C-W0042/S040030	79.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.LAKSHMAN		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Krishnamurthy layout From 1st to 4th cross roads and surrounding cross roads in ward no. 152	1500000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/117/11-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0192	1st Crs, Krishna Murthy Lyt	ZENITH EXPORTS
SegmentNo	TotalLength	
152/S-W0192/S040546	129.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.LAKSHMAN		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Krishnamurthy layout From 1st to 4th cross roads and surrounding cross roads in ward no. 152	1500000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/117/11-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0204	2nd Crs	ZENITH EXPORT
SegmentNo	TotalLength	
152/S-W0204/S040748	128.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.LAKSHMAN		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Krishnamurthy layout From 1st to 4th cross roads and surrounding cross roads in ward no. 152	1500000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/117/11-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0206	3rd Crs	ZENITH EXPORTS
SegmentNo	TotalLength	
152/S-W0206/S040944	118.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.LAKSHMAN		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Krishnamurthy layout From 1st to 4th cross roads and surrounding cross roads in ward no. 152	1500000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/117/11-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0216	4th Crs	HEALTH INDIA
SegmentNo	TotalLength	
152/S-W0216/S041116	116.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P.LAKSHMAN		0.00
PhoneNo	EmailId	
9916335298		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Krishnamurthy layout From 1st to 4th cross roads and surrounding cross roads in ward no. 152	1500000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/117/11-12	02/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		4 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0260	8th Crs Maruthi Nagar	Venkateshwara college
SegmentNo	TotalLength	
152/S-W0260/S064418	283.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.Santhosh		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Maruthi Nagara, 7th and 8th cross road and Surrounding Area cross roads in Ward No-152 Suddagunte Palya.	1750000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvement to drain	152-12-000023
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/J.E/WO/20/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0077	NA	Ayappa Swamy Temple
SegmentNo	TotalLength	
152/S-W0077/S090211	143.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		2nd main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0079	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0079/S091019	110.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT TO DARIN	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0026	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0026/S091349	116.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya.	1500000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT TO DARIN	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0030	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0030/S091643	94.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0013	5th Crs	TAVAREKERE PARK
SegmentNo	TotalLength	
152/S-W0013/S091941	136.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0010	Tank Bund Rd	TAVAREKERE PARK
SegmentNo	TotalLength	
152/S-W0010/S092218	685.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.DEVARAJAN		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Bhuvanappa Layout and surrounding area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN	152-12-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/12/12-13	12/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		tank bund road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0038	3rd Crs Venkateshwara Layout	GHOUSIA COLLEGE
SegmentNo	TotalLength	
152/S-W0038/S092617	298.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.ANITH		0.00
PhoneNo	EmailId	
9845366374		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Bad Roads, road side drain at Venkateshwara Layout from 1st cross to 9th cross road and surrounding area in Ward No-152 Suddagunte Pal	1500000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT TO DRAIN	152-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/101/12-13	25/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0042	5th Crs Venkateshwara Layout	GHOUSIA COLLEGE
SegmentNo	TotalLength	
152/S-W0042/S093130	271.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.ANITH		0.00
PhoneNo	EmailId	
9845366374		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Bad Roads, road side drain at Venkateshwara Layout from 1st cross to 9th cross road and surrounding area in Ward No-152 Suddagunte Pal	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	DRAIN	152-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/101/12-13	25/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0046	7th Crs Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0046/S093403	262.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.ANITH		0.00
PhoneNo	EmailId	
9845366374		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Bad Roads, road side drain at Venkateshwara Layout from 1st cross to 9th cross road and surrounding area in Ward No-152 Suddagunte Pal	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/101/12-13	25/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		7 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0050	8th Crs	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0050/S093605	156.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.ANITH		0.00
PhoneNo	EmailId	
9845366374		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Bad Roads, road side drain at Venkateshwara Layout from 1st cross to 9th cross road and surrounding area in Ward No-152 Suddagunte Pal	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/101/12-13	25/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0316	11th Crs	SRI RAMA TEMPLE
SegmentNo	TotalLength	
152/S-W0316/S093858	49.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Maruthinagara, 9th cross road (Sri Rama Temple Road) and surrounding area in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000019
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/41/12-13	14/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		12 th cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0175	19th Crs	SRI RAMA TEMPLE
SegmentNo	TotalLength	
152/S-W0175/S094453	165.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Maruthinagara, 9th cross road (Sri Rama Temple Road) and surrounding area in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000019
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/41/12-13	14/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rama temple road
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0284	3rd Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0284/S094721	67.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.K REDDY		0.00
PhoneNo	EmailId	
9845495051		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road side drain at Maruthinagara, 9th cross road (Sri Rama Temple Road) and surrounding area in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000019
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/41/12-13	14/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0151	3rd Crs Chikka Adugodi	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/S-W0151/S095729	423.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0178	1st Main Rd	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/S-W0178/S100235	140.48	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st main
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0232	2nd Main Rd Chikka Adugodi	VENKATESHWARA COLLEGE
SegmentNo	TotalLength	
152/S-W0232/S100838	410.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd main brindavangara
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0262	9th Crs Maruthi Nagar	VENKATESHWARA COLLEGE
SegmentNo	TotalLength	
152/S-W0262/S101116	142.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		9 th cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0252	4th Crs Maruthi Nagar	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/S-W0252/S101555	179.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0254	5th Crs Maruthi Nagar	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/S-W0254/S101959	241.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0258	7th Crs Maruthi Nagar	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/S-W0258/S102147	300.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		7 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0260	8th Crs Maruthi Nagar	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/S-W0260/S102322	283.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.RAMESH		0.00
PhoneNo	EmailId	
9886002113		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Brindavan Nagara main and cross roads in ward no: 152 Suddagutepalya	5000000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ROAD	152-12-000034
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/35/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		8 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0088	1st Crs	SUBRAMANYA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0088/S102608	160.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.P PARAMASHIVIAH		0.00
PhoneNo	EmailId	
9845593888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to concrete roads, and Road side drain at Bharathi Layout and Surrounding Area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/99/12-13	23/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0060	2nd Crs	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0060/S103050	68.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.P.PARAMASHIVIAH		0.00
PhoneNo	EmailId	
9845593888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to concrete roads, and Road side drain at Bharathi Layout and Surrounding Area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/NO/99/12-13	23/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2nd cross
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0035	NA	SUBRAMANYA TEMPLE
SegmentNo	TotalLength	
152/S-W0035/S103808	60.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.P PARAMASHIVAIAH		0.00
PhoneNo	EmailId	
9845593888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to concrete roads, and Road side drain at Bharathi Layout and Surrounding Area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/NO/99/12-13	23/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0041	NA	SUBRAMANYA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0041/S104004	73.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.P PARAMASHIVIAH		0.00
PhoneNo	EmailId	
9845593888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to concrete roads, and Road side drain at Bharathi Layout and Surrounding Area cross roads in Ward No-152 Suddagunte Palya.	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/99/12-13	23/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0176, W0100, W0170, W0172, W0224, W0222, W0062, W	4th Crs, 1st Main Rd, Ramaiah Lyt, 1st Crs, Bhovi Colony, 2nd Crs, 6th Crs, Kishnanagar Main Rd, 3rd	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/C-W0176/S104611	1062.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath and drain at Thavarekere Main Road East Side Suddagunte palya in ward No: 152.	1985000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	EAST SIDE DRAIN	152-13-000045
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/13-14	17/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		tavarekere main road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0053	2nd Main Rd	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0053/S105521	232.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath at Venkateshwara Layout 1st & 2nd Main Road in Ward No. 152 (Suddagunte Palya).	1900000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/30/13-14	09/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0031	1st Main Rd Venkateshwara Layout	SRINIVASA THEATRE
SegmentNo	TotalLength	
152/S-W0031/S105947	574.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain & Footpath at Venkateshwara Layout 1st & 2nd Main Road in Ward No. 152 (Suddagunte Palya).	1900000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/30/13-14	09/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		7 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0092	1st Crs, Bharathi Rd	SUBRAMANYA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0092/S110334	91.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Concrete to the road cut Portions of Concrete Roads in Ward No. 152 (Suddagunte Palya).	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/25/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0096	2nd Crs	SUBRAMANYA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0096/S110706	90.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Concrete to the road cut Portions of Concrete Roads in Ward No. 152 (Suddagunte Palya).	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/25/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0033, W0098	2nd Main Rd, 3rd Crs	SUBRAMANYA SWAMY TEMPLE
SegmentNo	TotalLength	
152/C-W0033/S110935	82.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Concrete to the road cut Portions of Concrete Roads in Ward No. 152 (Suddagunte Palya).	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/25/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0146	9th Crs	CHRIST SCHOOL
SegmentNo	TotalLength	
152/S-W0146/S111116	44.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Laying Cement Concrete to the road cut Portions of Concrete Roads in Ward No. 152 (Suddagunte Palya).	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	CONCRETE	152-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/25/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		9 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0161	5th Crs	VENKATESHWARA COLLEGE
SegmentNo	TotalLength	
152/S-W0161/S111635	333.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling to the Roads during the year 2012-13 in Ward No. 152 (Suddagunte Palya).	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	POT HOLES	152-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/23/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross burial ground road
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0208	6th Main Rd	ZENITH EXPORT
SegmentNo	TotalLength	
152/S-W0208/S112205	164.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling to the Roads during the year 2012-13 in Ward No. 152 (Suddagunte Palya)	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	POT HOLES	152-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/23/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd main
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0033	2nd Main Rd	CHRIST SCHOOL
SegmentNo	TotalLength	
152/S-W0033/S112513	423.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling to the Roads during the year 2012-13 in Ward No. 152 (Suddagunte Palya)	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	POTHOLES	152-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/23/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0119	3rd Main Rd Bharati Layout	PREMALAYA SCHOOL
SegmentNo	TotalLength	
152/S-W0119/S113035	263.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling to the Roads during the year 2012-13 in Ward No. 152 (Suddagunte Palya)	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	POTHOLES	152-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/23/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3rd main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0222, W0130, W0216, W0218, W0134, W0206, W0121, W	6th Crs, 3rd Crs, 4th Crs, 5th Crs, 2nd Crs, 4th Main Rd Bharati Layout, 1st Crs	BALU HOUSE
SegmentNo	TotalLength	
152/C-W0222/S113602	202.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R PRATHEEK		0.00
PhoneNo	EmailId	
9916997189		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Pot Holes filling to the Roads during the year 2012-13 in Ward No. 152 (Suddagunte Palya)	1000000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	POTHOLES	152-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/23/13-14	03/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0014	Christ School Rd	CHRIST ENGLISH SCHOOL
SegmentNo	TotalLength	
152/S-W0014/S113847	714.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. PUSHPARAJ		0.00
PhoneNo	EmailId	
9448592779		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath and drain at Venkateswara Layout Main Road and	1500000	2012-13
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-12-000044
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/36/13-14	23/07/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vidhya bhavan road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0211	NA	BBMP OFFICE
SegmentNo	TotalLength	
152/S-W0211/S053620	63.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.Srinivasa Reddy		0.00
PhoneNo	EmailId	
9886041140		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab at Madiwala Extn., 1st Cross to 3rd cross and Surrounding area cross roads in Ward No-152 Suddagunte	1481000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-11-000010
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/05/11-12	15/04/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0217	1st Crs	BBMP OFFICE
SegmentNo	TotalLength	
152/S-W0217/S055410	149.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.Srinivasa Reddy		0.00
PhoneNo	EmailId	
9886041140		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab at Madiwala Extn., 1st Cross to 3rd cross and Surrounding area cross roads in Ward No-152 Suddagunte	1481000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-11-000010
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/VO/05/11-12	15/04/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0217, W0215, W0330	1st Crs, 2nd Crs, 2nd Main Rd	BBMP OFFICE
SegmentNo	TotalLength	
152/C-W0217/S055801	48.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.Srinivasa Reddy		0.00
PhoneNo	EmailId	
9886041140		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab at Madiwala Extn., 1st Cross to 3rd cross and Surrounding area cross roads in Ward No-152 Suddagunte	1481000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-11-000010
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/05/11-12	15/04/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0215, W0328, W0324, W0306, W0330	2nd Crs, NA, 1st Main Rd, 1st A Main Rd, 2nd Main Rd	BBMP OFFICE
SegmentNo	TotalLength	
152/C-W0215/S060100	57.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.Srinivasa Reddy		0.00
PhoneNo	EmailId	
9886041140		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab at Madiwala Extn., 1st Cross to 3rd cross and Surrounding area cross roads in Ward No- 152 Suddagunte	1481000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN	152-11-000010
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/05/11-12	15/04/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0192	1st Crs, Krishna Murthy Lyt	ZENITH EXPORT
SegmentNo	TotalLength	
152/S-W0192/S060235	129.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0100	1st Main Rd, Ramaiah Lyt	ORACLE
SegmentNo	TotalLength	
152/S-W0100/S060915	157.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st main ramaiah
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0074	NA	ORACLE
SegmentNo	TotalLength	
152/S-W0074/S061315	76.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0072	NA	ORACLE
SegmentNo	TotalLength	
152/S-W0072/S061628	84.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		3 rd cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0068	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0068/S061853	134.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		2 nd cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0066	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0066/S062055	145.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		1st cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0077	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0077/S062304	143.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		2nd main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0030	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0030/S062540	94.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0079	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0079/S062734	110.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0028	NA	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0028/S062942	30.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0260, W0252, W0173, W0302, W0256, W0254, W0250, W	8th Crs Maruthi Nagar, 4th Crs Maruthi Nagar, Srinivasa Temple Street, 7th Crs Maruthi Nagar, 6th	SRINIVASA TEMPLE
SegmentNo	TotalLength	
152/C-W0260/S063357	199.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
11/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0177	4th Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0177/S063553	245.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd main
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0181, W0177, W0254	1st Main Rd, 4th Crs, 5th Crs Maruthi Nagar	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/C-W0181/S063953	38.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0300	6th Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0300/S064403	44.70	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		6 th cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0306	1st A Main Rd	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0306/S064928	126.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		adjacent to aro office
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0215	2nd Crs	AYAPPA SWAMY TEMPLE
SegmentNo	TotalLength	
152/S-W0215/S065535	151.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Krishan murty layout Bhuvanappa Layout and cross Roads at suddaguntepalya in ward No.152	5000000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		152-11-000024
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/94/11-12	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0157, W0194, W0161, W0085, W0151	10th Crs, 2nd Main Rd, 5th Crs, NA, 3rd Crs Chikka Adugodi	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/C-W0157/S070816	98.36	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0198	3rd Crs	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/S-W0198/S071601	73.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd main
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0147	NA	VENKATESHWARA TEMPLE
SegmentNo	TotalLength	
152/S-W0147/S071849	61.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0224, W0149, W0147, W0228, W0232	4th Crs, 2nd Crs, NA, 2nd Main Rd Chikka Adugodi	VENKATESHWARA COLLEGE
SegmentNo	TotalLength	
152/C-W0224/S072206	116.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0292	NA	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0292/S072955	30.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0201	2nd Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0201/S073209	158.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. SATISH		0.00
PhoneNo	EmailId	
9886156277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Brindavan Nagara, Chikka Adugodi and surrounding area cross roads in Ward No. 152 Suddaguntepalya.	1987000	2010-11
Year	Type of Work	Other Work Type
2010 - 2011	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/33/10-11	16/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd main road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0161	5th Crs	BURIAL GROUND
SegmentNo	TotalLength	
152/S-W0161/S073552	333.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.G.BHASKAR		0.00
PhoneNo	EmailId	
9449669999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing covering slab and construction of Culverts at Brindavan Nagara, Chikka Adugodi and Surrounding area cross roads in	1492000	2011-12
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000009
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/91/11-12	31/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		burial ground road
Date of Inspection	Remarks	
23/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0203	3rd Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0203/S015329	217.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st and 2nd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/203/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0304, W0298, W0207, W0296	1st Main Rd, NA, 4th Crs	BBMP OFFICE
SegmentNo	TotalLength	
152/C-W0304/S022041	136.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st and 2nd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/203/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th main
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0201	2nd Crs	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0201/S022334	158.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 3rd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000060
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/202/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0292	NA	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0292/S022529	30.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 3rd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	152-11-000060
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/202/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0296	NA	AMARAVATHI HOTEL
SegmentNo	TotalLength	
152/S-W0296/S023002	69.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st and 2nd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/203/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0298	NA	BBMP OFFICE
SegmentNo	TotalLength	
152/S-W0298/S023451	39.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. SANTOSH		0.00
PhoneNo	EmailId	
9845089899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st and 2nd cross Maruthi Nagar in ward No.152 Suddaguntepalya	1000000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/203/11-12	08/09/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Cross road
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0001	1st Crs	ARUNODHAYA CHOULTRY
SegmentNo	TotalLength	
152/S-W0001/S024007	63.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.RAJANNA		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Bharathi nagar and Bhavani nagar and surrounding cross roads in ward no. 152	996000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/183/11-12	29/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		1st cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0005	3rd Crs	ARUNODHAYA CHOULTRY
SegmentNo	TotalLength	
152/S-W0005/S024841	71.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.RAJANNA		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Bharathi nagar and Bhavani nagar and surrounding cross roads in ward no. 152	996000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/183/11-12	29/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		3 rd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0003	2nd Crs	ARUNODHAYA CHOULTRY
SegmentNo	TotalLength	
152/S-W0003/S025034	67.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.RAJANNA		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Bharathi nagar and Bhavani nagar and surrounding cross roads in ward no. 152	996000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/183/11-12	29/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		2 nd cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0009	4th Crs	ARUNODHAYA CHOULTRY
SegmentNo	TotalLength	
152/S-W0009/S025652	123.68	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.RAJANNA		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Bharathi nagar and Bhavani nagar and surrounding cross roads in ward no. 152	996000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/183/11-12	29/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		4 th cross
Date of Inspection	Remarks	
11/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	152	Suddagunte Palya
StreetID	StreetName	Significant LandMark
W0013	5th Crs	ARUNODHAYA CHOULTRY
SegmentNo	TotalLength	
152/S-W0013/S033447	136.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.RAJANNA		0.00
PhoneNo	EmailId	
9844192235		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at Bharathi nagar and Bhavani nagar and surrounding cross roads in ward no. 152	996000	2010-11
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		152-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE/BTM/JE/WO/183/11-12	29/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		5 th cross
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	