



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0108, W0107, W0113, W0111, W0101, W0103, W0105	5th Crs Jayanagar 1st Block Rd, NA, 10th D Main Rd, 10th Crs, 10th A Main Rd, 10th B Main Rd, 10th C	Jayanagara 1st Block
SegmentNo	TotalLength	
153/S-W0108/S10237	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G. V Gopal Reddy		1802281.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providingdrain to 5th Cross (E/S) in Jayanagar 1st Block	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providingdrain to 5th Cross (E/S) in Jayanagar 1st Block	153-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/73/11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0106	4th Crs 1st Block Jayanagar	Jayanagara 1st Block
SegmentNo	TotalLength	
153/S-W0106/S10290	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Bhaskar Reddy		1718427.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing drain to 4th cross in jayanagara 1st Block	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing drain to 4th cross in jayanagara 1st Block.	153-11-000053
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/71/11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
22/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0148	2nd Crs Someshwara Nagara	Tippu School
SegmentNo	TotalLength	
153/S-W0148/S10867	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Nagaraj. T		443791.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction CC Roads and L Shape drain in Someshwara Nagara 2nd Cross	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Roads And Drain
Tender	WorkDetails	Job No Work Code
Tender	Construction CC Roads and L Shape drain in Someshwara Nagara 2nd Cross.	153-11-000014
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)PR/79/10-11	03/04/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
03/04/2011	03/04/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
13/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0106	4th Crs 1st Block Jayanagar	Ashoka Pillar Circle,Jayanagar 1st Block
SegmentNo	TotalLength	
153/S-W0106/S10906	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri. G.V Gopal Reddy		1754592.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing drain to 4th Cross (E/S) in jayanagar 1st Block	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing drain to 4th Cross (E/S) in jayanagar 1st Block .	153-11-000054
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/72/11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0104	3rd Crs 1st Block Jayanagar	Ashoka Pillar 1st block Jayanagar
SegmentNo	TotalLength	
153/S-W0104/S10516	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri. G.V Gopal Reddy		1701572.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing drain to cross(W/S) in jayangara 1st Block	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing drain to cross(W/S) in jayangara 1st Block.	153-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/70/11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0104	3rd Crs 1st Block Jayanagar	Ashoka pillar 1st Block Jayanagar
SegmentNo	TotalLength	
153/S-W0104/S10722	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Bhaskar Reddy. G		1696430.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing drain to 3rd Cross (E/S) In jayanagar 1st Block	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing drain to 3rd Cross (E/S) In jayanagar 1st Block.	153-11-000056
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/74/11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0027	Kazi Rd	Basavanagudi
SegmentNo	TotalLength	
153/S-W0027/S10728	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Dinesh		440286.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC Roads and L Shape Drain in Khazi Road	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	CC Roads And Drain
Tender	WorkDetails	Job No Work Code
Tender	Construction of CC Roads and L Shape Drain in Khazi Road.	153-11-000012
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/86/10-11	03/04/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
03/04/2011	03/04/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
12/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0047	Dasara Colony	Dasara Clolny
SegmentNo	TotalLength	
153/S-W0047/S10729	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. R. Rudra Prasad		619230.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC Roads of Dasara Colony Jayanagar 2nd Block	7000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of CC Roads of Dasara Colony Jayanagar 2nd Block .	153-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)Wo/321/11-12	07/03/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
13/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0240	2nd Main Rd Bhel Lyt	2nd Main Rd BHEL Lyt
SegmentNo	TotalLength	
153/S-W0240/S13535	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. P. Govindaswamy		1267220.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain in BHEL Layout	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain in BHEL Layout.	153-11-000043
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/96/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
14/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0259	1st A Crs	BHEL Lyt
SegmentNo	TotalLength	
153/S-W0259/S13540	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. P. Govindaswamy		1267220.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain in BHEL Layout	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain in BHEL Layout.	153-11-000043
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/96/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0259, W0261, W0281, W0257, W0279, W0277, W0244	Ambedkar Nagar Slum, NA	Near Chicken County
SegmentNo	TotalLength	
153/C-W0259/S012921	234.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dashathrami reddy		0.00
PhoneNo	EmailId	
9036090277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC drain at BHEL Officers Layout main road Northern side in ward no 153	1825000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing RCC drain at BHEL Officers Layout main road Northern side in ward no 153	153-14-000007
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/134/13-14	13/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at bhel layout northern side
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0259, W0261, W0281, W0257, W0279, W0277, W0244	Ambedkar Nagar Slum, NA	Chicken County
SegmentNo	TotalLength	
153/C-W0259/S013553	234.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dasharath rami reddy		0.00
PhoneNo	EmailId	
9036090277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC drain at BHEL Officers Layout main road Southern side in ward no 153	1825000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing RCC drain at BHEL Officers Layout main road Southern side in ward no 153	153-14-000008
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/132/13-14	13/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		providing rcc drain at bhel layout southern side i
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0195, W0198, W0200, W0206, W0202, W0208, W0204	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Tilak nagar main road
SegmentNo	TotalLength	
153/C-W0195/S045656	108.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dasharath rami reddy		0.00
PhoneNo	Emailld	
9036090277		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC drain and Cement concrete to roads at BTB Area 27th main from 30th cross to SWD in ward 153	1950000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		153-14-000006
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/171/13-14	28/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		providing cc drain and concrete road at 27th main
Date of Inspection	Remarks	
17/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0262, W0235, W0237, W0264	2nd Crs, NA, Slum Rd, 1st Crs	Gulbarga Slum
SegmentNo	TotalLength	
153/S-W0262/S35063	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dilip Kumar N		574397.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Sanitary Lines, CC road and L shape drain to Gulbarga Slum in ward no- 153	1495000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	CC Rd
Tender	WorkDetails	Job No Work Code
Tender	Providing Sanitary Lines, CC road and L shape drain to Gulbarga Slum in ward no- 153	153-11-000020
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/112/10-11	13/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/03/2011	13/03/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
12/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0216, W0189, W0193, W0183, W0181	StreetName 1st Main Rbi Colony Rd, 3rd Crs Rbi Colony, 4th Crs Rbi Colony, NA, 2nd Crs Rbi Colony	Significant LandMark BTB Area RBI Colony cross roads
SegmentNo 153/S-W0216/S32357	TotalLength 0.00	
ContractorDetails		
NameofContractor K R KUMAR	ContractorRegNo	Expenditure 1445585.00
PhoneNo	EmailId	
Work Details		
NameOfWork Impts to drain, culverts and retaining wall to BTB Area RBI colony in ward no - 62	Sanctioned Amount 1500000	Sanctioned Year 2010
Year 2009 - 2010	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Impts to drain, culverts and retaining wall to BTB Area RBI colony in ward no - 62	Job No Work Code 110-10-NGEC-IM-001
Work OrderNo EE/JNR/WO/24/09-10	Work Order Date 17/08/2009	Period of Extention 90Days
Defect Liability Period From 17/08/2009	Defect Liability Period To 17/08/2010	Multiple Road Involved Yes
Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 21/11/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0045, W0043, W0028, W0037, W0039, W0041	StreetName NA, Om Shakthi Lyt, 9th Crs	Significant LandMark RV teachers college
SegmentNo 153/C-W0045/S045006	TotalLength 678.90	

ContractorDetails		
NameofContractor Mahesh V T	ContractorRegNo	Expenditure 0.00
PhoneNo 9886827056	EmailId	

Work Details		
NameOfWork Improvements to drain at acharya layout in ward no-153	Sanctioned Amount 3200000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drain at acharya layout in ward no-153	Job No Work Code 153-14-000054
Work OrderNo ee/ckp/wo/22/14-15	Work Order Date 04/06/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 02/02/2016	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0135, W0126, W0141, W0139, W0124	NA	Post office road
SegmentNo	TotalLength	
153/C-W0135/S112501	239.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J Sunil		0.00
PhoneNo	EmailId	
9845999123		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 10th main from 9th cross to 7th cross 1st block Jayanagar in ward 153	1900000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drains at 10th main from 9th cross to 7th cross 1st block Jayanagar in ward 153	153-14-000020
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/50/14-15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
05/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0101, W0129, W0122, W0103, W0110, W0105	StreetName Om Shakthi Lyt 1st Crs, NA	Significant LandMark ABC park
SegmentNo 153/C-W0101/S113439	TotalLength 254.86	

ContractorDetails		
NameofContractor J Sunil	ContractorRegNo	Expenditure 0.00
PhoneNo 9845999123	EmailId	

Work Details		
NameOfWork Improvements to road side drains to 6th cross eastern side from 10th main to ABC park, 1st block Jayanagar in ward 153	Sanctioned Amount 1900000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type
Tender Tender	WorkDetails Improvements to road side drains to 6th cross eastern side from 10th main to ABC park, 1st block Jayanagar in ward 153	Job No Work Code 153-14-000022
Work OrderNo ee/ckp/wo/54/14-15	Work Order Date 03/07/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
05/02/2016	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0048	13th Crs	13th cross, 11th A Cross
SegmentNo	TotalLength	
153/S-W0048/S043328	87.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Muddneme Gowda		0.00
PhoneNo	EmailId	
9900626664		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to road side drains at 13th cross and 11th A cross from 7th main to RV Road, 2nd block Jayanagara in ward no - 153	2275000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Impts to road side drains at 13th cross and 11th A cross from 7th main to RV Road, 2nd block Jayanagara in ward no - 153	153-14-000044
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/20/14-15	04/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/08/2014	31/08/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0119, W0123, W0117, W0108	StreetName NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Significant LandMark Rajaprakruthi appartment
SegmentNo 153/C-W0119/S034850	TotalLength 159.96	



ContractorDetails		
NameofContractor AFZAL pASHA	ContractorRegNo CBS/C1/CIVIL/326/2015	Expenditure 1408200.00
PhoneNo 9742855442	EmailId	

Work Details		
NameOfWork Improvements to drain at 10th E main from 5th cross to 4th cross 1st block Jayanagar in ward no 153	Sanctioned Amount 1500000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drain at 10th E main from 5th cross to 4th cross 1st block Jayanagar in ward no 153	Job No Work Code 153-15-000010
Work OrderNo EE/CKP/WO/103/14-15	Work Order Date 24/11/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
17/12/2015	completed	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0101	Om Shakthi Lyt 1st Crs	GIRIAS INVESTMENT
SegmentNo	TotalLength	
153/S-W0101/S040238	232.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFZAL PASHA		0.00
PhoneNo	EmailId	
9742855442		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain from 10th a main from 6th cross to 5th cross 1st block Jayanagar in ward 153	2400000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain from 10th a main from 6th cross to 5th cross 1st block Jayanagar in ward 153	153-15-000008
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/94/14-15	17/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
17/12/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0130, W0137, I0008	NA	Madhavan park
SegmentNo	TotalLength	
153/C-W0130/S044517	159.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFZAL PASHA		1404100.00
PhoneNo	EmailId	
9742855442		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Madhavrao park 1st block jayanagar in ward 153	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Madhavrao park 1st block jayanagar in ward 153	153-15-000017
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/102/14-15	14/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
17/12/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0029, W0010	NA	TRINITY HOSPITAL
SegmentNo	TotalLength	
153/C-W0029/S045859	149.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFZAL PASHA		0.00
PhoneNo	EmailId	
9742855442		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN OF MAMADAN BLOCK IN BASAVANAGUDI IN WARD 153	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN OF MAMADAN BLOCK IN BASAVANAGUDI IN WARD 153	153-11-000045
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/76/14-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
17/12/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0195, W0173, W0165, W0191, W0163, M0144, W0199, M	28th B Main, NA, NA, 28th A Main Rd, 26th Main Rd, 30th Crs Bda Jayanagar, 30th D Crs, 8th Main Rd,	Bannerghatta Road
SegmentNo	TotalLength	
153/S-W0195/S34675	1400.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.L.MUNIRAJU		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Bannerghatta road to Byrasandra 8th man road in ward no - 62	5000000	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Providing asphaltting to Bannerghatta road to Byrasandra 8th man road in ward no - 62	110-10-MGER-AS-003
Work OrderNo	Work Order Date	Period of Extention
EE/JN/WO/53/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
21/11/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0203, W0208, W0199	NA, 30th A Crs, 30th D Crs	Bannerghatta road
SegmentNo	TotalLength	
153/S-W0203/S32373	56.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B K KESHVAMURTHY		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to f/p of 30th cross of Jayanagara from BG road to 8th main Byrasandra road N/s in ward no - 62	0	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Others	F/b
Tender	WorkDetails	Job No Work Code
Tender	Impts to f/p of 30th cross of Jayanagara from BG road to 8th main Byrasandra road N/s in ward no - 62	062-09-MSER-IM-001
Work OrderNo	Work Order Date	Period of Extention
EE/JNR/135/08-09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0266, W0269, W0273, W0268, W0271	NA, 2nd Crs Changaiah Compound, NA, NA, NA	BTB Area
SegmentNo	TotalLength	
153/S-W0266/S35070	70.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Chame Gowda		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing water supply line in BTB slum in ward no - 62	500000	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Others	Water supply
Tender	WorkDetails	Job No Work Code
Tender	Providing water supply line in BTB slum in ward no - 62	112-10-NWBU-WU-0002
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0130, W0141	NA, 9th Crs	9th main jaynagara
SegmentNo	TotalLength	
153/C-W0130/S35085	80.00	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S MALLIKARJUN		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to r/s drain of 9th a main road b/w 9th cross and 15th cross in 2dn blk jay in ward no - 50	1000000	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Others	CC
Tender	WorkDetails	Job No Work Code
Tender	Impts to r/s drain of 9th a main road b/w 9th cross and 15th cross in 2dn blk jay in ward no - 50	050-09-MSED-IM-010
Work OrderNo	Work Order Date	Period of Extention
EE/JNR/WO/60/09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		mohan
Date of Inspection	Remarks	
04/06/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0032	9th Crs	jayanagar 2nd block
SegmentNo	TotalLength	
153/S-W0032/S35106	92.00	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Mallikarjun		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to road side and footpath from 9th cross road to 15th cross 9th main road in 2nd block Jayanagara in ward no- 50	1200000	2009-10
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Impts to road side and footpath from 9th cross road to 15th cross 9th main road in 2nd block Jayanagara in ward no- 50	050-09-mged-im-002
Work OrderNo	Work Order Date	Period of Extention
EE/BG/WO/03-09-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
21/11/2015	

Category	Photo
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0140, W0142, W0157	NA, NA, NA	Someshwaranagara
SegmentNo	TotalLength	
153/S-W0140/S35119	68.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S ANIL		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC Box drain in Someshwaranagara main road from arch on R/s in ward no - 144	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing RCC Box drain in Someshwaranagara main road from arch on R/s in ward no - 144	144-11-00033
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/60/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0161, W0115, W0163, W0146, W0159	NA, 2nd A Main Rd, NA, 3rd Crs Someshwara Nagara, NA	sOMESHWARNAGARA
SegmentNo	TotalLength	
153/S-W0161/S35132	236.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SYED IBRAHIM		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPTS OF DRAINS OF SOMESHWARNAGARA 3RD CROSS IN WARD NO - 144	1000000	13-14
Year	Type of Work	Other Work Type
2013 - 2014	Others	RCC
Tender	WorkDetails	Job No Work Code
Tender	IMPTS OF DRAINS OF SOMESHWARNAGARA 3RD CROSS IN WARD NO - 144	144-13-000014
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/35/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parameshagowda
Date of Inspection	Remarks	
22/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0033, W0023, W0026, W0027, W0021	NA, NA, NA, Kazi Rd, NA	MNK Park
SegmentNo	TotalLength	
153/C-W0033/S35145	146.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
samrudhi Cons		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain and footpath on E/s of KR Road near MNK Park from BP Wadia road to Armugam Circle in ward no - 153	2000000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	rcc
Tender	WorkDetails	Job No Work Code
Tender	Impts to drain and footpath on E/s of KR Road near MNK Park from BP Wadia road to Armugam Circle in ward no - 153	153-12-000010
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0018, W0015	NA, R R Rd	MNK Park Road
SegmentNo	TotalLength	
153/C-W0018/S35152	68.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
BHASKAR REDDY		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain and fooapth at KR Road W/s near MNK Park BP wadia road to Armugam circle in ward no - 153	0	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Others	RCC
Tender	WorkDetails	Job No Work Code
	Impts to drain and fooapth at KR Road W/s near MNK Park BP wadia road to Armugam circle in ward no - 153	153-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/339/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0159	NA	Someshnagara
SegmentNo	TotalLength	
153/S-W0159/S35209	23.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
asphalting to someshwaranagara crosses and Siddapura lalbagh crosses and surrounding roads in ward no - 144	0	2012-13
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Someshwanraangar and lalbagh crosses	144-13-000024
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
21/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0161, W0163, W0157, W0146, W0159	NA, NA, NA, 3rd Crs Someshwara Nagara, NA	Someshwaranagara main road
SegmentNo	TotalLength	
153/S-W0161/S35211	154.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N HARISH		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC box drain in Someshwaranagara main road in ward no - 144	2000000	2011-12
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing RCC box drain in Someshwaranagara main road in ward no - 144	144-11-000030
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/54/11-12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0150, W0163	1st Crs Someshwara Nagara, NA	Someshwaranagara
SegmentNo	TotalLength	
153/S-W0150/S35214	82.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B S ANIL		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC drain someshwaranagara main road from arch in ward no - 144	2000000	2011-12
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	someshwaramangara main road near arch	144-11-000031
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/58/10-11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
24/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0135	NA	Jayanagar 1st block
SegmentNo	TotalLength	
153/S-W0135/S123616	345.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3		0.00
PhoneNo	EmailId	
9448494352		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to 7th cross from 10th main to dead end 1st block jayanagar in ward no 153	3500000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		153-14-000023
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/47/14-15	03/07/2014	NO
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/09/2014	30/09/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 7th cross in ward no 153
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0101	Om Shakthi Lyt 1st Crs	Jayanagar 1st block
SegmentNo	TotalLength	
153/S-W0101/S125751	147.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.N JANARDHAN		0.00
PhoneNo	EmailId	
9880364596		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 10th A main from 4th cross to 5th cross 1st block jayanagar in ward no 153	1550000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		153-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/135/13-14	13/12/2013	120DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/07/2014	28/07/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 10 th a main in ward no 1
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0113	3rd Crs	Jayanagar 1st block
SegmentNo	TotalLength	
153/S-W0113/S010659	163.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B N Janardhan		0.00
PhoneNo	EmailId	
9880364596		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 10th D main from 4th cross to 5th cross 1st block Jayanagar, in ward no 153	1700000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		153-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/133/13-14	13/12/2013	120DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/07/2014	31/07/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 10 th d main in ward no 1
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0246	NA	BHEL layout
SegmentNo	TotalLength	
153/S-W0246/S011422	103.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B N JANARDHAN		0.00
PhoneNo	EmailId	
9880364596		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st main, 1st cross of BHEL officers layout in ward no 153	900000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		153-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/136/13-14	13/12/2013	120DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/07/2014	31/07/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 1 at main krishnappa gard
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0029, M0128, W0033, W0015, W0019, W0027	Sri Ramamandira Rd, Dewan Madhavarao Rd, NA, R R Rd, NA, Kazi Rd	Basavangudi
SegmentNo	TotalLength	
153/S-W0029/S23100	113.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. G.R Somashekar		637953.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Cross Roads in Basavangudi	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	C C Roads
Tender	WorkDetails	Job No Work Code
Tender	Improvements To Cross Roads in Basavangudi.	153-11-000044
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/97/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Prasad
Date of Inspection	Remarks	
19/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0029, M0128, W0024, W0027	StreetName Sri Ramamandira Rd, Dewan Madhavarao Rd, NA, Kazi Rd	Significant LandMark Basavangudi
SegmentNo 153/S-W0029/S23101	TotalLength 48.00	

ContractorDetails		
NameofContractor Sri. G.R Somashekar	ContractorRegNo	Expenditure 637953.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements To Cross Roads in Basavangudi.	Sanctioned Amount 1500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type C C Roads
Tender Tender	WorkDetails Improvements To Cross Roads in Basavangudi.	Job No Work Code 153-11-000044
Work OrderNo EE(CKP)WO/97/11-12	Work Order Date	Period of Extention 60 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 2	Other Information	Name Prasad
Date of Inspection 20/11/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0018, W0007, W0020, W0022	StreetName NA, Church Rd, NA, NA	Significant LandMark Basavangudi
SegmentNo 153/S-W0018/S23103	TotalLength 67.00	

ContractorDetails		
NameofContractor Sri. G.R Somashekar	ContractorRegNo	Expenditure 637953.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements To Cross Roads in Basavangudi	Sanctioned Amount 1500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type C C Roads
Tender Tender	WorkDetails Improvements To Cross Roads in Basavangudi.	Job No Work Code 153-11-000044
Work OrderNo EE(CKP)WO/97/11-12	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 1	Other Information	Name Prasad
Date of Inspection 20/11/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0195, W0198, W0189, W0193, W0184, W0197, W0186, W	28th B Main, NA, 3rd Crs Rbi Colony, 4th Crs Rbi Colony, 2nd B Crs, 30th C Crs, 2nd B Crs, 28th A Ma	RBI Colony
SegmentNo	TotalLength	
153/S-W0195/S24259	160.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K S Mylegowda		1534400.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Byrasandra Tank Bed Pathway	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Byrasandra Tank Bed Pathway	153-11-000049
Work OrderNo	Work Order Date	Period of Extention
EE(CKP) W0/140/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	Parmesh gowda
Date of Inspection	Remarks	
19/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0195, W0206, W0208, W0191	StreetName 28th B Main, 30th B Crs, 30th A Crs, 28th A Main Rd	Significant LandMark RBI Colony
SegmentNo 153/S-W0195/S24649	TotalLength 56.00	




ContractorDetails		
NameofContractor K S Mylegowda	ContractorRegNo	Expenditure 1534400.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to Byrasandra Tank Bed Pathway	Sanctioned Amount 2000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to Byrasandra Tank Bed Pathway.	Job No Work Code 153-11-000049
Work OrderNo EE(CKP) W0/140/11-12	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 21/11/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0073, W0045, W0331, W0098, W0071	StreetName 3rd Main Rd, 1st Main Rd, NA, 3rd Crs 1st Block Jayanagar, 2nd Main Rd	Significant LandMark Ashoka Piller, Kanakana Palya
SegmentNo 153/S-W0073/S25095	TotalLength 517.00	

ContractorDetails		
NameofContractor Sri Prakash Babu	ContractorRegNo	Expenditure 1702175.00
PhoneNo	Emailld	

Work Details		
NameOfWork Improvements to footbath	Sanctioned Amount 2000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Footpath Layering	Other Work Type
Tender Tender	WorkDetails Improvements to footbath	Job No Work Code 153-11-000071
Work OrderNo EE(CkP)WO/128/11-12	Work Order Date	Period of Extention 90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name parameshagowda
Date of Inspection 25/03/2014	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0141, W0004, W0147, W0008	StreetName 9th Crs, NA, NA, NA	Significant LandMark 9th Cross Rd
SegmentNo 153/S-W0141/S25100	TotalLength 210.00	

ContractorDetails		
NameofContractor M. Srinivas	ContractorRegNo	Expenditure 540379.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvement to Mountain Road in 1st Block	Sanctioned Amount 1500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Roads
Tender Tender	WorkDetails Improvement to Mountain Road in 1st Block.	Job No Work Code 153-11-000046
Work OrderNo EE(CKP)WO/75/11-12	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name Parmesh gowda
Date of Inspection 19/03/2014	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0175, W0216, W0189, W0193, W0177, W0179, W0183, W	NA, 1st Main Rbi Colony Rd, 3rd Crs Rbi Colony, 4th Crs Rbi Colony, NA, 1st Crs Rbi Colony, NA, 2nd	Rbi Colony
SegmentNo	TotalLength	
153/S-W0175/S26250	172.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. G,P Prakash		615490.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Construction of culverts in RBI Colony	1060000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Culverts
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain and Construction of culverts in RBI Colony.	153-11-000015
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/107/10-11	08/03/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/03/2011	08/03/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
19/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0179	StreetName 1st Crs Rbi Colony	Significant LandMark RBI Colony
SegmentNo 153/S-W0179/S26252	TotalLength 150.00	

ContractorDetails		
NameofContractor Sri. G,P Prakash	ContractorRegNo	Expenditure 615490.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to Drain and Construction of culverts in RBI Colony	Sanctioned Amount 1060000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Drain & Culverts
Tender Tender	WorkDetails Improvements to Drain and Construction of culverts in RBI Colony.	Job No Work Code 153-11-000015
Work OrderNo EE(CKP)WO/107/10-11	Work Order Date 08/03/2011	Period of Extention 60 Days
Defect Liability Period From 08/03/2011	Defect Liability Period To 08/03/2012	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 3	Other Information	Name Paramesh Gowda
Date of Inspection 19/11/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0181, W0182	2nd Crs Rbi Colony, NA	RBI Colony
SegmentNo	TotalLength	
153/S-W0181/S26257	134.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. G,P Prakash		615490.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Construction of culverts in RBI Colony	1060000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Culverts
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain and Construction of culverts in RBI Colony.	153-11-000015
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/107/10-11	08/03/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/03/2011	08/03/2011	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		Paramesh Gowda
Date of Inspection	Remarks	
19/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0189, W0182	3rd Crs Rbi Colony, NA	RBI Colony
SegmentNo	TotalLength	
153/S-W0189/S26259	129.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. G,P Prakash		615490.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Construction of culverts in RBI Colony	1060000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Culverts
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain and Construction of culverts in RBI Colony.	153-11-000015
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/107/10-11	08/03/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/03/2011	08/03/2011	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		Paramesh Gowda
Date of Inspection	Remarks	
19/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0193, W0197, W0182	4th Crs Rbi Colony, 30th C Crs, NA	RBI Colony
SegmentNo	TotalLength	
153/S-W0193/S26260	122.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. G,P Prakash		615490.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and Construction of culverts in RBI Colony	1060000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & Culverts
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain and Construction of culverts in RBI Colony.	153-11-000015
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/107/10-11	08/03/2011	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/03/2011	08/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		Paramesh Gowda
Date of Inspection	Remarks	
19/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0195, W0214, W0212, W0206, W0197, W0208, W0204	StreetName 28th B Main, NA, NA, 30th B Crs, 30th C Crs, 30th A Crs, NA	Significant LandMark RBI Colony
SegmentNo 153/S-W0195/S26276	TotalLength 161.00	

ContractorDetails		
NameofContractor Sri. K Prakash Babu	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing RCC Drain	Sanctioned Amount 1500000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Providing RCC Drain .	Job No Work Code 153-13-000006
Work OrderNo EE(CKP)WO/08/13-14	Work Order Date	Period of Extention 90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name M santhosh kumar
Date of Inspection 21/03/2014	Remarks incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0039, W0045, W0043, W0041, W0028, W0037, M0163	StreetName NA, 1st Main Rd, NA, 2nd Crs, 2nd Crs, NA, Rashtriya Vidyalaya Rd	Significant LandMark 1st Block Jayangra
SegmentNo 153/S-W0039/S26350	TotalLength 147.00	

ContractorDetails		
NameofContractor Sunil. J	ContractorRegNo	Expenditure 0.00
PhoneNo	Emailld	

Work Details		
NameOfWork Improvments Of Drains	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type Improvments Of Drain
Tender	WorkDetails Improvments Of Drains	Job No Work Code 153-13-000012
Work OrderNo EE(CKP)/WO/34/13-14	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name Sandeep
Date of Inspection 20/03/2014	Remarks incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0082, W0071	1st A Crs, 2nd Main Rd	3rd Cross 1st block Jayanagra
SegmentNo	TotalLength	
153/S-W0082/S26360	92.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.V. Gopal Reddy		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road Drians Footh	1600000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	Roads, Drain & Footpath
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Road Drians Footh	153-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/44/2011-12	05/04/2012	120 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/04/2012	05/04/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0004	K R Rd	Basavanagudi
SegmentNo	TotalLength	
153/S-W0004/S26397	317.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Sunil.J		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Road Side Drain St North Squire Southern Side Basavanagudi	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	Drain & Footbath
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Road Side Drain St North Squire Southern Side Basavanagudi.	153-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/33/13-14		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandeep
Date of Inspection	Remarks	
20/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0266, W0269, W0273, W0268, W0267, W0275, W0271, W	NA, 2nd Crs Changaiah Compound, NA, NA, 1st Crs, NA, NA, NA	Sri Krishnappa Garden
SegmentNo	TotalLength	
153/S-W0266/S27471	207.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads In Krishnappa Garden	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Road Improvements
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Roads In Krishnappa Garden	153-11-000042
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/146/2011-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
22/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0266, W0269, W0271	StreetName NA, 2nd Crs Changaiah Compound, NA	Significant LandMark Sri Krishnappa Garden
SegmentNo 153/S-W0266/S27495	TotalLength 33.00	

ContractorDetails		
NameofContractor M. Ramesh	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to Roads In Krishnappa Garden	Sanctioned Amount 1500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Road Improvements
Tender Tender	WorkDetails Improvements to Roads In Krishnappa Garden	Job No Work Code 153-11-000042
Work OrderNo EE(CKP)/WO/146/2011-12	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name M.Santhosh kumar
Date of Inspection 20/11/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0266, W0273, W0268	NA, NA, NA	Sri Krishnappa Garden
SegmentNo	TotalLength	
153/S-W0266/S27497	33.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads In Krishnappa Garden	1500000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	Road Improvements
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Roads In Krishnappa Garden	153-11-000042
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/146/2011-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.Santhosh kumar
Date of Inspection	Remarks	
20/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0268, W0275	NA, NA	Sri Krishnappa Garden
SegmentNo	TotalLength	
153/S-W0268/S27499	42.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads In Krishnappa Garden	1500000	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	Road Improvements
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Roads In Krishnappa Garden	153-11-000042
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/146/2011-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		M.Santhosh kumar
Date of Inspection	Remarks	
20/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0231, W0210	NA, NA	Vinayaka GAS Agency
SegmentNo	TotalLength	
153/S-W0231/S27500	81.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J. Sunil		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Roads to Behind Krishna Garden	1000000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	CC Rods
Tender	WorkDetails	Job No Work Code
Tender	Providing CC Roads to Behind Krishna Garden	153-12-000019
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/23/2012-13	05/02/2012	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/02/2012	05/02/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
20/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0243, W0252, W0240, W0239	StreetName 4th Crs, NA, 2nd Main Rd Bhel Lyt, NA	Significant LandMark Church
SegmentNo 153/S-W0243/S27513	TotalLength 107.00	

ContractorDetails		
NameofContractor J Sunil	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing CC Roads to Behind Krishna Garden	Sanctioned Amount 1000000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type CC Roads
Tender Tender	WorkDetails Providing CC Roads to Behind Krishna Garden	Job No Work Code 153-12-000019
Work OrderNo EE(CKP)/WO/23/2012-13	Work Order Date 05/02/2012	Period of Extention 60 Days
Defect Liability Period From 05/02/2012	Defect Liability Period To 05/02/2013	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 21/11/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0228, W0243, W0241, W0238, W0239	NA, 4th Crs, NA, 3rd Main Rd B H E L Lyt, NA	Rajanna Layout
SegmentNo	TotalLength	
153/S-W0228/S27514	137.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J. Sunil		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing CC Roads to Behind Krishna Garden	0	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	CC Roads
Tender	WorkDetails	Job No Work Code
Tender	Providing CC Roads to Behind Krishna Garden	153-12-000019
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/23/2012-13	05/02/2012	60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/02/2012	05/02/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0190, W0198, W0194, W0208, W0191, W0192, W0188	1st Crs 8th Main, NA, 30th A Crs, 30th A Crs, 28th A Main Rd, 30th B Crs, 2nd Crs 8th Main Rd	Rbi Colony
SegmentNo	TotalLength	
153/S-W0190/S27545	115.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dharashatah Rami Reddy.K		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain CC Roads	1600000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	Roads & Drains
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain CC Roads	153-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/47/2011-12	05/04/2012	120 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/04/2012	05/04/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
21/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0195, W0198, W0200, W0206, W0202, W0197, W0186, W	28th B Main, NA, 30th D Crs, 30th B Crs, 30th C Crs, 30th C Crs, 2nd B Crs, 30th A Crs, 2nd A Crs, N	Rbi Colony
SegmentNo	TotalLength	
153/S-W0195/S27550	161.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dharashatah Rami Reddy.K		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain CC Roads	1600000	2012
Year	Type of Work	Other Work Type
2010 - 2011	Others	Drain & CC Roads
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain CC Roads	153-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/47/2011-12	05/04/2012	120 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/04/2012	05/04/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0212, W0208, W0199	NA, 30th A Crs, 30th D Crs	Rbi Colony
SegmentNo	TotalLength	
153/S-W0212/S27553	64.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Dharashatah Rami Reddy.K		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain CC Roads	1600000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	CC Roads, Drain
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drain CC Roads	153-12-000012
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/47/2011-12	05/04/2012	120 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/04/2012	05/04/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0105, W0104, W0071, W0099	10th C Main Rd, 3rd Crs 1st Block Jayanagar, NA, NA	VTU School
SegmentNo	TotalLength	
153/S-W0105/S27556	293.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.V. Gopal Reddy		1701572.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Drain to Cross W/S in Jayanagra	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain
Tender	WorkDetails	Job No Work Code
Tender	Providing Drain to Cross W/S in Jayanagra	153-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/70/2011-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0128, W0130, W0141, W0004, W0147, W0126, W0008	7th Crs, NA, 9th Crs, NA, NA, 10th Main, NA	9th Cross Rd
SegmentNo	TotalLength	
153/S-W0128/S27562	285.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Yogananda		1289924.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements To Drains And RCC deck Slab	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain & deck Slab
Tender	WorkDetails	Job No Work Code
Tender	Improvements To Drains And RCC deck Slab	153-11-000047
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/104/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
22/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0029, W0018, W0016, W0033, W0015, W0019, M0163	StreetName Sri Ramamandira Rd, NA, NA, NA, R R Rd, NA, Rashtriya Vidyalaya Rd	Significant LandMark Church
SegmentNo 153/S-W0029/S31054	TotalLength 202.00	

ContractorDetails		
NameofContractor R. Venkatesh	ContractorRegNo	Expenditure 909980.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing CC Roads	Sanctioned Amount 1000000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type CC Roads
Tender Tender	WorkDetails Providing CC Roads	Job No Work Code 153-12-000025
Work OrderNo EE(CKP)/WO/69/12-13	Work Order Date 05/09/2012	Period of Extention 90 Days
Defect Liability Period From 05/09/2012	Defect Liability Period To 09/05/2013	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name parameshagowda
Date of Inspection 22/03/2014	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0281, W0257, W0279, W0277, W0244	StreetName NA, NA, NA, NA, 1st Crs	Significant LandMark Provisional Store
SegmentNo 153/S-W0281/S31064	TotalLength 181.00	

ContractorDetails		
NameofContractor R. Rudra Prasad	ContractorRegNo	Expenditure 829034.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements To Drain From Krishna Garden	Sanctioned Amount 1000000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type Drain
Tender Tender	WorkDetails Improvements To Drain From Krishna Garden	Job No Work Code 153-12-000018
Work OrderNo EE(CKP)/PR/WO/17/2012-13	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information no	Name M santhosh kumar
Date of Inspection 22/03/2014	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0128, W0130, W0129, W0122, W0141, W0135, W0126, W	7th Crs, NA, 6th Crs 1st Block Jayanagar, 10th Main, 9th Crs, Jayanagar 1st Block 7th Crs, 10th Main	Jayanagara 1st Block
SegmentNo	TotalLength	
153/S-W0128/S31067	463.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. V T Mahesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing C C Roads Kerb Stones & Improvements to Drain in 9th Crs Road Up to 10th C Mn in Jayanagara 1st Block	1000000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing C C Roads Kerb Stones & Improvements to Drain in 9th Crs Road Up to 10th C Mn in Jayanagara 1st Block.	153-12-000014
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/97/11-12	06/08/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/08/2012	06/08/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
22/03/2014	incompleted	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0262, W0235, W0237, W0264, W0260, W0258, W0263	2nd Crs, NA, Slum Rd, 1st Crs, 3rd Crs, 4th Crs, NA	Krishnappa Garden
SegmentNo	TotalLength	
153/S-W0262/S31073	245.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri M Ramesh		1746140.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drains in Krishnappa Garden	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC drains in Krishnappa Garden.	153-11-000041
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/168/11-12		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	parameshagowda
Date of Inspection	Remarks	
22/03/2014	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0101, W0107, W0103, W0123, W0108, W0113, W0105, W	10th A Main Rd, NA, 10th B Main Rd, 6th Crs 1st Block Jayanagar, 5th Crs Jayanagar 1st Block Rd, 10t	Nursury End road
SegmentNo	TotalLength	
153/S-W0101/S31074	308.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.V. Gopal Reddy		1802281.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Drain	2000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain
Tender	WorkDetails	Job No Work Code
Tender	Providing Drain	153-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)/WO/73-11-12		90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0235, W0237, W0264, W0263	StreetName NA, Slum Rd, 1st Crs, NA	Significant LandMark Kishnappa Garden
SegmentNo 153/S-W0235/S31075	TotalLength 72.00	

ContractorDetails		
NameofContractor Sri M Ramesh	ContractorRegNo	Expenditure 1746140.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of RCC drains in Krishnappa Garden	Sanctioned Amount 2000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of RCC drains in Krishnappa Garden.	Job No Work Code 153-11-000041
Work OrderNo EE(CKP)WO/168/11-12	Work Order Date	Period of Extention 60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name Paramesh Gowda
Date of Inspection 19/11/2014	Remarks complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0264	1st Crs	Krishnappa Garden
SegmentNo	TotalLength	
153/S-W0264/S31079	73.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri. Sunil.J		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Drains in Krishnappa Garden	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements of Drains in Krishnappa Garden.	153-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/32/13/14		60 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0	no	M santhosh kumar
Date of Inspection	Remarks	
20/03/2014	incompleted	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0073, W0045, W0331, W0098, W0071	StreetName 3rd Main Rd, 1st Main Rd, NA, 3rd Crs 1st Block Jayanagar, 2nd Main Rd	Significant LandMark Ashoks Pillar
SegmentNo 153/S-W0073/S31132	TotalLength 522.00	

ContractorDetails		
NameofContractor Sri. K. Prakash Babu	ContractorRegNo	Expenditure 1613025.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to Footbath	Sanctioned Amount 2000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Footpath Layering	Other Work Type
Tender Tender	WorkDetails Improvements to Footbath.	Job No Work Code 153-11-000072
Work OrderNo EE(CKP)WO/129/11-12	Work Order Date	Period of Extention 90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 21/11/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0048, W0089	NA	14th cross Jayanagar 2nd block
SegmentNo	TotalLength	
153/S-W0048/S033951	205.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J Sunil		0.00
PhoneNo	EmailId	
9845999123		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 14th cross from 9th main to 7th main 2nd block Jayanagar in ward No 153	1150000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	drains maintaince	153-14-000043
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/53/14-15	03/09/2014	56DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	29/11/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 14 th cross
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0050	NA	12 th cross, jayanagar 2nd block
SegmentNo	TotalLength	
153/S-W0050/S034536	206.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J SUNIL		0.00
PhoneNo	EmailId	
9845999123		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 12th cross from 9th main to 7th main 2nd block jayanagar in ward No 153	1150000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	drain maintenance	153-14-000045
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/51/14-15	03/07/2014	56DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/11/2014	29/11/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 12 th cross
Date of Inspection	Remarks	
11/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0067, W0057, W0059, W0036, W0061, W0063, W0065, W	13th Crs, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Om Shakthi Lyt 7th Crs, Om S	13th cross Jayanagar 2nd block
SegmentNo	TotalLength	
153/S-W0067/S040104	426.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Muddneme Gowda		0.00
PhoneNo	EmailId	
9900626664		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 13th cross and 11th A cross from 7th main to RV road 2nd block Jayanagar in ward No 153	2275000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	drain maintenance	153-14-000044
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/20/14-15	04/06/2014	NO DELAY
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/08/2014	27/08/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
15/02/2016		
Category	Photo	
Drain Condition		
Footpath Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0107, W0123, W0108, W0113, W0115, W0111	StreetName Subhash Chandra Bose Lyt, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, 3rd Crs	Significant LandMark Asha Nursery
SegmentNo 153/C-W0107/S031230	TotalLength 102.34	



ContractorDetails		
NameofContractor Raghavendra	ContractorRegNo	Expenditure 0.00
PhoneNo 9845930585	EmailId	

Work Details		
NameOfWork Improvements to drains and footpath at 5th cross from 10th Cmain to Nursery Jayanagar 1st block in ward 153	Sanctioned Amount 1300000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drains and footpath at 5th cross from 10th Cmain to Nursery Jayanagar 1st block in ward 153	Job No Work Code 153-15-000014
Work OrderNo ee/ckp/wo/84/14-15	Work Order Date 03/11/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0269, W0267, W0274, W0263	NA, Maheshwari Nagar Ambedkar Rd, 2nd Crs, Maheshwari Nagar	Krishnappa garden
SegmentNo	TotalLength	
153/C-W0269/S032900	316.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Raghavendra		0.00
PhoneNo	EmailId	
9845930585		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 1st main north side Krishnappa garden in ward 153	1200000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain at 1st main north side Krishnappa garden in ward 153	153-15-000012
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/88/15-16	11/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
12/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0079, W0086, W0077, W0091, W0088	Om Shakthi Lyt 4th Crs, NA, Om Shakthi Lyt 3rd Crs	Muneshwara temple
SegmentNo	TotalLength	
153/C-W0079/S034003	397.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ragavendra		0.00
PhoneNo	EmailId	
9845930585		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains at Muneshwara swamy temple road and 1st cross of Kanakanapalya area Jayanagar 2nd block in ward 153	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drains at Muneshwara swamy temple road and 1st cross of Kanakanapalya area Jayanagar 2nd block in ward 153	153-14-000062
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/139/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0076, W0083, W0074, W0077, W0091, W0081, W0090, W	NA, Om Shakthi Lyt 3rd Crs, 14th Crs	Ranganatha swamy temple
SegmentNo	TotalLength	
153/C-W0076/S035718	680.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Raghavendra		0.00
PhoneNo	EmailId	
9845930585		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains at kanakanapalya area Jayanagar 2nd block in ward 153	4900000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drains at kanakanapalya area Jayanagar 2nd block in ward 153	153-14-000061
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/138/14-15	05/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
12/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0266, W0267	NA, 1st Crs	Acharaya Layout
SegmentNo	TotalLength	
153/C-W0266/S052759	96.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Maresh VT		0.00
PhoneNo	EmailId	
9886054523		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drain at Acharaya Lyt in Ward No-153	3200000	2013-14
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Impts to drain at Acharaya Lyt in Ward No-153 1st cross, 2nd cross, Andal Temple road	153-14-000054
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/22/13-14	04/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/08/2014	31/08/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandeep
Date of Inspection	Remarks	
20/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0076, W0073, W0072, W0080, W0054, W0050, W0066, W	StreetName NA	Significant LandMark Executive Engineer Chickpete division office road
SegmentNo 153/C-W0076/S010336	TotalLength 746.34	
ContractorDetails		
NameofContractor N Chethan kumar	ContractorRegNo	Expenditure 0.00
PhoneNo 9902067334	EmailId	
Work Details		
NameOfWork Improvements to drains and footpath at 7th main eastern side from 15th cross to kanakanapalya main road 2nd block, jayanagar in ward no 153	Sanctioned Amount 3645000	Sanctioned Year 2013-14
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails drain maintainace and footpath	Job No Work Code 153-14-000038
Work OrderNo EE/CKP/WO.NO/44/2014-15	Work Order Date 02/07/2014	Period of Extention NO
Defect Liability Period From 30/08/2014	Defect Liability Period To 30/08/2016	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		improvements to drain at 7 th main eastern side ka
Date of Inspection	Remarks	
11/03/2016		
Category	Photo	
Drain Condition		
Footpath Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0004	K R Rd	KR Road
SegmentNo	TotalLength	
153/C-W0004/S8177	0.00	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Chamundi Constructions		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of New Toilet at KR Road in ward no - 142	1000000	2010-11
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
Tender	Construction of New Toilet at KR Road in ward no - 142	113-10-NGERB-FO-001
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandeep
Date of Inspection	Remarks	
20/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0073, W0331, W0098	3rd Main Rd, NA, 3rd Crs 1st Block Jayanagar	rv TEACHES COLLEGE
SegmentNo	TotalLength	
153/C-W0073/S8349	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphaltting to Krishna road, BS ranoi rao road and Kanakanapalya main road	0	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Providing asphaltting to Krishna road, BS ranoi rao road and Kanakanapalya main road in ward no-143	143-12-000040
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		Nagaraj
Date of Inspection	Remarks	
14/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0274	StreetName 1st Main Rd Changaiah Compound	Significant LandMark Chengyya compound
SegmentNo 153/C-W0274/S8393	TotalLength 0.00	

ContractorDetails		
NameofContractor Sunil Jagadish	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing CC roads to behind Krishnappa Garden Ebebezer Church road and Changayya compound near Vinayaka Gas Agency in Ward No-153	Sanctioned Amount 1000000	Sanctioned Year
Year	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Providing CC roads to behind Krishnappa Garden Ebebezer Church road and Changayya compound near Vinayaka Gas Agency in Ward No-153	Job No Work Code 153-12-000019
Work OrderNo EE/CKP/WO/23/12-13	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/11/2015	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0082	1st A Crs	Jayanagara 1st block
SegmentNo	TotalLength	
153/S-W0082/S8396	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GOPAL REDDY		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to road drains and footpath in1st A cross Jayanagara 2nd block in ward no-153	1600000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
	Impts to road drains and footpath in1st A cross Jayanagara 2nd block in ward no-153	153-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/44/11-12	05/04/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0032, W0053, W0051, W0049, W0055	9th Crs, NA, NA, NA, NA	Jayanagara 1st block
SegmentNo	TotalLength	
153/S-W0032/S8399	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V.T.Mahesh		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing kerb stones and impts todrain in 9th cross road upto 10th c main in ward no - 153	0	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing kerb stones and impts todrain in 9th cross road upto 10th c main in ward no -153	153-12-000014
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/97/11-12	08/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0262	StreetName 2nd Crs	Significant LandMark Krishnappa Garden cross roads
SegmentNo 153/S-W0262/S8403	TotalLength 0.00	

ContractorDetails		
NameofContractor M.RAMESH	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Impts to roads in krishnappa garden layout in ward no-153	Sanctioned Amount 1500000	Sanctioned Year 2012-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Cross roads of Krishnappa Garden layout	Job No Work Code 153-11-000042
Work OrderNo EE/CKP/WO/146/11-12	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 21/11/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0204, W0214, W0212, W0206, W0197	NA, NA, NA, 30th B Crs, 30th C Crs	BTB AREA
SegmentNo	TotalLength	
153/S-W0204/S8412	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Prakash babu		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing RCC box drain in BTB area in ward no-153	1500000	2012-13
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	BTB Area	153-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/08/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0244, W0279, W0277, W0281, W0259	1st Crs, NA, NA, NA, 1st A Crs	Krishnappa garden
SegmentNo	TotalLength	
153/S-W0244/S8417	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SUNIL.J		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
impts of drains in krishnappa garden 1st cross in ward no- 153	1000000	2012-13
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	1ST CROSS OF KRISHNAPPA GARDEN	153-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/32/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0178	NA	Gulbarga slum
SegmentNo	TotalLength	
153/S-W0178/S8422	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Prakash Babu		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts of roads and dains in Gularga slum in ward no-153	1500000	2012-13
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Cross roads of Gulbarga slum	153-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/09/13-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0186, W0196, W0198, W0200, W0202, W0204, W0206, W	StreetName 2nd B Crs, 2nd A Crs, NA, 30th D Crs, 30th C Crs, NA, 30th B Crs, 30th A Crs, 28th B Main	Significant LandMark swagath main road
SegmentNo 153/S-W0186/S8428	TotalLength 0.00	
ContractorDetails		
NameofContractor dashratharami reddy	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	
Work Details		
NameOfWork Impts to drain and CC road from 26th main to 28th main cross roads in Jaibheemanagara in ward no- 153	Sanctioned Amount 1600000	Sanctioned Year 2012-13
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails cross roads of 26th main	Job No Work Code 153-12-000022
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0225	NA	Byrasandra tank bed road
SegmentNo	TotalLength	
153/S-W0225/S8431	0.00	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.P.PRAKASH		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to Byrasandra tank bed pathway from CH 0.00 to 200.00	2000000	2012-13
Year	Type of Work	Other Work Type
	Others	tank bed imots
Tender	WorkDetails	Job No Work Code
Tender	Impts to tank bed area byrasandra	153-11-000048
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0182, W0181, W0179, W0189	NA, 2nd Crs Rbi Colony, 1st Crs Rbi Colony, 3rd Crs Rbi Colony	Malayahali masjid
SegmentNo	TotalLength	
153/C-W0182/S8434	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Bhaskar reddy		0.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to road drains and footpath to malayahalli masjid road in adjacent to RBI COLONY in ward no-153	1900000	2012-13
Year	Type of Work	Other Work Type
	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		153-12-000027
Work OrderNo	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5	no	mohan
Date of Inspection	Remarks	
04/06/2014	completed	



Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
M0167	8th Main Rd, Bairasandra	Byrasandra junction
SegmentNo	TotalLength	
153/S-M0167/S8440	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Gopal reddy		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Impts to drainand footpath in swagath main road from 8th main byrasandra junction to Krishnappa Garden main road junction in ward no-153	0	2012-13
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
Tender		153-12-000020
Work OrderNo	Work Order Date	Period of Extention
EE/CKP/WO/45/12-13	05/04/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Sandeep
Date of Inspection	Remarks	
20/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0146, W0159, W0161, W0163	3rd Crs Someshwara Nagara, NA, NA, NA	Connecting to Someshwar Nagar
SegmentNo	TotalLength	
153/S-W0146/S8459	242.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Syed Ibrahim		981536.06
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Imp to drains	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		144-13-000014
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/35/13-14		60days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0152, W0146, W0150, W0148, W0090, W0096, W0092, W	NA, 3rd Crs Someshwara Nagara, 1st Crs Someshwara Nagara, 2nd Crs Someshwara Nagara, NA, 12th Crs, 1	Near Arch
SegmentNo	TotalLength	
153/S-W0152/S8473	809.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Satish		10795777.12
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting	9900000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		144-13-000025
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/12/13-14		90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		M.Santhosh kumar
Date of Inspection	Remarks	
18/11/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0182, W0181, W0179, W0189, W0193, W0197, W0191	NA, 2nd Crs Rbi Colony, 1st Crs Rbi Colony, 3rd Crs Rbi Colony, 4th Crs Rbi Colony, 30th C Crs, 28th	Rbi Colony
SegmentNo	TotalLength	
153/S-W0182/S9982	0.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri.Bhaskar Reddy		1711200.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Roads drains footbath to malayali masid road in adjacent to RBI Colony	1900000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	Drain and footbath
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Roads drains footbath to malayali masid road in adjacent to RBI Colony	153-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE(CKP)WO/42/12-13	05/04/2012	120 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/04/2012	05/04/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0235, W0229, W0231, W0203, W0199, W0173, W0001, W	StreetName NA, NA, NA, NA, 30th D Crs, NA, 28th Main Rd, East End Main Rd, 2nd Main Rd, 3rd Main Rd, 30th Crs B	Significant LandMark Canara Bank
SegmentNo 153/S-W0235/S9986	TotalLength 0.00	

ContractorDetails		
NameofContractor Sri. G V Gopal Reddy	ContractorRegNo	Expenditure 1709105.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvementa to drain footbath in nJaibeem Nagara swagath Main Road from 8th Main byasandra junction to kroshnappa garaden main road junction	Sanctioned Amount 1900000	Sanctioned Year 2012
Year 2011 - 2012	Type of Work Others	Other Work Type Drain and footbath
Tender Tender	WorkDetails Improvementa to drain footbath in nJaibeem Nagara swagath Main Road from 8th Main byasandra junction to kroshnappa garaden main road junction	Job No Work Code 153-12-000020
Work OrderNo EE(CKP)WO/45/12-13	Work Order Date 05/04/2012	Period of Extention 120 Days
Defect Liability Period From 05/04/2012	Defect Liability Period To 05/04/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		sandeep
Date of Inspection	Remarks	
21/11/2015		
Category	Photo	
Drain Condition		
Footpath Condition		




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0103	NA	Adigas hotel
SegmentNo	TotalLength	
153/S-W0103/S123945	220.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shivraj		0.00
PhoneNo	EmailId	
9448834119		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 10th B main from 6th cross 1st block Jayanagar in ward no 153	2400000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drain at 10th B main from 6th cross 1st block Jayanagar in ward no 153	153-15-000009
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/90/13-14	11/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
14/01/2016	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0106, W0119, W0117, W0113	StreetName NA, 3rd Crs	Significant LandMark ADIGAS HOTEL
SegmentNo 153/C-W0106/S125516	TotalLength 141.76	



ContractorDetails		
NameofContractor SHIVRAJ	ContractorRegNo	Expenditure 0.00
PhoneNo 9448834119	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN AT 3RD CROSS 10TH C MAIN TO RAJA PRAKRUTHI APPARTMENT 1ST BLOCK JAYANAGAR IN WARD 153	Sanctioned Amount 1500000	Sanctioned Year 2011
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails IMPROVEMENTS TO DRAIN AT 3RD CROSS 10TH C MAIN TO RAJA PRAKRUTHI APPARTMENT 1ST BLOCK JAYANAGAR IN WARD 153	Job No Work Code 153-15-000011
Work OrderNo EE/CKP/WO/91/13-14	Work Order Date 11/11/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
14/01/2016	completed	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	153	Jayanagara
StreetID	StreetName	Significant LandMark
W0072, W0093, W0110	NA, 15th Crs	Community center
SegmentNo	TotalLength	
153/C-W0072/S121958	575.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sampanna satish		1010100.00
PhoneNo	EmailId	
9448040740		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and footpath to 9th main western side from 4th cross to 15th cross and 4th cross kanakanapalya 2nd block jayanagar in ward no 1	5000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to drains and footpath to 9th main western side from 4th cross to 15th cross and 4th cross kanakanapalya 2nd block jayanagar in ward no 153	153-14-000018
Work OrderNo	Work Order Date	Period of Extention
ee/ckp/wo/29/14-15	21/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5	completed	sandeep
Date of Inspection	Remarks	
14/01/2016	completed	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0072, W0093, W0110	StreetName NA, 15th Crs	Significant LandMark Community college
SegmentNo 153/C-W0072/S122607	TotalLength 521.75	

ContractorDetails		
NameofContractor Sampanna Satish	ContractorRegNo	Expenditure 1485400.00
PhoneNo 9448040740	EmailId	

Work Details		
NameOfWork Improvements to drains and footpath to 9th main eastern side from 4th cross to 15th cross kanakanapalya 2nd block jayanagar in ward no 153	Sanctioned Amount 5000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drains and footpath to 9th main eastern side from 4th cross to 15th cross kanakanapalya 2nd block jayanagar in ward no 153	Job No Work Code 153-14-000019
Work OrderNo ee/ckp/wo/30/14-15	Work Order Date 21/06/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		sandeep
Date of Inspection	Remarks	
14/01/2016	completed	

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 153	WardName Jayanagara
StreetID W0053, W0032, W0051, W0055, W0071, W0049	StreetName NA, Om Shakthi Lyt 8th Crs	Significant LandMark 9th cross
SegmentNo 153/C-W0053/S041441	TotalLength 282.74	

ContractorDetails		
NameofContractor Shivraj	ContractorRegNo	Expenditure 0.00
PhoneNo 9448834119	EmailId	

Work Details		
NameOfWork Improvements to drains at 9th cross 2nd block Jayanagar in ward 153	Sanctioned Amount 3000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Improvements to drains at 9th cross 2nd block Jayanagar in ward 153	Job No Work Code 153-15-000023
Work OrderNo ee/ckp/wo/154/14-15	Work Order Date 03/02/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name sandeep
Date of Inspection 16/01/2016	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start

