



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0058	Chandrashekar Azad Rd	Rajkumar Statue
SegmentNo	TotalLength	
155/S-W0058/S012758	182.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Rames.M Contractor,#2,G.S Shivarudrappa Road,Main 1st cross,Hanumathnagara Bangalore-19		869820.00
PhoneNo	EmailId	
Work Details		
9845268085		

NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and imrovments to drains at Chandrashekhar Azad Road And surrounding roads in Ward no-155 Hanumanthnagara	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and imrovments to drains at Chandrashekhar Azad Road And surrounding roads in Ward no-155 Hanumanthnagara	155-12-000044
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/86/12/13	17/10/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2012	17/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0233, W0105, W0223, W0256, W0229, W0235, W0227, W	NA, 5th Main Gavi Gangadareshwara Temple Rd, Ramanjaneya Rd ,3rd Main Rd, 8th Crs, Panje Mangeshasay	Govt School
SegmentNo	TotalLength	
155/C-W0233/S031432	170.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K Suresh		795370.00
PhoneNo	Emailld	
9448050973		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and improvement to drain at Ramanjeneya road from 3rd main to maradi subbaiah chowltry and surrounding roads in ward no- 155 Hanumathnagara	900000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and improvement to drain at Ramanjeneya road from 3rd main to maradi subbaiah chowltry and surrounding roads in ward no-155 Hanumathnagara	155-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/62/12/13	06/09/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/09/2012	06/09/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0048	Harsha Chakravathi Rd	Ashoka Chakravarthy Road
SegmentNo	TotalLength	
155/S-W0048/S041323	330.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S Sathish contractor no 218 2nd cross Nagasandra,Basavanagudi,B anglore		1587660.00
PhoneNo	EmailId	
Work Details		
9901333577		

NameOfWork	Sanctioned Amount	Sanctioned Year
Aspalting to ashok chakravarthy road from Hanumathnagar Swimming pool to BBMP chowltly in hanumathnagara in ward no 155	1600000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Aspalting to ashok chakravarthy road from Hanumathnagar Swimming pool to BBMP chowltly in hanumathnagara in ward no 155	155-2-000059
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/153/12-3	26/03/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2013	17/01/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
10		Benakesh
Date of Inspection	Remarks	
11/12/2014	complete	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0021, W0018, W0020, W0022, W0012, W0016, W0014	StreetName 8th Crs, NA	Significant LandMark BANDI MAHA KALAMMA TEMPLE
SegmentNo 155/C-W0021/S070611	TotalLength 185.63	

ContractorDetails		
NameofContractor KUMARA SWAMY R	ContractorRegNo	Expenditure 403208.00
PhoneNo 9448160234	EmailId	

Work Details		
NameOfWork IMPROVEMENT TO DRAIN AND FOOTPATH AT WESTERN SIDE OF KAVERI NADI FROM HINDUMAHASANGANRA ROAD TO KAVI KESHARAJA ROAD	Sanctioned Amount 700000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type DRAIN AND FOOTPATH
Tender Tender	WorkDetails DRAIN AND FOOT PATH WORK	Job No Work Code 155-12-000045
Work OrderNo EE/BG/EST/10/2013-14	Work Order Date 30/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
04/03/2016	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0024, W0006, W0002, W0007, W0004	StreetName NA, 5th Main Godavarinadi Rd, 6th Crs Lakshmipura Main Rd	Significant LandMark Dhobi ghat
SegmentNo 155/C-W0024/S105311	TotalLength 334.66	

ContractorDetails		
NameofContractor S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28	ContractorRegNo	Expenditure 1490870.00
PhoneNo 924567500	EmailId	

Work Details		
NameOfWork Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godva ri nadhi road etc) In ward no- 155	Sanctioned Amount 1999000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	Job No Work Code 155-12-000007
Work OrderNo EE/BG/AE/Wo No/267/11-12	Work Order Date 20/01/2012	Period of Extention 90days
Defect Liability Period From 20/01/2012	Defect Liability Period To 20/01/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0009, W0024, W0002, W0004, W0011	4th Main Bramaputranadi Rd, NA, 6th Crs Lakshmipura Main Rd, 3rd Main Sindunadi Rd	Dhobi ghat
SegmentNo	TotalLength	
155/C-W0009/S111521	351.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1490870.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godva ri nadhi road etc) In ward no- 155	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	155-12-000007
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/267/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0024, W0002, W0004, W0011	StreetName NA, 6th Crs Lakshmipura Main Rd, 3rd Main Sindunadi Rd	Significant LandMark Dhobi ghat
SegmentNo 155/C-W0024/S112504	TotalLength 196.83	

ContractorDetails		
NameofContractor S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28	ContractorRegNo	Expenditure 1490870.00
PhoneNo 1024567890	EmailId	

Work Details		
NameOfWork Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godva ri nadhi road etc) In ward no- 155	Sanctioned Amount 1999000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	Job No Work Code 155-12-000007
Work OrderNo EE/BG/AE/Wo No/267/11-12	Work Order Date 20/01/2012	Period of Extention 90days
Defect Liability Period From 20/01/2012	Defect Liability Period To 20/01/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0028, W0010, W0021, W0100, W0024, W0018, W0096, W	NA, 4th Main Basavanana Rd, 10th Crs Kavi Ragavanka Rd, 10th A Crs Kavi Kesharaj Rd, Kaverinadi Rd,	Veerabhadra swamy temple
SegmentNo	TotalLength	
155/C-W0028/S113036	542.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1490870.00
PhoneNo	EmailId	
9344618990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godva ri nadhi road etc) In ward no- 155	1999000	2012
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	155-12-000007
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/267/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0006, W0007, W0005	NA, 5th Main Godavarinadi Rd, 6th Main Krishnanadi Rd	Dhobi ghat
SegmentNo	TotalLength	
155/C-W0006/S113802	34.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1490870.00
PhoneNo	EmailId	
9244613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Brindavana nagara (Sindhu nadhi,Bramaputranadhi,Godvari nadhi road etc) In ward no-155	155-12-000007
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/267/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		satish
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0160, W0211, W0168, W0207, W0164, W0209, W0114	NA, 6th Main T P Kailasam Rd, 6th Main T P Kailasam Rd6th Main T P Kailasam Rd, Devasathana Rd, 1st	Bank of india atm
SegmentNo	TotalLength	
155/C-W0160/S121627	155.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0160, W0195, W0166, W0197, W0199, W0114	NA, 3rd Main Hasha Vardhana Rd, Devasthana Rd, 7th Main K S Narasimhaswamy Rd, 1st Main Ramanjaneya	Nimble technologies
SegmentNo	TotalLength	
155/C-W0160/S123253	156.72	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northern side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northern side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0195, W0166, W0158, W0114, W0193	3rd Main Hasha Vardhana Rd, NA, 1st Main Ramanjaneya Rd, 8th Main Rd, Ta Ra Subarao Rd	Freak Solutions
SegmentNo	TotalLength	
155/C-W0195/S124402	158.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0185, W0151, W0166, W0156, W0114	9th Main Rd, G P Rajarantham Rd, 9th Crs, NA, 1st Main Ramanjaneya Rd	Usha associatees
SegmentNo	TotalLength	
155/C-W0185/S011356	174.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0172, W0174, W0170, W0235, W0114	7th Crs K V Iyer Rd, 6th Crs Niranjan Rd, 8th Crs A N Puttana Rd, Shashamurga Ganapathi Rd, 1st Main	K.H.Kala soudha
SegmentNo	TotalLength	
155/C-W0172/S012249	158.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0172, W0223, W0235	7th Crs K V Iyer Rd, Ramanjaneya Rd ,3rd Main Rd, Shashamurga Ganapathi Rd	sri shesha maha balamuri temple
SegmentNo	TotalLength	
155/C-W0172/S013047	33.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0120, W0118, W0157	14th Main H S Parvathi Rd, 4th Crs Gubbireeranna Rd, 13th Main Rd , Bim Sen Joshi Rd	Hitech electronic service
SegmentNo	TotalLength	
155/C-W0120/S031618	59.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0120, W0165, W0118, W0178	14th Main H S Parvathi Rd, 12th Main Rd, K K Hebbar Rd, 4th Crs Gubbireeranna Rd, 10th Crs	Hitech Electronic service
SegmentNo	TotalLength	
155/C-W0120/S032255	63.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0120, W0171, W0116, W0118, W0169, W0114, W0178	14th Main H S Parvathi Rd, 11th Main Rd, V K Gokar Rd, 3rd A Crs Puttana Kanagal Rd, 4th Crs Gubbire	Bescom
SegmentNo	TotalLength	
155/C-W0120/S032830	126.31	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-155	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	30/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0171, W0165, W0118, W0157	11th Main Rd, V K Gokar Rd, 12th Main Rd, K K Hebbar Rd, 4th Crs Gubbireeranna Rd, 13th Main Rd , B	Bescom
SegmentNo	TotalLength	
155/C-W0171/S033730	75.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.Satish Contractor no. 218, 2nd Cross,Nagasandra, Basavanagudi, Bangalore-28		1554720.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to road at Hanumanthanagara (Balance roads at Northen side of shivarama karanth road) and 13th main 14th main 2nd cross Srinagar in ward no-1	155-12-000006
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/268/11-12	20/01/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/01/2012	20/01/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0141, W0061, W0139, W0178	StreetName 13th A Main Rd, Pipeline Rd, Chi Udayashankar Rd, 10th Crs	Significant LandMark Maruthi circle
SegmentNo 155/C-W0141/S113316	TotalLength 35.59	

ContractorDetails		
NameofContractor B.H. Vijay Contractor #b-87 1st crossSamccrpura k.g. nagar Bangalore	ContractorRegNo	Expenditure 772300.00
PhoneNo 9245675000	EmailId	

Work Details		
NameOfWork Maintenance and Improvements to foot path and drains at V. Kru. Goka road, Chi Udayashankar road at road Hanumanthanagara in ward no-155	Sanctioned Amount 995000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type
Tender Tender	WorkDetails Maintenance and Improvements to foot path and drains at V. Kru. Goka road, Chi Udayashankar road at road Hanumanthanagara in ward no- 155	Job No Work Code 155-11-000008
Work OrderNo EE/BG1/JE/Wo No/26/10-11	Work Order Date 16/03/2011	Period of Extention 90days
Defect Liability Period From 16/03/2011	Defect Liability Period To 16/03/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Footpath Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0141, W0133, W0134	StreetName 13th A Main Rd, 14th Main Rd, 8th D Crs Sas	Significant LandMark MSR motors
SegmentNo 155/C-W0141/S115247	TotalLength 56.08	

ContractorDetails		
NameofContractor S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore	ContractorRegNo	Expenditure 1305620.00
PhoneNo 9344613990	EmailId	

Work Details		
NameOfWork Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross(E/S of Chi. Udayashankar	Sanctioned Amount 1550000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross (E/S of Chi. Udayashankar road) Hanumanthanagara in ward no-155	Job No Work Code 155-13-000012
Work OrderNo EE/BG/AE/Wo No/284/12-13	Work Order Date 20/03/2013	Period of Extention 90days
Defect Liability Period From 20/03/2013	Defect Liability Period To 20/03/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0128, W0159, W0141, W0133, W0135, W0132	StreetName 2nd Crs, 13th Main Rd, 13th A Main Rd, 14th Main Rd, 15th Main, 8th C Crs	Significant LandMark Sri balamuri ganapathi temple
SegmentNo 155/C-W0128/S120334	TotalLength 87.24	

ContractorDetails		
NameofContractor S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore	ContractorRegNo	Expenditure 1305620.00
PhoneNo 924567890	EmailId	

Work Details		
NameOfWork Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross(E/S of Chi. Udayashankar	Sanctioned Amount 1550000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross (E/S of Chi. Udayashankar road) Hanumanthanagara in ward no-155	Job No Work Code 155-13-000012
Work OrderNo EE/BG/AE/Wo No/284/12-13	Work Order Date 20/03/2013	Period of Extention 90days
Defect Liability Period From 20/03/2013	Defect Liability Period To 20/03/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0137, W0133, W0135, W0132	StreetName NA, 14th Main Rd, 15th Main, 8th C Crs	Significant LandMark maruthi circle
SegmentNo 155/C-W0137/S121118	TotalLength 85.18	

ContractorDetails		
NameofContractor S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore	ContractorRegNo	Expenditure 1305620.00
PhoneNo 9344613990	EmailId	

Work Details		
NameOfWork Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross(E/S of Chi. Udayashankar	Sanctioned Amount 1550000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross (E/S of Chi. Udayashankar road) Hanumanthanagara in ward no-155	Job No Work Code 155-13-000012
Work OrderNo EE/BG/AE/Wo No/284/12-13	Work Order Date 20/03/2013	Period of Extention 90days
Defect Liability Period From 20/03/2013	Defect Liability Period To 20/03/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0126, W0129, W0133, W0123, W0117, W0119, W0121	1st Main Rd, 1st Crs, 14th Main Rd, 2nd Crs, 3rd Crs, 3rd Main Rd, 2nd Main Rd	sri balamuri ganapathi temple
SegmentNo	TotalLength	
155/C-W0126/S121727	106.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1305620.00
PhoneNo	EmailId	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross(E/S of Chi. Udayashankar	1550000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at Cross roads, near BSK 1st stag 1st cross 1st A cross, 2nd cross and 3rd cross (E/S of Chi. Udayashankar road) Hanumanthanagara in ward no-155	155-13-000012
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/284/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	
Category	Photo	
Segment Start		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0009, W0004, W0011	4th Main Bramaputranadi Rd, 6th Crs Lakshmipura Main Rd, 3rd Main Sindunadi Rd	gavipuram ext
SegmentNo	TotalLength	
155/C-W0009/S020354	201.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		1215280.00
PhoneNo	Emailld	
Work Details 1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	155-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/251/12-13	01/03/2013	6monthes
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0008, W0005	NA, 6th Main Krishnanadi Rd	dhobi ghat
SegmentNo	TotalLength	
155/C-W0008/S021150	33.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		1215280.00
PhoneNo	EmailId	
Work Details		
1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	155-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/251/12-13	01/03/2013	6monthes
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0024, W0018, W0102, W0020, W0002, W0022, W0030, W	NA, 5th Main Sachinonnamma Rd, 6th Crs Lakshmipura Main Rd, Ganganadi Rd, Pipeline Rd	Brandavana english school
SegmentNo	TotalLength	
155/C-W0024/S022119	325.01	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		1215280.00
PhoneNo	EmailId	
Work Details 1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	155-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/251/12-13	01/03/2013	6monthes
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0021, W0096, W0030, W0015, W0011, W0061	4th Main Basavanana Rd, 1st Main Rd, NA, Ganganadi Rd, 3rd Main Sindunadi Rd, Pipeline Rd	sri vasavi all links
SegmentNo	TotalLength	
155/C-W0021/S023053	105.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		1215280.00
PhoneNo	EmailId	
Work Details 1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	155-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/251/12-13	01/03/2013	6monthes
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0113, W0021, W0100, W0102	3rd Main Kumarvyasa Rd, 4th Main Basavanana Rd, 10th Crs Kavi Ragavanka Rd, 5th Main Sachinonnamma R	veerabhadra swamy temple
SegmentNo	TotalLength	
155/C-W0113/S023839	158.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		1215280.00
PhoneNo	EmailId	
Work Details		
1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Brindavana nagar at Gangandi road Raghvanaka road and Surrounding road balance bad reaches In Ward No- 155	155-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/251/12-13	01/03/2013	6monthes
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0171, W0181, W0169, W0114, W0183	11th Main Rd, V K Gokar Rd, 10th Main Sri Ranga Rd, 11th Crs, 1st Main Ramanjaneya Rd, 10th Crs	axis bank
SegmentNo	TotalLength	
155/C-W0171/S032351	200.96	
ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S. Sathish Contractor no. 218, 2nd cross Nagasandra, basavangudi, Bangalore-28		1307380.00
PhoneNo	EmailId	
9344613990		
Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting To Ramanjaneya road from Hanumanthanagara from Hanumanthanagara 5th main to Chi. Udayashankar road in Hanumanthanagara in ward no-155	1300000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting To Ramanjaneya road from Hanumanthanagara from Hanumanthanagara 5th main to Chi. Udayashankar road in Hanumanthanagara in ward no- 155	155-12-000060
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/152/12-13	17/01/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/01/2013	17/01/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0046, W0061	1st Main Ambhabbhavani Temple Rd, 4th Main Jansirani Lakshmbai Rd	Kempampudhi kere
SegmentNo	TotalLength	
155/C-W0046/S111534	158.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1714790.00
PhoneNo	EmailId	
924567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no- 155	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no-155	155-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/97/12-13	31/10/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2012	31/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
4	Name
Date of Inspection	Remarks
13/01/2015	complete

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0051	3rd Main Samudragupta Mourya Rd	Kempambudhi kere
SegmentNo	TotalLength	
155/S-W0051/S112435	43.92	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1714790.00
PhoneNo	EmailId	
934461899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no- 155	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no-155	155-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/97/12-13	31/10/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2012	31/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		satish
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0053	3rd Main Samudragupta Mourya Rd	sri bhavani temple
SegmentNo	TotalLength	
155/S-W0053/S121057	62.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1714790.00
PhoneNo	EmailId	
934461899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no- 155	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drain at Kanishaka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no-155	155-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/97/12-13	31/10/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2012	31/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		satish
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0047, W0053, W0061	2nd Main Bhavaninagara Kanishka Maharaja Rd, 3rd Main Samudragupta Mourya Rd, 4th Main Jansirani Lak	kempegowda swimming pool
SegmentNo	TotalLength	
155/C-W0047/S121657	52.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1714790.00
PhoneNo	EmailId	
9344618899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain at Kanishka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no- 155	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drain at Kanishka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no-155	155-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/97/12-13	31/10/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2012	31/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		satish
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0047	2nd Main Bhavaninagara Kanishka Maharaja Rd	sri bhavani temple
SegmentNo	TotalLength	
155/S-W0047/S123422	78.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1714790.00
PhoneNo	EmailId	
934461899		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain at Kanishka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no- 155	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to road side drain at Kanishka Maharaja road Samudra Gupta mourya road Bhavaninagara in Hanumanthanagara ward no-155	155-12-000039
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/97/12-13	31/10/2012	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2012	31/10/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		satish
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0215, W0198, W0223, W0239, W0276	5th Main Gopal Krishna Adigar Rd, 1st Crs B M Shrikanthaiah Rd, Ramanjaneya Rd ,3rd Main Rd, 8th A C	BDIP
SegmentNo	TotalLength	
155/C-W0215/S124908	182.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1673070.00
PhoneNo	EmailId	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantaiah road and surrounding roads at Hanumanthanagara in ward no-	1990000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantaiah road and surrounding roads at Hanumanthanagara in ward no- 155	155-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/285/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
1	Name
Date of Inspection	Remarks
13/01/2015	complete

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0215, W0223, W0200, W0239, W0278, W0241	5th Main Gopal Krishna Adigar Rd, Ramanjaneya Rd ,3rd Main Rd, 1st Crs Veerappa Rd, 8th A Crs, 1st C	BDIP
SegmentNo	TotalLength	
155/C-W0215/S010732	181.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1673070.00
PhoneNo	EmailId	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantiah road and surrounding roads at Hanumanthanagara in ward no-	1990000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantiah road and surrounding roads at Hanumanthanagara in ward no- 155	155-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/285/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0202, W0241	StreetName 1st Crs, 4th Main Pampa Maha Kavi Rd	Significant LandMark BDIP
SegmentNo 155/C-W0202/S011402	TotalLength 36.76	

ContractorDetails		
NameofContractor S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore	ContractorRegNo	Expenditure 1673070.00
PhoneNo 9344618990	EmailId	

Work Details		
NameOfWork Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantaiah road and surrounding roads at Hanumanthanagara in ward no-	Sanctioned Amount 1990000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Maintenance and Improvements to drains at cross road near veerappa road, B,M, Srikantaiah road and surrounding roads at Hanumanthanagara in ward no- 155	Job No Work Code 155-13-000009
Work OrderNo EE/BG/AE/Wo No/285/12-13	Work Order Date 20/03/2013	Period of Extention 90days
Defect Liability Period From 20/03/2013	Defect Liability Period To 20/03/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		satish
Date of Inspection	Remarks	
13/01/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0171, W0151, W0110, W0169, W0114	11th Main Rd, V K Gokar Rd, 9th Crs, 1st Crs, 11th Crs, 1st Main Ramanjaneya Rd	Kurl-on
SegmentNo	TotalLength	
155/C-W0171/S013246	114.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1522800.00
PhoneNo	EmailId	
924567500		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarithnam road, Srinagar road, V,K. Gokak road Hanumant	1700000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarithnam road, Srinagar road, V,K. Gokak road Hanumanthanagara in ward no- 155	155-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/283/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0181, W0151, W0114, W0183	10th Main Sri Ranga Rd, 9th Crs, 1st Main Ramanjaneya Rd, 10th Crs	Pankaj electronics
SegmentNo	TotalLength	
155/C-W0181/S015525	108.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1522800.00
PhoneNo	EmailId	
1024567800		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarathnam road, Srinagar road, V.K. Gokak road Hanumant	1700000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarathnam road, Srinagar road, V.K. Gokak road Hanumanthanagara in ward no-155	155-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/283/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0185, W0151, W0156, W0114	9th Main Rd, G P Rajarantham Rd, 9th Crs, NA, 1st Main Ramanjaneya Rd	just insides
SegmentNo	TotalLength	
155/C-W0185/S020324	102.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R. Manjunath Contractor #198, Rudraswamy road, Gavipuram West, Bangalore		1522800.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarathnam road, Srinagar road, V,K. Gokak road Hanumant	1700000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to drains at cross roads near N/S of Ramanjaneya road G.P. Rajarathnam road, Srinagar road, V,K. Gokak road Hanumanthanagara in ward no-155	155-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/Wo No/283/12-13	20/03/2013	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/03/2013	20/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Benakesh
Date of Inspection	Remarks	
13/01/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0171, W0146, W0144, W0150, W0061	11th Main Rd, V K Gokar Rd, 2nd B Crs Veenesheshanna Rd, 7th Crs Ram Shri Murali Rd, 6th A Crs Thinu	Graveyard
SegmentNo	TotalLength	
155/C-W0171/S112415	147.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.H. Vijay Contractor #b-87 1st crossSamccrpura k.g. nagar Bangalore		772300.00
PhoneNo	EmailId	
9344613990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Maintenance and Improvements to foot path and drains at V. Kru. Goka road, Chi Udayashankar road at road Hanumanthanagara in ward no-155	995000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	Maintenance and Improvements to foot path and drains at V. Kru. Goka road, Chi Udayashankar road at road Hanumanthanagara in ward no- 155	155-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE/BG1/JE/Wo No/26/10-11	16/03/2011	90days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
16/03/2011	16/03/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		Manjunath
Date of Inspection	Remarks	
13/01/2015	complete	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0041, W0043, W0049, W0045, W0055, W0004	1st Main Chandragupta Mourya Rd, Nalwadi Krishna Odeyar Rd ,10th Crs, Vidyaranya Rd, NA, 8th Crs Kit	155 HANUMANTHNAGARA
SegmentNo	TotalLength	
155/C-W0041/S114101	136.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0047, W0043, W0049, W0048, W0004	StreetName 2nd Main Bhavaninagara Kanishka Maharaja Rd, Nalwadi Krishna Odeyar Rd ,10th Crs, Vidyaranya Rd, Har	Significant LandMark ASHOKA CHAKRAVARTHY MAIN ROAD
SegmentNo 155/C-W0047/S120022	TotalLength 86.24	
ContractorDetails		
NameofContractor KRTDL	ContractorRegNo	Expenditure 1785340.00
PhoneNo 1234567890	EmailId	
Work Details		
NameOfWork Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Sanctioned Amount 1900000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Job No Work Code 155-13-000029
Work OrderNo EE/BG/AE/WO NO/252/12-13	Work Order Date 01/03/2013	Period of Extention 180 DAYS
Defect Liability Period From 01/03/2013	Defect Liability Period To 01/03/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/08/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0053, W0048, W0055, W0004	3rd Main Samudragupta Mourya Rd, Harsha Chakravathi Rd, 8th Crs Kitturani Chennamma & Vidyaranga Rd,	ASHOKA CHAKRAVARTHY MAIN ROAD
SegmentNo	TotalLength	
155/C-W0053/S120439	71.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/NO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0059	Shrikrishnadevaraya Rd , 7th Crs	nAJUNDESHWARA SWAMY TEMPLE
SegmentNo	TotalLength	
155/S-W0059/S121229	207.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0071	StreetName 5th Crs Kumara Rama Rd	Significant LandMark GAVIPURA
SegmentNo 155/S-W0071/S121452	TotalLength 185.36	

ContractorDetails		
NameofContractor KRTDL	ContractorRegNo	Expenditure 1785340.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Sanctioned Amount 1900000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Job No Work Code 155-13-000029
Work OrderNo EE/BG/AE/WO NO/252/12-13	Work Order Date 01/03/2013	Period of Extention 180 DAYS
Defect Liability Period From 19/02/2013	Defect Liability Period To 01/03/2014	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name raghavendra
Date of Inspection 24/08/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0079	StreetName Madakarinarayaka Rd , 4th Crs	Significant LandMark GAVIPURA
SegmentNo 155/S-W0079/S121715	TotalLength 186.33	

ContractorDetails		
NameofContractor KRTDL	ContractorRegNo	Expenditure 1785340.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Sanctioned Amount 1900000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	Job No Work Code 155-13-000029
Work OrderNo EE/BG/AE/WO NO/252/12-13	Work Order Date 01/03/2013	Period of Extention 180 DAYS
Defect Liability Period From 01/03/2013	Defect Liability Period To 01/03/2014	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name raghavendra
Date of Inspection 24/08/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0085	3rd Crs, Mayura Verama Rd	JALAKANTESHWARA SWAMY TEMPLE
SegmentNo	TotalLength	
155/S-W0085/S121855	186.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltng to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0087	2nd Crs, Ranadira Kanteerava Rd	SRI JALAKANTESHWARA SWAMY TEMPLE
SegmentNo	TotalLength	
155/S-W0087/S122106	130.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0089	1st Crs, H M Nayak Rd	SRI JALAKANTESHWARA SWAMY TEMPLE
SegmentNo	TotalLength	
155/S-W0089/S122241	144.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspaltting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		raghavendra
Date of Inspection	Remarks	
24/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0045	NA	Grevyard
SegmentNo	TotalLength	
155/S-W0045/S122707	34.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRTDL		1785340.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Aspalting to laxmipura Main rd and crs road bad reaches in hanumathnagara ward no155	155-13-000029
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/252/12-13	01/03/2013	180 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	01/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0041, W0051, W0047, W0037, W0063, W0069, W0046, W	StreetName 1st Main Chandragupta Mourya Rd, 3rd Main Samudragupta Mourya Rd, 2nd Main Bhavaninagara Kanishka Ma	Significant LandMark NEAR LAKE
SegmentNo 155/C-W0041/S123658	TotalLength 230.01	

ContractorDetails		
NameofContractor SRI BH VIJAY	ContractorRegNo	Expenditure 1079040.00
PhoneNo 2000001507	EmailId	

Work Details		
NameOfWork improvement to footpath and road side drain at VSR kalyana mantapa road in hanumathnagara ward no 155	Sanctioned Amount 1200000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type improvement to footpath and road side drain
Tender Tender	WorkDetails improvement to footpath and road side drain at VSR kalyana mantapa road in hanumathnagara ward no 155	Job No Work Code 155-12-000041
Work OrderNo EE/BG/AE/WO NO/80/12/13	Work Order Date 17/10/2012	Period of Extention 90 DAYS
Defect Liability Period From 17/10/2012	Defect Liability Period To 17/10/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0215, W0184, W0182, W0203, W0199, W0188, W0237, W	5th Main Gopal Krishna Adigar Rd, 9th Crs, 3rd Crs, S L Byrappa Rd, NA, 7th Main K S Narasimhaswamy	PU Ti Narasimhachar raod
SegmentNo	TotalLength	
155/C-W0215/S010734	257.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N M Cheluva Raju		1236660.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
maintenance and improvement to drain from bhasa mahakavi road to k s narashimhaswamy road and pu ti narashimhachar road balance portion and surroundin	1400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	maintenance and improvement to drain from bhasa mahakavi road to k s narashimhaswamy road and pu ti narashimhachar road balance portion and surrounding road in ward no 155 hanumanthanagara	155-12-000040
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO NO/67/12-13	06/09/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/09/2012	06/09/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0113, W0021, W0189, W0112, W0185, W0096, W0142, W	3rd Main Kumaryyasa Rd, 4th Main Basavanana Rd, 3rd Main Rd, 4th Main Kavi Basavanna Rd, 5th Main Rd	pipe line road
SegmentNo	TotalLength	
155/C-W0113/S014417	258.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
chandra shekar B C		826065.00
PhoneNo	EmailId	
9535252126		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
maintenance and improvement to drain cross road near mahadeshwara temple in brindavana nagara in ward no 155 hanumanthanagara	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	maintenance and improvement to drain cross road near mahadeshwara temple in brindavana nagara in ward no 155 hanumanthanagara	155-12-000046
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/NO NO/36/12-13	25/07/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
25/07/2012	25/07/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		Manjunath
Date of Inspection	Remarks	
11/12/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0113, W0104, W0106, W0108, W0112, W0125	3rd Crs, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Veera Anjaneya Temple Rd	near kamala nursing home
SegmentNo	TotalLength	
155/C-W0113/S125602	330.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B P S BABU		1227038.00
PhoneNo	EmailId	
9342519718		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT KAVIRAJANNA KAVIRANNA AND KAVIPRNA AND SORROUNDING ROADS	1615000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN WORK
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-14-000016
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/141/2013-2014	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID I0046, W0061, W0069, W0063	StreetName NA, Om Shakthi Lyt 7th Crs, Om Shakthi Lyt 6th Crs	Significant LandMark BHAVANI TEMPLE
SegmentNo 155/C-I0046/S010749	TotalLength 461.17	

ContractorDetails		
NameofContractor B P S BABU	ContractorRegNo	Expenditure 1406632.00
PhoneNo 9342519718	EmailId	

Work Details		
NameOfWork MAINTANANCE AND IMPROVEMENTS TO DRAIN AT JANSIRANI LAXMIBAI ROAD RAJA POURAVA ROAD SHIVAJI MAHARAJA ROAD AND SORROUNDING ROADSOU	Sanctioned Amount 1990000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type DRAIN WORK
Tender Tender	WorkDetails DRAIN WORK	Job No Work Code 155-14-000015
Work OrderNo EE/BG/AE/WO/142/2013-2014	Work Order Date 16/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0006, W0007	NA	BRUNDAVANA SCHOOL
SegmentNo	TotalLength	
155/C-W0006/S012123	103.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K SURESH		694547.00
PhoneNo	EmailId	
9845188394		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF FLOODED DAMEGED SECONDARY DRAIN CULVERT ACROSS THE 5TH MAIN GODAVARI NADI ROAD	694545	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN WORK
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-15-000021
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/23/2014-2015	03/11/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0048	NA	AK COLONY PARK
SegmentNo	TotalLength	
155/S-W0048/S013327	330.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H M PRABHAKAR		848568.00
PhoneNo	EmailId	
9343718908		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN FOOTPATH AT HARSHA CHAKRAVERTHY ROAD LAKSHMIPURA	1545162	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN, FOOTPATH WORK
Tender	WorkDetails	Job No Work Code
Tender	DRAIN.FOOTFATH	155-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/148/2013-2014	18/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0199	NA	NEAR RAMA MANDHIRA
SegmentNo	TotalLength	
155/S-W0199/S014007	339.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H M PRABHAKAR		412569.00
PhoneNo	EmailId	
9343718908		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN K S NARASIMHA SWAMY ROAD FROM RAMANJANEYA ROAD RAMAMANDIRA GAVIPURAM AND SURROUNDING ROADS	1108885	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN
Tender	WorkDetails	Job No Work Code
Tender	DRAI WORK	155-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/143/2013-2014	16/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0026	StreetName NA	Significant LandMark mahadeshwara temple
SegmentNo 155/S-W0026/S015130	TotalLength 56.24	

ContractorDetails		
NameofContractor M RAMESH	ContractorRegNo	Expenditure 485155.00
PhoneNo 9845268085	EmailId	

Work Details		
NameOfWork PROCEED WITH MODIFIED WORK OF CONSTRUCTION OF CULVERTSAND IMPROVEMENTS TO DRAIN AT DRAIN AYT BRINDHAVANA NAGARAAND LAXMIPURA	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type DRAIN, CULVERT
Tender Tender	WorkDetails CULVERTS, DRAIN WORK	Job No Work Code 155-12-000004
Work OrderNo EE/BG/AE/WO/287/2011-2012	Work Order Date 16/02/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0026	NA	MAHADESHWARA TEMPLE
SegmentNo	TotalLength	
155/S-W0026/S020049	56.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M RAMESH		1752098.00
PhoneNo	EmailId	
9845268085		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY WORKS IN THE AREA	2089904	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	EMERGENCY WORK
Tender	WorkDetails	Job No Work Code
Tender	EMERGENCY WORK	155-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/178/2013-2014	21/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0161, W0159	StreetName NA	Significant LandMark KAGGIS BNAKERY
SegmentNo 155/C-W0161/S021919	TotalLength 97.89	

ContractorDetails		
NameofContractor T G RAVI KUMAR	ContractorRegNo	Expenditure 863718.00
PhoneNo 9141632224	EmailId	

Work Details		
NameOfWork MAINTANANCE AND IMPROVEMENTS TO DRAIN AT 4TH MAIN 12 TH MAIN AND 13TH MAIN ROAD B/W 50 FT ROAD AND PIPELINE ROAD AND SURROUNDING ROADS	Sanctioned Amount 1140216	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type DRAIN
Tender Tender	WorkDetails DRAIN WORK	Job No Work Code 155-14-000008
Work OrderNo EE/BG/AE/WO/136/2013-2014	Work Order Date 16/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0086	NA	HARI HARA GUDDA
SegmentNo	TotalLength	
155/S-W0086/S024516	65.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
D CHANDRA SHEKAR		500000.00
PhoneNo	EmailId	
9449132168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT DE JAVARE GOUDA ROAD OF BASAPPA LAYOUT AND SURROUNDING ROADS	520059	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-14-000019
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/186/2013-2014	31/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0084	NA	hari hara park
SegmentNo	TotalLength	
155/S-W0084/S025614	97.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
D CHANDRA SHEKAR		500000.00
PhoneNo	EmailId	
9449132168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT BANKIMACHANDRA CHATARJI ROAD BALANCE PORTION AND SURROUNDING ROADS	522798	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/194/2013-2014	07/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0102, W0015, W0133, W0121, W0130, W0113, W0100, W	NA, Vinayaka Lyt 4th Crs, 3rd Crs	NEAR 50FT ROAD
SegmentNo	TotalLength	
155/C-W0102/S030220	217.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
D CHANDRA SHEKAR		507003.00
PhoneNo	Emailld	
9449132168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT KUMARAVYASA ROAD AND BASAVANNA ROAD AND SOROUNDING ROADS	519517	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	DRAIN WORK	155-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/185/2013-2014	31/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
26/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0116	NA	ANJANEYA TEMPLE
SegmentNo	TotalLength	
155/S-W0116/S031310	168.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SHIVALINGE GOWDA		766942.00
PhoneNo	EmailId	
9341228174		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT MYSORE ANANTHASWAMY ROAD FROM BASAMAHAKHAVI ROAD TO G P RAJARATHNAM ROAD AND SOURROUNDING ROADS	1096582	2013
Year	Type of Work	Other Work Type
2014 - 2015	Rehabilitation	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/151/2013-2014	23/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0021, W0030, W0015, W0011, W0024	StreetName 8th Crs, NA	Significant LandMark PIPE LINE ROAD
SegmentNo 155/C-W0021/S032518	TotalLength 182.72	

ContractorDetails		
NameofContractor B H VIJAY	ContractorRegNo	Expenditure 1543400.00
PhoneNo 9972030074	EmailId	

Work Details		
NameOfWork MAINTANANCE AND IMPROVEMENTS TO DRAIN AT KAVIKASHARAJA ROAD FROM VARSHA RUTHU ROAD PIPELINE ROAD BEETWEEN KAVERI NADI ROAD AND GODAVARI NADI ROAD	Sanctioned Amount 1783466	Sanctioned Year 2013
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails DRAIN WORK	Job No Work Code 155-14-000020
Work OrderNo EE/BG/AE/WO/159/2013-2014	Work Order Date 30/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0140, W0146, W0186, W0193, W0195, W0158, W0114	StreetName 3rd Crs, NA, Vinayaka Lyt 2nd Crs	Significant LandMark AUTO ASSEMBLY
SegmentNo 155/C-W0140/S124454	TotalLength 273.91	

ContractorDetails		
NameofContractor SHIVA SHANKAR	ContractorRegNo	Expenditure 1395000.00
PhoneNo 9448493639	EmailId	

Work Details		
NameOfWork MAINTANANCE AND IMPROVEMENTS TO DRAINSAT THARA SUBBAROA ROAD FROM 50 FEET ROAD TO 4TH CROSS AND FROM RAMANJANEYA ROAD TOWARDS NORTHERN SIDE AND SORROUN	Sanctioned Amount 1445020	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails DRAIN ,MAINTANANCE	Job No Work Code 155-14-000009
Work OrderNo EE/BG/WO/140/2013-2014	Work Order Date 16/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
25/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0128, W0126, W0133, W0134, W0135, W0132, W0130	StreetName NA, Vinayaka Lyt 4th Crs, 1st Crs	Significant LandMark MARUTI CIRCLE
SegmentNo 155/C-W0128/S011458	TotalLength 139.79	

ContractorDetails		
NameofContractor SHIVASHANKAR	ContractorRegNo	Expenditure 669492.00
PhoneNo 9448493639	EmailId	

Work Details		
NameOfWork PROCEED WITH MODIFIED WORK OF MAINTANCE AND IMPROVEMENTH TO DRAIN AND FOOTPATH AT BOTH SIDESOF CHI UDAYASHANKARA ROAD FROM MARUTHI CIRCLE TO 50FT ROA	Sanctioned Amount 1425000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails DRAIN MAINTANANCE	Job No Work Code 155-14-000006
Work OrderNo EE/BG/AE/WO/139/2013-2014	Work Order Date 16/12/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
25/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0182, W0237	NA	BALAJI VIDYANIKETHAN SCHHOL
SegmentNo	TotalLength	
155/C-W0182/S023732	163.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C CHANDRA KUMAR		832809.00
PhoneNo	EmailId	
9341224673		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAIN AT S L BYRAPPA ROAD AND SORROUNDING ROADS	834509	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN MAINTANANCE	155-14-000011
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/218/2013-2014	01/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
25/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 155	WardName Hanumanth Nagara
StreetID W0120, W0165, W0118, W0163, W0178, W0143, W0171, W	StreetName NA	Significant LandMark KAMALA NURSING HOME
SegmentNo 155/C-W0120/S024727	TotalLength 351.02	

ContractorDetails		
NameofContractor C CHANDRASHEKAR	ContractorRegNo	Expenditure 950555.00
PhoneNo 9341224673	EmailId	

Work Details		
NameOfWork PROCEED WITH MODIFIED WORK OF MAINTANANCE AND IMPROVEMENTS TO DRAIN AT VEENE SHESHANNA ROAD AND KK HEBBAR ROAD SORROUNDING ROADS	Sanctioned Amount 1285000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails DRAIN WORK	Job No Work Code 155-14-000010
Work OrderNo EE/BG/AE/WO/173/2013-2014	Work Order Date 01/01/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
25/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	155	Hanumanth Nagara
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	mangala hotel
SegmentNo	TotalLength	
155/S-W0144/S032507	142.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B H VIJAY		1080000.00
PhoneNo	EmailId	
9972030074		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE AND IMPROVEMENTS TO DRAINS AT G S SHIVARUDRAPPA ROAD PARVATHAVANI ROAD AND SORROUNDING ROADS	1131198	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DRAIN WORK	155-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/BG/AE/WO/2013-2014	30/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		vinod
Date of Inspection	Remarks	
25/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition

