ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0012, W0011, W0008, W0083	NA, 12th Main Rd, 14th Main Rd, 12th Main Ragavendra Block	SBI ATM
SegmentNo	**TotalLength**	
156/C-W0012/S122446	145.09	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		1780200.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	1999000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	156-11-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/327/11-12	19/03/2012	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/03/2012	19/03/2013	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
25/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0093, W0011, W0120	10th Main Rd, 3rd Crs Ragavendra Block, Avalahalli Main Rd	canara bank
SegmentNo	**TotalLength**	
156/C-W0093/S124308	155.14	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		1780200.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	1999000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	156-11-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/327/11-12	19/03/2012	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/03/2012	19/03/2013	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0184, W0217, W0176, W0172	5th Crs, 17th Main Rd, 5th C Crs, 5th A Crs	Radha nilaya
SegmentNo	**TotalLength**	
156/C-W0184/S125308	127.70	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		1780200.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	1999000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and widening of footpath of BSK 1st stag 2nd block in ward no-156	156-11-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/327/11-12	19/03/2012	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/03/2012	19/03/2013	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0004, W0002, W0006, W0009	NA, 13th Crs, 13th Main	Deepthi engineering
SegmentNo	**TotalLength**	
156/C-W0004/S120202	131.67	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
D. Shekar #412/413, 7th main a block, Subramanyanagar, Bangalore		270200.00
PhoneNo	**EmailId**	
9234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain in 13th main road ragavendra nagara ward no-156	296000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain in 13th main road ragavendra nagara ward no-156	156-11-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/126/11-12	29/08/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/08/2011	29/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
25/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0038, W0032, W0053, W0034, W0024, W0213, W0036, W	Balal Rd, Onayakobhava Rd, Vikramaditya Main Rd, Chikkadevaraya Rd, Mallikatamma Temple Rd, Shathava	Rajiv gandhi sports complex
SegmentNo	**TotalLength**	
156/C-W0038/S123819	166.16	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
C. Balraj Contractor, no.2 1st cross 2nd main someshwaranagar jaynagar 1st block bangalore		865090.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain In Srinagar and surrounding area in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain In Srinagar and surrounding area in ward no-156	156-11-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/01/11-12	01/04/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/04/2011	01/04/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0154, W0177	1st Main Rd, 9th Main Rd	Srinagar hospitl
SegmentNo	**TotalLength**	
156/C-W0154/S033502	32.99	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
C. Balraj Contractor, no.2 1st cross 2nd main someshwaranagar jaynagar 1st block bangalore		865090.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain In Srinagar and surrounding area in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain In Srinagar and surrounding area in ward no-156	156-11-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/01/11-12	01/04/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
01/04/2011	01/04/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0065, W0107, W0117, W0111, W0084, W0055, W0057, W	Rastrakuta Rd, 8th Main, 8th Main K Block, 9th Main S Block, 2nd Crs, 11th Main, Netravathi Nadi Rd,	Mother terasa english school
SegmentNo	**TotalLength**	
156/C-W0065/S120952	268.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
C Chandrakumar Contractor #768/A 6th cross, gokal 1st stage 2nd phase Bangalore		737000.00
PhoneNo	**EmailId**	
9241567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and Culverts in pipeline road in ward no-156	995000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and Culverts in pipeline road in ward no-156	156-11-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/64/10-11	24/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2011	24/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0038, W0043, W0032, W0039, W0034, W0055, W0024, W	Balal Rd, 12th Main Kalapa Block, Onayakobhava Rd, 12th B Main Kalapa Block, Chikkadevaraya Rd, 11th	Rajiv gandhi sports complex
SegmentNo	**TotalLength**	
156/C-W0038/S121810	210.34	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
C Chandrakumar Contractor #768/A 6th cross, gokal 1st stage 2nd phase Bangalore		737000.00
PhoneNo	**EmailId**	
9241567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and Culverts in pipeline road in ward no-156	995000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and Culverts in pipeline road in ward no-156	156-11-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/64/10-11	24/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2011	24/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0015, W0006, W0013	11th Main Rd, 13th Crs, NA	49 bus stop
SegmentNo	**TotalLength**	
156/C-W0015/S123459	147.56	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		0.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain in 5th cross Kalidasa layout in ward no-156	292000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain in 5th cross Kalidasa layout in ward no-156	156-11-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/100/11-12	29/08/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/08/2011	29/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
25/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0010, W0087, W0017, W0006, W0016, W0019	NA, 3rd Crs Kaledasa Badavane, 13th Crs, 4th Crs Kaledasa Badavane	49B bus stop
SegmentNo	**TotalLength**	
156/C-W0010/S125605	219.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0041, W0039, W0061	Anantamurthy Badavane, 12th B Main Kalapa Block, Pipeline Rd	Kalidasa layout bus stop
SegmentNo	**TotalLength**	
156/C-W0041/S010557	75.90	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
9234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0041, W0043, W0039, W0061	Anantamurthy Badavane, 12th Main Kalapa Block, 12th B Main Kalapa Block, Pipeline Rd	Evershine english school
SegmentNo	**TotalLength**	
156/C-W0041/S011338	80.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
9241567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0043, W0039, W0048, W0061	12th Main Kalapa Block, 12th B Main Kalapa Block, NA, Pipeline Rd	Kalidasa layout bus stop
SegmentNo	**TotalLength**	
156/C-W0043/S012543	127.98	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0043, W0012, W0048	12th Main Kalapa Block, NA	Exlent school
SegmentNo	**TotalLength**	
156/C-W0043/S013102	82.57	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
9224567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0043, W0048	12th Main Kalapa Block, NA	Exlent school
SegmentNo	**TotalLength**	
156/C-W0043/S013501	13.06	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
.Renukhya Contractor no 10 17th cross 13th main JP nagar 5th stag Bangalore		881120.00
PhoneNo	**EmailId**	
9234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement conerete road balance portion in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing cement conerete road balance portion in ward no-156	156-11-000021
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/81/10-11	31/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/03/2011	31/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0015, W0031, W0017, W0023, W0006, W0019, W	1st Crs Kaledasa Badavane, 11th Main Rd, 2nd Crs Kaledasa Badavane, NA, 13th Crs, 4th Crs Kaledasa B	rajiv gandhi sports complex
SegmentNo	**TotalLength**	
156/C-W0033/S014126	137.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		249750.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains in Ragavendra nagara main road in ward no-156	275000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains in Ragavendra nagara main road in ward no-156	156-11-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/102/11-12	29/08/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/08/2011	29/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0070, W0066	NA	Raghavendra blc
SegmentNo	**TotalLength**	
156/S-W0070/S122442	232.84	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V RAVIKUMAR		0.00
PhoneNo	**EmailId**	
9448077241		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drains and footpath from 7th cross to 12th cross in Raghavendra block in ward no 156	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to drains and footpath from 7th cross to 12th cross in Raghavendra block in ward no 156	156-15-000010
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/42/14-15	31/12/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/12/2014	30/12/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
13		Ramadasappa
Date of Inspection	**Remarks**	
26/03/2016	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0002, W0009, W0004	NA	KARI THIMMANA HALLI PARK
SegmentNo	**TotalLength**	
156/C-W0002/S123052	133.08	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V RAVIKUMAR		0.00
PhoneNo	**EmailId**	
9448077241		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AND FOOTPATH AND ROADS IN 13TH MAIN RAGHAVENDRA NAGARA AND SURROUNDING AREA IN WARD NO 156	1400000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	IMPROVEMENTS TO DRAINS AND FOOTPATH AND ROADS IN 13TH MAIN RAGHAVENDRA NAGARA AND SURROUNDING AREA IN WARD NO 156	156-15-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/45/14-15	02/01/2015	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
02/01/2015	01/01/2016	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramadasappa
Date of Inspection	**Remarks**	
26/03/2016	complete	

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0015, W0031, W0017, W0007, W0023, W0006, W	NA, 8th Crs	SWD DRIAN
SegmentNo	**TotalLength**	
156/C-W0033/S125001	478.91	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
RAVIKUMAR		0.00
PhoneNo	**EmailId**	
9448077241		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY GRANTS IN WARD NO 156	200000	2014
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	EMERGENCY GRANTS IN WARD NO 156	156-15-00004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/02/15-16	08/04/2015	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
08/04/2015	03/04/2016	No

Field Inspection Details

Number of Trees	Other Information	Name
25		Ramadasappa
Date of Inspection	**Remarks**	
26/03/2016	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0180, W0231, W0182	NA, 11th Main Rd	Date vision software solutions pvt ltd
SegmentNo	**TotalLength**	
156/C-W0180/S120930	232.23	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Madheva Contractor no.158 11th main road 4th cross Hanumanth nagar Bangalore-18		879700.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 11th and 12th main road bsk 1st stag 2nd block in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains at 11th and 12th main road bsk 1st stag 2nd block in ward no-156	156-11000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/09/10-11	13/04/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/04/2011	13/04/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0229, M0132, W0182	12th Main Rd, Kumaraswamy Temple Rd, NA	Viday nilayam
SegmentNo	**TotalLength**	
156/C-W0229/S123334	233.32	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Madheva Contractor no.158 11th main road 4th cross Hanumanth nagar Bangalore-18		879700.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains at 11th and 12th main road bsk 1st stag 2nd block in ward no-156	990000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains at 11th and 12th main road bsk 1st stag 2nd block in ward no-156	156-11000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/09/10-11	13/04/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/04/2011	13/04/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0005, W0003, W0008	NA, 15th Main, 14th Main Rd	ragavendra block
SegmentNo	**TotalLength**	
156/C-W0005/S010928	211.10	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Pavankumar Contractor #116 vinayaka layot kempegowda nagar Bangalore		738720.00
PhoneNo	**EmailId**	
9224567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Culverts in 17th main road ragavendra block and surrounding area in ward no-156	995000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains and Culverts in 17th main road ragavendra block and surrounding area in ward no-156	156-11-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/23/10-11	25/07/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/07/2011	25/07/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0015, W0010, W0012, W0008	11th Main Rd, NA, 14th Main Rd	Ragavendra block
SegmentNo	**TotalLength**	
156/C-W0015/S013241	377.82	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Pavankumar Contractor #116 vinayaka layot kempegowda nagar Bangalore		738720.00
PhoneNo	**EmailId**	
9241567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains and Culverts in 17th main road ragavendra block and surrounding area in ward no-156	995000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains and Culverts in 17th main road ragavendra block and surrounding area in ward no-156	156-11-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/JE/Wo No/23/10-11	25/07/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/07/2011	25/07/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
25/08/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0117, W0084, W0119, W0061	8th Main K Block, 2nd Crs, 9th Main Kalapa Block, Pipeline Rd	Pipeline road
SegmentNo	**TotalLength**	
156/C-W0117/S015517	60.15	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
D Shekar Contractor no 412/413 7th main a block subramanya nagar Bangalore		463750.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Rectification of concrete road cut portion done by bwssb in ward no-156	500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Rectification of concrete road cut portion done by bwssb in ward no-156	156-11-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/37/10-11	18/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
18/03/2011	18/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0043, W0039, W0048, W0061	12th Main Kalapa Block, 12th B Main Kalapa Block, NA, Pipeline Rd	Sri Bisilu maramma temple
SegmentNo	**TotalLength**	
156/C-W0043/S023755	127.13	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
D Shekar Contractor no 412/413 7th main a block subramanya nagar Bangalore		463750.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Rectification of concrete road cut portion done by bwssb in ward no-156	500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Rectification of concrete road cut portion done by bwssb in ward no-156	156-11-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/37/10-11	18/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
18/03/2011	18/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0015, W0031, W0017, W0023, W0006, W0019, W	1st Crs Kaledasa Badavane, 11th Main Rd, 2nd Crs Kaledasa Badavane, NA, 13th Crs, 4th Crs Kaledasa B	Police station
SegmentNo	**TotalLength**	
156/C-W0033/S030309	150.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Thammaiah #14/A chetana nilaya, 11th main, 7th cross raghavendra block,Srinagar Bangalore		244410.00
PhoneNo	**EmailId**	
9448075046		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drains in ragavendra nagar main road in ward no-156	275000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drains in ragavendra nagar main road in ward no-156	156-11-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/101/11-12	29/08/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/08/2011	29/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0217, W0176, W0205, W0209, W0172, W0219, W0215, W	NA, Chowdeshwari Temple Rd	PES COLLEGE SURROUNDING
SegmentNo	**TotalLength**	
156/C-W0217/S082012	310.94	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI.S. VINAYKUMAR		0.00
PhoneNo	**EmailId**	
9902926443		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CULVERTS AT JUNCTION OF ROADS IN BSK 1ST BLOCK,2ND BLOCK AND SURROUNDING AREA IN WARD NO 156 SRINAGARA	1000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	CULVERTS
Tender	**WorkDetails**	**Job No Work Code**
Tender	CONSTRUCTION OF CULVERTS AT JUNCTION OF ROADS IN BSK 1ST BLOCK,2ND BLOCK AND SURROUNDING AREA IN WARD NO 156 SRINAGARA.	156-14-000007
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/214/13/14	03/01/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/01/2014	01/01/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
20/06/2016		

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0217, W0209, W0176	17th Main Rd, NA, 5th C Crs	Kalyani jewellers
SegmentNo	**TotalLength**	
156/C-W0217/S112836	135.26	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		448320.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and Culverts in 5th A cross road 1st Stage 2nd block and surrounding area in ward no-156	500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and Culverts in 5th A cross road 1st Stage 2nd block and surrounding area in ward no-156	156-11-000010
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/42/11-12	25/05/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/05/2011	25/05/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0205, W0217, W0209, W0172	22nd Main Rd, 17th Main Rd, NA, 5th A Crs	A.S Cabs
SegmentNo	**TotalLength**	
156/C-W0205/S114112	180.91	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S. Thammaiah Contractor #14/A, 11th main 7th cross, R.V.block Srinagar , Bangalore		448320.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain and Culverts in 5th A cross road 1st Stage 2nd block and surrounding area in ward no-156	500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain and Culverts in 5th A cross road 1st Stage 2nd block and surrounding area in ward no-156	156-11-000010
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/42/11-12	25/05/2011	60days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/05/2011	25/05/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0015, W0031, W0017, W0005, W0007, W0023, W	1st Crs Kaledasa Badavane, 11th Main Rd, 2nd Crs Kaledasa Badavane, NA, 14th Main, 13th Crs, 12th Ma	Rajive gandhi sports complex
SegmentNo	**TotalLength**	
156/C-W0033/S122014	258.36	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0015, W0010, W0012, W0006, W0008, W0013	11th Main Rd, NA, 13th Crs, 14th Main Rd	Sri ragavendra swami mutt
SegmentNo	**TotalLength**	
156/C-W0015/S123635	253.80	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0038, W0032, W0053, W0034, W0055, W0024, W0213, W	Balal Rd, Onayakobhava Rd, Vikramaditya Main Rd, Chikkadevaraya Rd, 11th Main, Netravathi Nadi Rd, M	Kumaraswamy hot chips center
SegmentNo	**TotalLength**	
156/C-W0038/S124517	217.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0065, W0075, W0053, W0073, W0071, W0061, W0059, W	Rastrakuta Rd, 7th Main Narmadanadi Rd, Vikramaditya Main Rd, Yamuna Nadi Rd, 8th Main, Yamunanadi R	Axis bank atm
SegmentNo	**TotalLength**	
156/C-W0065/S125013	153.45	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0053, W0042, W0071, W0044	Vikramaditya Main Rd, NA, 8th Main, Yamunanadi Rd	dhobi ghat
SegmentNo	**TotalLength**	
156/C-W0053/S125708	154.27	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0142, W0187, W0061	5th Crs, Srinagara, 4th Main Rd, Srinagar, Pipeline Rd	Bangalore one
SegmentNo	**TotalLength**	
156/C-W0142/S010516	80.95	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0185, W0142, W0061	5th Main Rd, 5th Crs, Srinagara, Pipeline Rd	Maruthi complex
SegmentNo	**TotalLength**	
156/C-W0185/S011506	140.42	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0134, W0142, W0061, W0183	8th Crs, Srinagar, 5th Crs, Srinagara, Pipeline Rd, 6th Main Rd	indian post
SegmentNo	**TotalLength**	
156/C-W0134/S012708	180.61	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0181, W0134, W0142	8th Main Rd, 8th Crs, Srinagar, 5th Crs, Srinagara	indian post
SegmentNo	**TotalLength**	
156/C-W0181/S013326	149.89	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0123, W0105, W0175, W0125, W0181, W0134, W0109, W	8th Main Kalapa Block, 12th Crs, 8th Main Rd, NA, 8th Crs, Srinagar, 11th Main Kalapa Block, 13th M	hans info tech
SegmentNo	**TotalLength**	
156/C-W0123/S013951	328.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0136, W0175, W0161, W0173, W0167, W0121	7th Crs, Srinagar, 8th Main Rd, 13th Main Shrinagar, Serevice Rd, NA, 9th A Main Rd	Hans info tech
SegmentNo	**TotalLength**	
156/C-W0136/S021406	160.50	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6months
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0105, W0115, W0104, W0106, W0109, W0121	12th Crs, 10th Main Kalapa Block, NA, 2nd Crs, 11th Main Kalapa Block, 9th A Main Rd	Rashmi niwas
SegmentNo	**TotalLength**	
156/C-W0105/S022154	195.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0083	12th Main Ragavendra Block	Raghavendra brundavana trust
SegmentNo	**TotalLength**	
156/S-W0083/S013240	231.40	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N Devaraj		457560.00
PhoneNo	**EmailId**	
9710287372		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
improvement to drain in 12th main from avalahalli main road in ward-156	500000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	improvement to drain in 12th main from avalahalli main road in ward-156	156-12-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/61/12-13	06/09/2012	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/09/2012	06/09/2013	No

Field Inspection Details

Number of Trees	Other Information	Name
2		K.B.Ramadasappa
Date of Inspection	**Remarks**	
11/12/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0057	NA	Kalappa Block
SegmentNo	**TotalLength**	
156/S-W0057/S115953	170.88	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri Sanjay Namashivayam Babu		0.00
PhoneNo	**EmailId**	
9035274994		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Footpath in Kalappa block and Surrounding areas in Ward No-156	1000000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	Drains and Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains and Footpath in Kalappa block and Surrounding areas in Ward No-156	156-15-000006
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/92/14-15	18/03/2015	90Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
18/03/2015	18/03/2016	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramadasappa
Date of Inspection	**Remarks**	
23/02/2017		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0077	NA	7th Main Road(Narmadanadi Road)
SegmentNo	**TotalLength**	
156/S-W0077/S121323	170.09	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sanjay NB		0.00
PhoneNo	**EmailId**	
9035274994		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Footpath in Brundavana nagar 6th Main,7th main and Surrounding areas in Ward No-156	1000000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	Drains And Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains and Footpath in Brundavana nagar 6th Main,7th main and Surrounding areas in Ward No-156	156-15-000007
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/Ae/WO NO/91/14-15	13/03/2015	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/03/2015	13/03/2016	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramadasappa
Date of Inspection	**Remarks**	
23/02/2017		

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0003	NA	15th Main Road
SegmentNo	**TotalLength**	
156/S-W0003/S122849	218.21	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sanjay NB		0.00
PhoneNo	**EmailId**	
9035274994		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and footpath in 15th main Raghavendra block and surrounding areas in Ward no-156	1000000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	Drains and Footpath works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drains and footpath in 15th main Raghavendra block and surrounding areas in Ward no-156	156-15-000011
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/90/14-15	13/03/2015	9 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/03/2015	13/03/2016	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramadasappa
Date of Inspection	**Remarks**	
23/02/2017		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0029, W0118, W0083, W0070	NA	12 main Road
SegmentNo	**TotalLength**	
156/C-W0029/S125554	247.13	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
G Umapathi		0.00
PhoneNo	**EmailId**	
9448026974		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains And Footpath in 4th cross and 5th cross in Raghavendra block in Ward no-156	1000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drains and Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains And Footpath in 4th cross and 5th cross(140 meters to bo considered) in Raghavendra block in Ward no-156	156-16-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/33/15-16	20/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/02/2016	20/02/2017	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Samandaiah
Date of Inspection	**Remarks**	
23/02/2017		

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0053, W0036, W0032, W0051, W0034, W0067, W0063, W	NA, Om Shakthi Lyt 8th Crs, 13th Crs, Om Shakthi Lyt 6th Crs, Kaveri Nagar Near Society Mahadevpura	8th Main Road
SegmentNo	**TotalLength**	
156/C-W0053/S011910	460.38	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
G Umapathi		0.00
PhoneNo	**EmailId**	
9448026974		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Footpath in Bhuvaneswara colony Cross road and surrounding Areas in Ward - 156	1000000	2016
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drains and Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains and Footpath in Bhuvaneswara colony Cross road and surrounding Areas (15th main to be included) in Ward -156	156-16-000010
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/35/15-16	20/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/02/2016	20/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Samandaiah
Date of Inspection	**Remarks**	
23/02/2017		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0150, W0152, W0169, W0199, I0191, W0195, W0160, W	NA, Vinayaka Lyt 1st Crs, Vinayaka Lyt 2nd Crs	PES Collage
SegmentNo	**TotalLength**	
156/C-W0150/S013842	461.02	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
G Umapathi		0.00
PhoneNo	**EmailId**	
9448026974		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Footpath in Nagendra Block 3rd Main and Cross Road in Ward-156	1000000	2016
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drains and Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains and Footpath in Nagendra Block 3rd Main and Cross Road in Ward-156	156-16-000013
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/37/15-16	20/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
20/02/2016	20/02/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Samandaiah
Date of Inspection	**Remarks**	
23/02/2017		

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0154, W0179, I0142, W0181, W0148, W0144	NA, Vinayaka Lyt 3rd Crs	BSK 1st Block
SegmentNo	**TotalLength**	
156/C-W0154/S020021	319.99	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
G Umapathi		0.00
PhoneNo	**EmailId**	
9448026974		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains and Footpath from 7 to 9th main and surrounding area in BSK 1st Block in word no-156	1500000	2015
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	Drains and Footpath Works
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drains and Footpath from 7 to 9th main and surrounding area in BSK 1st Block in word no-156	156-15-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/68/14-15	19/01/2015	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
19/01/2015	19/01/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramadasappa
Date of Inspection	**Remarks**	
23/02/2017		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0229, I0184, W0213, W0223, W0217, W0211, W0219, W	NA, Chowdeshwari Temple Rd, Vinayaka Lyt 3rd Crs, 16th Crs, 15th Crs, Om Shakthi Lyt 2nd Crs, 8th Cr	K R HOSPITAL OPPT TO PES COLLEGE CONNECTING ROAD
SegmentNo	**TotalLength**	
156/C-W0229/S010516	2116.68	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
SRI B ESHWARAIAH		0.00
PhoneNo	**EmailId**	
9880413927		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH IN WARD NO 156 SRINAGARA IN BBMP LIMITS	9998000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	SSM DRAIN, KERB STONE, CC DRAIN, SADARAHALLI TILES, CULVERT ETC	156-11-000042
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WONO/168/12-13	15/02/2013	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
15/02/2013	15/02/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		K B RAMADAS
Date of Inspection	**Remarks**	
06/04/2016	complete	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0010, W0087, W0012, W0019	NA, 3rd Crs Kaledasa Badavane, 4th Crs Kaledasa Badavane	Kalidasa road
SegmentNo	**TotalLength**	
156/C-W0010/S045824	182.98	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri N Pavan Kumar Contractor #16 vinayaka Ext Kempegowda Nagara Banglore-560019		828290.00
PhoneNo	**EmailId**	
2972035017		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to Drain and footpath in 4th cross in kalidasa layout in ward - 156	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drain And Footpath
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to Drain and footpath in 4th cross in kalidasa layout in ward - 156	156-13-000006
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/09/12-13	16/05/2013	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
23/05/2013	23/05/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
4		K.B.Ramadasappa
Date of Inspection	**Remarks**	
11/12/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0115, W0109, W0116, W0105, W0106, W0102, W0134, W	NA, 1st Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, 3rd Crs	KALAPPABLOCK
SegmentNo	**TotalLength**	
156/C-W0115/S021239	699.49	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
VINOD KUMAR B K		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to bad reaches of roads in bsk 2nd block and surrounding roads in ward no 156	1950000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to bad reaches of roads in bsk 2nd block and surrounding roads in ward no 156	156-14-000011
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/AE/WO NO/08/14-15	07/07/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/07/2014	07/07/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
I0184, W0225, W0182, W0180, W0231, W0227, W0229	NA	POST OFFICE
SegmentNo	**TotalLength**	
156/C-I0184/S022146	934.03	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H B RAJENDRA		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to BED reaches of roads in bsk 2nd block and surrounding roads in ward no 156	1910000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to BED reaches of roads in bsk 2nd block and surrounding roads in ward no 156	156-14-000011
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/03/14-15	04/06/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/06/2014	04/06/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0020, W0018, W0022, W0012, W0006, W0015, W	NA	KALIDASA MAIN ROAD
SegmentNo	**TotalLength**	
156/C-W0033/S023352	759.09	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
B K VINOD KUMAR		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to BED reaches of roads in Kalidaasa main roads and surrounding roads in ward no 156	1925000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to BED reaches of roads in Kalidaasa main roads and surrounding roads in ward no 156	156-14-000013
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/EST/63/14-15	07/07/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/07/2014	07/07/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0201, W0205, I0184, W0203, W0197, I0193, W0170, W	NA, Vinayaka Lyt 1st Crs, Vinayaka Lyt 2nd Crs	nagendra b block,raghvendra b block,krishna b bloc
SegmentNo	**TotalLength**	
156/S-W0201/S023545	1438.70	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
providing asphalting to bad reaches of roads in in bsk 1st block srinagaraand surrounding area in ward no 156	5000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	providing asphalting to bad reaches of roads in in bsk 1st block srinagaraand surrounding area in ward no 156	156-14-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/237/13-14	03/03/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/03/2014	03/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0137, I0120, W0090, W0033, W0098, W0097, W0078, W	NA, 16th Crs, Vinayaka Lyt 4th Crs	AVALAHALLI
SegmentNo	**TotalLength**	
156/C-W0137/S025132	848.95	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H B RAJENDRA		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 14TH TO 17TH MAIN Srinagara from Avalihalli Mian Road in ward no 156	1975000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to 14TH TO 17TH MAIN Srinagara from Avalihalli Mian Road in ward no 156	156-14-000010
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/07/14-15	07/07/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/07/2014	07/07/2015	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0033, W0015, W0031, W0017, W0005, W0007, W0023, W	NA, 8th Crs	WEAVERS COLONY
SegmentNo	**TotalLength**	
156/C-W0033/S033432	255.63	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H B RAJENDRA		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Weavers coloiny main road and Yamunandi road and Surrounding area in ward no 156	1900000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to Weavers coloiny main road and Yamunandi road and Surrounding area in ward no 156	156-14-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/05/14-15	04/06/2014	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/06/2014	04/06/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
I0184, W0164, W0215, W0182, W0217, W0176, W0172, W	NA, Chowdeshwari Temple Rd	BSK 2ND BLOCK
SegmentNo	**TotalLength**	
156/C-I0184/S033420	2073.56	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
provinding asphalting to bad reaches in ward 156 srinagara	7500000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	complete	156-14-000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/250/13/14		90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/03/2014	04/03/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0058, W0056, W0081, W0064, W0012, W0007, W0006, W	NA, 14th Crs	Harishta nagara
SegmentNo	**TotalLength**	
156/C-W0058/S035657	1609.88	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to bad reaches of roads in kalappa block Kalidasa layout and balance roads in ward no 156	5000000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
	Asphalting to bad reaches of roads in kalappa block Kalidasa layout and balance roads in ward no 156	156-14-000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/235/13-14	03/03/2014	90DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/03/2014	03/03/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0031, W0066, W0068, W0070, I0120, W0029, W0118, W	NA, 15th Crs, Om Shakthi Lyt 2nd Crs	MUNEHSWARA BLOCK
SegmentNo	**TotalLength**	
156/C-W0031/S040157	473.09	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H.B. Rajendra		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
providing asphalting to bad reaches of roads from 18th main to 11th main from avalahalli main road and surrounding areas in ward no 156 srinagara	1990000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	providing asphalting to bad reaches of roads from 18th main to 11th main from avalahalli main road and surrounding areas in ward no 156 srinagara	156-14-000012
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/04/14-15	04/06/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/06/2014	04/06/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0180, W0231	NA	50 feet road Srinagra
SegmentNo	**TotalLength**	
156/C-W0180/S120129	98.25	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRDL		0.00
PhoneNo	**EmailId**	
9845085903		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC box drain on 50 feet road from 10th main road upto Mahila co-operative bank Ltd	3000000	2013
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Construction of RCC box drain on 50 feet road from 10th main road upto Mahila co-operative bank Ltd in ward no 156.	156-13-000020
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/190/12-13	26/02/2013	180
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/02/2013	26/02/2014	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
14/07/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0229, W0231, W0182	12th Main Rd, 11th Main Rd, NA	HDFC ATM
SegmentNo	**TotalLength**	
156/C-W0229/S012748	114.25	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Moinuddin Shariff Contractor No/27 dispesary road Kalasipalyam Bangalore		430000.00
PhoneNo	**EmailId**	
9241567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain in 13th main road bsk 1st stag 2nd block in ward no-156	4800000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain in 13th main road bsk 1st stag 2nd block in ward no-156	156-11-000016
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/41/10-11	18/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
18/03/2011	18/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0227, W0182	13th Main Rd, NA	HDFC ATM
SegmentNo	**TotalLength**	
156/C-W0227/S014525	232.29	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Moinuddin Shariff Contractor No/27 dispesary road Kalasipalyam Bangalore		430000.00
PhoneNo	**EmailId**	
9224567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road side drain in 13th main road bsk 1st stag 2nd block in ward no-156	480000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road side drain in 13th main road bsk 1st stag 2nd block in ward no-156	156-11-000016
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG1/JE/Wo No/41/10-11	18/03/2011	90days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
18/03/2011	18/03/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0105, W0102, W0109	12th Crs, 10th Crs, 11th Main Kalapa Block	Rashmi niwas
SegmentNo	**TotalLength**	
156/C-W0105/S022903	62.20	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0100, W0105	NA, 12th Crs	Rashmi niwas
SegmentNo	**TotalLength**	
156/C-W0100/S023410	35.88	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0156, W0154, W0146, W0185, W0148, W0142, W0158, W	1st Crs, 1st Main Rd, 2nd Crs, 5th Main Rd, 3rd Crs, 5th Crs, Srinagara, 4th A Crs	Apollo pharmacy
SegmentNo	**TotalLength**	
156/C-W0156/S024235	283.43	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0156, W0154, W0181, W0148, W0142, W0144	1st Crs, 1st Main Rd, 8th Main Rd, 3rd Crs, 5th Crs, Srinagara, 4th A Crs	Maruthi complex
SegmentNo	**TotalLength**	
156/C-W0156/S024834	273.49	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0179, W0142	7th Main Rd, 5th Crs, Srinagara	Srinagar hospital
SegmentNo	**TotalLength**	
156/C-W0179/S025548	156.49	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0154, W0142, W0177	1st Main Rd, 5th Crs, Srinagara, 9th Main Rd	Srinagar hospital
SegmentNo	**TotalLength**	
156/C-W0154/S030208	154.64	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0173, W0142	Serevice Rd, 5th Crs, Srinagara	BBMP
SegmentNo	**TotalLength**	
156/C-W0173/S030559	148.39	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragav	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no-156 Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0159, W0132	1st Main Rd, 1st Crs	RK hospital
SegmentNo	**TotalLength**	
156/C-W0159/S031522	106.37	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Krishnappa block Ragavendra main road in ward no156-Srinagar	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no156-Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0132, W0157	1st Crs, 2nd Main Rd	srinivas chicken store
SegmentNo	**TotalLength**	
156/C-W0132/S032215	107.48	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendr	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no156-Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2013	06/08/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0149, W0135, W0120, W0139	NA, 3rd Crs Ragavendra Block, Avalahalli Main Rd	Bhagya arcade
SegmentNo	**TotalLength**	
156/C-W0149/S033923	43.07	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager-3 KRIDL #119,11th cross East park road BBMP Malleshwaram Banagalore		9286070.00
PhoneNo	**EmailId**	
1234567890		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Raga	10000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to bad reaches of road BSK 1st block from 4th main to 7th main 9th main to 12th main Ragavendra block Krishnappa block Ragavendra main road in ward no156-Srinagar	156-13-000024
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/Wo No/84/13-14	06/08/2013	6monthes
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
		Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
26/08/2015		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0129, W0097, I0120, W0033, W0098, W0093, W0099, W	NA, 16th Crs, 15th Crs, Vinayaka Lyt 4th Crs, Om Shakthi Lyt 3rd Crs	muneshwara block
SegmentNo	**TotalLength**	
156/C-W0129/S041051	432.58	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H.B. Rajendra		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
providing asphalting to bad reachesof roads from 18th main to 11th main avalahalli main road and surrounding areas in ward 156 srinagara	1990000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	providing asphalting to bad reachesof roads from 18th main to 11th main avalahalli main road and surrounding areas in ward 156 srinagara	156-14-000012
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/04/14-15	04/06/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/06/2014	04/06/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016	Completed	

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0048, W0045, W0107, W0084, W0050, W0109, W0100, W	NA, Subhash Chandra Bose Lyt, 1st Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	PIPELINE
SegmentNo	**TotalLength**	
156/C-W0048/S042017	547.03	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
H B RAJENDRA		0.00
PhoneNo	**EmailId**	
8888888888		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to bad reaches of roads IN 8TH, 9TH, 10TH MAIN ROAD SURROUNDING AREAS IN KALAPPA BLOCK in ward no 156	1950000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Asphalting to bad reaches of roads IN 8TH, 9TH, 10TH MAIN ROAD SURROUNDING AREAS IN KALAPPA BLOCK in ward no 156	156-14-000009
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/10/14-15	07/07/2014	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/07/2014	07/07/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Ramdasappa
Date of Inspection	**Remarks**	
08/03/2016		

Category	Photo
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0089	NA	Near Govt school
SegmentNo	**TotalLength**	
156/S-W0089/S124143	32.93	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9448075046		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
WARD EMERGENCY GRANT	2500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	CONCRET, RETAINING WALL, ORNAMENTAL GRILL WORKS, S
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	WARD EMERGENCY GRANT CONCRET, RETAINING WALL, ORNAMENTAL GRILL WORKS, SS RAILINGS , ASHWATH KATTE AND GRANITE WORKS IN WARD NO 156	156-13-000019
Work OrderNo	**Work Order Date**	**Period of Extention**
BG/AE/W0 NO/236/14-15	03/03/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/03/2014	03/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
3	completed	Ramdasappa
Date of Inspection	**Remarks**	
04/06/2016	completed	

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0134, W0183, W0181	1st Crs, NA, Vinayaka Lyt 3rd Crs	MADDURAMMA TEMPLE
SegmentNo	**TotalLength**	
156/C-W0134/S043437	98.57	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	**EmailId**	
9448075046		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RETAINING WALL AND SECONDARY DRAIN AT MADDURAMMA GROUND WARD NO 156	500000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	CONSTRUCTION OF RETAINING WALL AND SECONDARY DRAIN AT MADDURAMMA GROUND IN WARD NO 156	156-14-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/234/13-14	03/03/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/03/2014	03/03/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0	complete	Ramdasappa
Date of Inspection	**Remarks**	
04/06/2016	complete	

Category	Photo
Segment End	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	
Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	156	Srinagara
StreetID	**StreetName**	**Significant LandMark**
W0053, W0024, W0213	NA	BEHIND RAJIVEGANDHI STADIUM
SegmentNo	**TotalLength**	
156/C-W0053/S013400	101.26	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
KRISHNA MURTHY .L		0.00
PhoneNo	**EmailId**	
9448417302		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
PROVINDING CEMENT CONCRETE TO DAMAGED ROADS AND KACHA ROADS IMPROVEMENT TO DRAIN IN MAHADESHWARA LAYOUT BEHIND RAJIV GANDHI STADIUM IN WARD NO 156	1000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	PROVINDING CEMENT CONCRETE TO DAMAGED ROADS AND KACHA ROADS IMPROVEMENT TO DRAIN IN MAHADESHWARA LAYOUT BEHIND RAJIV GANDHI STADIUM IN WARD NO 156	156-12-0000040
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/BG/AE/WO NO/39/2013-14	06/06/2013	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/06/2013	06/06/2014	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
0		Ramdasappa
Date of Inspection	**Remarks**	
08/06/2016		

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	