



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0170	NA	MARENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0170/S014100	83.89	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.N.SHASHIDHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8231677612		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CONCRETE ROADS TO 8TH MAIN ROAD AND CROSS ROADS IN MARENAHALLI IN WARD No.168	19	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	CONCRETE ROAD	168-012-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBE/241/12-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0154	NA	MARENAHALLI MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0154/S014617	81.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.N.SHASHIDHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8231677612		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CONCRETE ROADS TO 8TH MAIN ROAD AND CROSS ROADS IN MARENAHALLI IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-012-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBE/241/12-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0162	NA	MARENAHALLI MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0162/S014731	82.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.N.SHASHIDHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8231677612		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CONCRETE ROADS TO 8TH MAIN ROAD AND CROSS ROADS IN MARENAHALLI IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-012-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBE/241/12-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148	NA	MARENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0148/S014901	131.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.N.SHASHIDHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8231677612		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CONCRETE ROADS TO 8TH MAIN ROAD AND CROSS ROADS IN MARENAHALLI IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-012-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBE/241/12-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0129	NA	MARENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0129/S015044	196.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.N.SHASHIDHAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8231677612		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CONCRETE ROADS TO 8TH MAIN ROAD AND CROSS ROADS IN MARENAHALLI IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	CONCRETE ROAD	168-012-000046
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBE/241/12-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0034	<b>StreetName</b> NA	<b>Significant LandMark</b> 4TH 'T' BLOCK
<b>SegmentNo</b> 168/S-W0034/S020358	<b>TotalLength</b> 234.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9342137826	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & ASPHALTING TO 14TH MAIN ROAD FROM 31ST CROSS ROAD37TH CROSS ROAD & 31ST CROSS ROAD 32ND CROSS 33RD A CROSS ROADS FROM 11TH MAI	<b>Sanctioned Amount</b> 40	<b>Sanctioned Year</b>
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000064
<b>Work OrderNo</b> EE/JN/DM/W.O/220/12-13	<b>Work Order Date</b> 08/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0020	<b>StreetName</b> NA	<b>Significant LandMark</b> 4TH 'T' BLOCK
<b>SegmentNo</b> 168/S-W0020/S021820	<b>TotalLength</b> 195.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9342137826	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & ASPHALTING TO 14TH MAIN ROAD FROM 31ST CROSS ROAD37TH CROSS ROAD & 31ST CROSS ROAD 32ND CROSS 33RD A CROSS ROADS FROM 11TH MAI	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000064
<b>Work OrderNo</b> EE/JN/DM/W.O/220/12-13	<b>Work Order Date</b> 08/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0024	<b>StreetName</b> NA	<b>Significant LandMark</b> 4TH 'T' BLOCK
<b>SegmentNo</b> 168/S-W0024/S022612	<b>TotalLength</b> 499.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9342137826	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & ASPHALTING TO 14TH MAIN ROAD FROM 31ST CROSS ROAD37TH CROSS ROAD & 31ST CROSS ROAD 32ND CROSS 33RD A CROSS ROADS FROM 11TH MAI	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000064
<b>Work OrderNo</b> EE/JN/DM/W.O/220/12-13	<b>Work Order Date</b> 08/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Ashok
08/10/2015	Remarks
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0044	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR BDA PARK
<b>SegmentNo</b> 168/S-W0044/S040208	<b>TotalLength</b> 315.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9342137826	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & ASPHALTING TO 34TH CROSS ROAD FROM 26TH A MAIN ROAD TO EAST END MAIN ROAD & 20TH MAIN ROAD FROM 32ND E CROSS ROAD TO 36TH	<b>Sanctioned Amount</b> 40	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000062
<b>Work OrderNo</b> EE/JN/DM/W.O/218/12-13	<b>Work Order Date</b> 05/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ashok
Date of Inspection	Remarks	
08/10/2015		
Category	Photo	
Road Condition		
Road Condition		




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0089	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR GANESHA TEMPLE
<b>SegmentNo</b> 168/S-W0089/S040702	<b>TotalLength</b> 425.23	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9342137826	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS & ASPHALTING TO 34TH CROSS ROAD FROM 26TH A MAIN ROAD TO EAST END MAIN ROAD & 20TH MAIN ROAD FROM 32ND E CROSS ROAD TO 36TH	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000062
<b>Work OrderNo</b> EE/JN/DM/W.O/218/12-13	<b>Work Order Date</b> 05/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
25		Ashok s biradar
Date of Inspection	Remarks	
29/01/2016		
Category	Photo	
Drain Condition		
Segment Start		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0046	NA	NEAR BHAVI PLAY GROUND
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0046/S070633	216.42	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. NARYANANASWAMY		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8372524687		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS SIDE DRAIN AT 34TH CROSS ROAD FROM 7TH MAIN ROAD TO 9TH MAIN ROAD IN 4TH BLOCK JAYANAGAR WARD No. 168	16	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ROAD SIDE DRAIN MAINTENANCE	168-13-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/DM/e-tender/W.O/308/12- 13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ashok
Date of Inspection	Remarks	
08/10/2015		

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0115	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR S.W.DRAIN MARENAHLLI
<b>SegmentNo</b> 168/S-W0115/S071922	<b>TotalLength</b> 321.00	
<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. SURI	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 8364253675	<b>EmailId</b>	
<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS ASPHATING 11TH A, 11TH B MAIN ROAD & 25TH MAIN ROAD FROM 41ST CROSS ROAD TO RING ROAD IN 9TH BLOCK JAYANAGAR WARD No. 168	<b>Sanctioned Amount</b> 18.5	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 168-13-000012
<b>Work OrderNo</b> EE/JN/DM/e-proc/TEND/212/12-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ashok
Date of Inspection	Remarks	
08/10/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0117	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR S.W.DRAIN MARENAHAIL
<b>SegmentNo</b> 168/S-W0117/S072251	<b>TotalLength</b> 153.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. SURI	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 8364253675	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS ASPHATING 11TH A, 11TH B MAIN ROAD & 25TH MAIN ROAD FROM 41ST CROSS ROAD TO RING ROAD IN 9TH BLOCK JAYANAGAR WARD No. 168	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> ASPHALTING	<b>Job No Work Code</b> 168-13-000012
<b>Work OrderNo</b> EE/JN/DM/e-proc/TEND/212/12-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0178	NA	TANK BUND MARENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0178/S072822	424.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI M.V KEMPEGOWDA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8124238787		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS ROAD AND RSD 8TH CROSS ROAD FROM 18TH MAIN ROAD TO 4TH MAIN ROAD, MARENAHALLI TANK BUND AREA IN WARD No.168	15	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	ROAD SIDE DRAIN	168-11-000075
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/101/2014-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0081	14th Crs	NEAR PLAY GROUND
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0081/S074119	187.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9478368972		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS ASPHATING 19TH MAIN FROM 35TH TO 36TH CROSS ROAD 21ST MAIN ROAD FROM 32ND CROSS ROD TO 36TH CROSS ROAD 17TH MAIN ROAD FROM 33RD	40	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-13-000063
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/109/2014-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0093	15th Crs	NEAR BWSSB QRTS
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0093/S074926	190.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9478368972		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS ASPHATING 19TH MAIN FROM 35TH TO 36TH CROSS ROAD 21ST MAIN ROAD FROM 32ND CROSS ROD TO 36TH CROSS ROAD 17TH MAIN ROAD FROM 33RD		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-13-000063
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/109/2014-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0069	NA	NEAR CANARA BANK
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0069/S075359	417.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9478368972		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROADS ASPHATING 19TH MAIN FROM 35TH TO 36TH CROSS ROAD 21ST MAIN ROAD FROM 32ND CROSS ROD TO 36TH CROSS ROAD 17TH MAIN ROAD FROM 33RD	40	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-13-000063
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/109/2014-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0073	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR WARD OFFICE (MLA OFFICE)
<b>SegmentNo</b> 168/S-W0073/S075617	<b>TotalLength</b> 326.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9478368972	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS ASPHATING 19TH MAIN FROM 35TH TO 36TH CROSS ROAD 21ST MAIN ROAD FROM 32ND CROSS ROD TO 36TH CROSS ROAD 17TH MAIN ROAD FROM 33RD	<b>Sanctioned Amount</b> 40	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 168-13-000063
<b>Work OrderNo</b> AEE/JN/SBC/109/2014-15	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
08/10/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0081	<b>StreetName</b> 14th Crs	<b>Significant LandMark</b> NEAR WARD OFFICE (MLA OFFICE)
<b>SegmentNo</b> 168/S-W0081/S075836	<b>TotalLength</b> 187.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9478368972	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OF ROADS ASPHATING 19TH MAIN FROM 35TH TO 36TH CROSS ROAD 21ST MAIN ROAD FROM 32ND CROSS ROD TO 36TH CROSS ROAD 17TH MAIN ROAD FROM 33RD	<b>Sanctioned Amount</b> 40	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 168-13-000063
<b>Work OrderNo</b> AEE/JN/SBC/109/2014-15	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Ashok
Date of Inspection	Remarks	
08/10/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0115	NA	5TH BLOCK JAYANAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0115/S080629	321.00	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. K.L.KAUSHIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8234674328		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO 11TH A 11TH B MAIN ROAD AND 13TH & 14TH CROSS ROAD IN 5TH BLOCK JAYANAGAR IN WARD No.168	19.98	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-12-000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/244/2012-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0117	NA	5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0117/S081313	153.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. K.L.KAUSHIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8234674328		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO 11TH A 11TH B MAIN ROAD AND 13TH & 14TH CROSS ROAD IN 5TH BLOCK JAYANAGAR IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-12-000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/244/2012-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0119	NA	5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0119/S081835	164.10	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. K.L.KAUSHIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8234674328		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO 11TH A 11TH B MAIN ROAD AND 13TH & 14TH CROSS ROAD IN 5TH BLOCK JAYANAGAR IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-12-000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/244/2012-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0132	NA	NEAR PARK
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0132/S081932	82.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. K.L.KAUSHIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8234674328		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO 11TH A 11TH B MAIN ROAD AND 13TH & 14TH CROSS ROAD IN 5TH BLOCK JAYANAGAR IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-12-000034
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBC/244/2012-13	31/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0015	NA	NEAR NMKRV COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0015/S082720	92.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.VINOD KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9238787233		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAINS AT 7TH MAIN ROAD FROM 25TH CROSS ROAD TO 27TH CROSS ROAD IN 3RD BLOCK JAYANAGAR IN WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-14-000016
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBR/41/2014-15	28/05/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004	NA	NEAR NMKRV COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0004/S083321	138.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.JAYANTH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980079579		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF ROAD SIDE DRAINS AT 24TH A CROSS ROAD FROM 7THB MAIN ROAD 8TH F MAIN ROAD IN 3RD BLOCK JAYANAGAR WARD NO.168	9.97	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-13-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SB/128/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	168	Pattabhiram Nagar
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0006	NA	NEAR NMKRV COLLEGE
<b>SegmentNo</b>	<b>TotalLength</b>	
168/S-W0006/S084023	370.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI .M.JAYANTH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980079579		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROAD SIDE DRAIN AT 25TH CROSS ROAD FROM 7TH B MAIN ROAD TO 8TH MAIN ROAD 3RD BLOCK JAYANAGAR WARD No.168		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		168-13-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
AEE/JN/SBR/129/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Ashok
<b>Date of Inspection</b>	<b>Remarks</b>	
08/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b> SOUTH	<b>WardNo</b> 168	<b>WardName</b> Pattabhiram Nagar
<b>StreetID</b> W0050	<b>StreetName</b> NA	<b>Significant LandMark</b> 4TH BLOCK
<b>SegmentNo</b> 168/S-W0050/S084654	<b>TotalLength</b> 234.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI.N.SHAHIDHAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 8237647612	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS OTO DRAIN AND COVERING THE DRAINS IN 34TH B CROSS ROAD FROM 11TH MAIN ROAD 16TH MAIN ROAD AT 4TH T BLOCK JAYANAGAR WARD No.168	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 168-11-000061
<b>Work OrderNo</b> AEE/JN/SBR/239/12-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
8		Ashok s biradar
Date of Inspection	Remarks	
29/01/2016		
Category	Photo	
Road Condition		
Segment Start		