



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0213	NA	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0213/S023856	398.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.S.RAJANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448056030		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RSD AT 11TH MAIN ROAD LEFT SIDE (WEST) BTM LAY-OUT 1ST STAGE IN WARD-171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		171-13.000015
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/DM/e-proc/TEND/W.O/232/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0213	NA	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0213/S024714	398.60	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RSD AT 11TH MAIN ROAD BTM LAY-OUT 1ST STAGE IN WARD-171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		171-13-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/TEND/W.O/261/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0193	Vinayaka Lyt 2nd Crs	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0193/S025135	183.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.S.RAJANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448056030		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RSD AT 9TH B MAIN ROAD BTM LAY- OUT 1ST STAGE IN WARD- 171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		171-13.000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/DM/e- proc/tend/W.O/158/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0195	NA	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0195/S025755	168.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.S.RAJANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448056030		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RSD AT 9TH C MAIN ROAD BTM LAY-OUT 1ST STAGE IN WARD-171	11	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Others	RSD
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		171-13.000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/DM/e- proc/tend/W.O/160/13-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0201	NA	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0201/S031651	183.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.S.RAJANNA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448056030		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS OF RSD AT 9TH D MAIN ROAD BTM LAY-OUT 1ST STAGE IN WARD-171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	171-13.000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/JN/DM/e-proc/tend/W.O/04/13 -14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0079	Om Shakthi Lyt 4th Crs	NEAR MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0079/S120407	219.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO MAIN ROAD,CROSSROAD & SURROUNDING AREAS IN NEW GURAPPANAPALYA IN WARD No.171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		171-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
W.O.EE/JN/DM/W.O/248/12.13/22 /2/14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 171	<b>WardName</b> Gurappanapalya
<b>StreetID</b> W0135	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR BAZAR STREET
<b>SegmentNo</b> 171/S-W0135/S122117	<b>TotalLength</b> 92.99	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO MAIN ROAD,CROSSROAD & SURROUNDING AREAS IN NEW GURAPPANAPALYA IN WARD No.171	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Routine Maintenance	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> WETMIX & BM TO ROAD CUT PORTION & SDBC TO CARRIAGE WIDTH	<b>Job No Work Code</b> 171-14-000006
<b>Work OrderNo</b> W.0.EE/JN/DM/W.O/248/12.13/22 /2/14	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/01/2016	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 171	<b>WardName</b> Gurappanapalya
<b>StreetID</b> W0003	<b>StreetName</b> NA	<b>Significant LandMark</b> BISMILLANAGAR
<b>SegmentNo</b> 171/S-W0003/S123414	<b>TotalLength</b> 207.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI PRATHICK.K.R.	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING AND LAYING CONCRETE TO 1ST CROSS ROAD IN WRD 171	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> WMM TO ROAD CUT PORTIONS FIXING OF KERB AND LAYING OF M20 RMC TO ROAD EXPENSION JOINT AND KERB	<b>Job No Work Code</b> 171.13.000028
<b>Work OrderNo</b> W.O.EE/JN/DM/EAST/WO/31/13- 14/29.7.13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
30/01/2016		

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 171	<b>WardName</b> Gurappanapalya
<b>StreetID</b> W0163	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR URDU SCHOOL
<b>SegmentNo</b> 171/S-W0163/S124418	<b>TotalLength</b> 187.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI PRATHICK.K.R.	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9740246979	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING AND LAYING TO CONCRETE TO D CROSS ROAD F CROSS ROAD 3RD TMAIN TO 2ND MAIN ROADIN WARD NO 171	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> WMM TO ROAD CUT PORTION FIXING OF KERB STONE M20 RMC	<b>Job No Work Code</b> 17-13.000035
<b>Work OrderNo</b> W.O.EE/JN/DM/EPRO/30/13.14/2 9.7.13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
30/01/2016		
Category	Photo	
Drain Condition		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100	NA	NEAR ABOOKUL MASJID
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0100/S125741	156.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI PRATHICK.K.R.		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740246979		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING AND LAYING TO CONCRETE TO F CROSS ROAD 3RD MAIN TO 2ND MAIN ROAD IN WARD NO 171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	50MTS LENGTH 5 MTS WIDTHFILLING ROAD CUTTING WITH WMM FIXING KERB AND LAYING M20 RMC	171-13.000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
W.O.EE/JN/DM/EPRO/O.S/W.O/3 2/13.14/29.7.13		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/01/2016	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0094	NA	GLOBAL SCHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0094/S010619	119.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO MAIN ROAD, & SURROUNDING AREAS IN NEW GURAPPANAPALYA IN WARD No.171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	96MTS LENGTH LAYING OF M7.5 FOLLOWED BY M20 RMC	171-14-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
W.0.EE/JN/DM/251/13.14/22/2/14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 171	<b>WardName</b> Gurappanapalya
<b>StreetID</b> W0089	<b>StreetName</b> NA	<b>Significant LandMark</b> MADARSAB LAY-OUT
<b>SegmentNo</b> 171/S-W0089/S015611	<b>TotalLength</b> 406.41	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448279917	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS TO MAIN ROAD, & SURROUNDING AREAS IN NEW GURAPPANAPALYA IN WARD No.171	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> 260 MTS. LENGTH 4MTS TO 8 MTS WIDTH.SCARIFING & LAYING M 7.50 AT WORST STRECTH LAYING M 20 RMC	<b>Job No Work Code</b> 171-14-000005
<b>Work OrderNo</b> W.O.EE/JN/DM/251/13.14/22/2/14	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/01/2016	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	171	Gurappanapalya
StreetID	StreetName	Significant LandMark
W0058	NA	GURAPPANAPALYA
SegmentNo	TotalLength	
171/S-W0058/S020934	517.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI SHASHIDHRAN		0.00
PhoneNo	EmailId	
9480319999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS ASPHALTING TO BAD ROADS IN GURAPPANPALYA NEW LAY-OUT IN WARD 171		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	425.0MTS LENGTH 6.5 TO 8 MTS WIDTH. PROVIDING BM TO WIDENING AND POT HOLES AND LAYING SDBC	171-12-000032
Work OrderNo	Work Order Date	Period of Extention
W.O.EE/JN/DM/EPRO/W.O/183/1 2-13.15.2.13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name suresh
Date of Inspection	Remarks
30/01/2016	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0144	3rd Crs	BAZAR STREET
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0144/S021600	569.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448279917		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS RSD & ROADS IN BAZAR STREET AND CONNECTING ROAD IN WARD NO.171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	200 MTS LENGTH 5.0MTS WIDTH SCARIFYING & LAYING M7.5 FOLLOWED BY M20 RMC TO ROADS	171-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
W.O.EE/JN/D.M/W.O/02/14/15/	31/05/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
SOUTH	171	Gurappanapalya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0012	NA	BISMILLANAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
171/S-W0012/S022454	196.63	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.SHIVARAJ		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9008463969		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING AND LAYING CONCRETE TO 4TH MAIN ROAD FROM 1ST CROSS ROAD F CROSS ROAD BISMILLANAGAR IN WRD 171		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	195 MTS LENGTH 6.50 TO 4.30 MTS C.C. ROAD.WET MIXING TO ROAD CUTTING FIXING OF KERB AND LAYING M20 RMC TO ROAD AND KERB PAINTING	171-13-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
W.O.EE/JN/DM/EPRO/PROP/TE NT/118/13-14	25/10/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
30/01/2016		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> SOUTH	<b>WardNo</b> 171	<b>WardName</b> Gurappanapalya
<b>StreetID</b> W0211	<b>StreetName</b> NA	<b>Significant LandMark</b> NEAR WARD OFFICE
<b>SegmentNo</b> 171/S-W0211/S023434	<b>TotalLength</b> 406.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b> S.SATISH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9901333577	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> PROVIDING CEMENT CONCRETE DRAIN AT 10TH MAIN ROAD WESTERN SIDE AT BTM 1ST STAGE MODIFIED TO SSM AND SOLID BLOCKS FLAGGI COURSE WESTERN SIDE	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> 375 MTS LENGTH (WESTERN SIDE SSM & SOLID BLOCKS FLAGGING COURSE TO EXISTING B,DS SLAB DRAIN COVERING WITH DRESSES B.S.SLAB KERB FIXING AND PAINTING	<b>Job No Work Code</b> 171-13-000013
<b>Work OrderNo</b> W.O.EE/JN/DM/EPRO/PROP/TE NT/W.O/171/12-13	<b>Work Order Date</b>	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/01/2016	

Category	Photo
Drain Condition	