



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0172	8th Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0172/S021830	59.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumulated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh.M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0174	7th C Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0174/S022125	81.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumulated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0170	7th B Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0170/S022321	142.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0090	7th Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0090/S022530	152.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0092	7th A Crs	Green view hospital
SegmentNo	TotalLength	
173/S-W0092/S022731	57.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumulated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0168	7th A Crs	Agara Tank,14th main road.
SegmentNo	TotalLength	
173/S-W0168/S022907	61.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0082	7th Crs	Vintage Bio-Fuels
SegmentNo	TotalLength	
173/S-W0082/S023153	129.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling pot holes by Concrete	173-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/21/2013 -14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0080	StreetName NA	Significant LandMark Vintage Bio-Fuels
SegmentNo 173/S-W0080/S023410	TotalLength 57.07	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0049	Kalyana Mantap Rd (Jakkasandra)	Government School, Sarjapura road, Jakkasandra
SegmentNo	TotalLength	
173/S-W0049/S023633	325.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	173-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/21/2013 -14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0074	StreetName NA	Significant LandMark Government School, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0074/S023915	TotalLength 73.75	
ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	
Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0040	StreetName 1st Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0040/S030320	TotalLength 71.22	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumulated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0061	StreetName 2nd Main Rd	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0061/S030739	TotalLength 77.64	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0059	StreetName 2nd Main Rd	Significant LandMark Government School, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0059/S031002	TotalLength 95.42	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0067	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra.
SegmentNo 173/S-W0067/S031213	TotalLength 57.36	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0075	StreetName NA	Significant LandMark Government School, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0075/S031502	TotalLength 38.08	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0050	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0050/S032042	TotalLength 76.11	


ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumulated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0056	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0056/S032301	TotalLength 78.47	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0058	StreetName 5th A Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0058/S032457	TotalLength 76.78	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0060	StreetName 6th Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0060/S032910	TotalLength 65.06	


ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0066	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0066/S033129	TotalLength 75.96	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0070	StreetName NA	Significant LandMark Agara tank, 14th Main road.
SegmentNo 173/S-W0070/S033333	TotalLength 185.62	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Not a Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0084	StreetName 6th B Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0084/S042523	TotalLength 61.55	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0086	NA	Agara Tank,14th main road.
SegmentNo	TotalLength	
173/S-W0086/S042737	131.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh.M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0088	StreetName NA	Significant LandMark Agara Tank,14th Main,HSR 5th Sector.
SegmentNo 173/S-W0088/S042931	TotalLength 28.65	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0076	StreetName 6th B Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0076/S043507	TotalLength 49.09	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		
Category	Photo	
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0068	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0068/S044005	TotalLength 48.12	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumulated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0062	StreetName 6th Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0062/S044147	TotalLength 129.29	



ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0069	StreetName 2nd Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0069/S044451	TotalLength 39.76	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0054	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0054/S045031	TotalLength 69.64	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0048	StreetName 1st Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0048/S045213	TotalLength 78.03	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0044	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0044/S045404	TotalLength 18.62	


ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0042	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0042/S045629	TotalLength 52.78	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0057	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0057/S045838	TotalLength 51.58	


ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0053	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0053/S050927	TotalLength 71.85	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0064	StreetName 5th Crs	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0064/S051500	TotalLength 58.69	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0051	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0051/S051648	TotalLength 47.50	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0063	StreetName NA	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0063/S051853	TotalLength 71.25	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
14/09/2015		
Category	Photo	
Road Condition		
Segment Start		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0047	StreetName 1st Main Rd	Significant LandMark Government school, Sarjapura road, Jakkasandra
SegmentNo 173/S-W0047/S052257	TotalLength 161.73	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0166	StreetName NA	Significant LandMark Green view Hospital
SegmentNo 173/S-W0166/S053342	TotalLength 118.30	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0139	NA	Green view Hospital
SegmentNo	TotalLength	
173/S-W0139/S054255	26.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumulated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0140	8th Crs Venkatapura	Government School,Venkatapura
SegmentNo	TotalLength	
173/S-W0140/S054853	401.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M a
Date of Inspection	Remarks	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0122	StreetName 9th Crs	Significant LandMark Government school,8th cross,Venkatapura
SegmentNo 173/S-W0122/S055827	TotalLength 96.50	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0126	NA	Government School,Venkapura.
SegmentNo	TotalLength	
173/S-W0126/S060216	50.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0202	10th Crs, Venkatapura Village	Grammer school,Venkatapura.
SegmentNo	TotalLength	
173/S-W0202/S060355	139.92	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	173-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/21/2013 -14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0204	11th Crs	Grammer school,Venkatapura
SegmentNo	TotalLength	
173/S-W0204/S060652	133.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	173-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/21/2013 -14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0206	12th Crs	Grammer school,Venkatapura.
SegmentNo	TotalLength	
173/S-W0206/S060938	365.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.Pratheek		0.00
PhoneNo	EmailId	
9740246979		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	Filling of pot holes by providing PCC 40mm & d/s and RMC M20 grade.	173-13-000003
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/21/2013 -14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0230	13th A Crs	Carmel Garden Public School, Teachers colony
SegmentNo	TotalLength	
173/S-W0230/S061438	116.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Manjunath		2055105.00
PhoneNo	EmailId	
9901233339		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads drains and culverts at 13th 'A' Cross in ward No.173(Jakkasandra) for the year	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Constructed RCC box drain at both sides and concreting to road portion.	173-12-000032
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/e-proc/W.O/86/2013-14	28/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0228	StreetName 13th B Crs	Significant LandMark Carmal Garden Public school,Teacher's colony
SegmentNo 173/S-W0228/S062128	TotalLength 89.97	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0224	StreetName 13th D Crs	Significant LandMark Carmel Garden school,Teacher's Colony
SegmentNo 173/S-W0224/S062856	TotalLength 99.30	



ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0016	1st Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0016/S064558	91.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged asphlat road surface	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh.M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0018	2nd Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0018/S065025	110.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged asphlat road surface	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0020	3rd Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0020/S065301	109.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing tack coat,Bituminous concrete and road marking	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0022	StreetName 3rd A Crs	Significant LandMark Model primary Governemnt school,KSRP Quarters
SegmentNo 173/S-W0022/S065508	TotalLength 107.68	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0026	3rd B Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0026/S065647	106.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0030	4th Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0030/S065827	106.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Providing tack coat,Bituminous concrete and road marking	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0024	3rd Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0024/S070006	85.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing tack coat,Bituminous concrete and road marking	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0028	3rd A Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0028/S070158	91.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing tack coat,Bituminous concrete and road marking	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0032	4th Crs	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0032/S070334	126.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0010	NA	Model primary Governemnt school,KSRP Quarters
SegmentNo	TotalLength	
173/S-W0010/S070632	757.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura 1st,2nd cross and surrounding cross roads Venkatapura in ward no. 173 (Jakkasandra)	4990000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing tack coat,Bituminous concrete and road marking	173-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/226/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0116	StreetName 7th A B C Crs	Significant LandMark Model primary Governemnt school,KSRP Quarters
SegmentNo 173/S-W0116/S041914	TotalLength 24.97	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Removing of accumulated debris
Tender Tender	WorkDetails Removing of debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0120	StreetName 7th C Crs	Significant LandMark Model primary Governemnt school,KSRP Quarters
SegmentNo 173/S-W0120/S042316	TotalLength 27.91	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0103	StreetName 6th Crs	Significant LandMark Government School,Venkatapura 8th cross
SegmentNo 173/S-W0103/S042926	TotalLength 118.01	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0119	StreetName 3rd Main Rd	Significant LandMark 8th cross, Government School, Venkatapura.
SegmentNo 173/S-W0119/S043234	TotalLength 115.10	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0123	StreetName 4th Main Rd	Significant LandMark 8th cross, Government School, Venkatapura.
SegmentNo 173/S-W0123/S043603	TotalLength 115.10	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2014 - 2015	Type of Work	Other Work Type
Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0125	StreetName 5th Main Rd	Significant LandMark 8th cross, Government School, Venkatapura.
SegmentNo 173/S-W0125/S043738	TotalLength 115.23	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013-14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0129	StreetName 6th Main Rd	Significant LandMark 8th cross, Government School, Venkatapura.
SegmentNo 173/S-W0129/S043943	TotalLength 116.30	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0131	StreetName 7th Main Rd	Significant LandMark 8th cross, Government School, Venkatapura.
SegmentNo 173/S-W0131/S044150	TotalLength 117.77	

ContractorDetails		
NameofContractor S.R.Ravindra	ContractorRegNo	Expenditure 0.00
PhoneNo 9886985169	EmailId	

Work Details		
NameOfWork Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	Sanctioned Amount 1200000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender Tender	WorkDetails Removing of accumalated debris	Job No Work Code 173-13-000002
Work OrderNo EE(BTM)/JE/E-Proc/W.O/73/2013 -14	Work Order Date 23/10/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0137	8th Main Rd	Green view Hospital
SegmentNo	TotalLength	
173/S-W0137/S044454	200.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumulated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0164	6th B Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0164/S044711	128.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0162	6th C Crs	Green View Hospital
SegmentNo	TotalLength	
173/S-W0162/S044908	123.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0158	14th Crs	Green view hospital
SegmentNo	TotalLength	
173/S-W0158/S045135	119.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging private tractor and labours for maintainance of footpath roads and road side drains Emergency works in ward No.173(Jakkasandra) for the year	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Removing of accumalated debris	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0238	StreetName Sree Kanteshwara Temple Street	Significant LandMark Park,HSR 5th sector
SegmentNo 173/S-W0238/S045343	TotalLength 270.63	

ContractorDetails		
NameofContractor K.R.Pratheek	ContractorRegNo	Expenditure 0.00
PhoneNo 9740246979	EmailId	

Work Details		
NameOfWork Filling of Pot holes and Road Cut portions of Main and Cross roads in ward No.173 Jakkasandra for the Year 2012 -13	Sanctioned Amount 800000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Pothole filling	Other Work Type
Tender Tender	WorkDetails Filling of pot hole by providing PCC 40mm & d/s and RMC M20 grade.	Job No Work Code 173-13-000003
Work OrderNo EE(BTM)/JE/E-Proc/W.O/21/2013 -14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
15/09/2015	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0236	5th Crs	GREEN VEIW HOSPITAL
SegmentNo	TotalLength	
173/S-W0236/S055341	148.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TECHNICAL MANAGER KRID Ltd		0.00
PhoneNo	EmailId	
9448279917		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th,5th cross and Surrounding Cross roads, HSR Layout,Jakkasandra in ward no. 173 (Jakkasandra)	1100000	
Year	Type of Work	Other Work Type
	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Providing Asphaltting to damaged asphalt surface	173-14-000020
Work OrderNo	Work Order Date	Period of Extention
EE (BTM)/WO/212/13-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0244	4th Crs	Green view Hospital
SegmentNo	TotalLength	
173/S-W0244/S023545	234.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448021479		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th,5th cross and Surrounding Cross roads, HSR Layout,Jakkasandra in ward no. 173 (Jakkasandra)	1100000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000020
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/212/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



Category	Photo
Road Condition	 <p> AG OF WORK Presenting Accounting for this fine street road Presenting City roads, up Estimated data sample in road no. 173 (Kachowale) ESTIMATE COST IN US \$ 100,000 CONTRACTORS NAME 100,000 </p> <p> <i>Handwritten:</i> 100,000 <i>Handwritten:</i> 100,000 <i>Handwritten:</i> 100,000 <i>Handwritten:</i> 100,000 </p>



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0236	5th Crs	Green view Hospital
SegmentNo	TotalLength	
173/S-W0236/S024547	148.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 11th,12th main and Surrounding Cross roads, HSR Layout in ward no. 173 (Jakkasandra)	4795000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting	173-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/227/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0232	6th Crs	Devi eye hospital
SegmentNo	TotalLength	
173/S-W0232/S024937	231.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 11th,12th main and Surrounding Cross roads, HSR Layout in ward no. 173 (Jakkasandra)	4795000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged asphalt surface	173-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/227/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0185	12th Main Rd	Devi eye hospital
SegmentNo	TotalLength	
173/S-W0185/S025603	258.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 11th,12th main and Surrounding Cross roads, HSR Layout in ward no. 173 (Jakkasandra)	4795000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/227/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0226	StreetName 13th C Crs	Significant LandMark Devi eye hospital
SegmentNo 173/S-W0226/S031155	TotalLength 417.46	
ContractorDetails		
NameofContractor Technical Manager,Karnataka Rural Infrastructure Development Ltd.,	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	
Work Details 9448279917		
NameOfWork Providing Asphaltting to 11th,12th main and Surrounding Cross roads, HSR Layout in ward no. 173 (Jakkasandra)	Sanctioned Amount 4795000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphaltting	Other Work Type
Tender	WorkDetails Providing Asphaltting to existing damaged surface and Construction of SSM flagging course drain (Individual work)	Job No Work Code 173-14-000018
Work OrderNo EE(BTM)/W.O/227/2013-14	Work Order Date 27/01/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
31/08/2015	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0031	Venkatapura Main Rd	ksrp quarters
SegmentNo	TotalLength	
173/S-W0031/S034457	715.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura main road and Teachers colony ward no. 173 (Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing Asphaltting to existing damaged surface	173-14-000016
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/225/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0161	5th Main Rd	carmal garden school
SegmentNo	TotalLength	
173/S-W0161/S040756	305.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Venkatapura main road and Teachers colony ward no. 173 (Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000016
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/225/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0187	13th Main Crs H S R Lyt	Devi eye Hospital
SegmentNo	TotalLength	
173/S-W0187/S041426	346.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 13th main,I gate road and Surrounding Cross roads, HSR Layout,Jakkasandra in ward no. 173 (Jakkasandra)	1950000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000019
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/213/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0176	8th Crs Jakkasandra	Green view hospital,Agara tank road
SegmentNo	TotalLength	
173/S-W0176/S041826	241.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 13th main,I gate road and Surrounding Cross roads, HSR Layout,Jakkasandra in ward no. 173 (Jakkasandra)	1950000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged asphalt surface	173-14-000019
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/213/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M ,
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0182	Venkatepura Main Rd	carmal garden school
SegmentNo	TotalLength	
173/S-W0182/S042617	370.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0210	1st Avenue Teachers Colony	Carmal garden school
SegmentNo	TotalLength	
173/S-W0210/S043027	206.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone SOUTH	WardNo 173	WardName Jakkasandra
StreetID W0147	StreetName 1st Main Rd Teacher's Colony	Significant LandMark Carmal garden school
SegmentNo 173/S-W0147/S043230	TotalLength 547.77	

ContractorDetails		
NameofContractor Technical Manager,Karnataka Rural Infrastructure Development Ltd.,	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details 9448279917		
NameOfWork Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	Sanctioned Amount 4996000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Asphaltting	Other Work Type
Tender Not a Tender	WorkDetails 1.)Providing Asphaltting to existing damaged asphalt surface and 2.)Construction of SSM Flagging couse drain along with cc to road widening portion (Individual work)	Job No Work Code 173-14-000014
Work OrderNo EE(BTM)/W.O/223/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
31/08/2015	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0208	13th Crs	Carmal garden school
SegmentNo	TotalLength	
173/S-W0208/S043550	358.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged asphalt surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0165	5th B Main Rd Teacher Colony	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0165/S044544	104.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0218	5th Avenue Teachers Colony	BBMP Contact point
SegmentNo	TotalLength	
173/S-W0218/S044832	102.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0163	NA	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0163/S045201	76.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Asphaltting to damaged road surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0167	NA	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0167/S045520	56.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 1st Avenue & main road inTeachers colony ward no. 173 Jakkasandra)	4996000	2014
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Asphaltting to damaged road surface	173-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/223/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0212	4th Avenue Teachers Colony	Carmal Garden public school
SegmentNo	TotalLength	
173/S-W0212/S045750	367.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0192	3rd Crs	Carmal Garden public school
SegmentNo	TotalLength	
173/S-W0192/S050852	204.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0216	6th Avenue Teachers Colony	Carmal Garden public school
SegmentNo	TotalLength	
173/S-W0216/S051127	150.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Providing Asphaltting to existing damaged road surface	173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0198	5th Crs	Carmal Garden public school
SegmentNo	TotalLength	
173/S-W0198/S051347	140.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged road surface	173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0006	8th Crs	Krupanidhi collage
SegmentNo	TotalLength	
173/S-W0006/S023059	195.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S.R.Ravindra		0.00
PhoneNo	EmailId	
9886985169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Engaging Private Tractor and Labours For Maintenance of Footpath Roads and Road side drains Emergency Works in ward no 173 Jakkasandra for the y	1200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Clearing of debris adjacent to road	173-13-000002
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/73/2013-14	23/10/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
14/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0186	2nd Avenue Teachers Colony	Carmel garden public school
SegmentNo	TotalLength	
173/S-W0186/S032451	360.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 2nd, & other avenues in Teacher's colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing Asphaltting to Existing damaged Asphalt surface and Construction of SSM flagging course drain (Individual Work)	173-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/221/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0184	1st Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0184/S034349	140.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 2nd, & other avenues in Teacher's colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
	Providing asphaltting to existing damaged asphalt surface	173-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/221/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0188	2nd Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0188/S034659	140.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 2nd, & other avenues in Teacher's colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/221/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0190	3rd Avenue Teachers Colony	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0190/S034953	363.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 2nd, & other avenues in Teacher's colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing Asphaltting to damaged asphalt surface and construction of SSM flagging course drain (Individual work)	173-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/221/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0149	2nd Main Rd	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0149/S035336	261.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0151	2nd A Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0151/S035702	92.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphating to damaged asphalt surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0153	2nd B Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0153/S035929	83.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0155	3rd Main Rd	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0155/S040141	229.85	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing asphaltting to existing damaged asphalt surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0157	4th Main Rd	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0157/S040425	221.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0169	6th Main Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0169/S040654	190.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
15/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0033	2nd Main Rd	KSRP Quarters,Venkatapura
SegmentNo	TotalLength	
173/S-W0033/S041319	162.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0095	NA	Government School,Venkatapura
SegmentNo	TotalLength	
173/S-W0095/S041615	80.28	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 3rd, to 7th main in Teachers colony ward no. 173 (Jakkasandra)	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender		173-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/222/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0196	5th A Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0196/S043716	66.18	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0194	3rd A Crs	Carmal garden public school
SegmentNo	TotalLength	
173/S-W0194/S043939	66.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.,		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 4th Avenue & main road inTeachers colony ward no. 173 (Jakkasandra)	4995000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphaltting to damaged road surface	173-14-000015
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/224/2013-14	27/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
09/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0089	NA	Venkateshwara Temple
SegmentNo	TotalLength	
173/S-W0089/S050042	96.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Srikanta		0.00
PhoneNo	EmailId	
9886009149		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concret road at 2nd main/ 1st 'A' main and surrounding roads at Venkatapura and surrounding area in ward No.173 Jakkasandra.	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Cocreting to damaged CC road	173-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/306/2013-14	18/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0128	NA	Venkateshwara temple
SegmentNo	TotalLength	
173/S-W0128/S051509	41.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Srikanta		0.00
PhoneNo	EmailId	
9886009149		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concret road at 2nd main/ 1st 'A' main and surrounding roads at Venkatapura and surrounding area in ward No.173 Jakkasandra.	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting to Road	173-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/306/2013-14	18/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0132	NA	Venkateshwara Temple
SegmentNo	TotalLength	
173/S-W0132/S051810	55.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.Srikanta		0.00
PhoneNo	EmailId	
9886009149		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing cement concret road at 2nd main/ 1st 'A' main and surrounding roads at Venkatapura and surrounding area in ward No.173 Jakkasandra.	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Concreting to road portion	173-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/JE/E-Proc/W.O/306/2013-14	18/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0111	2nd Main Rd	Venkateshwara temple
SegmentNo	TotalLength	
173/S-W0111/S052048	195.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details		
9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads,drains and Culverts at 10th C cross venkatapura in ward No.173	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of Drain and Providing Concreting to road	173-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/263/2013-14	01/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	173	Jakkasandra
StreetID	StreetName	Significant LandMark
W0091	8th Crs	Government School
SegmentNo	TotalLength	
173/S-W0091/S053312	141.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager,Karnataka Rural Infrastructure Development Ltd.		0.00
PhoneNo	EmailId	
Work Details 9448279917		

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads,drains and Culverts at 10th C cross venkatapura in ward No.173	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Concreting to road portion	173-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE(BTM)/W.O/263/2013-14	01/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Rajesh M
Date of Inspection	Remarks	
18/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	