ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0092, W0058, W0175, W0090, W0177, W0169, W0171, W	NA	Masidi and Kadernahalli Cricle
SegmentNo	**TotalLength**	
181/C-W0092/S021838	266.17	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S.Srinivasan		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Repair and construction of culverts and drains in Bendrenagar in Ward no 181.	1995000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drian, culvert and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Tender	Repair and construction of culverts and drains in Bendrenagar in Ward no 181.	181-14-000001
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/264/2013-14	03/02/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/02/2014	03/02/2015	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
05/03/2016	Completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0202, W0377, W0373, W0375	NA, V S T Opposite, 5th Crs, East Park Reje Lyt, 6th Crs, Muthkurappa Lyt	Bloss School
SegmentNo	**TotalLength**	
181/S-W0202/S024653	77.58	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S.Srinivasan		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert and improvements and drain 14th main and 58th cross junction ks layout in ward no 181	1995000	2014
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drian and Culvert
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction of culvert and improvements and drain 14th main and 58th cross junction ks layout in ward no 181	181-14-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/265/13-14	03/02/2014	90
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/02/2014	03/02/2015	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
05/03/2016	Completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0220, W0214, W0339, W0335	NA	Ambabavani Temple
SegmentNo	**TotalLength**	
181/C-W0220/S031153	105.91	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S.Srinivasan		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Repair and Improvements to drain and culvert at 58th cross and 49th Main Junction in Kumarswamy Layout Ward No. 181	800000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Repair and Improvements to drain and culvert at 58th cross and 49th Main Junction in Kumarswamy Layout Ward No. 181	181-15-000012
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/92/14-15	29/12/2014	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/12/2014	29/12/2015	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		A Narendra kumar
Date of Inspection	**Remarks**	
18/04/2016		

Category	Photo
Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0256	Ambedkar Nagar Slum	50 Feet Road Kumarswamy Layout
SegmentNo	**TotalLength**	
181/S-W0256/S035157	147.93	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S.Srinivasan		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 16th Cross road in K.S.Layout 2nd Stage in Ward No-181	800000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain at 16th Cross road in K.S.Layout 2nd Stage in Ward No-181	181-16-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/93/15-16	24/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/02/2016	24/02/2017	No

Field Inspection Details

Number of Trees	Other Information	Name
0		A Narendra kumar
Date of Inspection	**Remarks**	
27/04/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0227, W0134, W0136, W0138, W0140, W0098, W0096, W	NA, 1st Crs, 2nd Crs, 3rd Crs	Teachers Colony
SegmentNo	**TotalLength**	
181/C-W0227/S062556	337.65	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S.Srinivasan		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to left out drain at 1st Cross to 6th Cross Roads in Teachers Colony in Ward No-181	1200000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to left out drain at 1st Cross to 6th Cross Roads in Teachers Colony in Ward No-181	181-16-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/94/15-16	24/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/02/2016	24/02/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		A Narendra kumar
Date of Inspection	**Remarks**	
27/04/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0155, W0124	NA	Magnific School
SegmentNo	**TotalLength**	
181/C-W0155/S011837	51.27	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
N.Rajashekar		0.00
PhoneNo	**EmailId**	
9448082676		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and Culvert from 4th Cross to 6th Cross K.S.Layout 1st Stage in Ward No-181	600000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drains and Culvert
Tender	**WorkDetails**	**Job No Work Code**
	Improvements to drain and Culvert from 4th Cross to 6th Cross K.S.Layout 1st Stage in Ward No-181	181-16-000006
Work OrderNo	**Work Order Date**	**Period of Extention**
AE/WoNo/102/2015-16	25/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
25/02/2016	25/02/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar A
Date of Inspection	**Remarks**	
03/05/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0124	NA	Masjid
SegmentNo	**TotalLength**	
181/S-W0124/S012402	245.90	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Narasimharaju		0.00
PhoneNo	**EmailId**	
9845797979		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and culvert at 9th Cross JHBCS Layout in Ward No-181	1900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain and culvert at 9th Cross JHBCS Layout in Ward No-181	181-16-000008
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/62/2015-16	04/02/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/02/2016	04/02/2017	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar A
Date of Inspection	**Remarks**	
13/05/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0297, W0166, W0215, W0174, W0172	Old Panchayathi Office Rd, NA	Telephone Exchange
SegmentNo	**TotalLength**	
181/C-W0297/S014343	198.16	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3), KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culvert & Concreting to Bad reaches in Kumaraswamy Layout in Ward No-181	2000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Culvert and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Construction of culvert & Concreting to Bad reaches in Kumaraswamy Layout in Ward No-181	181-17-000005
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/35/2016-17	03/09/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/09/2016	01/09/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan h d
Date of Inspection	**Remarks**	
09/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0541, W0539, W0551	NA	APJ Abdul Kalam Park
SegmentNo	**TotalLength**	
181/S-W0541/S020037	256.33	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain culvert surrounding APJ Abdul Kalam Park ISRO Layout in Ward No-181	2500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain culvert surrounding APJ Abdul Kalam Park ISRO Layout in Ward No-181	181-17-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/34/2016-17	03/09/2016	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/09/2016	02/09/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan h d
Date of Inspection	**Remarks**	
09/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0541, I0333, W0543, I0549, W0551	NA	Near APJ Abdul kalam park
SegmentNo	**TotalLength**	
181/C-W0541/S020804	310.15	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3), KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain culvert & Improvements to drain surrounding Park at 12th Main road ISRO Layout in Ward No-181	2500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Culvert and Drains
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain culvert & Improvements to drain surrounding Park at 12th Main road ISRO Layout in Ward No-181	181-17-000002
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/33/2016-17	03/09/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/09/2016	02/09/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan h d
Date of Inspection	**Remarks**	
09/11/2016	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0517, W0511, W0497, W0529, W0509, W0495, W0531, W	NA, Doddenakundi Indstrial Rd	Satish Dhavan Park
SegmentNo	**TotalLength**	
181/C-W0517/S021528	331.47	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3), KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain culvert surrounding Satish Dhavan Park ISRO Layout in Ward No-181.	3000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain culvert surrounding Satish Dhavan Park ISRO Layout in Ward No-181.	181-17-000004
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/32/2016-17	03/09/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
03/09/2016	02/09/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Chethan h d
Date of Inspection	**Remarks**	
09/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0220, W0357, W0214, W0363, W0226, W0355	57th Crs, 61st Crs, 58th Crs, 61st Crs, 44th Crs, 62nd Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0220/S69455	134.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri K. Srikanta,		923730.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drain and Concrete Road 61 cross road Kumarswamy layout	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	Drain and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to drain and Concrete Road 61 cross road Kumarswamy layout	181-11-000053
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/44/11-12	22/07/2011	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/07/2011	22/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
0		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0339	64th Crs	Kumarsamy layout
SegmentNo	**TotalLength**	
181/S-W0339/S69850	331.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri R.J Srinivas		908380.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction masonry drains with covering at 64th cross road in ward no 181	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction masonry drains with covering at 64th cross road in ward no 181	181-11-000045
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/143/11-12	13/09/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/09/2011	13/09/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		H.Prakash
Date of Inspection	**Remarks**	
31/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0461, W0467, W0465, W0409, W0266, W0463	Isro Lyt, NA, NA, 4th Main Rd Kumarswamy Lyt, 14th Main Rd, 14th Main Rd	Kumarswamy loyuot
SegmentNo	**TotalLength**	
181/S-W0461/S69855	69.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri Prakas,Contractor		180400.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Masonary drain with BS Slab cover in Police station Road at 14th main junction in ward No-181	200000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Masonary drain with BS Slab cover in Police station Road at 14th main junction in ward No-181	181-11-000059
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/137/11-12	13/09/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/09/2011	13/09/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		H.Prakash
Date of Inspection	**Remarks**	
31/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0291	18th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0291/S69909	174.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri rajashekar Contractor		1773980.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction Culvert and Lead of Drain from B.W.S.S.B Pipeline Crossing to 18th main Kumarswamy layout	1999000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Construction Culvert and Lead of Drain from B.W.S.S.B Pipeline Crossing to 18th main Kumarswamy layout	181-11-000009
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/109/10-11	24/03/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2011	24/03/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0144, W0257, W0239	NA, 45th Crs, NA	Kumarswamy layput
SegmentNo	**TotalLength**	
181/S-W0144/S69933	54.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1718032.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layput	1600000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layput	181-11-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/57/11-12	27/07/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/07/2011	27/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
10/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0333	45th Crs	Kumaraswamy layout
SegmentNo	**TotalLength**	
181/S-W0333/S69951	80.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1503510.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layout	1600000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/57/11-12	27/07/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/07/2011	27/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
3		prakash
Date of Inspection	**Remarks**	
10/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0228, W0226, W0335, W0331	45th Crs, 44th Crs, 49th Main Rd, 9th Main Rd	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0228/S69964	138.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1503510.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layout	1600000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 45th cross road near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000034
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/57/11-12	27/07/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
27/07/2011	27/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0263, W0144, W0265, W0271, W0237	44th Crs, NA, 43rd Crs, 42nd Crs, 50 Ft Rd Kumarswamy Lyt	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0263/S69970	124.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1866720.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/66/11-12	28/07/2011	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/07/2011	28/07/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
2		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0335, W0224, W0331	49th Main Rd, 17th Crs, 9th Main Rd	kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0335/S69975	109.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1866720.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/66/11-12	28/07/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/07/2011	28/07/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
1		prakash
Date of Inspection	**Remarks**	
10/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0335, W0222	49th Main Rd, 16th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0335/S69986	50.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		1866720.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 43rd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000032
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/66/11-12	28/07/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/07/2011	28/07/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
18/02/2015	complet	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0379, W0234, W0226, W0367	53rd Main Rd, 25th Crs, 44th Crs, 52nd Main Rd	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0379/S69997	110.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
G.Krishna murthy		1781000.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drain and Providing Cement Concrete to 53rd main road and Conservancy lanes in Kumaraswamy layout 1st and 2nd stage	2000000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to drain and Providing Cement Concrete to 53rd main road and Conservancy lanes in Kumaraswamy layout 1st and 2nd stage	181-11-000013
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/114/10-11	24/03/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2011	24/03/2011	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	**Other Information**	**Name**
1		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0261, W0267, W0259, W0269, W0146	44th Crs, 43rd Crs, 45th Crs, 42nd Crs, 35th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0261/S70011	159.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
K.S Srinivasan		933284.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drain and Providing Covering Slabs to Drain at 36th cross of Kumarswamy layout	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to drain and Providing Covering Slabs to Drain at 36th cross of Kumarswamy layout	181-11-000030
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/77/11-12	07/08/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/08/2011	05/08/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
0		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0271	42nd Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0271/S70020	107.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar.		1863010.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000031
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/99/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0265	43rd Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0265/S70031	100.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1863010.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000031
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/99/11-12	06/08/2011	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
10/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0218	15th Crs	kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0218/S70035	103.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1863010.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	2000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 42nd cross roads near Pushpanjali and Lavakusha park of Kumaraswamy layout	181-11-000031
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/99/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
10/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0230, W0333	46th Crs, 45th Crs	Kumarswamy lyt
SegmentNo	**TotalLength**	
181/C-W0230/S050118	169.30	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1401710.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 46th cross roads Near Pushpanjali and lavakusha park of kumarswamy layout	1500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 46th cross roads Near Pushpanjali and lavakusha park of kumarswamy layout	181-11-000035
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/ 96/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0253, W0144, W0255, W0239, W0146	46th Crs, NA, 35th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0253/S104353	65.28	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1401710.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 46th cross roads Near Pushpanjali and lavakusha park of kumarswamy layout	1500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	Road and drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 46th cross roads Near Pushpanjali and lavakusha park of kumarswamy layout	181-11-000035
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/ 96/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
3		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0220, W0226, W0345, W0343	57th Crs, 44th Crs, 64th Crs, 63rd Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0220/S105848	29.49	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.T Srinivas		921050.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to Drain Concrete road 64th cross road at Kumarswamy layout	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to Drain Concrete road 64th cross road at Kumarswamy layout	181-11-000056
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/37/11-12	22/07/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
22/07/2011	22/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
5		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0177	3rd Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0177/S112104	40.80	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri B.H Shivakumar		1403950.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	2050000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	181-11-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/03/11-12	11/04/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
11/04/2011	11/04/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
2		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0175, W0090, W0058, M0142, W0173	4th Crs, NA, Subhash Chandra Boss Rd, Subramanyapura Mn Rd	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0175/S113838	39.81	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri B.H Shivakumar		1403950.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	2050000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	181-11-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/03/11-12	11/04/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
11/04/2011	11/04/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0171	5th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0171/S114346	42.94	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri B.H Shivakumar,		1403950.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	2050000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Detailed estimate for the work of improvement to drain and Providing B.S covering Slab to Bendrenagar 3rd Cross to 5th Cross	181-11-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/03/11-12	11/04/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
11/04/2011	11/04/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
11/02/2015	complete	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0169, W0173, W0090, W0177	NA	Subramanyapura Main Road
SegmentNo	**TotalLength**	
181/S-W0169/S052217	321.16	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V.K.Gopal		0.00
PhoneNo	**EmailId**	
9901000009		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains with covering slab and asphalting to roads to 6th cross road bendrenagar K S Layout in ward No.181	1900000	2012
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drain and Asphalting
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drains with covering slab and asphalting to roads to 6th cross road bendrenagar K S Layout in ward No.181	181-12-000037
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/103/13-14	23/10/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
23/10/2013	23/10/2014	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
27/05/2016		

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0169, W0175, W0167, W0058, W0213, W0171, W0177, W	NA	Subrmanyapura main Road
SegmentNo	**TotalLength**	
181/C-W0169/S054915	260.31	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V.K.Gopal		0.00
PhoneNo	**EmailId**	
9901000009		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to roads 8th cross bendrenagar K L layout in ward no.181	1950000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drain and asphalting
Tender	**WorkDetails**	**Job No Work Code**
	Improvements and asphalting to roads 8th cross bendrenagar K L layout in ward no.181	181-13-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/105/13-14	23/10/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
23/10/2013	23/10/2014	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
27/05/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0149	NA	Bhuvaneshwari School
SegmentNo	**TotalLength**	
181/S-W0149/S060121	188.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V.K.Gopal		0.00
PhoneNo	**EmailId**	
9901000009		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to road and asphalting to 9th cross in bendrenagar ward 181	1485000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drain and Asphalting
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to road and asphalting to 9th cross in bendrenagar ward 181	181-13-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/108/13-14	23/10/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
23/10/2013	23/10/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
27/05/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0147	NA	Subramanaypura Main Road
SegmentNo	**TotalLength**	
181/S-W0147/S061451	193.90	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
V.K.Gopal		0.00
PhoneNo	**EmailId**	
9901000009		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to roads 10th cross bendrenagar K L layout in ward no.181	1650000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	Drain And Asphalting
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements and asphalting to roads 10th cross bendrenagar K L layout in ward no.181	181-13-000016
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/107/13-14	23/10/2013	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
23/10/2013	23/10/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar
Date of Inspection	**Remarks**	
27/05/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0250, W0252, W0409, W0254, W0258, W0240, W0381, W	NA, Ambedkar Nagar Slum, 1st Crs, 3rd Crs	Kumarswamy Layout Police Station
SegmentNo	**TotalLength**	
181/C-W0250/S122440	873.51	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Vinod Kumar B.K		0.00
PhoneNo	**EmailId**	
9845222227		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11	5000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Asphalting
Tender	**WorkDetails**	**Job No Work Code**
Tender	Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11 works) Package-1 Improvements and asphalting to pipe line road from 71st Cross road to ISRO Layout road in ward No-181)	181-16-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(PN)AE/Wo N o/44/2016-17	03/09/2016	180 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/12/2016	20/12/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Chethan H D
Date of Inspection	**Remarks**	
24/12/2016	completed	

Category	Photo
Drain Condition	
Drain Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0299, W0389, W0170, W0395, W0174, W0391, W0399, W	Maheshwari Nagar Main Rd, V S T Opposite, 4th Crs, NA, Bimel Behind Rd, V S T Opposite, 3rd Crs	Sagar Hospital
SegmentNo	**TotalLength**	
181/S-W0299/S124040	761.54	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Vinod Kumar B.K		0.00
PhoneNo	**EmailId**	
9845222227		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11	5000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Asphalting
Tender	**WorkDetails**	**Job No Work Code**
Tender	Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11 works) Package-1 Improvements and asphalting to Sagar Hospital road from Water tank road to Pipe line in ward No-181)	181-16-000015
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(PN)AE/WO No/44/2016-17	03/09/2016	180 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/12/2016	20/12/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan H D
Date of Inspection	**Remarks**	
24/12/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0329, W0214, W0335	Lakshmi Sagar Lyt North Side, 1st Crs, NA	OPP to 15F Bus stop
SegmentNo	**TotalLength**	
181/C-W0329/S010301	168.33	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Vinod Kumar B.K		0.00
PhoneNo	**EmailId**	
9845222227		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11	10000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11 works) Package-1 Improvements and asphalting to water tank road from sagar College gate to 18th Main road in ward No-181)	181-16-000016
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(PN)AE/WoNo/44/2016-17	03/09/2016	180 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/12/2016	20/12/2017	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan H D
Date of Inspection	**Remarks**	
24/12/2016	completed	

Category	Photo
Drain Condition	
Footpath Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0152, W0251, W0261, W0267, W0148, W0259, W0269, W	NA, Maheshwaramma Temple Behind Rd, Maheshwari Nagar Ambedkar Rd, Ambedkar Nagar Slum	Pushpanjali and Lavakush park
SegmentNo	**TotalLength**	
181/C-W0152/S011237	485.08	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Vinod Kumar B.K		0.00
PhoneNo	**EmailId**	
9845222227		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11	5000000	2015-16
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Compreshensive Development of bad roads by providing asphalting and iprovements of roads side drains in Ward No-161, 181, 182 and 183 comprising of 11 works) Package-1 Improvements and asphalting to Subramanyapura Main road from Kadirenahalli Under Pass to Gowdanapalya Junction in ward No-182)	182-16-000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE(PN)AE/WoNo/ 44/2016-17	03/09/2016	180 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
21/12/2016	20/12/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan H D
Date of Inspection	**Remarks**	
24/12/2016	completed	

Category	Photo
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0551	NA	DR// APJ Kalam Park
SegmentNo	**TotalLength**	
181/S-W0551/S104511	153.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (West) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting work to 12th Main road in ISRO layout in Ward No-181	1500000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Asphalting work to 12th Main road in ISRO layout in Ward No-181	181-16-000017
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/43/2016-17	03/09/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
28/10/2016	28/10/2017	No

Field Inspection Details

Number of Trees	Other Information	Name
0		chethan H D
Date of Inspection	**Remarks**	
30/12/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0379	53rd Main Rd	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0379/S111717	98.06	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri Krishna murty		1379210.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain concrete road 53 main road from 24th to 26th cross road in ward no 181	1500000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to drain concrete road 53 main road from 24th to 26th cross road in ward no 181	181-11-000051
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/142/11-12	13/09/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/09/2011	13/09/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		H.Prakash
Date of Inspection	**Remarks**	
31/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0263	44th Crs	Kumaraswamy layout
SegmentNo	**TotalLength**	
181/S-W0263/S123632	65.18	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1690050.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 44th cross Near Pushpagiri and lava kusha Park of Kumaraswamy layout	1800000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 44th cross Near Pushpagiri and lava kusha Park of Kumaraswamy layout	181-11000033
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/97/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
3		prakash
Date of Inspection	**Remarks**	
18/02/2015	complet	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0232	47th Crs	Kumaraswamy layout
SegmentNo	**TotalLength**	
181/S-W0232/S125021	200.65	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.G.Yeshokumar		1690050.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Cement Concrete to 44th cross Near Pushpagiri and lava kusha Park of Kumaraswamy layout	1800000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Cement Concrete to 44th cross Near Pushpagiri and lava kusha Park of Kumaraswamy layout	181-11000033
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/97/11-12	06/08/2011	120 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/08/2011	06/08/2012	Yes

Field Inspection Details

Number of Trees	Other Information	Name
2		prakash
Date of Inspection	**Remarks**	
18/02/2015	complet	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0551	12th Main Rd	Kumarswamy layout
SegmentNo	**TotalLength**	
181/S-W0551/S125533	29.76	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri Krishna murty		1757650.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Details estimate for Improvement to drain water drain in 12th main road of ISRO layout in ward No-181	2000000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Details estimate for Improvement to drain water drain in 12th main road of ISRO layout in ward No-181	181-11-000014
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/112/10-11	24/03/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/03/2011	24/03/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
1		H.Prakash
Date of Inspection	**Remarks**	
29/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0248, W0383, W0409, W0246, W0250	NA, 1st Crs	Sri Raghavendra Temple
SegmentNo	**TotalLength**	
181/C-W0248/S031022	222.11	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and concreting to 75th and 76th Cross road in K.S.Layout in Ward no-181	1998000	2013-14
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Concret
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain and concreting to 75th and 76th Cross road in K.S.Layout in Ward no-181	181-13-000081
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/59/2015-16	26/11/2015	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/11/2015	26/11/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		narendra Kumar A
Date of Inspection	**Remarks**	
10/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0252, W0383, W0409, W0250	NA, 1st Crs	Sri Ragavendra Temple
SegmentNo	**TotalLength**	
181/C-W0252/S032556	215.79	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Impreovements to drains and concreteing to 77th, 68th Cross Road K.S layout in Ward No-181	1971000	2013-14
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Impreovements to drains and concreteing to 77th, 68th Cross Road K.S layout in Ward No-181	181-13-000083
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoN/60/15-16	26/11/2015	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/11/2015	25/11/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		narendra Kumar A
Date of Inspection	**Remarks**	
10/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0244, W0383, W0246, W0242, W0409	NA, 1st Crs	Raghevendra swamy temple
SegmentNo	**TotalLength**	
181/C-W0244/S033937	218.05	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and concreting to 73rd and 74th Cross road in K.S.Layout in ward No-181	1997000	2013-14
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drains and concreting to 73rd and 74th Cross road in K.S.Layout in ward No-181	181-13-000080
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/58/15-16	26/11/2015	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/11/2015	26/11/2016	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra Kumar A
Date of Inspection	**Remarks**	
10/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0242, W0383	NA, 1st Crs	Sri Raghavendra Swamy Temple
SegmentNo	**TotalLength**	
181/C-W0242/S034923	153.55	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drains and concreting to 72nd Cross road in K.S.Layout in ward No-181	1365000	2013-14
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Others	Drain and Concrete
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drains and concreting to 72nd Cross road in K.S.Layout in ward No-181	181-13-000079
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/57/2015-16	26/11/2015	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
11/02/2016	10/02/2017	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra Kumar A
Date of Inspection	**Remarks**	
10/11/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
M0142, W0070, W0068, W0121	Subramanyapura Mn Rd, Teacher Layout, NA, 4th Main Rd	banashankari
SegmentNo	**TotalLength**	
181/C-M0142/S031319	97.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri,L.R.Shambhulingappa		1451135.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement to drain and Culvert in 8th 9th and 10th cross of Teachers Colony Banashankari	2000000	2012
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement to drain and Culvert in 8th 9th and 10th cross of Teachers Colony Banashankari	180-12-000047
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/248/11-12	31/12/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
31/12/2011	31/12/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Paramesh Gowda
Date of Inspection	**Remarks**	
28/10/2014	complete	

Category	Photo
Drain Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0143, W0151, W0116, W0124	NA	Menaznagar Masjid
SegmentNo	**TotalLength**	
181/C-W0143/S021341	117.19	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Manjunatha.M.K		0.00
PhoneNo	**EmailId**	
9448085873		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Emergency Work in Ward No-181	1500000	2015
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Secondary drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Emergency Work in Ward No-181	181-16-000011
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/25/16-17	04/07/2016	90 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
04/07/2016	04/07/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra Kumar A
Date of Inspection	**Remarks**	
23/08/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
I0549, W0551	NA	Near Dr//APJ Kalam Park
SegmentNo	**TotalLength**	
181/C-I0549/S055241	110.96	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (3)		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Emergency Construction of RCC drain at 12th Main road, ISRO Layout in Ward No-181	4900000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC Drain Construction on w/s only
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Emergency Construction of RCC drain at 12th Main road, ISRO Layout in Ward No-181	181-16-000027
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/29/2016-17	16/07/2016	180 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
16/07/2016	16/07/2017	No

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar A
Date of Inspection	**Remarks**	
01/09/2016	completed	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0471, W0469, W0473, W0196, W0383, W0409, W0262	NA, 3rd Crs, 1st Crs, Ambedkar Nagar Slum	Kumarswamy Layout Bus stop
SegmentNo	**TotalLength**	
181/C-W0471/S040400	159.68	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical manager (3)		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Development and Improvements to roads and drains in Main road and cross roads in Ward no-181, Kumaraswamy Layout	5000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	SWD drain and drain
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Development and Improvements to roads and drains in Main road and cross roads in Ward no-181, Kumaraswamy Layout	181-16-000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WoNo/16/2016-17	06/06/2016	120 Days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
06/06/2016	06/06/2017	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra Kumar A
Date of Inspection	**Remarks**	
08/09/2016		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0234	25th Crs	petrol bunk
SegmentNo	**TotalLength**	
181/S-W0234/S8448	157.00	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
yathis	421	2000000.00
PhoneNo	**EmailId**	
	asas@gmail.com	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
asphalting	1500000	2012
Year	**Type of Work**	**Other Work Type**
2012 - 2013	Asphalting	
Tender	**WorkDetails**	**Job No Work Code**
Tender		181-12-000001
Work OrderNo	**Work Order Date**	**Period of Extention**
01	06/12/2012	
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
07/03/2013	06/03/2014	No

Field Inspection Details

Number of Trees	Other Information	Name
0		narendra
Date of Inspection	**Remarks**	
21/08/2015		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0220, W0214, W0369, W0361, W0226	57th Crs, 58th Crs, 60th Crs, 44th Crs	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0220/S021335	52.51	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.Prakash		825030.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Drain and Concrete Road at 60th cross at Kumarswamy layout	1000000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Others	Road and drain
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement of Drain and Concrete Road at 60th cross at Kumarswamy layout	181-11-000047
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/135/11-12	13/09/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
13/09/2011	13/09/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
1		H.Prakash
Date of Inspection	**Remarks**	
31/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0347, W0220, W0214, W0351, W0349, W0226	62nd Crs, 57th Crs, 58th Crs, 50th A Main Rd, 63rd Crs, 44th Crs	Kumarswamylayout
SegmentNo	**TotalLength**	
181/C-W0347/S022543	35.77	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri Kushal Group		814130.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of Drain and Concrete Road at 62nd cross road at Kumarswamy layout	900000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvement of Drain and Concrete Road at 62nd cross road at Kumarswamy layout	181-11-000054
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/71/10-11	29/07/2011	60 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
29/07/2011	29/07/2012	No

Field Inspection Details

Number of Trees	Other Information	Name
2		H.Prakash
Date of Inspection	**Remarks**	
31/10/2014	complete	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Road Condition	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition	
Segment End	
Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0443, W0214, W0260, W0212, W0196, W0339, W0206, W	13/5th Crs , Vajramuni Rd, 58th Crs, 71st Crs, 66th Crs, 69th Crs, 64th Crs, 67th Crs, 70th Crs, 68t	Kumarswamy layout
SegmentNo	**TotalLength**	
181/C-W0443/S024045	108.63	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Sri.Prakash		1558430.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drain and providing B.S covering slabs at 13main road from 64 cross road at Kumarswamy layout	1700000	2011
Year	**Type of Work**	**Other Work Type**
2011 - 2012	Drain Maintenance	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Improvements to Drain and providing B.S covering slabs at 13main road from 64 cross road at Kumarswamy layout	181-11-000003
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/81/11-12	05/08/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
05/08/2011	05/08/2012	No

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		narendra
Date of Inspection	**Remarks**	
21/08/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0142, W0300, W0304, W0387, W0270, W0268, W0313, W	NA, 6th Crs Gowdana Palya, Uttarahalli-bansankari Main Rd, 1st Main Rd, 1st B Crs K.s Layout, 35th C	Padmanabhanagara
SegmentNo	**TotalLength**	
181/C-W0142/S025914	144.60	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Technical Manager (west)		8480530.00
PhoneNo	**EmailId**	

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphalting to Roads of Gowdwnapalya muneswaranagar, Govinayakanahalli and Srinivasa tent road in ward no 182 of Padmanabhanagar	9080000	2011
Year	**Type of Work**	**Other Work Type**
2010 - 2011	Road	
Tender	**WorkDetails**	**Job No Work Code**
Tender	Providing Asphalting to Roads of Gowdwnapalya muneswaranagar, Govinayakanahalli and Srinivasa tent road in ward no 182 of Padmanabhanagar	182-11-000018
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/JE/WO NO/57/10-11	26/02/2011	90 days
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
26/02/2011	26/02/2012	Yes

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details

Number of Trees	Other Information	Name
0		narendra
Date of Inspection	**Remarks**	
21/08/2015		

Category	Photo
Drain Condition	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
SOUTH	181	Kumaraswamy Layout
StreetID	**StreetName**	**Significant LandMark**
W0203, W0118, W0211, W0209, W0207, W0205, W0120, W	NA	BWSSB Office
SegmentNo	**TotalLength**	
181/C-W0203/S042533	354.29	

ContractorDetails

NameofContractor	ContractorRegNo	Expenditure
Techanical Manager(3) KRIDL		0.00
PhoneNo	**EmailId**	
9986697126		

Work Details

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and roads kumarswamy layout in Ward No. 181	4000000	2013
Year	**Type of Work**	**Other Work Type**
2013 - 2014	Others	drain and roads
Tender	**WorkDetails**	**Job No Work Code**
Not a Tender	Improvements to drain and roads kumarswamy layout in Ward No. 181	181-14-000016
Work OrderNo	**Work Order Date**	**Period of Extention**
EE/PN/AE/WO NO/291/13-14	25/02/2014	120 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple Road Involved**
24/02/2014	14/03/2017	Yes

Field Inspection Details

Number of Trees	Other Information	Name
0		Narendra kumar A
Date of Inspection	**Remarks**	
02/04/2016		

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start	