



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0289	Chikkanna Lyt	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0289/S033505	365.02	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYANA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN IN 6TH CROSS RIGHT SIDE AT BANK OF BARODA COLONY IN WARD NO 187 PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL06/WO/103/2014- 15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0428	NA	SAHYADRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0428/S035814	185.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADIANARAYAN		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING FLAGGING COURSE AND R C C COVERING TO DRAIN IN SAYADRI LAYOUT IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/90/2013- 14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0283	NA	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0283/S040155	355.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
LINGEWODA SOMASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
0		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN IN 5TH CROSS LEFT SIDE AT BANK OF BARODA COLONY IN WARD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/167/2014- 15	28/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0301	Bimel Behind Rd	SLV Hotel
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0301/S033301	464.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Technical manager KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Drain, Culverts and Asphalt to road from 24th main road SLV Hotel to Brigade millenium Front gate in ward no 187 Puttenahalli	9990000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Drains Culver and Asphalt	187-14-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grants/W.O/200/2013-14	03/03/2014	117
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		m j kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
30/01/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Footpath Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0034	NA	Puttenahalli Palya
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0034/S055823	86.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Uday kumar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845183166		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Drain and Improvements to Road From Puttenahalli main road to SRK Layout In Puttenahalli Palya 16th main in ward no 187	9995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-12-000030
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 03/W.O/163/2014 -15	25/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
26/04/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0280	2nd Crs, Lakshmi Sagar Lyt	Puttenahalli
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0280/S043455	30.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Road and RCC Drain in Vinayaka Nagara in ward no 187 Puttenahalli	2000000	2015-16
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-16-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 02/W.O/09/2015-16	09/02/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tambraz
<b>Date of Inspection</b>	<b>Remarks</b>	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0329	Lakshmi Sagar Lyt North Side, 1st Crs	PUTTENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0329/S043932	289.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC DRAIN AND RCC DRAIN IN VINAYAKA NAGARA IN WARD NO 187 PUTTENAHALLI	2000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-16-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 02/W.O/21/2015-16	09/02/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0179	NA	MEDICAL STORE
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0179/S052447	215.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M VENKATASWAMY		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448617922		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN AT 22ND A MAIN ROAD IN SARAKKI KERE IN PUTTENAHALLI WARD		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/91/2013- 14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0185	NA	MEDICAL STORE
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0185/S053938	151.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M VENKATASWAMY		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448617922		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN AT 22ND MAIN ROAD IN SAFRFAKKI KERE IN PUTTENAHALLI WARD		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/91/2013- 14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0021	8th Crs	Puttenahalli Palya
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0021/S032816	27.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Adinarayana		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Drain and Improvements to roads in Ramappa Layout Puttenahalli in ward no 187	9995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 03/W.O/164/2014 -15	25/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
22/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0023	NA	Puttenahalli Palya
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0023/S033306	27.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Adinarayana		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Drain and Improvements to Roads in Ramappa Layout Puttenahalli Palya in ward no 187	9995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 03/W.O/164/2014 -15	25/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
22/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0034	NA	PUTTENAHALLI PALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0034/S033635	86.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYAN		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC Drain and Improvements to Roads in Ramappa Layout Puttenahalli Palya in ward no	9995000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-12-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/GL 03/W.O/164/2014 -15	25/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
22/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0193	Vinayaka Lyt 2nd Crs	Vinayaka Nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0193/S123544	396.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to road From Vinayaka nagara to Doresaani palya In ward No 187 Puttenahalli	5000000	2012-13
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
5		Kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0223	NA	vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0223/S010621	25.65	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
3		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0198	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0198/S010917	281.25	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0196	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0196/S013539	281.00	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
1		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0194	NA	Near Balumuri Ganesha Temple
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0194/S013838	296.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
3		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0202	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0202/S014228	278.10	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
8		kumat
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0197	Vinayaka Lyt 1st Crs	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0197/S014855	70.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0199	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0199/S015049	76.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL Bangalore		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doresaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add,Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0201	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0201/S015535	77.99	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Asphaltting to Roads From Vinayaka nagara to Doreasaani palya in ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/365/2 012-13	16/03/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumat
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0123	NA	Vinayaka nagara
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0123/S021442	60.08	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL Bangalore		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to Shamanna Garden and Murugarajendra Layout In ward no 187 Puttenahalli	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-14-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/213/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
8		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0119	NA	Muruga rajendra layout
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0119/S022023	395.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to Shamanna Garden and Murugarajendra Layout in ward no 187 Puttenahalli	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-14-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/213/2 013-14	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0106	NA	Shamanna Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0106/S023538	71.09	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to Shamanna Garden and Murugarajendra layout in ward no 187	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-14-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/213/2 013-14	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0117	NA	15 th Main road
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0117/S023916	612.71	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL Bangalore		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to Roads at Puttenahalli main road in ward no 187 Puttenahalli	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-13-000033
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/367/2 013-14	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
12		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0100	NA	Bommanna Compound
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0100/S033348	88.51	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to roads at Bommanna Compound in ward no 187 Puttenhalli	775000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	0	187-14-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/212/2013-14	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
6		Kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0113	3rd Crs	Bommanna Compound
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0113/S033812	148.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448683802		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing Asphaltting to Roads at Bommanna Compound in ward no 187 Puttenahalli	775000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-14-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/Add.Grant/W.O/212/2013-14	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
8		kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
21/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0049	NA	Murugarajendra layout
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0049/S111258	182.14	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
D MADAIAH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880089327		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN IN 1ST CROSS ROAD OF MURUGARAJENDRA LAYOUT IN WARD NO 187 PUTTENAHALLI	2150000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 06/W.O/71/2014- 15	15/12/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tambraz
<b>Date of Inspection</b>	<b>Remarks</b>	
29/11/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0290	NA	Silver Oak Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0290/S112209	149.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
V CHANDRASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886403151		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC Drain at Right Side of main Road Siver Oak Layout Puttenahalli in Ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO175/2014-15	09/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tamras
<b>Date of Inspection</b>	<b>Remarks</b>	
27/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0294	NA	SILVER OAK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0294/S112743	389.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
V CHANDRASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886403151		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC Drain at Right Side of main Road Siver Oak Layout Puttenahalli in Ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/175/2014-15	09/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tamras
<b>Date of Inspection</b>	<b>Remarks</b>	
27/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0296	1st Crs	SIVER OAK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0296/S113039	298.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
V CHANDRASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886403151		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC Drain at Right Side of main Road Siver Oak Layout Puttenahalli in Ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/175/2014-15	09/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tamras
<b>Date of Inspection</b>	<b>Remarks</b>	
27/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0286	4th Crs, Maheshwari Nagar	SILVER OAK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0286/S113252	93.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
V CHANDRASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886403151		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of CC Drain at Right Side of main Road Siver Oak Layout Puttenahalli in Ward no 187	5000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/175/2014-15	09/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tamras
<b>Date of Inspection</b>	<b>Remarks</b>	
27/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0275	NA	BOB Colony
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0275/S121837	208.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing RCC Drains in 5th Cross Right Side at Bank of Boraoda Colony in ward no 187 Puttenahalli	2890000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 07/W.O/128/2014 -15	07/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tambraz
<b>Date of Inspection</b>	<b>Remarks</b>	
06/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0242	NA	BOB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0242/S122303	40.99	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing RCC Drains in 5th Cross Right Side at Bank of Boraoda Colony in ward no 187 Puttenahalli	2890000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		187-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 07/W.O/128/2014 -15	07/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
06/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0293	Maheshwari Nagar Opp Police Station Rd	BOB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0293/S122444	139.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYANA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINS FROM PUTTENAHALLI MAIN ROAD TO 24TH MAIN ROAD VIA BOB COLONY IN WARD NO 187 PUTTENAHALLI	3360000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		187-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL 06/W.O/102/2014 -15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		F Tabraz
<b>Date of Inspection</b>	<b>Remarks</b>	
06/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0286	4th Crs, Maheshwari Nagar	24TH MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0286/S041719	93.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
LINGEGOWDA SOMASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
0		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN TO MAIN ROAD OF JAWARAJU LAYOUT IN WADRD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN07/WO/168/2014-15	28/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0292	3rd Crs Lakshmi Sagar Lyt	24TH MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0292/S041856	83.93	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
LINGEGOWDA SOMASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
0		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN TO MAIN ROAD OF JAWARAJU LAYOUT IN WADRD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/168/2014- 15	28/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0381	NA	DORESANI PALYA
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0381/S042615	509.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYANA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN AND CEMENT CONCRETE PAVEMENTS IN DORESANI PALYA IN WARD NO 187 PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	100 MTR	187-14-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/89/2013-14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	Ambedkar Nagar Slum	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0259/S043601	349.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYANA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN IN 3RD MAIN ROAD OF BOB COLONY IN WARD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/117/2013- 14	22/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0294	NA	24TH MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0294/S044159	389.05	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K LOKA RAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
0		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF C C DRAIN AT LEFT SIDE OF MAIN ROAD SILVER OAK LAYOUT IN PUTTENAHALLI WARD NO 187		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL09/WO/ /2014-15	09/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0289	Chikkanna Lyt	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0289/S044756	365.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYAN		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAINS IN 6TH CROSS LEFT SIDE AT BANK OF BARODA COLONY IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
WW/BH/TEN/GL06/WO/101/2014-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	Ambedkar Nagar Slum	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0259/S045103	349.94	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
ADINARAYAN		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449818087		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAIN IN 3RD MAIN ROAD OF BOB COLONY IN WARD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL05/WO/88/2013- 14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0161	NA	MURUGARAJENDRA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0161/S045518	308.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT SHAMANNA GARDEN AND MURUGARAJENDRA LAYOUT IN WARD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/21 3/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0246	NA	NEAR PETROL BUNK
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0246/S050026	121.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNIAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT PUTTENAHALLI MAIN ROAD IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/ADDGRANTS/WO/21 5/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0250	NA	PUTTENAHALLI MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0250/S050235	132.68	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT PUTTENAHALLI MAIN ROAD IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	187-14-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/ADDGRANTS/WO/215/20 12-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
07/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0253	NA	BANK OF BARODA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0253/S051102	394.76	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT BANK OF BARODA COLNY 2ND 3RD AND 4TH CROSS ROADS IN WARD NO 187 PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/21 6/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	Ambedkar Nagar Slum	BANK OF BAROADA COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0259/S051324	349.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT BANK OF BAROADA COLNY 2ND 3RD AND 4TH CROSS ROADS IN WARD NO 187 PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/21 6/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0327	Lakshmi Sagar Lyt North Side, 2nd Crs	SILVER OAK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0327/S051655	365.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADDS AT SILVER OAK LAYOUT IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/214/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0283	NA	MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0283/S052409	355.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING R C C DRAINS IN 5TH CROSS RIGHT SIDE AT BANK OF BARODA COLONY IN WARD NO 187- PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL07/WO/128/2014- 15	07/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		KUMAR M J
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0283	NA	DOLLARS COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0283/S052932	355.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT DOLLARS COLONY ROAD AND PRIDE APARTMENT ROAD IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/21 0/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0289	Chikkanna Lyt	BOB COLONY
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0289/S053311	365.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER K R I D L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9945510720		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING ASPHALTING TO ROADS AT DOLLARS COLONY ROAD AND PRIDE APARTMENT ROAD IN WARD NO 187-PUTTENAHALLI		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		187-14-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/EST/ADDGRANTS/WO/21 0/2012-13	03/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Kumar M J
<b>Date of Inspection</b>	<b>Remarks</b>	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0275	NA	PUTTENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0275/S055655	208.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINS IN SURI NARAYANA COMPOUND IN WARD NO. 187 PUTTENAHALLI	3550000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	RCC DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	RCC DRAIN	187-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL06/WO/104/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2015	28/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		gopal reddy
<b>Date of Inspection</b>	<b>Remarks</b>	
09/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0248	NA	PUTTENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0248/S055930	41.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINS IN SURI NARAYANA COMPOUND IN WARD NO. 187 PUTTENAHALLI	3550000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	RCC DRAIN	187-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL06/WO/104/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2015	28/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		gopal reddy
<b>Date of Inspection</b>	<b>Remarks</b>	
09/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	187	Puttenahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0277	NA	PUTTENAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
187/S-W0277/S060020	87.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
BASAVARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972233039		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAINS IN SURI NARAYANA COMPOUND IN WARD NO. 187 PUTTENAHALLI	3550000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	RCC DRAIN	187-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BH/TEN/GL06/WO/104/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2015	28/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		gopal reddy
<b>Date of Inspection</b>	<b>Remarks</b>	
09/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	