



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0612	3rd Crs	Royla park residency layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0612/S092236	278.29	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	196-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/485/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0701	NA	Royla park residency layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0701/S093405	209.57	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	196-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/485/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0697	NA	Royal park residency layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0697/S093638	160.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/485/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0691	NA	Royal park residency layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0691/S093808	196.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of cross roads of Royal park layout in Avalahalli in Ward No 196	196-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/485/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0713	NA	Srinivasareddy layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0713/S095003	289.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain from Amrthnagara main road Shanidevara Temple road in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain from Amrthnagara main road Shanidevara Temple road in Avalahalli in Ward No 196	196-14-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/483/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0683	NA	Coconut garden Srinivasara Reddy layout
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0683/S100201	78.31	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Mettaling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0687	NA	Coconut garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0687/S101018	79.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		R Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0604	1st Crs	Coconut garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0604/S101340	417.94	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BS/D/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		R Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0705	NA	Coconut Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0705/S101615	64.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		R Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0703	NA	Coconut Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0703/S101846	56.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		R Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0707	NA	Coconut garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0707/S102007	56.87	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0709	NA	Coconut garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0709/S102112	124.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		R Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0711	NA	Coconut Garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0711/S102235	125.76	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BS/D/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0715	NA	Coconut garden
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0715/S102356	115.65	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828220		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	4000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	Metalling laying
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements of road and drain at Coconut garden in Avalahalli in Ward No 196	196-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/484/13-14	01/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		RMahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0056	NA	KEB Office
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0056/S015542	251.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
A.Francis		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9036718749		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Cross roads and drains at Annapoorneshwari layout in ward no 196	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		196-14-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/302/2013-14	22/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
17		R.Mahesh
<b>Date of Inspection</b>	<b>Remarks</b>	
21/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0126	NA	Harinagara Beereshwara Temple Road
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0126/S034448	324.95	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480282822		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Fixing of Covering slabs and Kerb to the drains at Harinagara main road in ward no 196	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	RCC Covering Slab and Kerb
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-14-000061
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/191/2014-15	02/02/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0563	Sathya Lyt	Avalahalli Chikka Masjid
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0563/S010950	115.27	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.C.Umesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9141667771		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Cross roads and drains at Avalahalli Zandagalli and Surrounding area in ward no 196	1800000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	RCC Road, Culverts and BS Slab drain
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		196-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/333/2013-14	22/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0480	NA	Avalahalli Chikka Masjid
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0480/S011514	173.52	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.C.Umesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9141667771		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Cross roads and drains at Avalahalli Zandagalli and surrounding area in ward no 196	1800000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		196-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/WO/333/2013-14	22/01/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0497	NA	Avalahalli Chikka Masjid
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0497/S012603	302.31	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.C.Umesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9141667771		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Cross roads and drains at Avalahalli Chikka Masjid Surrounding area in ward no 196	1800000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	0	196-14-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSO/NO/332/2013-14	22/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0466	1st Main Rd	BDA link Road
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0466/S013810	195.18	


ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.C.Umesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9141667771		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Cross roads and drains at Chittor Colony of Bhaskar Nagara in ward no 196	2013	1800000
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	RCC Road and Culverts
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		196-14-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/252/2013-14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0839	NA	Nandi Garden Phase 1
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0839/S014549	263.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
H.C.Umesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9141667771		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of road from Promac to Burial Ground next to Nadi Garden in ward no 196	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	RCC Road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		196-14-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/253/2013-14	16/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0255	Mahadevapura Village Rd	Near KPTCL Office
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0255/S064502	169.86	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480282822		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Roads, Drains culverts and UGD works in ward no 196 Anjanapura	5000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Resurfacing	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/298/2014-15	24/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0257	NA	Near KPTCL
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0257/S064816	172.54	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480282822		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Roads, Drains culverts and UGD works in ward no 196 Anjanapura	5000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Resurfacing	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/298/2014-15	24/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0587	2nd Crs	Near BSNL Office
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0587/S065040	97.01	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480282822		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Roads, Drains culverts and UGD works in ward no 196 Anjanapura	5000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	CC Road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/298/2014-15	24/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
BOMMANAHALLI	196	Anjanapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0566	NA	Near Gurukul School
<b>SegmentNo</b>	<b>TotalLength</b>	
196/S-W0566/S065224	426.81	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.R.I.D.L		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480282822		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements of Roads, Drains culverts and UGD works in ward no 196 Anjanapura	5000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	CC Road and Covering Slab
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		196-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BSD/WO/298/2014-15	24/03/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		maresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/01/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	