



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0459, W0340, W0344, W0439, W0342	1st Main Rd, NA, 1st Crs, 2nd Crs	Bharath English School
SegmentNo	TotalLength	
2/C-W0461/S121624	130.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		2811915.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain a	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construnction of CC drain to western side balance
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain at pump house in ward no-2	002-12-000010
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O.189.2011 -2012	18/08/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completrd	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0459, W0344, W0374	NA, 1st Crs	Bharath English high School
SegmentNo	TotalLength	
2/C-W0459/S122646	67.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		2811915.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain a	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construnction of CC drain to western side balance
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain at pump house in ward no-2	002-12-000010
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O.189.2011-2012	18/08/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramwsanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0410, W0519, W0428, W0396	NA, Masjid Rd	Juma Masidi
SegmentNo	TotalLength	
2/C-W0410/S123608	89.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		2811915.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain a	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construnction of CC drain to western side balance
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC drain to western side balance main and cross roads of Kamakshamma layout and providing CC Covering to Existing strom water drain at pump house in ward no-2	002-12-000010
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O.189.2011-2012	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0086, W0141, W0084	NA	Muneshwara temple
SegmentNo	TotalLength	
2/C-W0086/S124454	26.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B.Bumesh SMPL Construncton and Asphalt no- 2 1st Flor reddy complex Mejor sandhip Unnikrishna ro		126576.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC roads and covering slab to nagenahalli village in ward no-02	134700000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC roads and covering slab to nagenahalli village in ward no-02	002-22-000073
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 07/W.O.277.2011-2012	01/12/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/12/2011	01/12/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0086, W0141, W0135, W0139	NA	Muneshwara temple
SegmentNo	TotalLength	
2/C-W0086/S125505	67.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B.Bumesh SMPL Construncton and Asphalt no- 2 1st Flor reddy complex Mejor sandhip Unnikrishna ro		126576.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC roads and covering slab to nagenahalli village in ward no-02	134700000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC roads and covering slab to nagenahalli village in ward no-02	002-22-000073
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 07/W.O.277.2011-2012	01/12/2011	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/12/2011	01/12/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramassnjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0127, W0125, W0129	2nd Crs, NA	Muneshwara temple
SegmentNo	TotalLength	
2/C-W0127/S125858	22.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B.Bumesh SMPL Construncton and Asphalt no- 2 1st Flor reddy complex Mejor sandhip Unnikrishna ro		126576.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of CC roads and covering slab to nagenahalli village in ward no-02	134700000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of CC roads and covering slab to nagenahalli village in ward no-02	002-22-000073
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 07/W.O.277.2011-2012	01/12/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/12/2011	01/12/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0284, W0395	13th Crs, NA	Masidi
SegmentNo	TotalLength	
2/C-W0284/S010458	85.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Y.R Sridhar no-987 old Middal school road yelahanka		1723495.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	1900000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	002-11-000058
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 06/W.O.218.2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0413, W0298, W0393	NA	Chowdeshwari Layout
SegmentNo	TotalLength	
2/C-W0413/S011524	90.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Y.R Sridhar no-987 old Middal school road yelahanka		1723495.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	1900000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	002-11-000058
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 06/W.O.218.2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjrleevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0413, W0415, W0304, W0306, W0401, W0385, W0393	NA, 2nd Main Rd, 1st Main Rd, 9th Crs	Markandaya Temple
SegmentNo	TotalLength	
2/C-W0413/S012231	220.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Y.R Sridhar no-987 old Middal school road yelahanka		1723495.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	1900000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of Concrete roads at Kondappa layout eastern side in ward no-02	002-11-000058
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 06/W.O.218.2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0141, W0131, W0135, W0084, W0139	NA, 1st Crs	Muneshwara Temple
SegmentNo	TotalLength	
2/C-W0141/S022413	98.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri N Shivakumar Nagenahalli Singnayakanahalli (post) Yelahanka Hobli		902632.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of RCC drain and CC road at Nagenahalli cross roads in ward no-02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of RCC drain and CC road at Nagenahalli cross roads in ward no-02	002-11-000063
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend- 06/W.O.248.2011-2012	15/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/10/2011	15/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0252, W0349	Kalkki-bhagwan Rd 1st Main Rd, 1st Crs	bbmp help centrl
SegmentNo	TotalLength	
2/C-W0252/S021844	45.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
EE(YNK.D)E-TEND-06/W.O/239/2011-12		1364000.00
PhoneNo	Emailld	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	002-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-06/W.O/239/2011-12	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0123, W0127, W0125, W0129	3rd Crs, 2nd Crs, NA	Muneshwara Temple
SegmentNo	TotalLength	
2/C-W0123/S023225	48.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri N Shivakumar Nagenahalli Singnayakanahalli (post) Yelahanka Hobli		902632.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of RCC drain and CC road at Nagenahalli cross roads in ward no-02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construnction of RCC drain and CC road
Tender	WorkDetails	Job No Work Code
Tender	Construnction of RCC drain and CC road at Nagenahalli cross roads in ward no-02	002-11-000063
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)E-Tend-06/W.O.248.2011-2012	15/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/10/2011	15/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0341	NA	kendrya vidya c r p f
SegmentNo	TotalLength	
2/S-W0341/S023619	166.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
EE(YNK.D)E-TEND-06/W.O/239/2011-12		1364000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	002-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-06/W.O/239/2011-12	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0238, W0329	2nd Main Rd, 1st Crs	Ramanashri Hotel
SegmentNo	TotalLength	
2/C-W0238/S023824	139.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sRI Y.T.Kantharaj,no-977, Hosabeedi, Yelahanka		905150.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of RCC drain in main roads of Vinayaka Layout in ward no-02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construction of RCC drain in main roads
Tender	WorkDetails	Job No Work Code
Tender	Construnction of RCC drain in main roads of Vinayaka Layout in ward no-02	002-11-000064
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 06/W.O/221/2011-12	10/10/2011	90 dAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0345, W0341, W0347, W0343, W0264	NA	kendrya vidya C R P F
SegmentNo	TotalLength	
2/C-W0345/S024305	66.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
EE(YNK.D)E-TEND- 06/W.O/239/2011-12		1364000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no- 02	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	002-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 06/W.O/239/2011-12	10/10/2011	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0244, W0331	5th Main Rd, NA	Ramanashri Hotel
SegmentNo	TotalLength	
2/C-W0244/S025016	34.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sRI Y.T.Kantharaj,no-977, Hosabeedi, Yelahanka		905150.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of RCC drain in main roads of Vinayaka Layout in ward no-02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Construction of RCC drain in main roads
Tender	WorkDetails	Job No Work Code
Tender	Construnction of RCC drain in main roads of Vinayaka Layout in ward no-02	002-11-000064
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 06/W.O/221/2011-12	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0341, W0339	NA	kendraya vidya c r p f
SegmentNo	TotalLength	
2/C-W0341/S025107	26.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
EE(YNK.D)E-TEND-06/W.O/239/2011-12		1364000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of RCC drain at KHB COLONY PUTTENAHALLI IN WARD no-02	002-11-000061
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-06/W.O/239/2011-12	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0389, W0385, W0387, W0274	NA, 16th Crs	Kenchanahalli
SegmentNo	TotalLength	
2/C-W0389/S114531	178.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y.R.Sridhar no-987, old Middle school road Yelahanka		1530369.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	1700000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	002-12-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-03/W.O/15/2012-13	23/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0278, W0385, W0387, W0391	StreetName 15th Crs, NA	Significant LandMark Kenchanahalli
SegmentNo 2/C-W0278/S115443	TotalLength 112.56	

ContractorDetails		
NameofContractor Sri Y.R.Sridhar no-987, old Middle school road Yelahanka	ContractorRegNo	Expenditure 1530369.00
PhoneNo	EmailId	

Work Details		
NameOfWork providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	Sanctioned Amount 1700000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	Job No Work Code 002-12-000025
Work OrderNo EE(YNK.D)E-TEND-03/W.O/15/2012-13	Work Order Date 23/06/2012	Period of Extention 90 Days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0389, W0385	NA	Kenchanahalli
SegmentNo	TotalLength	
2/C-W0389/S115848	120.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y.R.Sridhar no-987, old Middle school road Yelahanka		1530369.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	1700000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	002-12-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/15/2012-13	23/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/06/2012	23/06/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
18/09/2015	completed

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0385, W0272	NA, 17th Crs	Kenchanahalli
SegmentNo	TotalLength	
2/C-W0385/S120209	97.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y.R.Sridhar no-987, old Middle school road Yelahanka		1530369.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	1700000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	providing RCC covering to Eastern side of Kondappa layout balance cross roads in ward no-02	002-12-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/15/2012-13	23/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0469, W0481, W0485, W0487, W0491, W0479, W0406	NA, 4th Main Rd, 8th Crs	anganavadi kendra
SegmentNo	TotalLength	
2/C-W0469/S115918	130.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y A dhanashekar no-1124 anjaneya temple street yelahanka		1336190.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc road at Besthare bheedhio in ward no;02	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc road at Besthare bheedhio in ward no;02	002-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/50/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0481, W0400, W0479, W0396, W0406	StreetName 4th Main Rd, 8th Crs, NA, Masjid Rd	Significant LandMark anganavadi kendra
SegmentNo 2/C-W0481/S121339	TotalLength 51.32	

ContractorDetails		
NameofContractor Sri Y A dhanashekar no-1124 anjaneya temple street yelahanka	ContractorRegNo	Expenditure 1336190.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of R cc road at Besthare bheedhio in ward no;02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Construction of R cc road at Besthare bheedhio in ward no;02	Job No Work Code 002-12-000022
Work OrderNo EE(YNK.D)E-TEND- 03/W.O/50/2012-13	Work Order Date 23/06/2012	Period of Extention 90 days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name ramasanjeevaiah
Date of Inspection 18/09/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0405, W0385, W0382, W0384, W0411	StreetName NA, 1st Crs	Significant LandMark Bharath English High School
SegmentNo 2/C-W0405/S121217	TotalLength 100.74	

ContractorDetails		
NameofContractor Sri Y.A.Dhanashekar no- 1124,Anjaneya temple street Yelahanka	ContractorRegNo	Expenditure 1349783.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain at Eastern side of Kama
Tender Tender	WorkDetails Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Job No Work Code 002-12-000026
Work OrderNo EE(YNK.D)E-TEND- 03/W.O/16/2012-13	Work Order Date 23/06/2012	Period of Extention 90 Days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0405, W0372, W0368, W0385, W0411, W0370	StreetName NA, 2nd Crs	Significant LandMark Bharath English High School
SegmentNo 2/C-W0405/S122128	TotalLength 99.49	

ContractorDetails		
NameofContractor Sri Y.A.Dhanashekar no- 1124,Anjaneya temple street Yelahanka	ContractorRegNo	Expenditure 1349783.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain at Eastern side of Kama
Tender Tender	WorkDetails Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Job No Work Code 002-12-000026
Work OrderNo EE(YNK.D)E-TEND- 03/W.O/16/2012-13	Work Order Date 23/06/2012	Period of Extention 90 Days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0405, W0366, W0385	StreetName NA	Significant LandMark Bharath English High School
SegmentNo 2/C-W0405/S122504	TotalLength 48.74	

ContractorDetails		
NameofContractor Sri Y.A.Dhanashekar no-1124,Anjaneya temple street Yelahanka	ContractorRegNo	Expenditure 1349783.00
PhoneNo	Emailld	

Work Details		
NameOfWork Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain at Eastern side of Kama
Tender Tender	WorkDetails Construnction of RCC drain at Eastern side of Kamakshamma layout balance cross roads in ward no-02	Job No Work Code 002-12-000026
Work OrderNo EE(YNK.D)E-TEND-03/W.O/16/2012-13	Work Order Date 23/06/2012	Period of Extention 90 Days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0467, W0396, W0411, W0394	StreetName NA, Masjid Rd	Significant LandMark anganavadi kendra
SegmentNo 2/C-W0467/S122625	TotalLength 31.49	

ContractorDetails		
NameofContractor Sri Y A dhanashekar no-1124 anjaneya temple street yelahanka	ContractorRegNo	Expenditure 1336190.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of R cc road at Besthare bheedhio in ward no;02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Construction of R cc road at Besthare bheedhio in ward no;02	Job No Work Code 002-12-000022
Work OrderNo EE(YNK.D)E-TEND-03/W.O/50/2012-13	Work Order Date 23/06/2012	Period of Extention 90 days
Defect Liability Period From 23/06/2012	Defect Liability Period To 23/06/2013	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name ramasanjeevaiah
Date of Inspection 18/09/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0513, W0446, W0493	NA, 1st Crs	vovt girls model school
SegmentNo	TotalLength	
2/C-W0513/S123029	64.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y A dhanashekar no-1124 anjaneya temple street yelahanka		1336190.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc road at Besthare bheedhio in ward no;02	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc road at Besthare bheedhio in ward no;02	002-12-000022
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/50/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0513, W0432, W0501, W0491, W0222, W0430, W0503	NA, 5th Crs, 7th Crs	govt urdu school
SegmentNo	TotalLength	
2/C-W0513/S012234	80.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y A dhanashekar no-1124 anjaneya temple street yelahanka		361335.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at masidi road near mahabub house in ward no-02	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at masidi road near mahabub house in ward no-02	002-11-000010
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 02/W.O/133/2011-12	17/05/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/05/2011	17/05/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
20/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0471, W0475, W0473	NA, 5th Main Rd	venu gopal swame temple
SegmentNo	TotalLength	
2/C-W0471/S020655	33.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri N thirunagendra no;184 besthara beedi yalahanka		754885.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of concrete road at kotebbedi cross roads in ward no;02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of concrete road at kotebbedi cross roads in ward no;02	002-11-000017
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 02/W.O/83/2011-12	22/03/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/03/2011	22/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0509, W0497, W0485, W0495, W0491, W0499, W	1st Main Rd, NA, Masjid Rd	GOVT Urdu High School
SegmentNo	TotalLength	
2/C-W0461/S022446	175.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri Y.A.Dhanashekar no- 1124,Anjaneya temple street Yelahanka		726240.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of Culverts at Masidi road near Mahabub house in ward no-02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of Culverts at Masidi road near Mahabub house in ward no-02	002-11-000018
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 02/W.O/42/2011-12	07/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0473	NA	venu gopal swane temple
SegmentNo	TotalLength	
2/S-W0473/S023039	39.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri N thirunagendra no;184 besthara beedi yalahanka		754885.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of concrete road at kotebbedi cross roads in ward no;02	1000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Road	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of concrete road at kotebbedi cross roads in ward no;02	002-11-000017
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 02/W.O/83/2011-12	22/03/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/03/2011	22/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0471, W0436, W0444, W0414, W0481, W0424, W0440	StreetName NA, 4th Crs, 2nd Crs, 4th Main Rd, 6th Crs, 3rd Crs	Significant LandMark anganavadi kendra
SegmentNo 2/C-W0471/S025937	TotalLength 80.71	

ContractorDetails		
NameofContractor Shri N thirunagendra no;184 besthara beedi yalahanka	ContractorRegNo	Expenditure 817122.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Construction of R cc drain at kote bheedi in ward -02	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of R cc drain at kote bheedi in ward -02	Job No Work Code 002-11-000009
Work OrderNo EE(YNK.D)E-TEND- 06/W.O/91/2011-12	Work Order Date 07/04/2011	Period of Extention 90 days
Defect Liability Period From 07/04/2011	Defect Liability Period To 07/04/2012	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 4	Other Information	Name ramasanjeevaiah
Date of Inspection 19/02/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0367, W0276, W0290, W0280, W0391, W0020, W0017, W	NA, 2nd Crs, 2nd Crs, Lakshmi Sagar Lyt, Chikkanna Lyt 4th Crs, Shetty Lyt, 4th Main Rd, Shetty Lyt	Yelahanka old town and Nagenahalli Road
SegmentNo	TotalLength	
2/C-W0367/S095501	24.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SAMBHASHIVAREDDY		0.00
PhoneNo	EmailId	
9972741359		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culvert at Yelahanka old town area in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	800000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CULVERT
Tender	WorkDetails	Job No Work Code
Tender	Construction of Culvert at Yelahanka old town area in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000002
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 3/WO/69/2016-17	19/05/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/05/2016	18/05/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		DAYANANDA
Date of Inspection	Remarks	
18/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0158, W0070, M0009	NA, Doddaballapura Rd	CRPF Quarters
SegmentNo	TotalLength	
2/C-W0158/S011222	453.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s, S.M.P.L Construction & Asphalt (B.B. Umesh), #2, 1st floor, reddy complex, major sandeep unnikr		734589.00
PhoneNo	EmailId	
Work Details		
1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Providing asphalt to main road and cross road of nagenahalli in ward no.2	1500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Providing asphalt to main road and cross road of nagenahalli in ward no.2	002-11-000062
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend-06/W.O/250/2011-12	15/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
13/07/2012	13/07/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0020, W0017, W0040, W0069	StreetName NA, 7th Crs, Isro Lyt, 5th Crs	Significant LandMark NAGENAHALLI and ISRO LAYOUT
SegmentNo 2/C-W0020/S104436	TotalLength 13.95	



ContractorDetails		
NameofContractor ADINARAYANA REDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9449217522	EmailId	

Work Details		
NameOfWork Construction of Culverts at Village area in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Sanctioned Amount 500000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Others	Other Work Type Culverts
Tender Tender	WorkDetails Construction of Culverts at Village area in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Job No Work Code 002-16-000003
Work OrderNo EE (YNK.D) E-PMT- 01/WO/15/2015-16	Work Order Date 24/02/2016	Period of Extention 90 DAYS
Defect Liability Period From 31/08/2016	Defect Liability Period To 30/08/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	DAYANADA
Date of Inspection	Remarks
10/01/2017	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0236, W0329	StreetName 1st Main Rd, 1st Crs	Significant LandMark Ramanashree Hotel
SegmentNo 2/C-W0236/S121858	TotalLength 228.14	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 4240000.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Sanctioned Amount 4500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type construction of cc drain and providing Asphaltting
Tender Tender	WorkDetails construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Job No Work Code 002-12-000009
Work OrderNo EE(YNK.D)E- TEND/W.O.188.2011-2012	Work Order Date 18/08/2011	Period of Extention 90 Days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0307, W0238, W0329	StreetName NA, 2nd Main Rd, 1st Crs	Significant LandMark Ramanashree Hotel
SegmentNo 2/C-W0307/S123245	TotalLength 265.33	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 4240000.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Sanctioned Amount 4500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type construction of cc drain and providing Asphaltting
Tender Tender	WorkDetails construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Job No Work Code 002-12-000009
Work OrderNo EE(YNK.D)E- TEND/W.O.188.2011-2012	Work Order Date 18/08/2011	Period of Extention 90 Days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0240, W0329	3rd Main Rd, 1st Crs	Vinayaka layout
SegmentNo	TotalLength	
2/C-W0240/S123805	184.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		4240000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	4500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	construction of cc drain and providing Asphaltting
Tender	WorkDetails	Job No Work Code
Tender	construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	002-12-000009
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E- TEND/W.O.188.2011-2012	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanieevaiah
Date of Inspection	Remarks	
19/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0242, W0329	4th Main Rd, 1st Crs	Vinayaka Layout
SegmentNo	TotalLength	
2/C-W0242/S124058	158.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		4240000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	4500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	construction of cc drain and providing Asphaltting
Tender	WorkDetails	Job No Work Code
Tender	construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	002-12-000009
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E- TEND/W.O.188.2011-2012	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0244, W0333, W0335, W0331, W0329	5th Main Rd, NA, 1st Crs	Vinayaka Layout
SegmentNo	TotalLength	
2/C-W0244/S124444	157.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		4240000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	4500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	construction of cc drain and providing Asphaltting
Tender	WorkDetails	Job No Work Code
Tender	construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	002-12-000009
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E- TEND/W.O.188.2011-2012	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0244, W0238, W0236, W0242, W0240, W0329	StreetName 5th Main Rd, 2nd Main Rd, 1st Main Rd, 4th Main Rd, 3rd Main Rd, 1st Crs	Significant LandMark Vinayaka Layout
SegmentNo 2/C-W0244/S124917	TotalLength 135.89	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 4240000.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Sanctioned Amount 4500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type construction of cc drain and providing Asphaltting
Tender Tender	WorkDetails construction of cc drain and providing Asphaltting to main and cross roads of Vinayaka layout in ward no-02	Job No Work Code 002-12-000009
Work OrderNo EE(YNK.D)E- TEND/W.O.188.2011-2012	Work Order Date 18/08/2011	Period of Extention 90 Days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0211, W0359, W0212, W0209, M0009	NA, Kenchanahalli Rd, Doddaballapura Rd	Brijesh Kumar I F S
SegmentNo	TotalLength	
2/C-W0211/S010202	635.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		4623790.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing Asphaltting from Doddaballapura main road to Kenchanahalli in ward no-02	4900000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	providing Asphaltting from Doddaballapura main road to Kenchanahalli in ward no-02	002-11-000053
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E- TEND/W.O.158.2011-2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevsiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0116, W0045, W0039, W0126, W0037, W0110, W0175, W	StreetName NA, Herohalli Rd, 1st Main Rd, 4th Crs, 3rd Crs, 2nd Crs	Significant LandMark Womens Association
SegmentNo 2/C-W0116/S012417	TotalLength 836.03	

ContractorDetails		
NameofContractor Y.B.Ramesh,No;34 Down Bazar road, yelahanka.	ContractorRegNo	Expenditure 853730.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Resectioning and desilting of primarystrome water drain at Harohalli, Putanahalli and Yelahanka 5th Phase near neha prakash Hospital in ward no-02	Sanctioned Amount 96500000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Resectioning and desilting of primarystrome water
Tender Tender	WorkDetails Resectioning and desilting of primarystrome water drain at Harohalli, Putanahalli and Yelahanka 5th Phase near neha prakash Hospital in ward no-02	Job No Work Code 002-12-000001
Work OrderNo EE(YNK.D)E-TEND- 05/W.O.202.2011-2012	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	
Category	Photo	
Drain Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0365, W0367, W0385, W0276	NA	masidi
SegmentNo	TotalLength	
2/C-W0365/S023350	217.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s hamsa no;895,6th main, 2nd stage 9th block,nagarabhavi		1348215.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at western side of kondappa lyt cross roads in ward no-02	1600000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at western side of kondappa lyt cross roads in ward no-02	002-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-03/W.O/51/2012-13	23/06/2012	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0367, W0276	NA	masidi
SegmentNo	TotalLength	
2/C-W0367/S024514	48.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s hamsa no;895,6th main, 2nd stage 9th block,nagarabhavi		1348215.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at western side of kondappa lyt cross roads in ward no-02	1600000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at western side of kondappa lyt cross roads in ward no-02	002-12-000027
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/51/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0392, W0396, W0517	StreetName NA, Masjid Rd	Significant LandMark Ashwath Katte
SegmentNo 2/C-W0392/S025114	TotalLength 79.97	

ContractorDetails		
NameofContractor sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage	ContractorRegNo	Expenditure 1621414.00
PhoneNo	Emailld	

Work Details		
NameOfWork Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Sanctioned Amount 1995000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain and CC Roads at Manavar
Tender Tender	WorkDetails Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Job No Work Code 002-12-000055
Work OrderNo EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	Work Order Date 16/08/2012	Period of Extention 90 days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0461, W0396, W0378	StreetName 1st Main Rd, Masjid Rd, NA	Significant LandMark BWSSB Pump House
SegmentNo 2/C-W0461/S030305	TotalLength 71.12	

ContractorDetails		
NameofContractor sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage	ContractorRegNo	Expenditure 1621414.00
PhoneNo	Emailld	

Work Details		
NameOfWork Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Sanctioned Amount 1995000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain and CC Roads at Manavar
Tender Tender	WorkDetails Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Job No Work Code 002-12-000055
Work OrderNo EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	Work Order Date 16/08/2012	Period of Extention 90 Days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0461, W0376, W0463, W0378	StreetName 1st Main Rd, NA	Significant LandMark BWSSB Pump House
SegmentNo 2/C-W0461/S030758	TotalLength 49.96	

ContractorDetails		
NameofContractor sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage	ContractorRegNo	Expenditure 1621414.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Sanctioned Amount 1995000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain and CC Roads at Manavar
Tender Tender	WorkDetails Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Job No Work Code 002-12-000055
Work OrderNo EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	Work Order Date 16/08/2012	Period of Extention 90 days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0459, W0344, W0374	NA, 1st Crs	Kamakshamma Layout
SegmentNo	TotalLength	
2/C-W0459/S031247	67.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage		1621414.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	1995000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	Construnction of RCC drain and CC Roads at Manavar
Tender	WorkDetails	Job No Work Code
Tender	Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no- 02	002-12-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	16/08/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
16/08/2012	16/08/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0352, W0374, W0358, W0457	StreetName NA	Significant LandMark Kamakshamma Layout
SegmentNo 2/C-W0352/S031600	TotalLength 51.52	

ContractorDetails		
NameofContractor sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage	ContractorRegNo	Expenditure 1621414.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Sanctioned Amount 1995000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain and CC Roads at Manavar
Tender Tender	WorkDetails Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Job No Work Code 002-12-000055
Work OrderNo EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	Work Order Date 16/08/2012	Period of Extention 90 days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0372, W0364, W0435, W0429, W0362	StreetName NA	Significant LandMark Bharath English high School
SegmentNo 2/C-W0372/S032053	TotalLength 54.95	

ContractorDetails		
NameofContractor sri B.R Mohan no-18 Govendappa Compound N.S.H RMV 2nd stage	ContractorRegNo	Expenditure 1621414.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Sanctioned Amount 1995000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construnction of RCC drain and CC Roads at Manavar
Tender Tender	WorkDetails Construnction of RCC drain and CC Roads at Manavarthi thota main and cross roads in ward no-02	Job No Work Code 002-12-000055
Work OrderNo EE(YNK.D)E-TEND- 04/W.O.102.2011-2012	Work Order Date 16/08/2012	Period of Extention 90 days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0280, W0391	2nd Crs, Lakshmi Sagar Lyt, NA	13th D Cross Roads of Eastern Side kondappa Layout
SegmentNo	TotalLength	
2/S-W0280/S010614	109.57	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
LINGRAJU		0.00
PhoneNo	EmailId	
9945799229		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to Drains at 13th D Cross Roads of Eastern Side kondappa Layout in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	800000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	DRAIN
Tender	WorkDetails	Job No Work Code
Tender	Improvements to Drains at 13th D Cross Roads of Eastern Side kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-15-000015
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 04/WO/68/2014-15	28/01/2015	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/04/2015	29/04/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		RAMASANJEEVAIAH
Date of Inspection	Remarks	
29/01/2017	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0380, W0385	StreetName 9th Crs Lakshmi Sagar Lyt, 8th Crs Gramatana	Significant LandMark SWD Drain near Easwarappa house Kamakshamma Layout
SegmentNo 2/C-W0380/S011554	TotalLength 37.97	

ContractorDetails		
NameofContractor LINGRAJU	ContractorRegNo	Expenditure 0.00
PhoneNo 9945799229	EmailId	

Work Details		
NameOfWork Providing CC Covering to Existing SWD Drain near Easwarappa house Kamakshamma Layout in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Others	Other Work Type SWD DRAIN
Tender Tender	WorkDetails Providing CC Covering to Existing SWD Drain near Easwarappa house Kamakshamma Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Job No Work Code 002-15-000017
Work OrderNo EE (YNK.D) E-PMT- 04/WO/69/2014-15	Work Order Date 28/01/2015	Period of Extention 90 DAYS
Defect Liability Period From 30/04/2015	Defect Liability Period To 29/04/2016	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		RAMASANJEEVAIAH
Date of Inspection	Remarks	
29/01/2017	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0110, W0161	Herohalli Rd, NA	anjenaya swamy temple
SegmentNo	TotalLength	
2/C-W0110/S120325	70.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI N KEERTHI,2ND MAIN RD GANDHINAGARA,YELAHAN KA		1364630.00
PhoneNo	EmailId	
Work Details		
1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Desilting and improvements to drain at naganahalli main road in ward no-2	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	Desilting and improvements to drain
Tender	WorkDetails	Job No Work Code
Tender	Desilting and improvements to drain at naganahalli main road in ward no-2	002-12-000048
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-03/W.O/26/2012-13	23/06/2012	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/08/2012	31/08/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0123, W0127, W0074, W0131, W0121	3rd Crs, 2nd Crs, Nagenahalli Rd, 1st Crs, 4th Crs	MUNESHWARA TEMPLE
SegmentNo	TotalLength	
2/C-W0123/S122238	106.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI N KEERTHI,2ND MAIN RD GANDHINAGARA,YELAHAN KA		1364630.00
PhoneNo	EmailId	
Work Details		
1234567890		

NameOfWork	Sanctioned Amount	Sanctioned Year
Desilting and improvements to drain at naganahalli main road in ward no-2	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	Desilting and improvements to drain
Tender	WorkDetails	Job No Work Code
Tender	Desilting and improvements to drain at naganahalli main road in ward no-2	002-12-000048
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/26/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/08/2012	31/08/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0216, W0226, W0220, W0218, W0224, W0169	NA	DG plant
SegmentNo	TotalLength	
2/C-W0216/S122939	125.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri .L.ravi chandra,no101,3rd cross,3rd main ,muneshwara block ,mhalakashmi layout		1635585.00
PhoneNo	EmailId	
984567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of cc roads to cross rds of kenchenahalli ward no-2	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of cc roads to cross rds of kenchenahalli ward no-2	002-11-000071
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 07/W.O/158/2011-12	05/10/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/11/2012	30/11/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0220	NA	Dg plants
SegmentNo	TotalLength	
2/S-W0220/S124437	29.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri .L.ravi chandra,no101,3rd cross,3rd main ,muneshwara block ,mhalakashmi layout		1635585.00
PhoneNo	Emailld	
924567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of cc roads to cross rds of kenchenahalli ward no-2	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of cc roads to cross rds of kenchenahalli ward no-2	002-11-000071
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-07/W.O/158/2011-12	05/10/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/11/2012	30/11/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0226	NA	Dg plant
SegmentNo	TotalLength	
2/S-W0226/S125034	12.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri .L.ravi chandra,no101,3rd cross,3rd main ,muneshwara block ,mhalakashmi layout		1635585.00
PhoneNo	Emailld	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of cc roads to cross rds of kenchenahalli ward no-2	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of cc roads to cross rds of kenchenahalli ward no-2	002-11-000071
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-07/W.O/158/2011-12	05/10/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/11/2012	30/11/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0247	NA	Dg plant
SegmentNo	TotalLength	
2/S-W0247/S125507	102.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri .L.ravi chandra,no101,3rd cross,3rd main ,muneshwara block ,mhalakashmi layout		1635585.00
PhoneNo	Emailld	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of cc roads to cross rds of kenchenahalli ward no-2	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of cc roads to cross rds of kenchenahalli ward no-2	002-11-000071
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-07/W.O/158/2011-12	05/10/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/11/2012	30/11/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0224, W0247	NA	Dg plant
SegmentNo	TotalLength	
2/C-W0224/S010005	10.05	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri .L.ravi chandra,no101,3rd cross,3rd main ,muneshwara block ,mhalakashmi layout		1635585.00
PhoneNo	Emailld	
1024567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of cc roads to cross rds of kenchenahalli ward no-2	1999000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	Construction of cc roads to cross rds of kenchenahalli ward no-2	002-11-000071
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-07/W.O/158/2011-12	05/10/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/11/2012	30/11/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0283	1st Crs	KHB colony
SegmentNo	TotalLength	
2/S-W0283/S011530	104.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Y.G Manjunath ,no;476,3rd main 3rd cross Attur layout Yelahanka		1760110.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc drain to main road cross roads of yelahanka 5th phase in ward no-02	1950000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc drain to main road cross roads of yelahanka 5th phase in ward no-02	002-11-000060
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND-06/W.O/220/2011-12	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0367, W0318, W0397	StreetName NA, 3rd Crs	Significant LandMark GOVT school
SegmentNo 2/C-W0367/S012513	TotalLength 90.79	

ContractorDetails		
NameofContractor Sri T.C Shankrappa shivpura caligadanahalli post srinivasapura taluk kolur dist	ContractorRegNo	Expenditure 1295145.00
PhoneNo	Emailld	

Work Details		
NameOfWork Construction of R cc drain at Kamakshamma layout western side balance cross road in ward no-02	Sanctioned Amount 1500000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type Construction of R cc drain \$ CC roads
Tender Tender	WorkDetails Construction of R cc drain at Kamakshamma layout western side balance cross road in ward no-02	Job No Work Code 002-12-000024
Work OrderNo EE(YNK.D)E-TEND- 03/W.O/01/2011-12	Work Order Date 20/06/2012	Period of Extention 90 days
Defect Liability Period From 20/06/2012	Defect Liability Period To 20/06/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
1		ramasanjevaiah
Date of Inspection	Remarks	
18/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0385, W0318	NA	Vidya Jyothi English School
SegmentNo	TotalLength	
2/C-W0385/S013419	68.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sri T.C Shankrappa shivpura caligadanahalli post srinivasapura taluk kolur dist		1295145.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc drain at Kamakshamma layout western side balance cross road in ward no-02	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	Construction of R cc drain \$RCC roads
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc drain at Kamakshamma layout western side balance cross road in ward no-02	002-12-000024
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 03/W.O/01/2011-12	20/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
20/06/2012	20/06/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjevaiah
Date of Inspection	Remarks	
18/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0469, W0481, W0485, W0487, W0491, W0479, W0406	NA, 4th Main Rd, 8th Crs	GOVT School
SegmentNo	TotalLength	
2/C-W0469/S014058	130.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri N.M rudra murthy no;183 sector A,5th A main Yelahanka new Town		395400.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc drain Besthara Beedi in ward no-02	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc drain Besthara Beedi in ward no-02	002-11-000008
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 02/W.O/137/2010-11	18/05/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/05/2011	18/05/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
1		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0086, W0125, W0074, W0131, W0084, W0082	NA, Nagenahalli Rd, 1st Crs	muneshwara temple
SegmentNo	TotalLength	
2/C-W0086/S125224	127.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		4324000.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding asphaltting to main and cross roads of nagenahalli in ward no-02	4600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding asphaltting to main and cross roads of nagenahalli in ward no-02	002-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/157/2011- 2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
21/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0127, W0125, W0129, W0074	2nd Crs, NA, Nagenahalli Rd	muneshwara temple
SegmentNo	TotalLength	
2/C-W0127/S010245	108.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		4324000.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding asphaltting to main and cross roads of nagenahalli in ward no-02	4600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding asphaltting to main and cross roads of nagenahalli in ward no-02	002-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/157/2011- 2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0123, W0125, W0074, W0080	3rd Crs, NA, Nagenahalli Rd	muneshwara temple
SegmentNo	TotalLength	
2/C-W0123/S011013	95.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		4324000.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding asphaltting to main and cross roads of nagenahalli in ward no-02	4600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding asphaltting to main and cross roads of nagenahalli in ward no-02	002-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/157/2011- 2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0115, W0074, W0121	NA, Nagenahalli Rd, 4th Crs	muneshwara temple
SegmentNo	TotalLength	
2/C-W0115/S011428	92.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		4324000.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding asphaltting to main and cross roads of nagenahalli in ward no-02	4600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding asphaltting to main and cross roads of nagenahalli in ward no-02	002-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/157/2011- 2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0115, W0074, W0117	NA, Nagenahalli Rd	muneshwara temple
SegmentNo	TotalLength	
2/C-W0115/S011822	47.33	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		4324000.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding asphaltting to main and cross roads of nagenahalli in ward no-02	4600000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding asphaltting to main and cross roads of nagenahalli in ward no-02	002-11-000052
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/157/2011- 2012	01/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2011	01/06/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0459, W0374, W0457	1st Main Rd, NA	bharath english high school
SegmentNo	TotalLength	
2/C-W0461/S015328	99.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri R S sriharsha no;112/66,5th cross balaji lyt vijayanagara		924820.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain and cc road at chowdeshwari lyt ni ward no;02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	Constrution of RCC drain and cc road
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain and cc road at chowdeshwari lyt ni ward no;02	002-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E tend-03/W.O/17/2012-2013	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0141, W0074, W0131, W0135, W0084, W0139, W0082	NA, Nagenahalli Rd, 1st Crs	muneshwara temple
SegmentNo	TotalLength	
2/C-W0141/S031835	222.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
shri B B umesh smpl no;2,1st flood ,reddy complex mejar sandhip unnikrisna road attur		1058622.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of cc road and covering slab to nagenahalli village in ward no;02	1347000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	rodas and coverig slab
Tender	WorkDetails	Job No Work Code
Tender		002-11-000073
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E tend- 07/W.O/278/2011-2012	01/12/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/12/2011	01/12/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0529, W0428, W0420, W0527	NA	shamulinga temple
SegmentNo	TotalLength	
2/C-W0529/S033141	37.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
shri L ravichandra no;101,3rd cross 3rd main muneshwara block mahalakshmi lyt		1414525.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of cc roads and drain at a.d colony j p colony in ward no;02	1999000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	drain and road
Tender	WorkDetails	Job No Work Code
Tender	construction of cc roads and drain at a.d colony j p colony in ward no;02	002-11-000070
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E tend-07/W.O/284/2011-2012	21/12/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
21/12/2011	21/12/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
1		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0116, W0039, W0126, W0110, W0185, W0177, W0128, W	StreetName NA, Herohalli Rd, 1st Main Rd, 4th Crs, 3rd Crs, 2nd Crs	Significant LandMark eshwaea temle
SegmentNo 2/C-W0116/S034013	TotalLength 350.17	

ContractorDetails		
NameofContractor sri N M rudramurthy no;183,5th a main a sector yalahanka new town	ContractorRegNo	Expenditure 555040.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of damaged ssn wall near anjaneya swamy temple in horohalliu in ward no;02	Sanctioned Amount 1998000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of damaged ssn wall near anjaneya swamy temple in horohalliu in ward no;02	Job No Work Code 002-12-000052
Work OrderNo EE(YNK.D)E tend- 04/W.O/156/2012-2013	Work Order Date 05/10/2012	Period of Extention 90 days
Defect Liability Period From 05/10/2012	Defect Liability Period To 05/10/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0286, W0290, W0365, W0367, W0282, W0276	NA	masidi
SegmentNo	TotalLength	
2/C-W0286/S034858	171.31	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
shri N C suresh no;58,5th main rd h v r lyt		1776930.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain and at kondappa lyt western side in ward no;02	1960000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain and at kondappa lyt western side in ward no;02	002-11-000057
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E tend- 06/W.O/217/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0365, W0367, W0282	NA	masidi
SegmentNo	TotalLength	
2/C-W0365/S035514	118.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
shri N C suresh no;58,5th main rd h v r lyt		1776930.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain and at kondappa lyt western side in ward no;2	1960000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain and at kondappa lyt western side in ward no;2	002-11-000057
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E tend- 06/W.O/217/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0459, W0374, W0457	1st Main Rd, NA	bharth english high school
SegmentNo	TotalLength	
2/C-W0461/S035827	95.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		1864747.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at manavarthi thita balance main and crosss roads in ward no;2	1980000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at manavarthi thita balance main and crosss roads in ward no;2	002-12-000060
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)/W.O/134/2012-2013	17/09/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/09/2012	17/09/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0306, W0443, W0441, W0316, W0310	1st Main Rd, NA	markandaya temple
SegmentNo	TotalLength	
2/C-W0306/S040648	140.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		1859324.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at chowdeshwari lyt balance main and cross roads in ward no;02	1980000	20102
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at chowdeshwari lyt balance main and cross roads in ward no;02	002-12-000061
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)/W.O/136/2012-2013	17/09/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/09/2012	17/09/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
1		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0031, W0110	StreetName NA, Herohalli Rd	Significant LandMark GOVT High school
SegmentNo 2/C-W0031/S115833	TotalLength 86.61	

ContractorDetails		
NameofContractor Shri N Keerthy 2nd Main road Gandhi nagara Yelahanka	ContractorRegNo	Expenditure 1247270.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Constnution of CC Road and CC drain at Chowdeshwari layout in Nagenahalli of ward no-02	Sanctioned Amount 1380000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constnution of CC Road and CC drain
Tender Tender	WorkDetails Constnution of CC Road and CC drain at Chowdeshwari layout in Nagenahalli of ward no-02	Job No Work Code 002-11-000065
Work OrderNo EE(YNK.D)TEND- 06/W.O/235/2011-2012	Work Order Date 10/10/2011	Period of Extention 90 days
Defect Liability Period From 10/10/2011	Defect Liability Period To 10/10/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0110, W0033	StreetName Herohalli Rd, NA	Significant LandMark GOVT High School
SegmentNo 2/C-W0110/S120638	TotalLength 67.50	

ContractorDetails		
NameofContractor Shri N Keerthy 2nd Main road Gandhi nagara Yelahanka	ContractorRegNo	Expenditure 1247270.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Constnution of CC Road and CC drain at Chowdeshwari layout in Nagenahalli of ward no-02	Sanctioned Amount 1380000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constnution of CC Road and CC drain
Tender Tender	WorkDetails Constnution of CC Road and CC drain at Chowdeshwari layout in Nagenahalli of ward no-02	Job No Work Code 002-11-000065
Work OrderNo EE(YNK.D)TEND- 06/W.O/235/2011-2012	Work Order Date 10/10/2011	Period of Extention 90 Days
Defect Liability Period From 10/10/2011	Defect Liability Period To 10/10/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjevaiah
Date of Inspection	Remarks	
18/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0266, W0347, W0343, W0264	NA	Byraveshwara Temple
SegmentNo	TotalLength	
2/C-W0266/S122958	150.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		3739000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain and providing slab and improvments to roads at 5th phase of Yelahanka New Town ward no-02	9000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Constrution of RCC drain and providing slab and i
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain and providing slab and improvments to roads at 5th phase of Yelahanka New Town ward no-02	002-11-000048
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND/W.O/142/2011-2012	18/05/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/05/2011	18/05/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0266, W0264, W0224, W0226, W0282, W0479	StreetName NA, 5th Crs, Atturu Main Rd, 1st Crs, Dairy Crs (1st Main Rd)	Significant LandMark KHB Colony
SegmentNo 2/C-W0266/S124034	TotalLength 324.22	

ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 3739000.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Constrution of RCC drain and providing slab and improvements to roads at 5th phase of Yelahanka New Town ward no-02	Sanctioned Amount 9000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constrution of RCC drain and providing slab and i
Tender Tender	WorkDetails Constrution of RCC drain and providing slab and improvements to roads at 5th phase of Yelahanka New Town ward no-02	Job No Work Code 002-11-000048
Work OrderNo EE(YNK.D)TEND/W.O/142/2011- 2012	Work Order Date 18/05/2011	Period of Extention 90 days
Defect Liability Period From 18/05/2011	Defect Liability Period To 18/05/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0449, W0316	NA	Gnanabharathi Public School
SegmentNo	TotalLength	
2/C-W0449/S013849	48.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B Hemanth kumar. No;5 Muniyamma layout Hebbal Kempapura		1786930.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of RCC drain at Chowdeshwari layout in ward no-02	1980000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of RCC drain at Chowdeshwari layout in ward no- 02	002-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/233/2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0316, W0310, W0447	NA, 1st Main Rd	Gnanabharathi Public School
SegmentNo	TotalLength	
2/C-W0316/S014402	70.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B Hemanth kumar. No;5 Muniyamma layout Hebbal Kempapura		1786930.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of RCC drain at Chowdeshwari layout in ward no-02	1980000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of RCC drain at Chowdeshwari layout in ward no- 02	002-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/233/2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0443, W0316	NA	Gnanabharathi Public School
SegmentNo	TotalLength	
2/C-W0443/S014651	52.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B Hemanth kumar. No;5 Muniyamma layout Hebbal Kempapura		1786930.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constnution of RCC drain at Chowdeshwari layout in ward no-02	1980000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constnution of RCC drain at Chowdeshwari layout in ward no- 02	002-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/233/2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0437, W0439, W0316, W0310	NA, 1st Main Rd	Gnanabharathi Public school
SegmentNo	TotalLength	
2/C-W0437/S015201	59.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B Hemanth kumar. No;5 Muniyamma layout Hebbal Kempapura		1786930.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Chowdeshwari layout in ward no-02	1980000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Chowdeshwari layout in ward no-02	002-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-06/W.O/233/2011-2012	10/10/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0437, W0441, W0431, W0310, W0445, W0447	NA, 1st Main Rd	Gnanabharathi public school
SegmentNo	TotalLength	
2/C-W0437/S015418	88.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri B Hemanth kumar. No;5 Muniyamma layout Hebbal Kempapura		1786930.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Chowdeshwari layout in ward no-02	1980000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Chowdeshwari layout in ward no- 02	002-11-000055
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/233/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0413, W0298	NA	chowdeshwari layout
SegmentNo	TotalLength	
2/C-W0413/S015854	64.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Chandrashekhar A.V no;3076,Kambar pete Doddaballapura		382055.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Kondappa layout in ward no-02	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Kondappa layout in ward no-02	002-11-000013
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 02/W.O/36/2011-2012	07/03/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
1		ramasanjevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0407, W0338, W0316, W0326, W0409	5th Crs, NA, 6th Crs	Shri Chowdeshwari Telugu School
SegmentNo	TotalLength	
2/C-W0407/S020624	116.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Tuirunagendra .N no;184 Bestara Beedhi Yelahanka		1807130.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Kamakshamma Layout in ward no-02	1990000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Kamakshamma Layout in ward no-02	002-11-000056
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/234/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaih
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0403, W0407, W0328, W0411, W0326, W0409	4th Crs, 5th Crs, NA, 6th Crs	Shri Chowdeshwari GOVT Telugu School
SegmentNo	TotalLength	
2/C-W0403/S021214	40.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri Tuirunagendra .N no;184 Bestara Beedhi Yelahanka		1807130.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Kamakshamma Layout in ward no-02	1990000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Kamakshamma Layout in ward no-02	002-11-000056
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/234/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
2		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0336, W0346	R H B Colony, 6th Crs, NA	Western Side and Eastern Side of Kamakshamma
SegmentNo	TotalLength	
2/S-W0336/S104825	163.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G VENKATEGOWDA		0.00
PhoneNo	EmailId	
9845507797		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain at 1st and 2nd Cross Roads Western Side and Eastern Side of Kamakshamma in Ward no 02 of Yelahanka Sub-Division Yelahanka zo	1950000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Drain at 1st and 2nd Cross Roads Western Side and Eastern Side of Kamakshamma in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000007
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D)E-PMT-1/WO/18/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
24/02/2016	23/02/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		DAYANANDA
Date of Inspection	Remarks	
06/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0334, W0453, W0451, W0439	3rd Crs, NA	Yelahanka lake
SegmentNo	TotalLength	
2/C-W0334/S123450	127.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Lohith V>K 1st main road, venkata, Yelahanka		912851.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of RCC drain and CC roads at Manavarthi thota balance cross roads in wardno-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of RCC drain and CC roads at Manavarthi thota balance cross roads in wardno-02	002-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/14/2012-13	07/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2011	23/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0344	1st Main Rd, 1st Crs	Yelahanka lake
SegmentNo	TotalLength	
2/C-W0461/S124726	17.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Lohith V>K 1st main road, venkata, Yelahanka		912851.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of RCC drain and CC roads at Manavarthi thota balance cross roads in wardno-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of RCC drain and CC roads at Manavarthi thota balance cross roads in wardno-02	002-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/14/2012-13	07/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0037, W0110	NA, Herohalli Rd	govt higher primary school
SegmentNo	TotalLength	
2/C-W0037/S023708	183.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri R.Vasanth,no;28,A.T,layout,N .S.H,RMV 2nd Stage		1622547.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of RCC drain in front of apartment in nagenahalli in ward no-02	1996000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of RCC drain in front of apartment in nagenahalli in ward no-02	002-12-000053
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 04/W.O/96/2012-13	16/08/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
16/08/2012	16/08/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
3		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0513, W0256, W0258, W0448, W0483, W0489, W0299	NA, Bajar Rd, Railway Station Rd	Anjaneya swamy temple
SegmentNo	TotalLength	
2/C-W0513/S025430	154.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri N Thirunagendra, No;184,Besthara beedhi,Yelahanka,		1033951.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC road and CC drain beyond BBMP office in ward no-02	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC road and CC drain beyond BBMP office in ward no-02	002-12-000021
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/79/2012-13	12/07/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
12/07/2012	12/07/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0376, W0463, W0461, W0344, W0342	StreetName NA, 1st Main Rd, 1st Crs, 2nd Crs	Significant LandMark BWSSB Pump House
SegmentNo 2/C-W0376/S033847	TotalLength 97.44	

ContractorDetails		
NameofContractor sri B R Mohan no-18 Govendhappa compound NSH RMV 2nd stage	ContractorRegNo	Expenditure 1632984.00
PhoneNo	EmailId	

Work Details		
NameOfWork construnction of RCC drains behind markondiah temple in chowdashwari layout in ward no-02	Sanctioned Amount 1996000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails construnction of RCC drains behind markondiah temple in chowdashwari layout in ward no-02	Job No Work Code 002-12-000056
Work OrderNo EE(YNK.D)E-Tend - 04/W.O/101/2012-13	Work Order Date 16/08/2012	Period of Extention 90 Days
Defect Liability Period From 16/08/2012	Defect Liability Period To 16/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		b r mohan
Date of Inspection	Remarks	
20/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0461, W0378	1st Main Rd, NA	bharath english high school
SegmentNo	TotalLength	
2/C-W0461/S115845	97.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri D R ramesh babu no;1844/7,6th main rd ,2nd stage rajajinagara D bock		1480850.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc drain at manavsrthi thota in ward no;02	1950000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc drain at manavsrthi thota in ward no;02	002-11-000054
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 07/W.O/269/2011-12	10/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/11/2011	10/11/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
19/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0461, W0459, W0374, W0457	StreetName 1st Main Rd, NA	Significant LandMark bharath english high school
SegmentNo 2/C-W0461/S120920	TotalLength 96.80	

ContractorDetails		
NameofContractor Shri D R ramesh babu no;1844/7,6th main rd ,2nd stage rajajinagara D bock	ContractorRegNo	Expenditure 1480850.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of R cc drain at manavsrthi thota in ward no;02	Sanctioned Amount 1950000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of R cc drain at manavsrthi thota in ward no;02	Job No Work Code 002-11-000054
Work OrderNo EE(YNK.D)E-TEND- 07/W.O/269/2011-12	Work Order Date 10/11/2011	Period of Extention 90 days
Defect Liability Period From 10/11/2011	Defect Liability Period To 10/11/2012	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name ramasanjeevaiah
Date of Inspection 19/09/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0352, W0344, W0374, W0358, W0457	StreetName NA, 1st Crs	Significant LandMark bharath english high school
SegmentNo 2/C-W0352/S121353	TotalLength 66.73	

ContractorDetails		
NameofContractor Shri D R ramesh babu no;1844/7,6th main rd ,2nd stage rajajinagara D bock	ContractorRegNo	Expenditure 1480850.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of R cc drain at manavsrthi thota in ward no;02	Sanctioned Amount 1950000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of R cc drain at manavsrthi thota in ward no;02	Job No Work Code 002-11-000054
Work OrderNo EE(YNK.D)E-TEND- 07/W.O/269/2011-12	Work Order Date 10/11/2011	Period of Extention 90 days
Defect Liability Period From 10/11/2011	Defect Liability Period To 10/11/2012	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name ramasanjeevaiah
Date of Inspection 19/09/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0334, W0453, W0451, W0439	StreetName 3rd Crs, NA	Significant LandMark bharath english high school
SegmentNo 2/C-W0334/S122302	TotalLength 125.80	

ContractorDetails		
NameofContractor Shri D R ramesh babu no;1844/7,6th main rd ,2nd stage rajajinagara D bock	ContractorRegNo	Expenditure 1480850.00
PhoneNo	EmailId	

Work Details		
NameOfWork Construction of R cc drain at manavsrthi thota in ward no;02	Sanctioned Amount 1950000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Construction of R cc drain at manavsrthi thota in ward no;02	Job No Work Code 002-11-000054
Work OrderNo EE(YNK.D)E-TEND- 07/W.O/269/2011-12	Work Order Date 10/11/2011	Period of Extention 90 days
Defect Liability Period From 10/11/2011	Defect Liability Period To 10/11/2012	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name ramasanjeevaiah
Date of Inspection 22/09/2015	Remarks completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0342	2nd Crs	bharath english high school
SegmentNo	TotalLength	
2/S-W0342/S122743	118.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri D R ramesh babu no;1844/7,6th main rd ,2nd stage rajajinagara D bock		1480850.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of R cc drain at manavsrthi thota in ward no;02	1950000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of R cc drain at manavsrthi thota in ward no;02	002-11-000054
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-TEND- 07/W.O/269/2011-12	10/11/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/11/2011	10/11/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0322, W0439, W0449, W0316	StreetName R H B Colony, 2nd Crs, NA, 3rd Crs, Chikkanna Lyt 2nd Crs	Significant LandMark Jnanabharathi School in chowdeshwari Layout
SegmentNo 2/C-W0322/S092110	TotalLength 121.80	

ContractorDetails		
NameofContractor N.THIRUNAGENDRA	ContractorRegNo	Expenditure 0.00
PhoneNo 9845547072	EmailId	

Work Details		
NameOfWork Construction of CC Road and Drain at Cross roads of jnanabharathi School in chowdeshwari Layout in Ward no 02 of Yelahanka Sub- Division Yelahanka zon	Sanctioned Amount 1900000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Construction of CC Road and Drain at Cross roads of jnanabharathi School in chowdeshwari Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Job No Work Code 002-15-000004
Work OrderNo EE(YNK.D)/E-PMT- 4/WO/80/2014-15	Work Order Date 28/01/2015	Period of Extention 90 DAYS
Defect Liability Period From 28/01/2015	Defect Liability Period To 27/01/2016	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	RAMANANJEEVAIAH
Date of Inspection	Remarks
27/11/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0244	NA	Vinayaka Layout
SegmentNo	TotalLength	
2/S-W0244/S084304	154.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
7760405418		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Culverts And Improvements of Drains @ Vinayaka Layout in ward no.2 of Yelahanka Sub Divison	2500000	2017
Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		002-17-000014
Work OrderNo	Work Order Date	Period of Extention
000099/2016-17	05/01/2017	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pavana
Date of Inspection	Remarks	
19/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0283	NA	RO Plant
SegmentNo	TotalLength	
2/S-W0283/S092139	133.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
7760405418		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing and Fixing Cobble Stone Pathway at Yelahanka New Town %th Phase in Ward no.2	2500000	2017
Year	Type of Work	Other Work Type
2016 - 2017	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Not a Tender		002-17-000018
Work OrderNo	Work Order Date	Period of Extention
000101/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pavana
Date of Inspection	Remarks	
19/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0228	NA	ISAC Layout
SegmentNo	TotalLength	
2/S-W0228/S093746	379.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
7760405418		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of culverts and Improvements of Drains at Puttenahalli KHB Colony in ward no.02	2500000	2017
Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		002-17-000015
Work OrderNo	Work Order Date	Period of Extention
000100/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pavana
Date of Inspection	Remarks	
19/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0276	2nd Crs	Masjid
SegmentNo	TotalLength	
2/S-W0276/S120658	220.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
7760405418		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains @ kondappa layout western side cross roads in ward no.2	250000	2017
Year	Type of Work	Other Work Type
2016 - 2017	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		002-17-000019
Work OrderNo	Work Order Date	Period of Extention
000102/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pavana
Date of Inspection	Remarks	
19/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0371, W0369	StreetName Dr Ambekdar Govt Ashraya Colony Garudacharapalya, NA	Significant LandMark Kondappa layout near railway well
SegmentNo 2/C-W0371/S101041	TotalLength 134.91	



ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9449863065	EmailId	

Work Details		
NameOfWork Improvements to roads and Drains western side Kondappa layout near railway well in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	Sanctioned Amount 1900000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Improvements to roads and Drains western side Kondappa layout near railway well in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Job No Work Code 002-16-000027
Work OrderNo BBMP/EE (YNK.D)/WO/58/2016- 17	Work Order Date 30/04/2016	Period of Extention 90 DAYS
Defect Liability Period From 30/12/2016	Defect Liability Period To 29/12/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	RAMANANJEEVAIAH
Date of Inspection	Remarks
24/02/2017	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0334, W0453, W0451, W0439, W0427, W0435, W0340, W	StreetName R H B Colcny, 5th Crs, 6th Crs, NA, Mariyappa Lyt, R H B Colcny, 7th Crs	Significant LandMark Manavarthi Thoto Cross Roads
SegmentNo 2/C-W0334/S102656	TotalLength 179.16	
ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9449863065	Emailld	
Work Details		
NameOfWork Construction of CC road at Manavarthi Thoto Cross Roads near Anjeneyalu House and CC drain at Markandeya Temple in Ward no 02 of Yelahanka Sub-Divisio	Sanctioned Amount 1300000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Road	Other Work Type
Tender Not a Tender	WorkDetails Construction of CC road at Manavarthi Thoto Cross Roads near Anjeneyalu House and CC drain at Markandeya Temple in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	Job No Work Code 002-16-000034
Work OrderNo BBMP/EE (YNK.D)/WO/61/2016- 17	Work Order Date 30/04/2016	Period of Extention 90 DAYS
Defect Liability Period From 29/12/2016	Defect Liability Period To 28/12/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		RAMANANJEEVAIAH
Date of Inspection	Remarks	
24/02/2017	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0290, W0373	NA, East Park Reje Lyt	western Side Kondappa layout
SegmentNo	TotalLength	
2/S-W0290/S103652	58.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9449863065		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC road at 30th cross western Side Kondappa layout near Jangamaiah house in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	800000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of CC road at 30th cross western Side Kondappa layout near Jangamaiah house in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000032
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE (YNK.D)/WO/59/2016-17	30/04/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/12/2016	28/12/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	RAMANANJEEVAIAH
Date of Inspection	Remarks
24/02/2017	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0252, W0351, W0250, W0258, W0353, W0256	Kalkki-bhagwan Rd 1st Main Rd, 2nd Crs, 2nd Main Rd, NA, Puttenahalli Main Rd	Park
SegmentNo	TotalLength	
2/C-W0252/S011139	131.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2819250.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Puttenahalli KHB Colony main and cross roads in ward no-02	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Puttenahalli KHB Colony main and cross roads in ward no-02	002-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/160/2011- 2012	07/06/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/06/2011	07/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
6		ramasanjevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0252, W0258, W0355, W0357	Kalkki-bhagwan Rd 1st Main Rd, NA, 3rd Crs	Park
SegmentNo	TotalLength	
2/C-W0252/S012246	131.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2819250.00
PhoneNo	Emailld	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Puttenahalli KHB Colony main and cross roads in ward no-02	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Puttenahalli KHB Colony main and cross roads in ward no-02	002-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-W.O/160/2011-2012	07/06/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/06/2011	07/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0351, W0250, W0349	2nd Crs, 2nd Main Rd, 1st Crs	Park
SegmentNo	TotalLength	
2/C-W0351/S013702	130.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2819250.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Puuttenahalli KHB colony main and cross roads in ward no-02 Constrution of RCC drain at Puuttenahalli KHB colony main an	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Puuttenahalli KHB colony main and cross roads in ward no-02	002-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/160/2011-2012	07/06/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/06/2011	07/06/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0248, M0009	NA, Doddaballapura Rd	Temple
SegmentNo	TotalLength	
2/C-W0248/S014436	100.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2819250.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of RCC drain at Puuttenahalli KHB colony main and cross roads in ward no-02	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Constrution of RCC drain at Puuttenahalli KHB colony main and cross roads in ward no-02	002-11-000051
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/160/2011- 2012	07/06/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/06/2011	07/06/2012	No

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0283	1st Crs	Central Excise Quarters
SegmentNo	TotalLength	
2/S-W0283/S030013	66.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri; K.N Srinivasa no-25, 2nd cross 10th Main Indiranagara 2nd stage		1695040.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to Main road of Yelahanka 5th Phase in ward no-01	1890000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Provding and asphaltting to Main road of Yelahanka 5th Phase in ward no-01	002-11-000059
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 06/W.O/219/2011-2012	10/10/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
10/10/2011	10/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
7		Ramasanjeevaiah
Date of Inspection	Remarks	
18/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0316, W0310, W0447, W0443, W0304, W0306, W0423, W	Chikkanna Lyt 2nd Crs, Chikkanna Lyt 4th Crs, Shetty Lyt, 3rd Main Rd, Garudachar Palya Main Rd, NA,	Kamakshamma Layout and Chowdeshwari layout
SegmentNo	TotalLength	
2/C-W0316/S085045	480.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Construction of CC Roads at Kamakshamma Layout Western Side main and Cross Roads and Chowdeshwari layout main road and Cross R	9990000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		PAVANA NAGATHI
Date of Inspection	Remarks	
11/12/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0130	NA	Horohalli Srinidhi Layout
SegmentNo	TotalLength	
2/S-W0130/S090340	122.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Horohalli Anjeneyaswamy Temple to Horohalli lake and Horohalli Srinidhi Layout in Ward no 02 of Yelahanka Sub-Division Yelaha	9990000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT-2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		PAVANA NAGATHI
Date of Inspection	Remarks	
11/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0248, W0252, W0351, W0349, W0353, W0355, W0357, W	NA, S Krishnappa Lyt, 7th Main Rd, G M Palya, Mariyappa Lyt, Ambedkar Nagar Slum	Putenahalli KHB Colony
SegmentNo	TotalLength	
2/S-W0248/S092429	689.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to Putenahalli KHB Colony in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	4980000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		PAVANA NAGATHI
Date of Inspection	Remarks	
11/12/2016	COMPLETED	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0143, W0102, W0125, W0145, W0098, W0147, W0100, W	StreetName Nagenahalli Layout, NA	Significant LandMark Nagenahalli Layout
SegmentNo 2/C-W0143/S093547	TotalLength 710.85	

ContractorDetails		
NameofContractor A CHENNAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9448050627	EmailId	

Work Details		
NameOfWork Providing Asphaltting to Nagenahalli Layout main and Cross Roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	Sanctioned Amount 4990000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	Job No Work Code 001-16-000023
Work OrderNo EE (YNK.D) E-PMT- 2/WO/95/2016-17	Work Order Date 19/10/2016	Period of Extention 12 MONTHS
Defect Liability Period From 19/10/2016	Defect Liability Period To 18/10/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
7		PAVANA NAGATHI
Date of Inspection	Remarks	
11/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0286, W0290, W0367, W0282, W0276, W0365, W0389, W	4th Crs, Maheshwari Nagar, NA, 3rd A Crs Maheshwari Nagar, 2nd Crs, Chikka Muniswammappa Lyt, 2nd Cr	Kondappa Layout Western and Eastern Side Main and
SegmentNo	TotalLength	
2/C-W0286/S100714	1384.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC road at Kondappa Layout Western and Eastern Side Main and Cross Roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	9900000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		DAYANANDA
Date of Inspection	Remarks	
11/12/2016	COMPLETED	
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0283	NA	Yelhanka new town 5th phase at Nagarjuna apartment
SegmentNo	Totallength	
2/S-W0283/S102123	133.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to main and Cross Roads of Yelhanka new town 5th phase at Nagarjuna apartment in Ward no 02 of Yelahanka Sub-Division Yelahanka	4990000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT-2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
9		DAYANANDA
Date of Inspection	Remarks	
11/12/2016	COMPLETED	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 2	WardName Chowdeshwari Ward
StreetID W0213, W0219, W0170, W0217, W0215	StreetName NA, Chowdeshwari Temple Rd	Significant LandMark Kenchenahalli main road and Aruna apartments road
SegmentNo 2/C-W0213/S030750	TotalLength 214.20	

ContractorDetails		
NameofContractor A CHENNAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9448050627	EmailId	

Work Details		
NameOfWork Providing Asphaltting to Kenchenahalli main road and Aruna apartments road in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	Sanctioned Amount 9900000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	Job No Work Code 001-16-000023
Work OrderNo EE (YNK.D) E-PMT- 2/WO/95/2016-17	Work Order Date 19/10/2016	Period of Extention 12 MONTHS
Defect Liability Period From 19/10/2016	Defect Liability Period To 18/10/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		DAYANADA
Date of Inspection	Remarks	
11/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0276	2nd Crs	western side Kondappa Layout
SegmentNo	TotalLength	
2/S-W0276/S110416	220.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SAMBHASHIVAREDDY		0.00
PhoneNo	EmailId	
9972741359		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to 26th cross western side Kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	1900000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Providing Asphaltting to 26th cross western side Kondappa Layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-15-000007
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT-3/WO/72/2016-17	19/05/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/05/2016	18/05/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	DAYANANDA
Date of Inspection	Remarks
17/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0310, W0445, W0447, W0449, W0316	Chikkanna Lyt 4th Crs, Shetty Lyt, 4th Main Rd, Shetty Lyt, 3rd Main Rd, 3rd Crs, Chikkanna Lyt 2nd	Jnanabharathi School
SegmentNo	TotalLength	
2/C-W0310/S111437	95.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T C PRATHAP		0.00
PhoneNo	EmailId	
9448278808		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain at Jnanabharathi School in Ward no 02 of Yelahanka Sub- Division Yelahanka zone	1600000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Drain at Jnanabharathi School in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000008
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT- 1/WO/83/2015-16	08/06/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/06/2016	07/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	DAYANANDA
Date of Inspection	Remarks
17/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0431, W0316, W0310, W0437	NA, Chikkanna Lyt 2nd Crs, Chikkanna Lyt 4th Crs	chowde swhari Loyout 6th cross
SegmentNo	TotalLength	
2/C-W0431/S112440	68.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T C PRATHAP		0.00
PhoneNo	EmailId	
9448278808		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC Drain chowde swhari Loyout 6th cross roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	1600000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC Drain chowde swhari Loyout 6th cross roads in Ward no 02 of Yelahanka Sub-Division Yelahanka zone	002-16-000013
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT-1/WO/84/2015-16	08/06/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/06/2016	07/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	DAYANANDA
Date of Inspection	Remarks
17/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0172, W0174, W0182, W0176, W0186, W0178	NA	kenchanahalli main road
SegmentNo	TotalLength	
2/C-W0172/S010117	260.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Sainath santhosh ,no- 287,2nd H cross,3rd stage,Basaveshwaranagara.		1693668.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC road at Masque in kenchanahalli ward no-02	1900000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC road at Masque in kenchanahalli ward no-02	002-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/54/2012-13	23/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0194, W0251, W0184, W0180, W0212, W0210, W0170, W	NA, Kenchanahalli Rd	kenchanahalli main road
SegmentNo	TotalLength	
2/C-W0194/S011537	389.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Sainath santhosh ,no- 287,2nd H cross,3rd stage,Basaveshwaranagara.		1693668.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC road at Masque in kenchanahalli ward no-02	1900000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC road at Masque in kenchanahalli ward no-02	002-12-000036
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/54/2012-13	23/06/2012	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		ramasanjeevaiah
Date of Inspection	Remarks	
18/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0039, W0181, W0106, W0179	NA, 2nd Crs, 1st Crs	harohalli main rd
SegmentNo	TotalLength	
2/C-W0039/S013336	59.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Y.T. Kantharaju,no;77,Hosabeedhi , Yelahanka		896345.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC drain at harohalli village cross roads in ward no-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC drain at harohalli village cross roads in ward no-02	002-12-000030
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/19/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0108, W0181, W0106, W0183, W0112	NA, 2nd Crs	harohalli main rd
SegmentNo	TotalLength	
2/C-W0108/S014426	45.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Y.T. Kantharaju,no;77,Hosabeedhi , Yelahanka		896345.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC drain at harohalli village cross roads in ward no-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC drain at harohalli village cross roads in ward no-02	002-12-000030
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/19/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0185, W0106, W0179	1st Main Rd, NA, 1st Crs	harohalli main rd
SegmentNo	TotalLength	
2/C-W0185/S014927	47.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Y.T. Kantharaju,no;77,Hosabeedhi , Yelahanka		896345.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC drain at harohalli village cross roads in ward no-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC drain at harohalli village cross roads in ward no-02	002-12-000030
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/19/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0039, W0177	NA, 4th Crs	harohalli main rd
SegmentNo	TotalLength	
2/C-W0039/S020231	70.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Y.T. Kantharaju,no;77,Hosabeedhi , Yelahanka		896345.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC drain at harohalli village cross roads in ward no-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC drain at harohalli village cross roads in ward no-02	002-12-000030
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/19/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	2	Chowdeshwari Ward
StreetID	StreetName	Significant LandMark
W0104, W0177, W0106	NA, 4th Crs	harohalli main rd
SegmentNo	TotalLength	
2/C-W0104/S020538	49.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri Y.T. Kantharaju,no;77,Hosabeedhi , Yelahanka		896345.00
PhoneNo	Emailld	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of CC drain at harohalli village cross roads in ward no-02	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	construction of CC drain at harohalli village cross roads in ward no-02	002-12-000030
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend - 03/W.O/19/2012-13	23/06/2012	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
23/06/2012	23/06/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
4		ramasanjeevaiah
Date of Inspection	Remarks	
19/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE