



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0145	NA	dena bank
SegmentNo	TotalLength	
20/S-W0145/S060945	101.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
P VISHWANATH		951035.00
PhoneNo	EmailId	
9986457680		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of drian from dena bank to cbi road at lakshmaiah block in ward no 20 gangangara	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	cc drian with cc slab covering from cbi road to dena bank	020-15-000007
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/259/2014-15	04/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/02/2015	27/02/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
30/07/2015		




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	




ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	BALLERY SERVICE ROAD
SegmentNo	TotalLength	
20/S-W0144/S012512	842.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		226965.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING WMM AND SURFACE DRESSING TO BWSSB CUTTING PORTION IN CBI ROAD FROM BELLARY MAIN ROAD TO MAYURA HOTEL IN WARD 20	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	BWSSB CUTTING FILLING
Tender	WorkDetails	Job No Work Code
Tender	PROVINDING WMM AND SURFACE DRESSING	020-12-000063
Work OrderNo	Work Order Date	Period of Extention
EEVHAE\WO\162\2012-13	22/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/01/2014	31/01/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0080	NA	nandini milk parlor
SegmentNo	TotalLength	
20/S-W0080/S055713	120.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		523606.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing pipe line in keb layout, ashwathnagar, s.v. layout & 'a' block, in ward no. 20 ganganagar	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	pipe line and water taps
Tender	WorkDetails	Job No Work Code
Tender	pipe line and water taps	020-13-000074
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/168/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/03/2014	28/03/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0265	Ambedkar Nagar Slum	near twinkle star school
SegmentNo	TotalLength	
20/S-W0265/S014214	152.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L Gangadhar		1394578.49
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
construction of drain 2nd cross papanna block ward no 20	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	cc drian
Tender	WorkDetails	Job No Work Code
Tender	cc drain both side with bs slab covering	020-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/181/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0249	NA	mecca majid
SegmentNo	TotalLength	
20/S-W0249/S015222	102.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B H HARISH		933205.94
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drian at 5th cross vasanthappa block in ward no 20	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	cc drain work
Tender	WorkDetails	Job No Work Code
Tender	cc drian with bs slab covering both side	020-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/176/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 20	WardName Ganga Nagara
StreetID W0193	StreetName Vinayaka Lyt 2nd Crs	Significant LandMark modern publick school
SegmentNo 20/S-W0193/S030313	TotalLength 257.28	

ContractorDetails		
NameofContractor LOKESH G	ContractorRegNo	Expenditure 2083104.00
PhoneNo 9845383071	EmailId	

Work Details		
NameOfWork improvement to drian and providing footpath to weavers colony 5th main in ward no 20	Sanctioned Amount 2000000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type drian and footpath
Tender Tender	WorkDetails one side ssm drian with bs slab and other side bs slab drian bs slab covering	Job No Work Code 020-12-000036
Work OrderNo /EE/H/AE/ESD/4712-13	Work Order Date 16/08/2012	Period of Extention
Defect Liability Period From 28/12/2012	Defect Liability Period To 28/12/2013	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Anjaneyalu Br
Date of Inspection 28/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0257	NA	WARIER BAKERY
SegmentNo	TotalLength	
20/S-W0257/S031533	144.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		461490.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRAIN AT 5TH CROSS PAPANNA BLOCK IN WARD NO 20	500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	CC DRIAN
Tender	WorkDetails	Job No Work Code
Tender	CC DRIAN WITH BS SLAB PROVIDING TWO SIDE 45.M LEGHTH	020-14-000013
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/214/2012-13	22/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	30/08/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0269	NA	NEAR TWINKLE STAR SCHOOL
SegmentNo	TotalLength	
20/S-W0269/S032926	158.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L Gangadhar		1394578.49
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRIAN 2ND CROSS PAPANNA BLOCK IN WARD NO 20	1500000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC DRIAN
Tender	WorkDetails	Job No Work Code
Tender	CC DRIAN BOTH SIDE WITH BS SLAB COVERING	020-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/181/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0251	Maheshwaramma Temple Behind Rd	RADHAKRISHNA SCHOOL
SegmentNo	TotalLength	
20/S-W0251/S034243	111.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GOWRAMMA		946319.00
PhoneNo	EmailId	
9845183324		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION DRIAN AT 4TH CROSS VASANTHAPPA BLOCK IN WARD NO 20	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	CC DRIAN
Tender	WorkDetails	Job No Work Code
Tender	CC DRIAN BOTH SIDE WITH BS SLAB COVERING	020-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/221/2012-13	22/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/10/2014	31/10/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0039	NA	guddahalli circle
SegmentNo	TotalLength	
20/S-W0039/S023950	103.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		0.00
PhoneNo	EmailId	
9341260619		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drain at govindappa garden 1st cross in ward no 20 ganganagar	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	cc drain with cc slabs covering
Tender	WorkDetails	Job No Work Code
Tender	cc drain with cc slabs covering	020-13-000015
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/381/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0039	NA	GUDDAHALLI CIRCLE
SegmentNo	TotalLength	
20/S-W0039/S025247	103.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		813540.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRAIN AT GOVINDAPPA GARDEN 1ST CROSS WARD NO 20	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	CC DRAIN WITH CC COVERING	020-13-000015
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/381/12-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/03/2013	17/03/2014	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0170	NA	PARK
SegmentNo	TotalLength	
20/S-W0170/S064310	333.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		813332.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 5th main gangappa block to 3rd cross gangappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENT DRAIN AND CC COVERING BOOTH SIDE OF DRAIN	020-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/372/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0193	Vinayaka Lyt 2nd Crs	MODERN PUBLICK ENGLISH SCHOOL
SegmentNo	TotalLength	
20/S-W0193/S064725	257.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B H HARISH		838252.00
PhoneNo	EmailId	
8123228708		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 5th main vasanthappa block to muniramanna block swdrain in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRAIN AND PROVIDNG TILES	020-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/373/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0192	NA	CAKE PALACE
SegmentNo	TotalLength	
20/S-W0192/S065211	143.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R NITHIN		808422.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath from cake palace to HGH Layout 3rd cross in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT DRIAN AND CC COVERING	020-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/375/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0181	Vinayaka Lyt 3rd Crs	CAKE PALACE
SegmentNo	TotalLength	
20/S-W0181/S065713	440.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R NITHIN		808422.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 5th main gangappa block to 3rd cross gangappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT DRAIN AND CC COVERING	020-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/375/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0203	NA	VASANTHAPPA BLOCK BUS STOP
SegmentNo	TotalLength	
20/S-W0203/S065848	102.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		842468.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 6th main to CBI road vasanthappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT DRIAN AND CC COVERING	020-13-000018
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/377/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0154	NA	VASANTHAPPA BLOCK BUS STOP
SegmentNo	TotalLength	
20/S-W0154/S070523	69.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R NITHIN		808422.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 6th main to CBI road vasanthappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRAIN AND CC COVERING	020-13-000009
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/375/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0205	NA	KANTHI SWEET
SegmentNo	TotalLength	
20/S-W0205/S070903	128.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		828838.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 5th main to 6th main vasanthappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRAIN AND CC COVERING	020-13-000010
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/376/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0166	NA	KANTHI SWEETS
SegmentNo	TotalLength	
20/S-W0166/S071156	119.78	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		828838.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain and providing footpath to 5th main to 6th main vasanthappa block in ward no 20 ganganagara	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRIAN AND CC COVERING	020-13-000010
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/376/2012-13	17/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/04/2013	29/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0076	NA	INDIAN PETROL BUNK
SegmentNo	TotalLength	
20/S-W0076/S105507	125.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		3168776.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPLATING KEB LAYOUT CROSS ROAD, ASHWATHANAGAR CROSS ROAD AND AECS LAYOUT CROSS ROAD WARD NO 20 GANGANAGAR	45	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ASPLATING KEB LAYOUT CROSS ROAD, ASHWATHANAGAR CROSS ROAD AND AECS LAYOUT CROSS ROAD	020-13-000049
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/345/12-13	15/03/2013	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/03/2013	14/05/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
15	Name
Date of Inspection	Remarks
23/02/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0200	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	KRISHNA MURTHY HOUSE
SegmentNo	TotalLength	
20/S-W0200/S110027	143.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		4236753.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPLATING, IMPROVEMENT TO DRIAN TO 8TH CROSS, RAIN HERVESTING PITS AND DESILTING AND RESETING OF EXISTING DRAINAT HMT LAYOUT IN WARD NO. 20 GANGANAGAR	45	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	ASPLATING, RAN HERVESTING, ETC
Tender	WorkDetails	Job No Work Code
Tender	ASPLATING, IMPROVEMENT TO DRIAN TO 8TH CROSS, RAIN HERVESTING PITS AND DESILTING AND RESETING OF EXISTING DRAINAT HMT LAYOUT	020-13-000035
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/352/2012-13	15/03/2013	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/03/2013	14/05/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
15	Name
Date of Inspection	Remarks
23/02/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0228	NA	yellamma temple
SegmentNo	TotalLength	
20/S-W0228/S113809	118.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M Murali mohan	pwd	440675.09
PhoneNo	EmailId	
9980301348		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Resetting of Culverts, Deck slab & Kerb stones in Ward Jurisdiction No.20 Ganganagar	5	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Resetting of Culverts, Deck slab & Kerb stones in Ward Jurisdiction	020-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/216/213-14	22/02/2014	60
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/02/2014	21/04/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		Anjaneyalu b r
Date of Inspection	Remarks	
20/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0157	NA	anganavadi
SegmentNo	TotalLength	
20/S-W0157/S063928	96.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		522229.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVINDING PIPE LINE AT PAPANNA HUTS IN WARD NO 20	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPE LINE AND TAPS
Tender	WorkDetails	Job No Work Code
Tender	PIPE LINE and water taps	020-13-000072
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/169/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	01/03/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0135	NA	SLUM
SegmentNo	TotalLength	
20/S-W0135/S064923	30.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		522229.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVINDING PIPE LINE AT PAPANNA HUTS IN WARD NO 20	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPE LINE AND WATER TAPS
Tender	WorkDetails	Job No Work Code
Tender	PIPE LINE AND WATER TAPS	020-13-000072
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/169/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0108	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	PAPANNA HUTS
SegmentNo	TotalLength	
20/S-W0108/S065437	29.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		522229.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVINDING PIPE LINE AT PAPANNA HUTS IN WARD NO 20	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPE LINE AND WATER TAPS
Tender	WorkDetails	Job No Work Code
Tender	PIPE LINE AND WATER TAPS	020-13-000072
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/169/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0110	NA	PAPANNA HUTS
SegmentNo	TotalLength	
20/S-W0110/S070006	30.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		522229.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVINDING PIPE LINE AT PAPANNA HUTS IN WARD NO 20	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPE LINE AND WATER TAPS
Tender	WorkDetails	Job No Work Code
Tender	PIPE LINE AND WATER TAPS	020-13-000072
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/169/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2014	28/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0232	NA	BORE WELL
SegmentNo	TotalLength	
20/S-W0232/S120859	62.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		3060719.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing cement concrete to BWSSB cut portion of cross roads at pappanna block and vasanthappa block in ward no 20	308000	2014
Year	Type of Work	Other Work Type
2010 - 2011	Road	
Tender	WorkDetails	Job No Work Code
Tender	cc for bwsssb cut protion	020-14-000060
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/224/2014-15	18/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/01/2015	30/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 20	WardName Ganga Nagara
StreetID W0039	StreetName NA	Significant LandMark GUDDHADAHALLI CIRCLE
SegmentNo 20/S-W0039/S010114	TotalLength 103.20	

ContractorDetails		
NameofContractor B GANGADHARIAH	ContractorRegNo	Expenditure 519690.00
PhoneNo 9945698537	EmailId	

Work Details		
NameOfWork PROVINDING PIPE LINE TO GOVINDAPPA GARDEN 1ST MAIN ROAD IN WARD NO 20	Sanctioned Amount 497000	Sanctioned Year 2014
Year 2012 - 2013	Type of Work Others	Other Work Type UGD PIPE LINE WITH MANHOLE
Tender	WorkDetails UGD PIPE LINE WITH MANHOLE	Job No Work Code 020-14-000058
Work OrderNo EE/H/AE/WO/221/2014-15	Work Order Date 18/12/2014	Period of Extention
Defect Liability Period From 23/01/2015	Defect Liability Period To 23/01/2016	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Anjaneyalu Br
Date of Inspection 28/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0043	NA	guddadahlli circle
SegmentNo	TotalLength	
20/S-W0043/S104746	39.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		4466833.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing cement concert road and cc drain at chinna garden 2nd cross, govindappa garden 1st cross, chinnagarden 1st cross in ward 20 ganganagara	4500000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	providing cc road and drian
Tender	WorkDetails	Job No Work Code
Tender	providing cement concert road and cc drain at chinna garden 2nd cross, govindappa garden 1st cross, chinnagarden 1st cross	020-13-000043
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/360/12-13	15/03/2013	14/06/2013
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
14/06/2013	13/06/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
10	Name
Date of Inspection	Remarks
22/02/2016	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0015	NA	ashraya english school
SegmentNo	TotalLength	
20/S-W0015/S032708	68.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDS		1994187.69
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing concrete road in A Block Cross Roads & Chinnamary Layout remaining portion in Ward 20 Ganganagara	20	2013
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	providing concrete road in A Block Cross Roads & Chinnamary Layout remaining portion	020-13-000046
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/363/12-13	15/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
15/03/2013	14/06/2013	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		B R ANJANEYALU
Date of Inspection	Remarks	
22/02/2016		

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0038	NA	Ashraya english school
SegmentNo	TotalLength	
20/S-W0038/S033242	248.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		1496896.82
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing cement concert & drian (Main road and cross roads) at chinnamary Layout in ward no 20 Ganganagar	15	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	cc road and drian
Tender	WorkDetails	Job No Work Code
Tender	providing cement concert & drian (Main road and cross roads) at chinnamary Layout	020-13-000020
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/287/12-13	01/03/2013	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/03/2013	31/05/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		B R ANJANEYALU
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0012	NA	HARISH HOUSE
SegmentNo	TotalLength	
20/S-W0012/S033747	193.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		829867.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF DRIAN AND PROVIDING PIPE LINE AT GOVINDAPPA GARDEN IN WARD NO 20 GANGANAGARA	10	
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	CONSTRUCTION OF DRIAN AND PROVIDING PIPE LINE AT GOVINDAPPA GARDEN	020-13-000012
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/378/2012-13	17/03/2013	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/03/2013	16/05/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		B R ANJANEYALU
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0002	NA	RAILWAY TRACK
SegmentNo	TotalLength	
20/S-W0002/S034348	34.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		816446.05
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CONCERT ROAD IN SHYAMANNA GARDEN IN WARD 20 GANGANAGARA	10	2013
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING CONCERT ROAD IN SHYAMANNA GARDEN	020-13-000014
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/380/20112-13	17/03/2013	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
17/03/2013	16/05/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		B R ANJANEYALU
Date of Inspection	Remarks	
22/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 20	WardName Ganga Nagara
StreetID W0006	StreetName NA	Significant LandMark HARISH HOUSE
SegmentNo 20/S-W0006/S034754	TotalLength 228.45	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 822974.50
PhoneNo 9448061807	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF RETAINING AND IMPROVEMENT OF ROAD AT GOVINDPPA GARDEN IN WARD NO.20 GANGANAGAR	Sanctioned Amount 10	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type RETAINING WALL AND IMPROVEMENT OF ROAD
Tender Tender	WorkDetails CONSTRUCTION OF RETAINING AND IMPROVEMENT OF ROAD AT GOVINDPPA GARDEN	Job No Work Code 020-13-000013
Work OrderNo EE/H/AE/WO/379/2013-13	Work Order Date 17/03/2013	Period of Extention 60 DAYS
Defect Liability Period From 17/03/2013	Defect Liability Period To 16/05/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		B R ANJANEYALU
Date of Inspection	Remarks	
22/02/2016		

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0261	NA	TWINKLE STAR SCHOOL
SegmentNo	TotalLength	
20/S-W0261/S041044	147.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GOWRAMMA		965656.00
PhoneNo	EmailId	
9845183324		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRIAN AND FOOTH PATH TO PAPPANNA BLOCK 4TH CORSS AND 1ST CROSS IN WARD NO 20	950000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	DESILTING AND IMPROVEMENT OF DRIAN AND PROVIDING BS SLAB COVERING	020-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/138/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/11/2012	05/11/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0271	Ambedkar Nagar Slum	TWINKLE STAR SCHOOL
SegmentNo	TotalLength	
20/S-W0271/S042849	90.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
GOWRAMMA		965656.00
PhoneNo	EmailId	
9845183324		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRIAN AND FOOTH PATH TO PAPPANNA BLOCK 4TH CORSS AND 1ST CROSS IN WARD NO 20	950000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	IMPROVEMENT BS SLAB DRIAN AND BS SLAB COVERING
Tender	WorkDetails	Job No Work Code
Tender	DESILTING AND IMPROVEMENT OF DRIAN AND PROVIDING BS SLAB COVERING	020-12-000028
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/138/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
05/11/2012	05/11/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0234	NA	ex minister krishnappa house
SegmentNo	TotalLength	
20/S-W0234/S070553	27.30	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ABHIVRUDH NIRMAN		1454180.00
PhoneNo	EmailId	
9845239989		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drian and providing foot path at papanna block in ward no 20	1400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	improvement of drian and providing foot path	020-12-000029
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/205/12-13	15/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0232	NA	BOREWELL
SegmentNo	TotalLength	
20/S-W0232/S071427	62.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ABHIVRUDH NIRMAN		1454180.00
PhoneNo	EmailId	
9845239989		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drian and providing foot path at papanna block in ward no 20	1400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	improvement of drian and providing foot path	020-12-000029
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/205/12-13	15/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0176	NA	EX MINISTER KRISHNAPPA HOUSE
SegmentNo	TotalLength	
20/S-W0176/S071919	144.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ABHIVRUDH NIRMAN		1454180.00
PhoneNo	EmailId	
9845239989		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drian and providing foot path at papanna block in ward no 20	1400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	improvement of drian and providing foot path	020-12-000029
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/205/12-13	15/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0263	NA	EX MINISTER KRISHNAPPA HOUSE
SegmentNo	TotalLength	
20/S-W0263/S072329	75.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ABHIVRUDH NIRMAN		1454180.00
PhoneNo	EmailId	
9845239989		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvement of drian and providing foot path at papanna block in ward no 20	1400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	improvement of drian and providing foot path	020-12-000029
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/205/12-13	15/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 20	WardName Ganga Nagara
StreetID W0211	StreetName NA	Significant LandMark SWM DRIAN
SegmentNo 20/S-W0211/S072819	TotalLength 116.25	

ContractorDetails		
NameofContractor R VASANTH	ContractorRegNo	Expenditure 1297291.00
PhoneNo 9449109576	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRIAN AND PROVIDING FOOTPATH TO VASANTHAPPA BLOCK 6TH MAIN AND ASPHALTING TO 10TH CROSS ROAD OF PILLAPPA BLOCK IN WARD NO 20	Sanctioned Amount 1250000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Routine Maintenance	Other Work Type
Tender Tender	WorkDetails IMPROVEMENTS TO DRIAN AND PROVIDING FOOTPATH AND ASPHALTING	Job No Work Code 020-12-000026
Work OrderNo EE/H/AE/WO/186/2012-13	Work Order Date 07/11/2012	Period of Extention
Defect Liability Period From 30/01/2013	Defect Liability Period To 30/01/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
28/07/2015	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0158	NA	PILLAPPA BLOCK
SegmentNo	TotalLength	
20/S-W0158/S081735	317.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R VASANTH		1297291.00
PhoneNo	EmailId	
9449109576		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRIAN AND PROVIDING FOOTPATH VASANTHAPPA BLOCK 6TH MAIN & ASPHALTING TO 10TH CROSS ROAD OF PILLAPPA BLOCK IN WARD NO 20	1250000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRIAN AND PROVIDING FOOTPATH	020-12-000026
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/186/2012-13	07/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/01/2013	30/01/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Anjaneyalu Br
Date of Inspection	Remarks
28/07/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0002	NA	RAILWAY TRACK
SegmentNo	TotalLength	
20/S-W0002/S091742	34.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N VENKATESH		1144410.00
PhoneNo	EmailId	
9844511384		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT DRIANS AT CHINNANNA LAYOUT CROSS ROADS IN WARD NO 20 GANGANAGARA	1100000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT TO DRIAN AND COVERING CC SLAB	020-11-000090
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/190/2012-13	07/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/12/2012	27/12/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0190	NA	IETE BUILDING
SegmentNo	TotalLength	
20/S-W0190/S092912	64.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		999436.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING AND RESETTING OF DRIAN AT BELLARY MAIN ROAD IN FRONT OF IETE BUILDING AND CONCRETEING IN FRONT OF CBI COMPOUND IN WARD NO 20 GANGANAGARA	1000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Routine Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	DESILTING AND RESETTING OF DRIAN AT BELLARY MAIN ROAD IN FRONT OF IETE BUILDING AND CONCRETEING IN FRONT OF CBI COMPOUND	020-13-000048
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/365/2012-13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/09/2014	29/09/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0080	NA	INDIAN PETROL BUNK
SegmentNo	TotalLength	
20/S-W0080/S093809	120.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		209060.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROAD IN KEB LAYOUT 3RD CROSS AND DECK SLAB IN WARD NO 20 GANGANAGARA	200000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING CC ROAD IN KEB LAYOUT 3RD CROSS AND DECK SLAB	020-13-000082
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/17/2014-15	17/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/06/2014	30/06/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0128	NA	KARNATAKA SPRIT HOUSE
SegmentNo	TotalLength	
20/S-W0128/S100727	330.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		207335.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE IN FRONT OF DRY WASTE CELL AND LAKSHMAIAH BLOCK BWSSB CUT PORTITION PROVIDING MS GATE IN FRONT OF DRY WASTE C ELL IN WARD NO	200000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	CC TO CUT BWSSB PORTITION
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING CEMENT CONCRETE IN LAKSHMAIAH BLOCK BWSSB CUT PORTITION	020-13-000083
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/18/2014-15	17/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/06/2014	30/06/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0126	NA	IMPACT SCHOOL
SegmentNo	TotalLength	
20/S-W0126/S101249	282.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KIRDL		489640.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRIAN AND PROVIDING FOOTPATH TO VASANTHAPPA TOTHA 6TH CROSS IN WARD NO 20 GANGANGARA	500000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRIAN AND PROVIDING FOOTPATH REMAING PORTITION FROM IMPACT SCHOOL TO CBI MAIN ROAD	020-13-000039
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/356/2012-13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	30/08/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Anjaneyalu Br
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0055	NA	PARK
SegmentNo	TotalLength	
20/S-W0055/S102546	67.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N KUMAR REDDY		854692.00
PhoneNo	EmailId	
9035158247		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRIAN AT 1ST CROSS ROAD (REMAINING RIGHT SIDE DESILTING AND RESETTING OF DRIAN LEFT SIDE) AND 4TH CROSS SIDDIVINAYAKA LAYOUT IN WARD 20	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRIAN 4TH CROSS SIDDIVINAYAKA LAYOUT IN WARD 20 GANGANAGARA	020-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/87/2014-15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	30/08/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0065	Om Shakthi Lyt 5th Crs	PARK
SegmentNo	TotalLength	
20/S-W0065/S103051	96.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N KUMAR REDDY		854692.00
PhoneNo	EmailId	
9035158247		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRIAN AT 1ST CROSS ROAD (REMAINING RIGHT SIDE DESILTING AND RESETTING OF DRIAN LEFT SIDE) AND 4TH CROSS SIDDIVINAYAKA LAYOUT IN WARD 20	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Footpath Layering	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENT OF DRIAN AT 1ST CROSS ROAD(REMAINING RIGHT SIDE DESILTING AND RESETTING OF DRIAN LEFT SIDE)	020-14-000007
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/87/2014-15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	30/08/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 20	WardName Ganga Nagara
StreetID W0255	StreetName Mahadevapura Village Rd	Significant LandMark OPP GANESH JUICE
SegmentNo 20/S-W0255/S114418	TotalLength 102.23	




ContractorDetails		
NameofContractor GOWRAMMA	ContractorRegNo	Expenditure 946319.00
PhoneNo 9845183324	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF DRAIN AT 6TH CROSS PAPANNA BLOCK IN WARD NO 20 GANGANAGARA	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails CONSTRUCTION OF CC DRIAN WITH BS SLAB COVERING	Job No Work Code 020-14-000012
Work OrderNo EE/H/AE/WO/220/2012-13	Work Order Date 22/02/2014	Period of Extention
Defect Liability Period From 26/12/2014	Defect Liability Period To 26/12/2015	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name Anjaneyalu Br
Date of Inspection 29/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0060	NA	BEHIND K H MUNIYAPPA HOUSE
SegmentNo	TotalLength	
20/S-W0060/S115120	322.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G KENCHAPPA AND SONS		1189622.00
PhoneNo	EmailId	
9845535433		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF DRAINS AT SIDDIVINAYAKA LAYOUT IN WARD NO 20 GANGANAGARA	1100000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	DESILTING AND RESETING OF DRIAN AT 2ND MAIN SV LAYOUT 1ST CROSS & 2ND CROSS	020-12-000047
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/204/2012-13	13/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/01/2013	30/01/2014	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0038	NA	PSR APPARTMENT
SegmentNo	TotalLength	
20/S-W0038/S115732	248.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PM BENGALURE NIRMITHA KENDRA		1957871.00
PhoneNo	EmailId	
9448287518		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT IN WARD NO 20 GNAGANGARA	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT AND ALL CROSS ROADS	020-12-000042
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/149/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0014	NA	RAILWAY TRACK
SegmentNo	TotalLength	
20/S-W0014/S120533	92.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PM BENGALURE NIRMITHA KENDRA		1957871.00
PhoneNo	EmailId	
9448287518		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT IN WARD NO 20 GNAGANGARA	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT AND ALL CROSS ROADS	020-12-000042
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/149/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0031	NA	BEHIND PSR APPARTMENT
SegmentNo	TotalLength	
20/S-W0031/S120807	96.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PM BENGALURE NIRMITHA KENDRA		1957871.00
PhoneNo	EmailId	
9448287518		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT IN WARD NO 20 GNAGANGARA	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT AND ALL CROSS ROADS	020-12-000042
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/149/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0016	NA	NEERUBHAVI KEMPANNA LAYOUT
SegmentNo	TotalLength	
20/S-W0016/S120941	54.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PM BENGALURE NIRMITHA KENDRA		1957871.00
PhoneNo	EmailId	
9448287518		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT IN WARD NO 20 GNAGANGARA	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	ASPHALTING TO NEERUBHAVI KEMPANNA LAOUT AND ALL CROSS ROADS	020-12-000042
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/149/2012-13	05/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/03/2013	30/03/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0191	NA	TILAK WINES
SegmentNo	TotalLength	
20/S-W0191/S121516	443.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		2086438.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND PROVIDING FOOTPATH TO WEAVERS COLONY 4TH MAIN IN WARD NO 20 GANGANAGARA	2000000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	DRAIN AND FOOTPATH
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAIN AND PROVIDING DISGHNERY TILES TO FOOTPATH TO WEAVERS COLONY 4TH MAIN FROM CBI MAIN ROAD TO 5TH MAIN TILAK WINES	020-12-000035
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/59/2012-13	25/06/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/07/2012	31/07/2013	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0141	NA	GILMA
SegmentNo	TotalLength	
20/S-W0141/S122153	45.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
S V VASUDEVAIAH		398996.00
PhoneNo	EmailId	
9900161348		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENT OF CBI ROAD 1ST CROSS IN WARD NO 20 GANGANAGARA	400000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Road	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING CC ROAD TO 1ST CROSS CBI ROAD	020-12-000037
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/110/2012-13	16/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/09/2012	29/09/2013	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0232	NA	BOREWELL
SegmentNo	TotalLength	
20/S-W0232/S122649	62.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		521810.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING PIPELINE PAPANNA BLOCK IN WARDE NO 20 GNAGANAGARA	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPELIN
Tender	WorkDetails	Job No Work Code
Tender	PIPELINE CONNECTION TO BOREWELL AND TAPPING	020-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/170/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	30/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0234	NA	EX MINISTER KRISHNAPPA HOUSE
SegmentNo	TotalLength	
20/S-W0234/S123342	27.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		521810.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING PIPELINE PAPANNA BLOCK IN WARDE NO 20 GNAGANAGARA	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPELINE
Tender	WorkDetails	Job No Work Code
Tender	PIPELINE CONNECTION TO BOREWELL AND TAPPING	020-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/170/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	30/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0176	NA	EX MINISTER KRISHNAPPA HOUSE
SegmentNo	TotalLength	
20/S-W0176/S123543	144.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		521810.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING PIPELINE PAPANNA BLOCK IN WARDE NO 20 GNAGANAGARA	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPELINE
Tender	WorkDetails	Job No Work Code
Tender	PIPELINE CONNECTION TO BOREWELL AND TAPPING	020-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/170/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	30/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0271	Ambedkar Nagar Slum	SWM DRIAN
SegmentNo	TotalLength	
20/S-W0271/S123806	90.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		521810.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING PIPELINE PAPANNA BLOCK IN WARDE NO 20 GNAGANAGARA	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPELINE
Tender	WorkDetails	Job No Work Code
Tender	PIPELINE CONNECTION TO BOREWELL AND TAPPING	020-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/170/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	30/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0267	Maheshwari Nagar Ambedkar Rd	EX MINISTER KRISHNAPPA BLOCK
SegmentNo	TotalLength	
20/S-W0267/S123926	24.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		521810.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING PIPELINE PAPANNA BLOCK IN WARDE NO 20 GNAGANAGARA	500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	PIPELINE
Tender	WorkDetails	Job No Work Code
Tender	PIPELINE CONNECTION TO BOREWELL AND TAPPING	020-13-000073
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/170/2013-14	25/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	30/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0215	NA	PILLAPPABLOCK
SegmentNo	TotalLength	
20/S-W0215/S024859	103.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		299773.00
PhoneNo	EmailId	
9448210498	UPPRAMESH@GMAIL.COM	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Protective work to strom water drain ,providing plain cement concrete to damage portion and providing WBM TO BWSSBS cut portion roads of pillappa bloc	300000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Others	WBM TO BWSSBS cut portion roads
Tender	WorkDetails	Job No Work Code
	WBM TO BWSSBS cut portion roads	020-14-000061
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/225/2014-15	18/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
03/02/2015	31/01/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/07/2015	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0223	NA	pillappa block
SegmentNo	TotalLength	
20/S-W0223/S030652	105.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		299773.00
PhoneNo	EmailId	
9448210498	UPPRAMESH@GMAIL.COM	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Protective work to strom water drain ,providing plain cement concrete to damage portion and providing WBM TO BWSSBS cut portion roads of pillappa bloc	300000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Others	WBM TO BWSSBS cut portion
Tender	WorkDetails	Job No Work Code
	WBM TO BWSSBS cut portion	020-14-000061
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/225/2014-15	18/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/01/2015	31/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0150	NA	vasathappa block
SegmentNo	TotalLength	
20/S-W0150/S031047	32.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		299773.00
PhoneNo	EmailId	
9448210498	UPPRAMESH@GMAIL.COM	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Protective work to strom water drain ,providing plain cement concrete to damage portion and providing WBM TO BWSSBS cut portion roads of pillappa bloc	300000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Others	cc damaged portion
Tender	WorkDetails	Job No Work Code
	cc damaged portion	020-14-000061
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/225/2014-15	18/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/01/2015	31/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0114	NA	coffeeday
SegmentNo	TotalLength	
20/S-W0114/S033359	390.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		224202.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing WBM to BWSSBS cut portion 13 cross RBI Colony HMT Layout Sai Baba Temple roads in ward no. 20 Ganganagara	225000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Others	WBM to BWSSBS cut portion
Tender	WorkDetails	Job No Work Code
Tender	WBM to BWSSBS cut portion	020-14-000062
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/226/2014-15	14/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/01/2015	31/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0198	NA	BMTC BUS DEPO
SegmentNo	TotalLength	
20/S-W0198/S034350	202.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		224202.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing WBM to BWSSBS cut portion 13 cross RBI Colony HMT Layout Sai Baba Temple roads in ward no. 20 Ganganagara	225000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Others	WBM to BWSSBS cut portion
Tender	WorkDetails	Job No Work Code
Tender	WBM to BWSSBS cut portion	020-14-000062
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/226/2014-15	14/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/01/2015	31/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0087	NA	BEHIND GOVT SCHOOL
SegmentNo	TotalLength	
20/S-W0087/S034734	183.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		2035469.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction concrete drain at 2nd cross KEB Layout, desilting and resetting of drian at sanjayanagar main road from bellary road to air force gate in	2000000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	cc drain with bs slab covering	020-14-000001
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/237/2014-15	20/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
27/01/2015	27/01/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0253	NA	CANE JUICE CENTER
SegmentNo	TotalLength	
20/S-W0253/S035948	144.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C LOGANATHAN		1455324.00
PhoneNo	EmailId	
9448058579		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drain at 7th cross papanna block ward 20 ganganagara	1500000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	cc drain with bs slab covering	020-14-000011
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/66/2013-14	24/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
22/06/2015	22/06/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
29/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0161	NA	huliyappa briyani
SegmentNo	TotalLength	
20/S-W0161/S041606	251.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		871402.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of plant ponding at ce layout main road(vet collage behind) and construction of deck slabs at hmt layout 1st cross in ward no 20 gangana	1000000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	desilting and resetting of slabs and kerbs	020-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/277/2014-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2015	28/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0215	NA	PILLAPPA BLOCK
SegmentNo	TotalLength	
20/S-W0215/S042337	103.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		871402.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of plant ponding at ce layout main road(vet collage behind) and construction of deck slabs at hmt layout 1st cross in ward no 20 gangana	1000000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Desilting and restting slabs and kerbs	020-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/277/2014-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2015	28/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0223	NA	pillappa block
SegmentNo	TotalLength	
20/S-W0223/S043252	105.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		871402.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of plant ponding at ce layout main road(vet collage behind) and construction of deck slabs at hmt layout 1st cross in ward no 20 gangana	1000000	2014
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	desilting and resting slabs and kerbs	020-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/277/2014-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2015	28/02/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0229	NA	pillappa block
SegmentNo	TotalLength	
20/S-W0229/S043430	128.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
U RAMESH		871402.00
PhoneNo	EmailId	
9448210498		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of plant ponding at ce layout main road(vet collage behind) and construction of deck slabs at hmt layout 1st cross in ward no 20 gangana	1000000	2015
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	desilting and resetting slabs and kerbs	020-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/277/2014-15	11/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/02/2015	28/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0062	NA	SV LAYOUT
SegmentNo	TotalLength	
20/S-W0062/S125129	101.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		835736.00
PhoneNo	EmailId	
9448061807		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements to drain at sv layout 3rd cross and remaining portion ward no 20	1000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender	Improvement of drain and cc covering	020-13-000053
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/349/2012-13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/08/2014	30/08/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		B R Anjanryalu
Date of Inspection	Remarks	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	CBIROAD
SegmentNo	TotalLength	
20/S-W0144/S020635	842.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		226694.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing wmm and surface dressing to bwwssb cutting portion in cbi road from aplolo pharm to vasanthppa block in ward no 20	200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	PROVINDING WMM AND SURFACE DRESSING	020-12-000065
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/160/2012-13	22/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/01/2014	28/01/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	20	Ganga Nagara
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	HNT GROUND
SegmentNo	TotalLength	
20/S-W0144/S022044	842.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
L GANGADHAR		226694.00
PhoneNo	EmailId	
9341260169		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing wmm and surface dressing to bwwssb cutting portion in cbi road from STORM WATER DRAIN to 80 FEET ROAD in ward no 20	200000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Pothole filling	
Tender	WorkDetails	Job No Work Code
Tender	PROVINDING WMM AND SURFACE DRESSING	020-12-000066
Work OrderNo	Work Order Date	Period of Extention
EE/H/AE/WO/161/2012-13	22/01/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
28/01/2014	28/01/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Anjaneyalu Br
Date of Inspection	Remarks	
28/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start

