



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0130, W0193, W0205, W0132, W0197, W0201, W0215, W	NA, Vinayaka Lyt 2nd Crs, Vinayaka Lyt 1st Crs	CHITRA LAYOUT
SegmentNo	TotalLength	
3/C-W0130/S090640	606.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasantha, No.28, Nagashetty Halli, 2nd Stage, Rajamahall		1931741.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to roads in Chitra layout of Attur ward No:03	1995000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphaltting to roads in Chitra layout of Attur ward No:03	003-13-000004
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 9/W.O/323/2013-14	15/06/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/07/2013	30/07/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0044	StreetName NA	Significant LandMark DODDACHIKKANNA LAYOUT
SegmentNo 3/S-W0044/S091624	TotalLength 84.35	



ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 1095703.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork Construction of drains, culverts and Imptovements to roads in Doddchikkanna layout Ananthapuara Ward No:03	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Construction of drains, culverts and Imptovements
Tender Not a Tender	WorkDetails Construction of drains, culverts and Imptovements to roads in Doddchikkanna layout Ananthapuara Ward No:03	Job No Work Code 003-13-000043
Work OrderNo BBMP/EE(YNK.D)/W.O/299/2012 -13	Work Order Date 14/03/2013	Period of Extention 90 DAYS
Defect Liability Period From 31/05/2013	Defect Liability Period To 30/05/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0615	NA	JNANA VIDYA MANDIRA
SegmentNo	TotalLength	
3/S-W0615/S090045	157.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasantha		1895143.00
PhoneNo	EmailId	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to roads in Thirumala Nagara balance roads of Attur ward No:03	1990000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphaltting to roads in Thirumala Nagara balance roads of Attur ward No:03	003-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-9/W.O/325/2013-14	15/06/2013	90
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/06/2013	06/06/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0048	StreetName NA	Significant LandMark DODDACHIKKANNA LAYOUT
SegmentNo 3/S-W0048/S092115	TotalLength 189.39	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 1095703.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork Construction of drains, culverts and Imptovements to roads in Doddchikkanna layout Ananthapuara Ward No:03	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Construction of drains, culverts and Imptovements
Tender Not a Tender	WorkDetails Construction of drains, culverts and Imptovements to roads in Doddchikkanna layout Ananthapuara Ward No:03	Job No Work Code 003-13-000043
Work OrderNo BBMP/EE(YNK.D)/W.O/299/2012 -13	Work Order Date 14/03/2013	Period of Extention 90 DAYS
Defect Liability Period From 31/05/2013	Defect Liability Period To 30/05/2014	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0029	NA	ANANTHAPURA
SegmentNo	TotalLength	
3/S-W0029/S092928	45.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		1976545.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drains, culverts and Imptovements to roads in Ananthapuara Ward No:03	1800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of drains, culverts and Imptovements
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of drains, culverts and Imptovements to roads in Ananthapuara Ward No:03	003-13-000041
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/297/2012 -13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/05/2013	30/05/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0011	NA	ANANTHAPURA
SegmentNo	TotalLength	
3/S-W0011/S093335	175.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		1976545.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of drains, culverts and Imptovements to roads in Ananthapuara Ward No:03	1800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of drains, culverts and Imptovements
Tender	WorkDetails	Job No Work Code
Not a Tender	Construction of drains, culverts and Imptovements to roads in Ananthapuara Ward No:03	003-13-000041
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/297/2012 -13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/05/2013	30/05/2014	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0249	NA	RANGAMANDIRA
SegmentNo	TotalLength	
3/S-W0249/S063754	25.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
No.178, Uttanahalli Village, Jala Hobali, Bangalore-57		1838180.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Sat	1960000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of Concrete drain and Road in
Tender	WorkDetails	Job No Work Code
Tender	Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Satellite Town sub division	004-13-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend- 03/W.O/80/2012-13	12/07/2012	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2013	29/05/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/10/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0245	NA	RANGAMANDIRA
SegmentNo	TotalLength	
3/S-W0245/S065046	27.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
No.178, Uttanahalli Village, Jala Hobali, Bangalore-57		1838180.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Sat		
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of Concrete drain and Road
Tender	WorkDetails	Job No Work Code
Tender	Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Satellite Town sub division	004-13-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend- 03/W.O/80/2012-13	12/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2013	29/05/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
01/10/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0023	StreetName NA	Significant LandMark NISARGA LAYOUT
SegmentNo 3/S-W0023/S064308	TotalLength 107.94	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Sanctioned Amount	Sanctioned Year
Year	Type of Work Others	Other Work Type Construction of drains, culverts and Imptovements
Tender Not a Tender	WorkDetails Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Job No Work Code 003-13-000042
Work OrderNo BBMP/EE(YNK.D)/W.O/298/2012-13	Work Order Date 14/03/2013	Period of Extention 90
Defect Liability Period From 29/05/2013	Defect Liability Period To 30/05/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0025	StreetName NA	Significant LandMark NISARGA LAYOUT
SegmentNo 3/S-W0025/S065449	TotalLength 202.11	



ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Sanctioned Amount 1800000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type Construction of drains, culverts and Imptovements
Tender Not a Tender	WorkDetails Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Job No Work Code 003-13-000042
Work OrderNo BBMP/EE(YNK.D)/W.O/298/2012-13	Work Order Date 14/03/2013	Period of Extention 90
Defect Liability Period From 29/05/2013	Defect Liability Period To 30/05/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0349, W0347, W0208	7th Main Rd, G M Palya, R H B Colcny 2nd Main Rd, NA	RANGAMANDIRA
SegmentNo	TotalLength	
3/C-W0349/S065552	35.71	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
No.178, Uttanahalli Village, Jala Hobali, Bangalore-57		1838180.00
PhoneNo	Emailld	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Sat	1996000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of Concrete drain and Road
Tender	WorkDetails	Job No Work Code
Tender	Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Satellite Town sub division	004-13-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend- 03/W.O/80/2012-13	12/07/2012	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2013	29/05/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/10/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0194, W0313	NA	RANGAMANDIRA
SegmentNo	TotalLength	
3/C-W0194/S070015	30.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
No.178, Uttanahalli Village, Jala Hobali, Bangalore-57		1838180.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Sat	1996000	2012
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of Concrete drain and Road
Tender	WorkDetails	Job No Work Code
Tender	Construction of Concrete drain and Road in Sanitary Core 3rd Phase and Fensing to Park And Balance work of Rangamandira in ward No:04 in Yelahanka Satellite Town sub division	004-13-000025
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-Tend- 03/W.O/80/2012-13	12/07/2012	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2013	29/05/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/10/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0187	NA	MUNESHWARA LAYOUT
SegmentNo	TotalLength	
3/S-W0187/S071143	28.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasantha, No.28, Nagashetty Halli, 2nd Stage, Rajamahal		1470514.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	003-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-9/W.O/324/2013-14	15/06/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/06/2014	28/06/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0609, W0607, W0613, W0615, W0334, W0605	StreetName Vydhhi Hospital Main Rd, NA, R H B Colcny, 5th Crs	Significant LandMark Thirumala Nagara
SegmentNo 3/C-W0609/S071736	TotalLength 66.85	

ContractorDetails		
NameofContractor Vasantha	ContractorRegNo	Expenditure 1895143.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Improvements and asphalting to roads in Thirumala Nagara balance roads of Attur ward No:03	Sanctioned Amount 1995000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Improvements and asphalting to roads in Thirumala Nagara balance roads of Attur ward No:03	Job No Work Code 003-13-000007
Work OrderNo EE(YNK.D)E-PMT- 9/W.O/325/2013-14	Work Order Date 15/06/2013	Period of Extention
Defect Liability Period From 29/06/2013	Defect Liability Period To 30/06/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0270, W0375, W0367, W0248, W0373, W0256	2nd A Crs, Maheshwari Nagar, 6th Crs, Muthkurappa Lyt, NA, East Park Reje Lyt, Ambedkar Nagar Slum	VINAYAKA TEMPLE
SegmentNo	TotalLength	
3/C-W0270/S071551	198.44	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Y.S.ChennakeshavaNo03, 1st Main, Gandhinagara, KHB Colony,Yelahanka Bangalore- 64		1999000.00
PhoneNo	EmailId	
Work Details		
8888888888		

NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to Yelahanka New Town A Sector 7th Main and Other Roads in Ward No:04	2004202	2013
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphalting to Yelahanka New Town A Sector 7th Main and Other Roads in Ward No:04	004-13-000007
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 8/W.O/262/2012-1	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/07/2013	29/07/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
01/10/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	MUNESHWARA LAYOUT
SegmentNo	TotalLength	
3/S-W0144/S071945	309.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasantha, No.28, Nagashetty Halli, 2nd Stage, Rajamahall		1470514.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	003-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-9/W.O/324/2013-14	15/06/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/06/2013	28/06/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0164	NA	MUNESHWARA LAYOUT
SegmentNo	TotalLength	
3/S-W0164/S072405	186.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Vasantha, No.28, Nagashetty Halli, 2nd Stage, Rajamahall		1470514.00
PhoneNo	EmailId	
8888888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	1500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphalting to roads in Muneshwara layout of Attur ward No:03	003-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-9/W.O/324/2013-14	15/06/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/06/2013	28/06/2014	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0040	NA	MATHRU LAYOUT
SegmentNo	TotalLength	
3/S-W0040/S072601	81.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.R.MOHAN No18, Govindappa Compound, NSH,RMV 2nd Stage Bangalore-94		1910236.00
PhoneNo	EmailId	
Work Details 8888888888		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drains at Mathru Layout 2nd Cross Road Right Side in ward No:04 in Yelahanka Satellite town sub division	1998000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC drains at Mathru Layout 2nd Cross Road Right Side in ward No:04 in Yelahanka Satellite town sub division	004-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-8/W.O /260/2012-13	01/07/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/06/2013	28/06/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
01/10/2015	completed	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0018	NA	MATHRU LAYOUT
SegmentNo	TotalLength	
3/S-W0018/S073354	40.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B.R.MOHAN No18, Govindappa Compound, NSH,RMV 2nd Stage Bangalore-94		1910236.00
PhoneNo	EmailId	
Work Details		
8888888888		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drains at Mathru Layout 2nd Cross Road Right Side in ward No:04 in Yelahanka Satellite town sub division	1998000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC drains at Mathru Layout 2nd Cross Road Right Side in ward No:04 in Yelahanka Satellite town sub division	004-13-000005
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-8/W.O /260/2012-13	01/07/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/06/2013	28/06/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
01/10/2015	completed	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0720, W0644, W0724, W1159, W0722	StreetName NA, 2nd Crs	Significant LandMark Adithynagra Phase--I
SegmentNo 3/C-W0720/S073311	TotalLength 87.33	



ContractorDetails		
NameofContractor SRI. THILAK KUMAR. H S, NO:76/1, 17TH MAIN ROAD, J. C. R. NAGAR, GELEYARA BALAGA, BANGALORE	ContractorRegNo	Expenditure 1935949.00
PhoneNo	EmailId	
Work Details 8888888888		

NameOfWork ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03	Sanctioned Amount 1999000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type ReConstection of drain and improvements to roads
Tender Tender	WorkDetails ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03	Job No Work Code 003-13-000008
Work OrderNo EE(YNK.D)E-PMT- 8/W.O/252/2012-13	Work Order Date 14/03/2013	Period of Extention 90 DAYS
Defect Liability Period From 30/09/2013	Defect Liability Period To 29/09/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0644	2nd Crs	Adithynagra Phase--I
SegmentNo	TotalLength	
3/S-W0644/S074211	87.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI. THILAK KUMAR. H S, NO:76/1, 17TH MAIN ROAD, J. C. R. NAGAR, GELEYARA BALAGA, BANGALORE		1935949.00
PhoneNo	EmailId	
Work Details		
8888888888		

NameOfWork	Sanctioned Amount	Sanctioned Year
ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03 in Yelahanka Satellite town sub division	1999000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ReConstection of drain and improvements to roads
Tender	WorkDetails	Job No Work Code
Tender	ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03 in Yelahanka Satellite town sub division	003-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 8/W.O/252/2012-13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/09/2013	29/09/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W1139, W0644	NA, 2nd Crs	Adithynagra Phase--I
SegmentNo	TotalLength	
3/C-W1139/S075156	64.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI. THILAK KUMAR. H S, NO:76/1, 17TH MAIN ROAD, J. C. R. NAGAR, GELEYARA BALAGA, BANGALORE		1935949.00
PhoneNo	EmailId	
Work Details		
8888888888		

NameOfWork	Sanctioned Amount	Sanctioned Year
ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03 in Yelahanka Satellite town sub division	1999000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	ReConstection of drain and improvements to roads
Tender	WorkDetails	Job No Work Code
Tender	ReConstection of drain and improvements to roads in Adithynagra Phase--I of Attur ward No:03 in Yelahanka Satellite town sub division	003-13-000008
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 8/W.O/252/2012-13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/09/2013	29/09/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0335	NA	SANTHOSH NAGAR
SegmentNo	TotalLength	
3/S-W0335/S075455	75.16	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
VASANTH, NO-28, A.T. LAYOUT, NSH, RMV, 2ND STAGE, BANGALORE-94		990050.00
PhoneNo	EmailId	
9988888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drains and Asphaltting to (Balance road) in Santhoshhnagara in ward No:03	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of RCC drains and Asphaltting
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC drains and Asphaltting to (Balance road) in Santhoshhnagara in ward No:03	003-13-000015
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-8/W.O/256/2012-13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/05/2013	30/05/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0335, W0196, W0341	NA	SANTHOSH NAGAR
SegmentNo	TotalLength	
3/C-W0335/S080133	49.34	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
VASANTH, NO-28, A.T. LAYOUT, NSH, RMV, 2ND STAGE, BANGALORE-94		990050.00
PhoneNo	EmailId	
9988888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of RCC drains and Asphaltting to (Balance road) in Santhoshhnagara in ward No:03	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	Construction of RCC drains and Asphaltting
Tender	WorkDetails	Job No Work Code
Tender	Construction of RCC drains and Asphaltting to (Balance road) in Santhoshhnagara in ward No:03	003-13-000015
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-8/W.O/256/2012-13	14/03/2013	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
31/05/2013	30/05/2014	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0576	StreetName NA	Significant LandMark Sambram College
SegmentNo 3/S-W0576/S082143	TotalLength 93.40	

ContractorDetails		
NameofContractor SAGAR.S	ContractorRegNo	Expenditure 932121.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Construction of drains culverts and Imprvements of roads in LAKSHMI ENCLAVE behind Sambram Collage in Attur ward No:03 in Yelahanka Satellite town su	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Construction of drains culverts and Imprvements of
Tender Tender	WorkDetails Construction of drains culverts and Imprvements of roads in LAKSHMI ENCLAVE behind Sambram Collage in Attur ward No:03 in Yelahanka Satellite town sub division	Job No Work Code 003-13-000009
Work OrderNo EE(YNK.D)E-PMT-8/W.O/253/2012-13	Work Order Date 14/03/2013	Period of Extention 90
Defect Liability Period From 26/04/2013	Defect Liability Period To 27/04/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep. d.n
Date of Inspection	Remarks	
30/09/2015	completed	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0576, W0570, W1085, W0578	StreetName NA, 16th Crs	Significant LandMark SAMBARAM COLLEGE
SegmentNo 3/C-W0576/S083432	TotalLength 187.19	



ContractorDetails		
NameofContractor SAGAR.S	ContractorRegNo	Expenditure 932121.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Construction of drains culverts and Imprvements of roads in LAKSHMI ENCLAVE behind Sambram Collage in Attur ward No:03 in Yelahanka Satellite town su	Sanctioned Amount 1000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type Construction of drains culverts and Imprvements of
Tender Tender	WorkDetails Construction of drains culverts and Imprvements of roads in LAKSHMI ENCLAVE behind Sambram Collage in Attur ward No:03 in Yelahanka Satellite town sub division	Job No Work Code 003-13-000009
Work OrderNo EE(YNK.D)E-PMT- 8/W.O/253/2012-13	Work Order Date 14/03/2013	Period of Extention 90
Defect Liability Period From 26/04/2013	Defect Liability Period To 27/04/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0750	StreetName NA	Significant LandMark ANASUYA CHANDRAPPA LAYOUT
SegmentNo 3/S-W0750/S110409	TotalLength 229.92	

ContractorDetails		
NameofContractor B B UMESHA	ContractorRegNo	Expenditure 0.00
PhoneNo 9886213563	EmailId	

Work Details		
NameOfWork Intimation of work order to start work of modified estimate providing and asphaltting to balance road and providing and laying pipeline in chitra layout	Sanctioned Amount 1000000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Intimation of work order to start work of modified estimate providing and asphaltting to balance road and providing and laying pipeline in chitra layout in attur ward no Yelahanka division, Yelahanka zone	Job No Work Code 003-15-000003
Work OrderNo BBMP/EE/YD/WO/81/2015-16	Work Order Date 29/01/2016	Period of Extention 90 DAYS
Defect Liability Period From 29/01/2016	Defect Liability Period To 28/01/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		PRADEEP
Date of Inspection	Remarks	
04/11/2016	COMPLETED	
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0873, W0452	StreetName NA, Chadra Shekar Gowda Rd	Significant LandMark N S public school
SegmentNo 3/C-W0873/S120655	TotalLength 165.42	

ContractorDetails		
NameofContractor Technical manejar (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 3649000.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Sanctioned Amount 40000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constrution of drain and improvement to cross road
Tender Tender	WorkDetails Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Job No Work Code 003-11-000081
Work OrderNo E(YNK.D)E-TEND-/W.O/162/2E011-12	Work Order Date 07/06/2011	Period of Extention 90 days
Defect Liability Period From 07/06/2011	Defect Liability Period To 10/06/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0873, W0863, W0448	StreetName NA, Narayana Swamy Gowga Layout Rd	Significant LandMark N S publik school
SegmentNo 3/C-W0873/S122225	TotalLength 224.79	

ContractorDetails		
NameofContractor Technical manejar (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 3649000.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Sanctioned Amount 4000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constrution of drain and improvement to cross road
Tender Tender	WorkDetails Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Job No Work Code 003-11-000081
Work OrderNo E(YNK.D)E- TEND-/W.O/162/2E011-12	Work Order Date 07/06/2011	Period of Extention 90 days
Defect Liability Period From 07/06/2011	Defect Liability Period To 07/06/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completef	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0873, W0855	StreetName NA, Murthi Lyt	Significant LandMark N S PUBLIC SCHOOL
SegmentNo 3/C-W0873/S122659	TotalLength 60.57	

ContractorDetails		
NameofContractor Technical manejar (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 3649000.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Constnution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Sanctioned Amount 4000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constnution of drain and improvement to cross road
Tender Tender	WorkDetails Constnution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Job No Work Code 003-11-000081
Work OrderNo E(YNK.D)E- TEND-/W.O/162/2E011-12	Work Order Date 07/06/2011	Period of Extention 90 days
Defect Liability Period From 07/06/2011	Defect Liability Period To 07/06/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0873, W0464, W0865	NA, Doddabettahalli Village Conneting Rd, Hari Raju Lyt 3rd Crs	maruthi lyt
SegmentNo	TotalLength	
3/C-W0873/S123158	107.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manejar (west) KRIDL, BBMP bengalore		3649000.00
PhoneNo	Emailld	
1234567890		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	4000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Constrution of drain and improvement to cross road
Tender	WorkDetails	Job No Work Code
Tender	Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	003-11-000081
Work OrderNo	Work Order Date	Period of Extention
E(YNK.D)E- TEND-/W.O/162/2E011-12	07/06/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/06/2011	06/06/2012	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0464, W0875	StreetName Doddabettahalli Village Conneting Rd, 4th Crs	Significant LandMark maruthi lyt
SegmentNo 3/C-W0464/S123600	TotalLength 95.21	

ContractorDetails		
NameofContractor Technical manejar (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 3649000.00
PhoneNo 1234567890	Emailld	

Work Details		
NameOfWork Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Sanctioned Amount 4000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Constrution of drain and improvement to cross road
Tender Tender	WorkDetails Constrution of drain and improvement to cross roads in ambhabhavani layout in ward no -03	Job No Work Code 003-11-000081
Work OrderNo EE(YNK.D)TEND-/W.O/162/2011- 2012	Work Order Date 07/06/2011	Period of Extention 90 DAYS
Defect Liability Period From 07/06/2011	Defect Liability Period To 07/06/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0310, W0621, W0623	Thirumala Dhaba Rd, Church Rd, Tirumala Nagar, E-Block, NA	charch road
SegmentNo	TotalLength	
3/C-W0310/S013217	300.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4934657.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to Thirumala Nagara balance roads in ward no-03	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Provding and asphaltting to Thirumala Nagara balance roads in ward no-03	003-14-000066
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/485/2013-2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2014	31/05/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0310, W0631, W0330, W0336	Thirumala Dhaba Rd, NA, 7th Crs, 6th Crs, Akshaya Nagara	Thiruma Dhaba
SegmentNo	TotalLength	
3/C-W0310/S014041	271.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4934657.00
PhoneNo	Emailld	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphalting to Thirumala Nagara balance roads in ward no-03	4998000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Provding and asphalting to Thirumala Nagara balance roads in ward no-03	003-14-000066
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-W.O/485/2013-2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2014	31/05/2016	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0284, W0286, W0499	1st Crs, NA	KSSIDC Office
SegmentNo	TotalLength	
3/C-W0284/S015317	52.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4143300.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	4970000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	003-14-000065
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/484/2013- 2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2014	31/05/2016	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0284, W0286, W0497, W0495	1st Crs, NA	KSSIDC Office
SegmentNo	TotalLength	
3/C-W0284/S015942	48.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4143300.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	4970000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	003-14-000065
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/484/2013-2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/02/2014	06/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0284, W0286, W0489	1st Crs, NA	KSSIDC Office
SegmentNo	TotalLength	
3/C-W0284/S020247	45.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4143300.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	4970000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	003-14-000065
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/484/2013-2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/06/2014	31/05/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0286, W0491, W0224	NA, 5th Crs	KSSIDC Office
SegmentNo	TotalLength	
3/C-W0286/S020501	39.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4143300.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltng to cross roads in Industriel area in Attur ward no;03	4970000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding and asphaltng to cross roads in Industriel area in Attur ward no;03	003-14-000065
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/484/2013- 2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/02/2014	06/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Dayanand
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0286, W0497, W0495	NA	KSSIDC Office
SegmentNo	TotalLength	
3/C-W0286/S020656	39.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		4143300.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	4970000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Provding and asphaltting to cross roads in Industriel area in Attur ward no;03	003-14-000065
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND-/W.O/484/2013- 2014	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
01/02/2014	31/01/2015	No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Dayanand
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0019	StreetName NA	Significant LandMark NISARGA LAYOUT
SegmentNo 3/S-W0019/S042543	TotalLength 257.81	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Sanctioned Amount 1979796	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Others	Other Work Type Construction of drains, culverts and Imptovements
Tender Not a Tender	WorkDetails Construction of drains, culverts and Imptovements to roads in Nisaraga layout in Ananthapuara Ward No:03	Job No Work Code 003-13-000042
Work OrderNo BBMP/EE(YNK.D)/W.O/298/2012-13	Work Order Date 14/03/2013	Period of Extention 90 DAYS
Defect Liability Period From 29/05/2013	Defect Liability Period To 29/05/2014	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
30/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0419, I0224, W0381, W0283, W0409, W0226	NA	Yelhanka new town 5th phase at Nagarjuna apartment
SegmentNo	TotalLength	
3/C-W0419/S102753	672.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A CHENNAREDDY		0.00
PhoneNo	EmailId	
9448050627		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing Asphaltting to main and Cross Roads of Yelhanka new town 5th phase at Nagarjuna apartment in Ward no 02 of Yelahanka Sub-Division Yelahanka	4990000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Comprehensive Development of roads and Drains in ward no 1 & 2 in Yelahanka Sub Division Est Cost Rs 1131.40 Lakhs	001-16-000023
Work OrderNo	Work Order Date	Period of Extention
EE (YNK.D) E-PMT-2/WO/95/2016-17	19/10/2016	12 MONTHS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/10/2016	18/10/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		DAYANANDA
Date of Inspection	Remarks	
11/12/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W1303, I0760, W1273, W1277, W0716, W1267, W1323, W	StreetName NA, Kurpanidhi College Rd	Significant LandMark AMS Layout Dr Chandrappa Layout and Bharathnagara
SegmentNo 3/C-W1303/S105901	TotalLength 1629.10	

ContractorDetails		
NameofContractor A CHENNAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9448050627	EmailId	

Work Details		
NameOfWork Providing asphaltting to roads and Improvements to Drains in AMS Layout Dr Chandrappa Layout and Bharathnagara in ward no 03 Yelahanka Satellite Town S	Sanctioned Amount 7500000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Comprehensive Development of Roads and Drains in ward no 03 and 04 in Yelahanka Upanagara Sub Division Est Cost Rs 897.70 Lakhs	Job No Work Code 003-16-000026
Work OrderNo EE (YNK.D) E-PMT- 2/WO/87/2015-16	Work Order Date 31/08/2016	Period of Extention 240 DAYS
Defect Liability Period From 31/08/2016	Defect Liability Period To 30/08/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
9	CHANDRAKANTH
Date of Inspection	Remarks
13/12/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0545, W0512, W0464, W0869, W0468, W0867, W0871, W	StreetName NA, 1st Crs, 6th Crs, Renuka Lyt	Significant LandMark BHEL Layout Chowdappa Layout
SegmentNo 3/S-W0545/S111821	TotalLength 866.55	

ContractorDetails		
NameofContractor A CHENNAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9448050627	EmailId	

Work Details		
NameOfWork Improvements to Roads Drains and Footpath in BHEL Layout Chowdappa Layout and Construction of lead off Drain and Asphaltting in Doddabetahalli layout i	Sanctioned Amount 9000000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Comprehensive Development of Roads and Drains in ward no 03 and 04 in Yelahanka Upanagara Sub Division Est Cost Rs 897.70 Lakhs	Job No Work Code 003-16-000026
Work OrderNo EE (YNK.D) E-PMT- 2/WO/87/2015-16	Work Order Date 31/08/2016	Period of Extention 240 DAYS
Defect Liability Period From 31/08/2016	Defect Liability Period To 30/08/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
9	CHANDRAKANTH
Date of Inspection	Remarks
12/12/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W1281, I1283, W0424, W1109, W0614	StreetName NA	Significant LandMark Samramha Engineering Collage, Sainagar Ambabhavani
SegmentNo 3/C-W1281/S113257	TotalLength 723.54	

ContractorDetails		
NameofContractor A CHENNAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9448050627	EmailId	

Work Details		
NameOfWork Improvements to Roads Drains and Footpath in areas around to Samramha Engineering Collage, Sainagar Ambabhavani layout and other areas in ward no 03 Y	Sanctioned Amount 9500000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Comprehensive Development of Roads and Drains in ward no 03 and 04 in Yelahanka Upanagara Sub Division Est Cost Rs 897.70 Lakhs	Job No Work Code 003-16-000026
Work OrderNo EE (YNK.D) E-PMT-2/WO/87/2015-16	Work Order Date 31/08/2016	Period of Extention 240 DAYS
Defect Liability Period From 31/08/2016	Defect Liability Period To 30/08/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
6	CHANDRAKANTH
Date of Inspection	Remarks
12/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0400, W0739, W0406, W0733, W0737, W0369, W0402	StreetName NA	Significant LandMark SFS 407 Yelahanka Satellite Town
SegmentNo 3/C-W0400/S084407	TotalLength 245.00	

ContractorDetails		
NameofContractor SAMBHASHIVAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9972741359	EmailId	

Work Details		
NameOfWork Improvements to Roads and Drains in SFS 407 in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	Sanctioned Amount 1000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Improvements to Roads and Drains in SFS 407 in ward no 03 Yelahanka Satellite Town Sub- Division Yelahanka zone	Job No Work Code 003-16-000018
Work OrderNo EE (YNK.D) E-PMT- 3/WO/70/2016-17	Work Order Date 19/05/2016	Period of Extention 90 DAYS
Defect Liability Period From 19/05/2016	Defect Liability Period To 18/05/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
12	PRADEEP
Date of Inspection	Remarks
17/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0513, W0416, W0515, W0511, W0519	StreetName NA, 5th Crs	Significant LandMark Amba Bhavani Layout
SegmentNo 3/C-W0513/S085324	TotalLength 220.05	

ContractorDetails		
NameofContractor SAMBHASHIVAREDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 9972741359	EmailId	

Work Details		
NameOfWork Improvements to Roads and Drains in Amba Bhavani Layout in ward no 03 Yelahanka Satellite Town Sub- Division Yelahanka zone	Sanctioned Amount 1000000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Improvements to Roads and Drains in Amba Bhavani Layout in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	Job No Work Code 003-16-000016
Work OrderNo EE (YNK.D) E-PMT- 1/WO/80/2015-16	Work Order Date 24/02/2016	Period of Extention 90 DAYS
Defect Liability Period From 24/02/2016	Defect Liability Period To 23/02/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
2		PRADEEP
Date of Inspection	Remarks	
17/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0809, W0470, W0847, W0815	StreetName NA	Significant LandMark Sai Baba Temple
SegmentNo 3/C-W0809/S014745	TotalLength 210.26	

ContractorDetails		
NameofContractor Shri S Jayachandra no-01, 18th Across Bandappa Gaurden Muthyalangara	ContractorRegNo	Expenditure 644240.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements to roads and Construction of drain an
Tender Tender	WorkDetails Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Job No Work Code 003-11-000003
Work OrderNo EE(YNK.D)E-TEND- 02/W.O/50/2012-13	Work Order Date 07/03/2011	Period of Extention 90 Days
Defect Liability Period From 07/03/2011	Defect Liability Period To 07/03/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0821, W0470, W0847, W0827, W0831	StreetName NA	Significant LandMark Sai Baba Temple
SegmentNo 3/C-W0821/S015311	TotalLength 320.18	

ContractorDetails		
NameofContractor Shri S Jayachandra no-01, 18th Across Bandappa Gaurden Muthyalangara	ContractorRegNo	Expenditure 644240.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements to roads and Construction of drain
Tender Tender	WorkDetails Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no- 03	Job No Work Code 003-11-000003
Work OrderNo EE(YNK.D)E-TEND- 02/W.O/50/2011-12	Work Order Date 07/03/2011	Period of Extention 90 Days
Defect Liability Period From 07/03/2011	Defect Liability Period To 07/03/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0837, W0470, W0847, W0472, W0845	StreetName NA	Significant LandMark Sai Baba Tempe
SegmentNo 3/C-W0837/S015827	TotalLength 336.58	

ContractorDetails		
NameofContractor Shri S Jayachandra no-01, 18th Across Bandappa Gaurden Muthyalangara	ContractorRegNo	Expenditure 644240.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements to roads and Construction of drain an
Tender Tender	WorkDetails Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Job No Work Code 003-11-000003
Work OrderNo EE(YNK.D)E-TEND- 02/W.O/50/2011-12	Work Order Date 07/03/2011	Period of Extention 90 Days
Defect Liability Period From 07/03/2011	Defect Liability Period To 07/03/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0821, W0853, W0837, W0809, W0470, W0845, W0827, W	StreetName NA, 1st Crs, Ambabhavani Temple Rd	Significant LandMark Sai Baba Temple
SegmentNo 3/C-W0821/S020136	TotalLength 294.31	


ContractorDetails		
NameofContractor Shri S Jayachandra no-01, 18th Across Bandappa Gaurden Muthyalangara	ContractorRegNo	Expenditure 644240.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements to roads and Construction of drain an
Tender Tender	WorkDetails Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Job No Work Code 003-11-000003
Work OrderNo EE(YNK.D)E-TEND- 02/W.O/50/2011-12	Work Order Date 07/03/2011	Period of Extention 90 Days
Defect Liability Period From 07/03/2011	Defect Liability Period To 07/03/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0821, W0837, W0809, W0845, W0827, W0847, M0005, W	StreetName NA, Ambabhavani Temple Rd	Significant LandMark Sai Baba Temple
SegmentNo 3/C-W0821/S020419	TotalLength 241.56	

ContractorDetails		
NameofContractor Shri S Jayachandra no-01, 18th Across Bandappa Gaurden Muthyalangara	ContractorRegNo	Expenditure 644240.00
PhoneNo	EmailId	

Work Details		
NameOfWork Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Sanctioned Amount 1000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Improvements to roads and Construction of drain and culverts at BHEL layout of Attur ward no-03	Job No Work Code 003-11-000003
Work OrderNo EE(YNK.D)E-TEND- 02/W.O/50/2011-12	Work Order Date 07/03/2011	Period of Extention 90 Days
Defect Liability Period From 07/03/2011	Defect Liability Period To 07/03/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0374	1st Main Rd	AMBHA BHAVANI TEMPLE ROAD
SegmentNo	TotalLength	
3/S-W0374/S102953	304.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.CHANNAKESHAVAM URTHY NO:40, SANEGURVANAHALLI,3rd BLOCK, BASAVESHWARANAGAR, BANGALORE		948111.00
Work Details		
PhoneNo	EmailId	
1111111111		
NameOfWork	Sanctioned Amount	Sanctioned Year
INTIMATION OF WORK ORDER TO START THE WORK OF – PROVIDING OF BS SLAB DRAIN AT AMBHA BHAVANI TEMPLE ROAD	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	INTIMATION OF WORK ORDER TO START THE WORK OF – PR
Tender	WorkDetails	Job No Work Code
Tender	INTIMATION OF WORK ORDER TO START THE WORK OF – PROVIDING OF BS SLAB DRAIN AT AMBHA BHAVANI TEMPLE ROAD FROM SAMBARAM COLLEGE TO SUBBASH CHANDRA BOSE ROAD IN ATTUR, WARD NO-3	003-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 6/W.O/374/2013-14	19/12/2013	60 DYAS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/12/2013	30/07/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
05/10/2015	completed	

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0426	Gosale Rd	MUNESHWARA LAYOUT
SegmentNo	TotalLength	
3/S-W0426/S103755	174.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.CHANNAKESHAVAM URTHY NO:40, SANEGURVANAHALI,3rd BLOCK, BASAVESHWARANAGAR, BANGALORE		1829842.00
Work Details	EmailId	
PhoneNo		
1111111111		
NameOfWork	Sanctioned Amount	Sanctioned Year
INTIMATION OF WORK ORDER TO START THE WORK CONSTRUCTION OF DRAINS AND CULVERTS AT 8TH MAIN ROAD OF MUNESHWARA LAYOUT	1950000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	INTIMATION OF WORK ORDER TO START THE WORK CONSTRU
Tender	WorkDetails	Job No Work Code
Tender	INTIMATION OF WORK ORDER TO START THE WORK CONSTRUCTION OF DRAINS AND CULVERTS AT 8TH MAIN ROAD OF MUNESHWARA LAYOUT IN ATTUR, WARD NO- 3	003-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 8/W.O/426/2013-14	30/01/2014	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/01/2014	30/11/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
05/10/2015	completed

Category	Photo
Drain Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0829, W0823, W0464, W0825, W0853, W0841, W0813, W	NA, Doddabettahalli Village Conneting Rd, 1st Crs, B T Nagaraj Layout, Ambabhavani Temple Rd	ambhabhavani temple road
SegmentNo	TotalLength	
3/C-W0829/S032210	315.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager KRIDL		4792420.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and construnction to and of drain from SWD to Ambabhavani Temple main road in Attur Ward ;03	4800000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and construnction to and of drain from SWD to Ambabhavani Temple main road in Attur Ward ;03	003-14-000047
Work OrderNo	Work Order Date	Period of Extention
No;EE(YNK.D)/w.0/461/2013-14	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	01/06/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0871, W1127, W0616	Main Rd, NA	Ashrama main road
SegmentNo	TotalLength	
3/C-W0871/S034717	127.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager KRIDL		4497358.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement and asphaltting to road from sambram college main road to Havyakanagara in Ward no-03	4500000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphaltting	
Tender	WorkDetails	Job No Work Code
Tender	Improvement and asphaltting to road from sambram college main road to Havyakanagara in Ward no-03	003-14-000035
Work OrderNo	Work Order Date	Period of Extention
bbmpNo;EE(YNK.D)-05/w.0/449/2013-14	06/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/05/2014	01/06/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
22/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W1131, W0604, W1127, W0602, W0608, W0618, W0616, W	StreetName NA	Significant LandMark Ashrama main road
SegmentNo 3/C-W1131/S035900	TotalLength 208.66	

ContractorDetails		
NameofContractor Technical Manager KRIDL	ContractorRegNo	Expenditure 4497358.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvement and asphaltting to road from sambram college main road to Havyakanagara in Ward no-03	Sanctioned Amount 4500000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Asphaltting	Other Work Type
Tender Tender	WorkDetails Improvement and asphaltting to road from sambram college main road to Havyakanagara in Ward no-03	Job No Work Code 003-14-000035
Work OrderNo bbmpNo;EE (YNK.D)/w.0/449/2013-14	Work Order Date 06/02/2014	Period of Extention
Defect Liability Period From 30/05/2014	Defect Liability Period To 01/06/2015	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W1325, W1105, M0005, W0732	NA, 6th Crs, Ambabhavani Temple Rd	W1325, W1105,M0005, W0732
SegmentNo	TotalLength	
3/C-W1325/S122413	183.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri S.Somashekar no;403,4th main road 6th cross , WCR 1st stage 2nd Phase		474875.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnctor of culverts and drain in hill side meadows in attur ward no-03	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construnctor of culverts and drain in hill side meadows in attur ward no-03	003-11-000026
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 02/W.O/49/2010-11	07/03/2011	90 dAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadukrishna
Date of Inspection	Remarks	
23/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W1117, W0736	8th Crs, NA	Souharda Public school
SegmentNo	TotalLength	
3/C-W1117/S124428	86.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri S.Somashekar no;403,4th main road 6th cross , WCR 1st stage 2nd Phase		474875.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnction of culverts and drain in hill side meadows in attur ward no-03	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construnction of culverts and drain in hill side meadows in attur ward no-03	003-11-000026
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 02/W.O/49/2010-11	07/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W1327, W0736	NA	Souharda Public school
SegmentNo	TotalLength	
3/C-W1327/S124956	48.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Shri S.Somashekar no;403,4th main road 6th cross , WCR 1st stage 2nd Phase		474875.00
PhoneNo	EmailId	
Work Details		
1111111111		

NameOfWork	Sanctioned Amount	Sanctioned Year
Construnctor of culverts and drain in hill side meadows in attur ward no-03	500000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construnctor of culverts and drain in hill side meadows in attur ward no-03	003-11-000026
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)TEND- 02/W.O/49/2010-11	07/03/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
07/03/2011	07/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
6		yudhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0375	6th Crs, Muthkurappa Lyt	THIRTHA HOUSE
SegmentNo	TotalLength	
3/S-W0375/S113857	136.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.CHANNAKESHAVAM URTHY NO:40, SANEGURVANAHALI,3rd BLOCK, BASAVESHWARANAGAR, BANGALORE		990935.00
Work Details		
PhoneNo	EmailId	
1111111111		
NameOfWork	Sanctioned Amount	Sanctioned Year
INTIMATION OF WORK ORDER TO START THE WORK OF PROVIDING CEMENT CONCRETE ROAD FOR AT THIRTHA HOUSE AND CROSS ROAD OF DODDABETTAHALI	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	INTIMATION OF WORK ORDER TO START THE WORK OF PROVIDING CEMENT CONCRETE ROAD FOR AT THIRTHA HOUSE AND CROSS ROAD OF DODDABETTAHALI IN ATTUR, WARD NO-3	003-14-000014
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 6/W.O/375/2013-14	19/12/2013	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
19/12/2013	30/06/2014	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
05/10/2015	completed	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0627, W0629, W0635, W0637, W0641, W0330, W0645, W	StreetName NA, 1st Crs, 8th Crs, 2nd Crs, 4th Crs	Significant LandMark Akshayanagara area
SegmentNo 3/C-W0627/S091012	TotalLength 584.77	

ContractorDetails		
NameofContractor M B HOMBAL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900083697	EmailId	

Work Details		
NameOfWork Construction of Culvert and Improvements of Drains in Akshayanagara area in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Construction of Culvert and Improvements of Drains in Akshayanagara area in Attur ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	Job No Work Code 003-15-000013
Work OrderNo EE (YNK.D) E-PMT- 4/WO/38/2014-15	Work Order Date 08/01/2015	Period of Extention 90 DAYS
Defect Liability Period From 31/01/2015	Defect Liability Period To 30/01/2016	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
10	PRADEEP
Date of Inspection	Remarks
16/01/2017	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0373	StreetName East Park Reje Lyt	Significant LandMark 407 area
SegmentNo 3/S-W0373/S064605	TotalLength 243.21	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 3515186.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO-03	Sanctioned Amount 3552000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type IMPROVEMENTS OF DRAINS AND FOOTPATH
Tender Not a Tender	WorkDetails IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO- 03	Job No Work Code 003-14-000083
Work OrderNo BBMP/EE(YNK.D)/W.O/510/2013 -14	Work Order Date 04/03/2014	Period of Extention 90 DAYS
Defect Liability Period From 31/07/2014	Defect Liability Period To 30/07/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0246	StreetName NA	Significant LandMark 407 AREA
SegmentNo 3/S-W0246/S065259	TotalLength 405.10	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 3515186.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO-03	Sanctioned Amount 3552000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type IMPROVEMENTS OF DRAINS AND FOOTPATH
Tender Not a Tender	WorkDetails IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO- 03	Job No Work Code 003-14-000083
Work OrderNo BBMP/EE(YNK.D)/W.O/510/2013 -14	Work Order Date 04/03/2014	Period of Extention 90 DAYS
Defect Liability Period From 31/07/2014	Defect Liability Period To 30/07/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0383	StreetName 1st Crs	Significant LandMark 407 AREA
SegmentNo 3/S-W0383/S065717	TotalLength 301.40	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 3515186.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO-03	Sanctioned Amount 3552000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type IMPROVEMENTS OF DRAINS AND FOOTPATH
Tender Not a Tender	WorkDetails IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO- 03	Job No Work Code 003-14-000083
Work OrderNo BBMP/EE(YNK.D)/W.O/510/2013 -14	Work Order Date 04/03/2014	Period of Extention 90 DAYS
Defect Liability Period From 31/07/2014	Defect Liability Period To 30/07/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0401, W0252, W0421, W0411, W0242, W0391, W0383	StreetName NA, 1st Crs	Significant LandMark 407 AREA
SegmentNo 3/C-W0401/S070058	TotalLength 107.08	



ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 3515186.00
PhoneNo 8888888888	EmailId	

Work Details		
NameOfWork IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO-03	Sanctioned Amount 3552000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type IMPROVEMENTS OF DRAINS AND FOOTPATH
Tender Not a Tender	WorkDetails IMPROVEMENTS OF DRAINS AND FOOTPATH IN 4TH PHASE 407 AREA IN ATTUR WARD NO- 03	Job No Work Code 003-14-000083
Work OrderNo BBMP/EE(YNK.D)/W.O/510/2013 -14	Work Order Date 04/03/2014	Period of Extention 90 DAYS
Defect Liability Period From 31/07/2014	Defect Liability Period To 30/07/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completedcompleted

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0408, W0727, W0378, W0376	StreetName NA, 8th Crs Lakshmi Sagar Lyt, 7th Crs Lakshmi Sagar Lyt	Significant LandMark ATTUR LAYOUT
SegmentNo 3/C-W0408/S065821	TotalLength 218.98	

ContractorDetails		
NameofContractor SRI.K.CHANNAKESHAVAM URTHY, NO:40, SANEGURUVANAHALLI,3rd BLOCK,BASAVESHWARAN AGARA BANGALORE	ContractorRegNo	Expenditure 937702.00



WorkID 8888888888	EmailId
-----------------------------	----------------

NameOfWork IMPROVEMENTS TO DRAINS AT 407 2nd A MAIN NEAR AYURVEDIC CLINIC ATTUR WARD 03	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails IMPROVEMENTS TO DRAINS AT 407 2nd A MAIN NEAR AYURVEDIC CLINIC ATTUR WARD 03	Job No Work Code 003-14-000002
Work OrderNo EE(YNK.D)E-PMT- 8/W.O/424/2013-14	Work Order Date 30/01/2014	Period of Extention 60 DAYS
Defect Liability Period From 31/05/2014	Defect Liability Period To 30/05/2015	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0313	NA	ATTUR LAYOUT
SegmentNo	TotalLength	
3/S-W0313/S071702	104.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PATTEGARE PALYA, NEAR PRASHANTHAGARA, BANGALORE.		1045383.00
PhoneNo	EmailId	
9988888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	003-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-11/W.O/492/2013-14	03/01/2014	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/12/2014	28/12/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0311	StreetName NA	Significant LandMark ATTUR
SegmentNo 3/S-W0311/S072708	TotalLength 112.50	

ContractorDetails		
NameofContractor PATTEGARE PALYA, NEAR PRASHANTHAGARA, BANGALORE.	ContractorRegNo	Expenditure 1045383.00
PhoneNo 9988888888	EmailId	

Work Details		
NameOfWork PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	Job No Work Code 003-14-000008
Work OrderNo EE(YNK.D)E-PMT- 11/W.O/492/2013-14	Work Order Date 03/01/2014	Period of Extention 60 DAYS
Defect Liability Period From 29/12/2014	Defect Liability Period To 28/12/2015	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition



Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0465	StreetName NA	Significant LandMark PRAGATHI SCHOOL
SegmentNo 3/S-W0465/S071544	TotalLength 83.84	

ContractorDetails		
NameofContractor SRI. K. C. CHANNAKESHAVAMURTHY , NO40, SANEGURUVANAHALLI, 3RD BLOCK, BASAVESHWARANAGARA, BANGALORE	ContractorRegNo	Expenditure 939829.00
Work Details		
PhoneNo NameOfWork 8888888888	EmailId Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN AT PRAGATHI SCHOOL ROAD IN ATTUR WARD NO-03	1000000	2014
Year 2013 - 2014	Type of Work Others	Other Work Type CONSTRUCTION OF RCC DRAIN
Tender Tender	WorkDetails CONSTRUCTION OF RCC DRAIN AT PRAGATHI SCHOOL ROAD IN ATTUR WARD NO-03	Job No Work Code 003-14-000003
Work OrderNo EE(YNK.D)E-PMT- 8/W.O/425/2013-14	Work Order Date 30/01/2014	Period of Extention 90 DAYS
Defect Liability Period From 30/05/2014	Defect Liability Period To 29/05/2015	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0309	NA	ATTUR
SegmentNo	TotalLength	
3/S-W0309/S073445	77.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PATTEGARE PALYA, NEAR PRASHANTHAGARA, BANGALORE.		1045383.00
PhoneNo	EmailId	
9988888888		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING ASPHALTING AND BS SLAB DRAIN AT LAW COLLEGE CROSS ROADS IN ATTUR WARD NO 03	003-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT-11/W.O/492/2013-14	03/01/2014	60 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/12/2014	28/12/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
14/10/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Road Condition



Road Condition




Segment End





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0901, W0903, W0464	StreetName NA	Significant LandMark Adityanagar
SegmentNo 3/C-W0901/S114307	TotalLength 13.83	

ContractorDetails		
NameofContractor K.Chennakeshava Murthy	ContractorRegNo	Expenditure 9989339.00
PhoneNo 1234567890	EmailId	

Work Details		
NameOfWork Providing Cement Concrete road for at Thirthan house and sross road of Doddabettahalli in Attur Ward No.03	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Road	Other Work Type
Tender Tender	WorkDetails Providing Cement Concrete road for at Thirthan house and sross road of Doddabettahalli in Attur Ward No.03	Job No Work Code 003-14-000014
Work OrderNo EE(YNK.D)EPMT-6/W.O/375/2013-14	Work Order Date 19/12/2013	Period of Extention 90 DAYS
Defect Liability Period From 29/03/2014	Defect Liability Period To 30/03/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep.D.N
Date of Inspection	Remarks	
14/10/2015	completed	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0556, W0440, W0466, W0562, W0470, W0847, W0592, W	NA, Mani Lyt 3rd Crs, 1st Main Rd, 2nd Crs, 1st Crs	Sambram College
SegmentNo	TotalLength	
3/C-W0556/S123726	340.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.CHANNAKESHAVAM URTHY NO:40, SANEGURVANAHALI,3rd BLOCK, BASAVESHWARANAGAR, BANGALORE		948111.00
Work Details		
PhoneNo	EmailId	
1111111111		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing of BS Slabe Drine at Ambha Bhavani Temple road from Sambram College to Subhash Chandra Bose Road in Attur Ward No.03	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Providing of BS Slabe Drine at Ambha Bhavani Temple road from Sambram College to Subhash Chandra Bose Road in Attur Ward No.03	003-14-000017
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 6/W.O/374/2013-14	19/12/2013	90
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
30/06/2014	01/07/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0223, W0237, W0136, W0221	NA	Attur Layout
SegmentNo	TotalLength	
3/C-W0223/S011510	97.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.K.CHANNAKESHAVAM URTHY NO:40, SANEGURVANAHALLI,3rd BLOCK, BASAVESHWARANAGAR, BANGALORE		1829842.00
Work Details	EmailId	
PhoneNo		
1111111111		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Drains at 8th main road of Muneshwara Layout in Attur Ward No.03	1950000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	Construction of Drains at 8th main road of Muneshwara Layout in Attur Ward No.03	003-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE(YNK.D)E-PMT- 8/W.O/426/2013-14	30/01/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
29/03/2014	30/03/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0196	StreetName NA	Significant LandMark INDIRA PRIYADARSHINI COLLEGE
SegmentNo 3/S-W0196/S024950	TotalLength 478.38	

ContractorDetails		
NameofContractor PATTEGARE PALYA, NEAR PRASHANTHAGARA, BANGALORE.	ContractorRegNo	Expenditure 1045383.00
PhoneNo	EmailId	

Work Details		
NameOfWork Providing Asphaltting and BS Slab Drain at Law College cross Road in Attur Ward No.03	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type Providing Asphaltting and BS Slab Drain
Tender Tender	WorkDetails Providing Asphaltting and BS Slab Drain at Law College cross Road in Attur Ward No.03	Job No Work Code 003-14-000008
Work OrderNo EE(YNK.D)E-PMT- 11/W.O/492/2013-14	Work Order Date 03/01/2014	Period of Extention 90 DAYS
Defect Liability Period From 31/12/2014	Defect Liability Period To 01/01/2016	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0649, W0639, W0611, W0322, W0643	StreetName 8th Crs, NA, Tirumalanagara D Block	Significant LandMark Thirumala nagara
SegmentNo 3/C-W0649/S030922	TotalLength 246.93	

ContractorDetails		
NameofContractor sri P Anand, No;827,20th main road 37th cross road ,4th Tblock jaynagara	ContractorRegNo	Expenditure 1748310.00
PhoneNo	EmailId	

Work Details		
NameOfWork construnction of drains and improvements of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Sanctioned Amount 1998000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails construnction of drains and improvements of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Job No Work Code 003-12-000067
Work OrderNo EE(YNK.D)E-Tend - 04/W.O/111/2012-13	Work Order Date 28/08/2012	Period of Extention 90 days
Defect Liability Period From 28/08/2012	Defect Liability Period To 28/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
7		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0649, W0322, W0629	StreetName 8th Crs, NA	Significant LandMark Thirumalanagara
SegmentNo 3/C-W0649/S032234	TotalLength 417.18	

ContractorDetails		
NameofContractor sri P Anand, No;827,20th main road 37th cross road ,4th Tblock jaynagara	ContractorRegNo	Expenditure 1748310.00
PhoneNo	Emailld	

Work Details		
NameOfWork construnction of drains and improvmnts of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Sanctioned Amount 1998000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails construnction of drains and improvmnts of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Job No Work Code 003-12-000067
Work OrderNo EE(YNK.D)E-Tend - 04/W.O/111/2012-13	Work Order Date 28/08/2012	Period of Extention 90 Days
Defect Liability Period From 28/08/2012	Defect Liability Period To 28/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0627, W0649, W0635, W0641, W0645, W0629, W0637	StreetName NA, 8th Crs, 9th A Main Rd, Akshaya Nagara	Significant LandMark Thirumalanagara
SegmentNo 3/C-W0627/S032723	TotalLength 144.98	
ContractorDetails		
NameofContractor sri P Anand, No;827,20th main road 37th cross road ,4th Tblock jaynagara	ContractorRegNo	Expenditure 1748310.00
PhoneNo	EmailId	
Work Details		
NameOfWork construnction of drains and improvements of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Sanctioned Amount 1998000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails construnction of drains and improvements of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Job No Work Code 003-12-000067
Work OrderNo EE(YNK.D)E-Tend - 04/W.O/111/2012-13	Work Order Date 28/08/2012	Period of Extention 90 Days
Defect Liability Period From 28/08/2012	Defect Liability Period To 28/08/2013	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0631, W0649, W0641, W0330, W0645	StreetName NA, 8th Crs, 7th Crs, 9th A Main Rd, Akshaya Nagara	Significant LandMark g K Indian school
SegmentNo 3/C-W0631/S033114	TotalLength 131.95	

ContractorDetails		
NameofContractor sri P Anand, No;827,20th main road 37th cross road ,4th Tblock jaynagara	ContractorRegNo	Expenditure 1748310.00
PhoneNo	EmailId	

Work Details		
NameOfWork construnction of drains and improvmnts of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Sanctioned Amount 1998000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails construnction of drains and improvmnts of roads in rally layout attach to left Veerasagara main road s in attur ward No-03	Job No Work Code 003-12-000067
Work OrderNo EE(YNK.D)E-Tend - 04/W.O/111/2012-13	Work Order Date 28/08/2012	Period of Extention 90 Days
Defect Liability Period From 28/08/2012	Defect Liability Period To 28/08/2013	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yudhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0789, W0556, W1083, W0829, W0807, W0825, W0813, W	StreetName NA, 1st Main Rd	Significant LandMark Sainagara and other area around Sambram Collage
SegmentNo 3/C-W0789/S115623	TotalLength 401.38	

ContractorDetails		
NameofContractor K.GOPI REDDY	ContractorRegNo	Expenditure 0.00
PhoneNo 7760405418	EmailId	

Work Details		
NameOfWork Improvements To Roads and drains in Sainagara and other area around Sambram Collage in ward no 03 Yelahanka Satellite Sub-Division Yelahanka zone	Sanctioned Amount 1300000	Sanctioned Year 2015
Year 2016 - 2017	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails Improvements To Roads and drains in Sainagara and other area around Sambram Collage in ward no 03 Yelahanka Satellite Sub-Division Yelahanka zone	Job No Work Code 003-16-000017
Work OrderNo EE(YNK.D)/E-PMT- 1/WO/42/2015-16	Work Order Date 27/02/2016	Period of Extention 90 DAYS
Defect Liability Period From 27/02/2016	Defect Liability Period To 26/02/2017	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
6	
Date of Inspection	Name
30/11/2016	PRADEEP
Remarks	
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0270, W0276, W0387	StreetName 1st Main Rd 5th Phase, 6th Crs, NA	Significant LandMark bbmp park
SegmentNo 3/C-W0270/S030158	TotalLength 122.08	

ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements and asphaltting to roads and providing
Tender Tender	WorkDetails Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O/193/2011 -12	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yudhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0407	NA	bbmp park
SegmentNo	TotalLength	
3/S-W0407/S031039	51.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphaltting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0417, W0276, W0272	NA, 6th Crs	bbmp park
SegmentNo	TotalLength	
3/C-W0417/S031435	90.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphaltting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadhukridhna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0417, W0276, W0272, W0274, W0435	StreetName NA, 6th Crs	Significant LandMark central bank of india
SegmentNo 3/C-W0417/S031822	TotalLength 95.54	

ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvmnts and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvmnts and asphalting to roads and providing
Tender Tender	WorkDetails Improvmnts and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O/193/2011 -12	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0437	NA	sentral bank of india
SegmentNo	TotalLength	
3/S-W0437/S032309	76.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphalting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0410	NA	Shyamaiah KAS Officer
SegmentNo	TotalLength	
3/S-W0410/S032738	90.52	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvements and asphaltting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O.193.2011-2012	18/08/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0417	NA	central bank of india
SegmentNo	TotalLength	
3/S-W0417/S033214	134.93	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvements and asphaltting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
7		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0270, W0276, W0222, W0369, W0388, W0378	StreetName 1st Main Rd 5th Phase, 6th Crs, 5th Main Rd, 3rd Main Rd, NA	Significant LandMark Bank of Maharastra
SegmentNo 3/C-W0270/S033910	TotalLength 197.09	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvmnts and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvmnts and asphaltting to roads and providing
Tender Tender	WorkDetails Improvmnts and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O.193.2011 -2012	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0274	NA	central bank of india
SegmentNo	TotalLength	
3/S-W0274/S034309	76.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphalting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0417, W0276, W0272, W0435	StreetName NA, 6th Crs	Significant LandMark BBMP Park
SegmentNo 3/C-W0417/S034637	TotalLength 129.25	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements and asphaltting to roads and providing
Tender Tender	WorkDetails Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O.193.2011 -2012	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0270, W0473, W0457, W0479	StreetName 1st Main Rd 5th Phase, NA, Dairy Crs (1st Main Rd)	Significant LandMark BBMP Park
SegmentNo 3/C-W0270/S035144	TotalLength 101.66	

ContractorDetails		
NameofContractor Technical Manager(west) KRIDL BBMP Bangalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvements and asphaltting to roads and providing
Tender Tender	WorkDetails Improvements and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O.193.2011 -2012	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0367	5th Main Rd	vinyaka temple
SegmentNo	TotalLength	
3/S-W0367/S035317	147.24	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphalting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphalting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011-12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0408, W0727, W0725	NA	Shyamaiah KAS Officer
SegmentNo	TotalLength	
3/C-W0408/S035735	25.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager(west) KRIDL BBMP Bangalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and asphaltting to roads and providing
Tender	WorkDetails	Job No Work Code
Tender	Improvments and asphaltting to roads and providing covering slab to existing strom water drain in 4th and 5th phase of Attur ward no 03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O.193.2011-2012	18/08/2011	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0252, W0254, W0256, W0391	StreetName 4th Crs, NA, 3rd Crs	Significant LandMark bbmp park
SegmentNo 3/C-W0252/S040242	TotalLength 96.35	



ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvmnts and asphaltng to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvmnts and asphaltng to roads and providing
Tender Tender	WorkDetails Improvmnts and asphaltng to roads and providing covering slab to existing strom water drain in 4th and 5th phase of attur ward no-03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O/193/2011 -12	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
3		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0264, W0252, W0270, W0385, W0258, W0242, W0256, W	StreetName NA, 4th Crs, 1st Main Rd 5th Phase, 4th Main Rd, 3rd Crs	Significant LandMark bbmp park
SegmentNo 3/C-W0264/S113852	TotalLength 223.83	

ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvmnts and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvmnts and and asphalting to roads and provid
Tender Tender	WorkDetails Improvmnts and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O/193/2011 -12	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
4		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0270	1st Main Rd 5th Phase	sentral bank of india
SegmentNo	TotalLength	
3/S-W0270/S114504	46.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical manager (west) KRIDL, BBMP bengalore		2805925.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvments and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	3000000	2011
Year	Type of Work	Other Work Type
2011 - 2012	Others	Improvments and and asphalting to roads and provid
Tender	WorkDetails	Job No Work Code
Tender	Improvments and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	003-12-000024
Work OrderNo	Work Order Date	Period of Extention
BBMP/EE(YNK.D)/W.O/193/2011 -12	18/08/2011	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
18/08/2011	18/08/2012	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
6		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0252, W0391, W0383	StreetName 4th Crs, NA, 4th Main Rd	Significant LandMark ganesha temple
SegmentNo 3/C-W0252/S114915	TotalLength 28.34	

ContractorDetails		
NameofContractor Technical manager (west) KRIDL, BBMP bengalore	ContractorRegNo	Expenditure 2805925.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvments and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	Sanctioned Amount 3000000	Sanctioned Year 2011
Year 2011 - 2012	Type of Work Others	Other Work Type Improvments and and asphalting to roads and provid
Tender Tender	WorkDetails Improvments and and asphalting to roads and providing covering slab to existing strom water drain in 4th 5th phase of attur ward no- 03	Job No Work Code 003-12-000024
Work OrderNo BBMP/EE(YNK.D)/W.O/193/2011 -12	Work Order Date 18/08/2011	Period of Extention 90 days
Defect Liability Period From 18/08/2011	Defect Liability Period To 18/08/2012	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0230, W0228, W0252, W0234, W0242, W0246, W0226, W	StreetName NA, 4th Crs, 3rd Crs, Atturu Main Rd, 4th Main Rd	Significant LandMark g k naidu school
SegmentNo 3/C-W0230/S025037	TotalLength 291.42	

ContractorDetails		
NameofContractor Sri suresh s. kanaji, no;20/1,2nd floor 3rd cross nagappa road, place guttahalli	ContractorRegNo	Expenditure 1818215.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Constnution of RCC drain and providing covering slab from 4th cross to shivamandira road in 4th phase of attur ward no- 03	Sanctioned Amount 1999000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Tender	WorkDetails Constnution of RCC drain and providing covering slab from 4th cross to shivamandira road in 4th phase of attur ward no-03	Job No Work Code 003-12-000084
Work OrderNo EE(YNK.D)E-TEND- 03/W.O/122/2012-13	Work Order Date 01/09/2011	Period of Extention 90 days
Defect Liability Period From 01/09/2011	Defect Liability Period To 01/09/2012	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
8		yadhukrishna
Date of Inspection	Remarks	
23/02/2015	completed	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0127, W0139, W0131, W0108	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	Ramanashree california garden layout
SegmentNo	TotalLength	
3/C-W0127/S122332	134.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (West) KRIDL,BBMP, Bangalore		4500000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement and asphalting to balance roads in ananthpura village in ward no-03	4500000	6-2-2014
Year	Type of Work	Other Work Type
2013 - 2014	Road	
Tender	WorkDetails	Job No Work Code
Tender		003-14-000041
Work OrderNo	Work Order Date	Period of Extention
Bbmp/ee(ynk.d)/W.O/455/2013-14	06/02/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
06/02/2014	06/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone YELAHANKA	WardNo 3	WardName Atturu
StreetID W0704, W0730, W0692, W1271, W1265, W0716, W0710, W	StreetName NA	Significant LandMark holy Faith school
SegmentNo 3/C-W0704/S040044	TotalLength 204.97	

ContractorDetails		
NameofContractor Technical Manager (west) KRIDL, BBmp Bangalore	ContractorRegNo	Expenditure 3600000.00
PhoneNo 1111111111	EmailId	

Work Details		
NameOfWork Improvements of drain and balancev roads in Chikkabettahalli behind Masjid , in ard No-03	Sanctioned Amount 3600000	Sanctioned Year 6-2-2014
Year 2013 - 2014	Type of Work Others	Other Work Type Improvements of drain and balancev roads in Chikka
Tender Tender	WorkDetails Improvements of drain and balancev roads	Job No Work Code 003-14-000044
Work OrderNo bbmp/ee(YNK.D)/W.O/458/2013- 14	Work Order Date 06/02/2014	Period of Extention 90 Days
Defect Liability Period From 06/02/2014	Defect Liability Period To 06/02/2015	Multiple Road Involved Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0836, W1377, W0838	NA	crental public school
SegmentNo	TotalLength	
3/C-W0836/S042326	87.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Technical Manager (West) KRIDL,BBMP		3600000.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of drain and balancev roads in Chikkabettahalli behind Masjid , in ard No-03	3600000	6-2-2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	Improvements of drain and balancev roads
Tender	WorkDetails	Job No Work Code
Tender	Improvements of drain and balancev roads	003-14-000044
Work OrderNo	Work Order Date	Period of Extention
bbmp/EE(YNK.D)/W.0/458/2013- 14	06/02/2014	90 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
08/02/2014	06/02/2015	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Pradeep
Date of Inspection	Remarks	
22/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
YELAHANKA	3	Atturu
StreetID	StreetName	Significant LandMark
W0721	NA	Sandeep Unnikrishnan road
SegmentNo	TotalLength	
3/S-W0721/S073456	218.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
7760406054		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of Roads and Drains at Attur Ward No.03	10000000	2017
Year	Type of Work	Other Work Type
2016 - 2017	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		003-17-000001
Work OrderNo	Work Order Date	Period of Extention
000111/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		chandrakanth
Date of Inspection	Remarks	
09/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	