



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0205	NA	anganawadi
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0205/S115431	156.36	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphalting to bad roads of doddanna lane and surroundings in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0178	NA	anganawadi
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0178/S120204	50.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to bad roads of doddanna lane and surroundings in ward no 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0207	NA	anganawadi
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0207/S120443	93.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to bad roads of doddanna lane and surroundings in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0178	NA	nazeer house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0178/S120556	50.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to bad roads of doddanna lane and surroundings in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0211	NA	nazeer house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0211/S120801	122.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to bad roads of doddanna lane and surroundings in ward no 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0180	NA	anganawadi
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0180/S120959	122.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K N Srinivas		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448086373		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to bad roads of doddanna lane and surroundings in ward no 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
454/2011-12		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0285	NA	water tank
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0285/S110223	45.10	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B R Pradeep		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740744655		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains of rahmaniya mosque area and surroundings in ward no 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
163/2013-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0025	14th Crs, Amc Rd	Saukar lane mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0025/S061205	79.30	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B R Pradeep		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740744655		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC drain and road improvemetns to nehru and shastri street	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		031-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
162/2013-14	28/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
1		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0151	1st Mn, Hanifia Mosque Rd	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0151/S074455	95.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains of kushalnagara and surroundings in ward 31	1000000	2013-14
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0152	NA	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0152/S074818	24.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain of kushal nagara and surrounsings in ward 31	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0158	NA	hanifnia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0158/S075256	21.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain of kushal nagara and surrounsings in ward 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0150	NA	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0150/S075402	20.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain of kushal nagara and surrounsings in ward 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> EAST	<b>WardNo</b> 31	<b>WardName</b> Kushal Nagara
<b>StreetID</b> W0156	<b>StreetName</b> NA	<b>Significant LandMark</b> hanifia mosque
<b>SegmentNo</b> 31/S-W0156/S075445	<b>TotalLength</b> 23.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9980406048	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to roads and drain of kushal nagara and surrounsings in ward 31	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b>
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 031-14-000049
<b>Work OrderNo</b> 10/2014-15	<b>Work Order Date</b> 01/07/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> imran
<b>Date of Inspection</b> 07/02/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148	NA	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0148/S075524	20.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain of kushal nagara and surrounsings in ward 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0154	NA	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0154/S075601	19.40	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980406048		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drain of kushal nagara and surrounsings in ward 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		031-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
10/2014-15	01/07/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
07/02/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0182	Nehru Street	nagawara road total gas staion
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0182/S081131	53.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B R Pradeep		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9740744655		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
construction of rcc drain and road Improvements to nehru and shastri street in ward no 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		031-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
162/2013-14	28/12/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0010	NA	Ashrafia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0010/S042921	134.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R Subramani		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845015885		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads at Ashrafiya Mosque area in Ward No.31	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
153		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
14/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0052	NA	sayeeda masjid
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0052/S043531	79.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R Subramani		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845015885		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads of 1st, 2nd, 3rd cross Rama Tent road in surrounding area in Ward No.31.	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-15-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
155		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
1		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0321	NA	temple at corner
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0321/S044100	58.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing and asphaltting to shampura main road and surroundings in ward no 31	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0319	11th Crs Lakshmi Sagar Lyt	Priya Bar
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0319/S044348	86.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to shampura main road and surroundings in ward no 31	1500000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0215	NA	Achala matha
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0215/S044651	86.81	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to shampura main road and surroundings in ward no 31	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
2		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0217	NA	achala matha
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0217/S044755	27.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to shampura main road and surroundings in ward no 31	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0213	NA	shafi and philip house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0213/S044849	34.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to shampura main road and surroundings in ward no 31	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0013	NA	SWD
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0013/S045022	72.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Achutha Murthy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980054466		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains at Kasturba nagar in Ward No.31	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
186/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
14/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0011	NA	SWD
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0011/S045340	27.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Achutha Murthy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980054466		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains at Kasturba nagar in Ward No.31	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
186/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
14/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0004	NA	SWD
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0004/S045607	25.31	



<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Achutha Murthy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980054466		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to roads and drains at Kasturba nagar in Ward No.31	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
186/14-15	27/01/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
14/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0168	NA	doddanna lane
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0168/S050550	219.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Tousif		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886057553		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to roads of asnwre layout and surroundings in ward no 31	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-13-000001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
143/14-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0180	NA	HBR layout anganawadi
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0180/S050748	122.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Tousif		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886057553		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to roads of Anwer layout and surroundings in ward no 31	1000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-13-000001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
143/14-15		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
30/06/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0170	NA	Doddanna lane 2nd main
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0170/S050854	223.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Somanna		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480264442		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing asphaltting to shampura main road and surroundings in ward no 31	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
169		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0105	NA	oil factory compound
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0105/S050457	100.28	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Renu Kumar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9738931758		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC drain at Kasturba nagar parallel to SWD in ward No 31	1000000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-13-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
25/2013-14		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0070	NA	AMC road khan clinic
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0070/S084010	42.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting toa road and improvements to footpath and drain at Kushal Nagara main rand crose in ward no 95	9000000	2008
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0177	NA	national gym
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0177/S070125	80.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0183	NA	national gym
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0183/S070751	80.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0185	NA	Canara bank ATM
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0185/S070852	79.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0189	NA	Canara bank ATM
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0189/S070951	83.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0193	Vinayaka Lyt 2nd Crs	Canara bank ATM
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0193/S071107	86.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0179, W0183, W0131, W0181, W0049, W0185, W0129, W	NA, Vinayaka Lyt 3rd Crs	temple
<b>SegmentNo</b>	<b>TotalLength</b>	
31/C-W0179/S071243	110.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> EAST	<b>WardNo</b> 31	<b>WardName</b> Kushal Nagara
<b>StreetID</b> W0197, W0137, W0143, W0179, W0201, W0203	<b>StreetName</b> Vinayaka Lyt 1st Crs, NA	<b>Significant LandMark</b> Anwer sharif house
<b>SegmentNo</b> 31/C-W0197/S071357	<b>TotalLength</b> 66.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B K Dorai	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9880531598	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	<b>Sanctioned Amount</b> 8000000	<b>Sanctioned Year</b> 2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b> 038-10-NGER-CO-008
<b>Work OrderNo</b> 64/2009-10	<b>Work Order Date</b> 03/12/2009	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> imran
<b>Date of Inspection</b> 27/07/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0049	NA	transformer
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0049/S071936	126.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
2		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
10/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0133	Vinayaka Lyt 4th Crs	shakeel house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0133/S072335	77.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0173	NA	Khamar house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0173/S072437	80.37	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0175	NA	2nd cross
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0175/S072535	78.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0187	NA	national chicken shop
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0187/S072622	56.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0191	NA	canara ATM
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0191/S072720	57.91	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0195	NA	canara bank atm
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0195/S072811	46.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B K Dorai		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880531598		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to Anwar layout in ward no 38 (old ward No 95)	8000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		038-10-NGER-CO-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
64/2009-10	03/12/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0143	NA	BDA park
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0143/S095802	313.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P Vishwanath		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9448502747		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete road to Limra mosque area and surroundings in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
94/2011-12	10/05/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0251, W0143, W0160, W0257, W0253	Maheshwaramma Temple Behind Rd, NA	tamil sngha school
<b>SegmentNo</b>	<b>TotalLength</b>	
31/C-W0251/S103209	209.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Venkatesh		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9446923658		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC drain at P&T colony in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000075
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
443/2011-12	20/12/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0261	NA	milk dairy
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0261/S103816	86.41	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Pradeep Kumar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9738931746		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to cross roads of P&T colony in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	031-11-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
89/2011-12	10/05/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	Ambedkar Nagar Slum	milk dairy
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0259/S104146	85.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Pradeep Kumar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9738931746		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete to cross roads of P&T colony in ward no 31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
89/2011-12	10/05/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0263	NA	Milk Dairy
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0263/S110809	87.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S.K.Haroon		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341246488		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC drain at 1st cross P & T colony in Ward No.31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
219/2011-12	01/06/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
27/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0208	NA	Nobel school
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0208/S111340	133.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S.K.Haroon		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341246488		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of RCC drain at 1st cross P & T colony in Ward No.31	1000000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		031-11-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
219/2011-12	01/06/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
06/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0062	NA	K G Halli Police station
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0062/S031016	253.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
10/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0068	NA	K G Halli police station
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0068/S031538	231.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0069	NA	Khans clinic
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0069/S031738	161.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
10/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0064	NA	irshad house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0064/S031844	34.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0066	NA	Irhsad house
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0066/S031945	41.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0060	NA	Hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0060/S032046	104.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0058	NA	hanifia mosque
<b>SegmentNo</b>	<b>TotalLength</b>	
31/S-W0058/S032200	76.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphaltting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
	0	095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
21/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0089, W0169, W0054, W0085, W0093	NA, 15th Crs	income tax layout
<b>SegmentNo</b>	<b>TotalLength</b>	
31/C-W0089/S032354	69.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphalting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
10/07/2015	photos are uploaded from record book	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	31	Kushal Nagara
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0054, W0138, W0052, W0136, W0134, W0049, W0056, W	NA, 2nd Crs, 1st Crs	SWD
<b>SegmentNo</b>	<b>TotalLength</b>	
31/C-W0054/S032511	101.43	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
L Gangadhar		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9341260169		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing cement concrete, asphalting to aroads and improvement to footpath and drains at kushalnagara main and cross roads in ward no 95		
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		095-09-M-S-E-R-PC-008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
27/2008-09	27/05/2009	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		imran
<b>Date of Inspection</b>	<b>Remarks</b>	
10/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	