



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0007, W0017, I0458	NA	Chikkabanaswadi Main Road
<b>SegmentNo</b>	<b>TotalLength</b>	
50/C-W0007/S052358	142.21	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.BHARATH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9343143366		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Desilting of Road side drain and Culverts at Seenappa Layout Chikkabanaswadi and Surrounding area area in Ward No.50	500000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Others	Desilting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Desilting of Drain and Culverts	050-16-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/23/2015-16	21/03/2016	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/07/2016	01/08/2017	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Veerabadraiah
<b>Date of Inspection</b>	<b>Remarks</b>	
02/08/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Segment End	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0134	1st Crs	Channasandra Main Road
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0134/S032702	155.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
P. Malayan		1361000.00
<b>PhoneNo</b>	<b>EmailId</b>	
9742792315		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC road at chanassandra and other improvements works in ward No 50	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Concrete Road	050-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/148/2013-14	04/03/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0231	NA	jalavayu Towers
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0231/S034725	137.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KS MYLEGOWDA		3327132.00
<b>PhoneNo</b>	<b>EmailId</b>	
9742792315		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Providing CC to lanes and narrow roads at Hosanagar near Krishnayanapalya in ward 50	4000000	2009
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2010 - 2011	Routine Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Concrete Road	048-10-N-W-B-R-PC-004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/48/2013-14	14/08/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0246	NA	NGEF COMPOUND
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0246/S040712	180.58	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROAD TO 2ND MAIN,2ND CROSS KRISHNAIHANA PALYA AND ITS SURROUNDING AREA	200000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-14-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/124/2013-14	18/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0401	NA	YELLAMMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0401/S041348	52.30	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC AT MADURAMMA TEMPLE AND ITS SURROUNDING AREA	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-12-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR//DM/AG/229/12-13	08/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0272	1st Crs, Maheshwari Nagar	JALAVAYU TOWERS
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0272/S042013	590.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M LAKSHMAN REDDY		1751340.00
<b>PhoneNo</b>	<b>EmailId</b>	
9900094714		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO 2ND MAIN ROAD AT KRISHNAIANAH PALYA	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		050-13-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/138/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0041	Om Shakthi Lyt, 9th Crs	CHIKKABANASAVADI MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0041/S042639	168.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M LAKSHMAN REDDY		1779013.00
<b>PhoneNo</b>	<b>EmailId</b>	
9900094714		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
ASPHALTING TO MAIN ROAD AND CROSS ROADS AT OMBR LAYOUT IN WARD NO 50	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		050-13-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/134/2013-14	22/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0314	NA	GAJENDRANAGAR 7TH CROSS
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0314/S043529	126.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC TO ROADS MATAPPA LANE AND ITS SURROUNDING AREA	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-14-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
RR/CVR/WO/110/13-14	18/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0349	7th Main Rd, G M Palya	GAJENDRA NAGAR MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0349/S044444	154.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1807601.00
<b>PhoneNo</b>	<b>EmailId</b>	
802356633		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC TO ROADS MATAPPA LANE AND ITS SURROUNDING AREA	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		050-14-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/110/2013-14	17/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0403	NA	Byappanahalli Ashwathkattae
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0403/S105315	332.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING RCC DRAIN AT 2ND MAIN ROAD BYYAPANAHALLI IN WARD NO 50	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	RCC DRAIN
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONSTRUCTION OF RCC DRAIN	050-13-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/233/20012-13	08/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0318	1st Crs	SWD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0318/S110136	586.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROAD AT GAJENDRANAGAR MAIN ROAD AND ITS SURROUNDING AREA	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	PROVIDING CC ROAD	050-14-000035
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/114/2013-14	18/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0311	NA	GAJENDRA NAGAR MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0311/S110759	138.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROAD AND IMPROVEMENTS OF AK COLONY AT OLD BAYYAPANAHALI IN WARD NO 50	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-14-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/128/2013-14	18/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0309	NA	GAJENDRA NAGAR MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0309/S111343	140.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIDING CC ROAD TO PAPANNA LANE AND ITS SURROUNDING AREA IN WARD NO 50	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-14-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/111/2013-14	18/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		ks vijay kumar
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> EAST	<b>WardNo</b> 50	<b>WardName</b> Benniganahalli
<b>StreetID</b> W0360, W0358, W0356, W0405	<b>StreetName</b> NA, 8th A Crs	<b>Significant LandMark</b> Byappanahalli Slum
<b>SegmentNo</b> 50/C-W0360/S095922	<b>TotalLength</b> 39.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Lakshman Reddy	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 8792589055	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of GLSR and Providing water supply lines at old byappanahalli in Ward No.50	<b>Sanctioned Amount</b> 8000000	<b>Sanctioned Year</b> 2012
<b>Year</b> 2012 - 2013	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Construction of RCC drain, Cement concrete road, SSM drain GLSR work(in some other cross roads of slum also work done but not showing in the map)	<b>Job No Work Code</b> 050-11-000046
<b>Work OrderNo</b> EE/CVR/WO/271/2012-13	<b>Work Order Date</b> 20/03/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		girish kumar
Date of Inspection	Remarks	
04/03/2016		
Category	Photo	
Road Condition		
Road Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
EAST	50	Benniganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0223	NA	KRISHNAIAHANAPALYA MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
50/S-W0223/S024001	88.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1894547.00
<b>PhoneNo</b>	<b>EmailId</b>	
9480828222		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
PROVIFING CC ROADS TO 8 AND9TH CROSS NARYANASWAMY LAYOUT SC ST COLONY AT KRISHNAIAHANAPALYA IN WARD 50	2000000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	CONCRETE ROAD	050-13-000029
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/CVR/WO/232/2012-13	24/01/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
<b>Date of Inspection</b>	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

