



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0685	NA	gayathri saw mill
SegmentNo	TotalLength	
52/S-W0685/S041930	330.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
m venkatachalapathi		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Nrupathunga road and Gayathri road in ward No.52	2455000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to Nrupathunga road and Gayathri road in ward No.52	052-15-000005
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/34/15-16	11/09/2015	90 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0750	NA	SLV apartment
SegmentNo	TotalLength	
52/S-W0750/S012403	252.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting ro main road and cross roads of Ajith Layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
10		gurusiddappa gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0691	NA	W0750
SegmentNo	TotalLength	
52/S-W0691/S013107	149.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No. 52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
26		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0729	NA	W0750
SegmentNo	TotalLength	
52/S-W0729/S013411	148.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
8		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0725	NA	W0750
SegmentNo	TotalLength	
52/S-W0725/S013633	52.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
10		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0711	NA	W0750
SegmentNo	TotalLength	
52/S-W0711/S013934	89.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0715	NA	W0750
SegmentNo	TotalLength	
52/S-W0715/S014108	41.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0719	NA	W0750
SegmentNo	TotalLength	
52/S-W0719/S014257	47.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0709	NA	W0750
SegmentNo	TotalLength	
52/S-W0709/S014429	83.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
6		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0705	NA	W0750
SegmentNo	TotalLength	
52/S-W0705/S014554	37.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0699	NA	W0750
SegmentNo	TotalLength	
52/S-W0699/S014718	48.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
3		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0695	NA	W0750
SegmentNo	TotalLength	
52/S-W0695/S014820	81.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main road and cross roads of Ajith layout in ward No.52	4644000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000007
Work OrderNo	Work Order Date	Period of Extention
214/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		Gurusiddappa Gokhale
Date of Inspection	Remarks	
20/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0369	NA	Karnataka Medicals
SegmentNo	TotalLength	
52/S-W0369/S125948	192.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to main roads and cross roads of Subhas Nagara in ward No. 52	3900000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000008
Work OrderNo	Work Order Date	Period of Extention
198/15-16	20/04/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
4		Gurusiddappa Gokhale
Date of Inspection	Remarks	
28/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0375	6th Crs, Muthkurappa Lyt	Nrupathunga road
SegmentNo	TotalLength	
52/S-W0375/S044827	172.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		2400375.00
PhoneNo	EmailId	
9811508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to Nrupathunga road and Gayathiri road in ward NO.52	2455000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Asphalting to Nrupathunga road and Gayathiri road in ward No.52	052-15-000005
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/213/15-16	11/11/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
8		nrupathunga road
Date of Inspection	Remarks	
17/06/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0011	NA	More Super Bazar
SegmentNo	TotalLength	
52/S-W0011/S035207	469.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in MannamNagar and cross roads in K.R.Pura ward no.52	4000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements of roads and drains in MannamNagar and cross roads in K.R.Pura ward no.52	052-15-000013
Work OrderNo	Work Order Date	Period of Extention
19/2015-16	06/04/2015	240 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		Gurusiddappa Gokhale
Date of Inspection	Remarks	
19/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0683	NA	Vinayaka nagar
SegmentNo	TotalLength	
52/S-W0683/S114327	500.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Samppangi		0.00
PhoneNo	EmailId	
9448518338		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement to road at vinayaka nagar in bhattarahalli	1500000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		204/08/1/S/E/R/AS/008
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/56/07/08		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
13		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0609	Vydhi Hospital Main Rd	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0609/S114856	91.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura	3000000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0644	2nd Crs	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0644/S121208	83.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura	3000000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0642	4th Crs	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0642/S121544	53.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura	3000000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0607	NA	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0607/S122129	23.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura	3000000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0646	NA	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0646/S122347	45.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura		
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0631	NA	Srinivasa kalyana mandapam
SegmentNo	TotalLength	
52/S-W0631/S021808	149.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in B. Narayanapura Area of Devasandra	9500000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		055/11/000039
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/467/11/12	24/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0633	NA	Vidya Hospitals
SegmentNo	TotalLength	
52/S-W0633/S022039	127.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to roads in nisarga layout in KR Pura	3000000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/AS/002
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/4/14/44/2009/10	07/07/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0113	3rd Crs	Bhattarahalli main road
SegmentNo	TotalLength	
52/S-W0113/S022308	25.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sambashiva		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constructing concrete roads and drain in Bhattarahalli village	1780000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000019
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/2012/13	10/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0116	NA	Bhattarahalli main road
SegmentNo	TotalLength	
52/S-W0116/S022828	101.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Sambashiva		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Constructing concrete roads and drain in Bhattarahalli village	1780000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/13/000019
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/2012/13	10/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0270	StreetName 2nd A Crs, Maheshwari Nagar	Significant LandMark Maheshwari Nagar
SegmentNo 52/S-W0270/S023109	TotalLength 116.91	

ContractorDetails		
NameofContractor K.R.I.D.L	ContractorRegNo	Expenditure 0.00
PhoneNo 9945520405	EmailId	

Work Details		
NameOfWork Improvements of roads and drains in papanna layout in KR Pura	Sanctioned Amount 4755000	Sanctioned Year
Year 2013 - 2014	Type of Work Asphalting	Other Work Type
Tender	WorkDetails	Job No Work Code 052/14/000030
Work OrderNo EE/KPD/TND/NPW/237/13/14	Work Order Date 10/02/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name DINESH
Date of Inspection 02/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0275	NA	Maheshwari Nagar
SegmentNo	TotalLength	
52/S-W0275/S023739	44.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in papanna layout in KR Pura	4755000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0279	Ambedkar Nagar Slum	Ambedkar Nagar Slum
SegmentNo	TotalLength	
52/S-W0279/S024119	44.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in papanna layout in KR Pura	4755000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
31/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0233	NA	Majunatha Layout
SegmentNo	TotalLength	
52/S-W0233/S024557	135.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in old manjunatha layout main roud, urban clustar layout in TC palya	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/14/85/14/15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0227	NA	Majunatha Layout
SegmentNo	TotalLength	
52/S-W0227/S025048	125.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in old manjunatha layout main roud, urban clustar layout in TC palya	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/14/85/14/15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0225	NA	Majunatha Layout
SegmentNo	TotalLength	
52/S-W0225/S025257	156.93	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in old manjunatha layout main roud, urban clustar layout in TC palya	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/14/85/14/15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0238	NA	Majunatha Layout
SegmentNo	TotalLength	
52/S-W0238/S025508	174.25	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in old manjunatha layout main roud, urban clustar layout in TC palya	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/14/85/14/15	03/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0242	NA	Old Village
SegmentNo	TotalLength	
52/S-W0242/S030722	321.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in TC Palya Old Village in KR Pura	1925000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/31/20/13/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0266	NA	Old Village
SegmentNo	TotalLength	
52/S-W0266/S031253	19.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in TC Palya Old Village in KR Pura	1925000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/31/20/13/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0273	NA	Old Village
SegmentNo	TotalLength	
52/S-W0273/S031446	241.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in TC Palya Old Village in KR Pura	1925000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/31/20/13/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0255	Mahadevapura Village Rd	Old Village
SegmentNo	TotalLength	
52/S-W0255/S032212	318.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in TC Palya Old Village in KR Pura	1925000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/31/20/13/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0727	NA	RMS Colony
SegmentNo	TotalLength	
52/S-W0727/S032457	433.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of 1st 2nd and 3rd main road in RMS Colony and cross roads of basavanapura main road and ravindra layout	2800000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000024
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/234/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0731	NA	RMS Colony
SegmentNo	TotalLength	
52/S-W0731/S032928	231.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of 1st 2nd and 3rd main road in RMS Colony and cross roads of basavanapura main road and ravindra layout	2800000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000024
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/234/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0735	4th Main Rd	RMS Colony
SegmentNo	TotalLength	
52/S-W0735/S033132	139.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of 1st 2nd and 3rd main road in RMS Colony and cross roads of basavanapura main road and ravindra layout	2800000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000024
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/234/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0770	NA	RMS Colony
SegmentNo	TotalLength	
52/S-W0770/S033328	108.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of 1st 2nd and 3rd main road in RMS Colony and cross roads of basavanapura main road and ravindra layout	2800000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000024
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/234/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0772	NA	RMS Colony
SegmentNo	TotalLength	
52/S-W0772/S033542	62.37	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of 1st 2nd and 3rd main road in RMS Colony and cross roads of basavanapura main road and ravindra layout	2800000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000024
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/234/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0077	NA	Sunshine Vally
SegmentNo	TotalLength	
52/S-W0077/S034212	34.57	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads old Manjunath layout balance roads in sunshine and urbon cluster layout in kr pura	2550000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000027
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/239/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0231	NA	Sunshine Vally
SegmentNo	TotalLength	
52/S-W0231/S034946	167.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads old Manjunath layout balance roads in sunshine and urbon cluster layout in kr pura	2550000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000027
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/239/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0025	NA	Sunshine Vally
SegmentNo	TotalLength	
52/S-W0025/S035210	128.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads old Manjunath layout balance roads in sunshine and urbon cluster layout in kr pura	2550000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000027
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/239/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0555	NA	Gagotri Road
SegmentNo	TotalLength	
52/S-W0555/S035424	355.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of College road gangotri road and 7th main in old extention in kr pura	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/18/59/14/15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0662	NA	Gagotri Road
SegmentNo	TotalLength	
52/S-W0662/S035956	211.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of College road gangotri road and 7th main in old extention in kr pura	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/18/59/14/15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
13		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0664	NA	Gagotri Road
SegmentNo	TotalLength	
52/S-W0664/S040134	121.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of College road gangotri road and 7th main in old extention in kr pura	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/18/59/14/15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0551	NA	College Rd
SegmentNo	TotalLength	
52/S-W0551/S040406	432.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in new extention KR Pura	1990000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/07/58/278/12/13	18/09/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0457	NA	BEML Layout
SegmentNo	TotalLength	
52/S-W0457/S041050	886.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Chinnappa		0.00
PhoneNo	EmailId	
9448518338		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in BEML layout 1st main road VB layout TC palya to KR Pura Road and Gangamma Temple Road	3845000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/240/13/14	14/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0067	13th Crs	Secrede Heart Road
SegmentNo	TotalLength	
52/S-W0067/S042329	449.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in Manjunath layout behind Scerede Heart Road and Pavithra layout in KR Pura	3725000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000028
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/241/13/14	02/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0066	NA	Secrede Heart Road
SegmentNo	TotalLength	
52/S-W0066/S043055	223.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in Manjunath layout behind Scerede Heart Road and Pavithra layout in KR Pura	3725000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000028
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/241/13/14	02/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0268	NA	T.C Palya Village
SegmentNo	TotalLength	
52/S-W0268/S043341	143.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Chinnappa		0.00
PhoneNo	EmailId	
9448518338		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete drain in old TC palya Old Village in KR Pura	1700000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender		052/13/000018
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/38/34/13/14	24/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0289	Chikkanna Lyt	T.C Palya Village
SegmentNo	TotalLength	
52/S-W0289/S043910	74.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Chinnappa		0.00
PhoneNo	EmailId	
9448518338		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete drain in old TC palya Old Village in KR Pura	1700000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender		052/13/000018
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/38/34/13/14	24/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		Dinesh
Date of Inspection	Remarks	
01/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0287	Maheshwari Nagar 4th Main Rd	T.C Palya Village
SegmentNo	TotalLength	
52/S-W0287/S044125	23.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V. Chinnappa		0.00
PhoneNo	EmailId	
9448518338		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete drain in old TC palya Old Village in KR Pura	1700000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender		052/13/000018
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/38/34/13/14	24/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0474	4th Crs	Tank Road
SegmentNo	TotalLength	
52/S-W0474/S044420	229.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G. Anthony Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction CC Road to (Tank Road) 1st cross road KR Pura	1985000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	CC Road
Tender	WorkDetails	Job No Work Code
Tender		052/12/000034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/03/17/72/12/1 3	06/07/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0244	NA	Brindavanam layout
SegmentNo	TotalLength	
52/S-W0244/S053436	199.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of Cross roads drain in brindavan layout at T.C Palya	1800000	
Year	Type of Work	Other Work Type
2010 - 2011	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000008
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/16/65/133/10/11	21/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0246	NA	Bridavanam layout
SegmentNo	TotalLength	
52/S-W0246/S053947	193.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of Cross roads drain in brindavan layout at T.C Palya	1800000	
Year	Type of Work	Other Work Type
2010 - 2011	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000008
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/16/65/133/10/11	21/03/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0045	NA	GCC College
SegmentNo	TotalLength	
52/S-W0045/S054154	29.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Nagraj		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Bhattahalli kittiganur road of kr pura	1500000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000070
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/44/334/11/12	11/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
26		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0652	NA	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0652/S061612	150.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0617	2nd Crs	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0617/S062435	32.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0623	NA	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0623/S062711	81.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0654	NA	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0654/S062910	59.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0048	NA	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0048/S063244	18.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0629	1st Crs	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0629/S063438	127.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0627	NA	Nisarga Layout
SegmentNo	TotalLength	
52/S-W0627/S063656	53.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C.K. Arunedra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in nisarga layout in KR Pura	9979000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/10/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/187/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015	DINESH	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0359	NA	RK celestial
SegmentNo	TotalLength	
52/S-W0359/S064028	77.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anthoni Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and drain in bhattarahalli village 3rd cross (RK celestial) in KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
		052/11/000049
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/102/354/2 011/12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
4		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0362	NA	RK celestial
SegmentNo	TotalLength	
52/S-W0362/S071919	32.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anthoni Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and drain in bhattarahalli village 3rd cross (RK celestial) in KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000049
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/102/354/2 011/12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
4		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0346	NA	RK celestial
SegmentNo	TotalLength	
52/S-W0346/S072045	38.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anthoni Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and drain in bhattarahalli village 3rd cross (RK celestial) in KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000049
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/102/354/2 011/12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0344	NA	RK celestial
SegmentNo	TotalLength	
52/S-W0344/S072158	97.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anthoni Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and drain in bhattarahalli village 3rd cross (RK celestial) in KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012		
Tender	WorkDetails	Job No Work Code
		052/11/000049
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/102/354/2 011/12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0342	R H B Colony, 7th Crs	RK celestial
SegmentNo	TotalLength	
52/S-W0342/S072323	78.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Anthoni Swamy		0.00
PhoneNo	EmailId	
9886310668		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads and drain in bhattarahalli village 3rd cross (RK celestial) in KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000049
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/23/102/354/2 011/12	05/08/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0541	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0541/S072559	160.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0556	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0556/S073143	42.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0554	1st Crs	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0554/S073259	40.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0543	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0543/S073439	182.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0560	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0560/S073603	18.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0545	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0545/S073731	122.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0547	1st Crs	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0547/S073850	122.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	0	000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0552	4th Main Rd	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0552/S074012	59.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0539	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0539/S074148	99.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0537	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0537/S074310	127.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0535	NA	Gangamma Temple
SegmentNo	TotalLength	
52/S-W0535/S074439	99.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Srinivas		0.00
PhoneNo	EmailId	
9448124759		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of roads in gangamma temple layout and constructing cc roads in kr pura	9950000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/N/P/P/R/A/S/035
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/7/190/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0306	Chikkanna Lyt 5th Crs	Bosoco Nagar
SegmentNo	TotalLength	
52/S-W0306/S074649	260.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphaltingof roads and improvements of drains in lakecity road bosconagar in tc palay at KR Pura	1990000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000028
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/2/239/11/1 2	16/05/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0453	6th Crs	Muniyappa Garden Road
SegmentNo	TotalLength	
52/S-W0453/S075132	71.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. Nagraj		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Formation of roads and removal of debris from muniyappa garden 2nd 3rd and 5th main road in KR Pura	992000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
		052/12/000026
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/359/12/13	27/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0449	3rd Crs	Muniyappa Garden Road
SegmentNo	TotalLength	
52/S-W0449/S075616	57.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. Nagraj		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Formation of roads and removal of debris from muniyappa garden 2nd 3rd and 5th main road in KR Pura	992000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000026
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/359/12/13	27/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0451	NA	Muniyappa Garden Road
SegmentNo	TotalLength	
52/S-W0451/S075828	52.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N. Nagraj		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Formation of roads and removal of debris from muniyappa garden 2nd 3rd and 5th main road in KR Pura	992000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000026
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/359/12/13	27/11/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0549	NA	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0549/S080406	137.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0421	NA	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0421/S080922	199.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
9		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0422	Rama Anjaneya Lyt, 1st Crs	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0422/S081208	83.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0426	Gosale Rd	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0426/S081336	51.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0534	2nd Crs	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0534/S081746	36.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0538	1st Main Rd	Venkateshwara School Area
SegmentNo	TotalLength	
52/S-W0538/S082035	36.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Karthick		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads MVB layout (opp. Ayyappa Temple) and Venkateshwara School Area at KR Pura	9960000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/071
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/4/188/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
1		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0260	Ambedkar Nagar Slum	Ambedkar bhavan
SegmentNo	TotalLength	
52/S-W0260/S102343	30.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R.Srinivasa reddy		0.00
PhoneNo	EmailId	
9448642123		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing improvements of roads and drains in K.R.Pura ward No.52	3000000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/NPW/TND/06/18/95/2008-09	29/01/2008	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0277	NA	Mini water tank
SegmentNo	TotalLength	
52/S-W0277/S103438	45.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements of roads and drains in Papanna layout in K.R.Pura	4755000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052-14-000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/NPW/237/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0281	NA	Borwell
SegmentNo	TotalLength	
52/S-W0281/S104838	78.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements of roads and drains in Papanna Layout K.R.Pura	4755000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-14-000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/NPW/237/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0442	Own Use Rd	Masjid
SegmentNo	TotalLength	
52/S-W0442/S105257	49.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.Venugopla		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of Concrete road near Sarvodaya School Shettappa road (1st cross) opp. road of Masjid and ramaiah layout cross roads and rain water drai	1950000	2012-13
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		052-13-000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/20/12-13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0459	Shetty Lyt, 2nd Main Rd	M.M Choultry
SegmentNo	TotalLength	
52/S-W0459/S110216	191.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T VENUGOPAL		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in ward No.52	9974000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
	0	000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
14/2/186/2009-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0461	NA	RAJAPPA'S HOUES
SegmentNo	TotalLength	
52/S-W0461/S110605	60.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.VENUGOPALA		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING AND IMPROVEMENT OF ROADS IN MUNIYAPPA LAYOUT IN K.R.PURA WARD NO.52	9974000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		000-10-N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
14/2/186/09-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0438	Mani Lyt 2nd Crs	CHANDRU'S HOUSE
SegmentNo	TotalLength	
52/S-W0438/S111021	44.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.VENUGOPALA		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING AND IMPROVEMENTS ROADS IN MUNIYAPPA LAYOUT IN K.R.PURA WARD NO.52	9974000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
	0	000-10-N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
14/2/186/09-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0439	NA	CHOULTRY
SegmentNo	TotalLength	
52/S-W0439/S111351	486.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T VENUGOPALA		0.00
PhoneNo	EmailId	
9342722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING AND IMPROVEMENTS OF ROADS IN MUNIYAPPA LAYOUT IN K.R.PURA WARD NO.52	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
14/2/186/9-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
15		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0136	NA	OPP. SCHOOL
SegmentNo	TotalLength	
52/S-W0136/S112208	137.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.ANTHONY SWAMY		0.00
PhoneNo	EmailId	
9945200136		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CC ROADS IN BHATTARAHALLI VILLAGE	1985000	2010-11
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		052-11-000051
Work OrderNo	Work Order Date	Period of Extention
17/23/262/11-12	16/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0236	2nd Main Rd	Chowdeshwari temple road
SegmentNo	TotalLength	
52/S-W0236/S111233	207.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		3692472.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlting to Athithi Layout roads main rosds and cross roads of SLV Aprtment roads in ward No.52	3885000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000002
Work OrderNo	Work Order Date	Period of Extention
215/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0040	NA	OM Shkathi Layout
SegmentNo	TotalLength	
52/S-W0040/S112235	69.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		3692472.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlting to Athithi Layout roads main rosds and cross roads of SLV Aptment roads in ward No.52	3885000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-15-000002
Work OrderNo	Work Order Date	Period of Extention
215/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0019	NA	OM shkathi temple road
SegmentNo	TotalLength	
52/S-W0019/S112439	95.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		3692472.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphlting to Athithi Layout roads main rosds and cross roads of SLV Aptment roads in ward No.52	3885000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000002
Work OrderNo	Work Order Date	Period of Extention
215/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0019	NA	Om shakthi Layout
SegmentNo	TotalLength	
52/S-W0019/S031823	95.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M.Venkatachalapathi		3692472.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in OMSakthi layout cross roads and SLV Apartment main roads and cross in ward No. 52	3885000	
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052-15-000002
Work OrderNo	Work Order Date	Period of Extention
215/15-16	11/09/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		Gurusiddappa Gokhale
Date of Inspection	Remarks	
27/09/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0639	NA	Balance Road
SegmentNo	TotalLength	
52/S-W0639/S080133	362.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of Deepa Hospital road and balance area KR Pura old railyration	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000061
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/33/266/11/12	16/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0660	NA	Balance Road
SegmentNo	TotalLength	
52/S-W0660/S080739	89.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of Deepa Hospital road and balance area KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/11/000061
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/33/266/11/12	16/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0641	2nd Crs	Balance Road
SegmentNo	TotalLength	
52/S-W0641/S080903	27.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of Deepa Hospital road and balance area KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/11/000061
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/33/266/11/12	16/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0643	NA	Balance Road
SegmentNo	TotalLength	
52/S-W0643/S081100	146.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Arunendra		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of Deepa Hospital road and balance area KR Pura	1950000	
Year	Type of Work	Other Work Type
2011 - 2012	Others	
Tender	WorkDetails	Job No Work Code
		052/11/000061
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/33/266/11/12	16/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0502	2nd Crs	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0502/S082349	63.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0461	NA	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0461/S082517	60.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0508	Itpl Main Rd	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0508/S082636	107.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0506	NA	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0506/S082750	107.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0526	NA	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0526/S082916	140.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0430	Nagappa Lyt	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0430/S083032	60.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0438	Mani Lyt 2nd Crs	Muniyappa Road
SegmentNo	TotalLength	
52/S-W0438/S083203	44.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in KR Pura	9974000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/2009/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0252	NA	Bridavanam Colony
SegmentNo	TotalLength	
52/S-W0252/S092012	119.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads and improvement of about in Bridavanam Colony in KR Pura	1980000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/11/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/11/12	06/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0250	NA	Bridavanam Colony
SegmentNo	TotalLength	
52/S-W0250/S092525	247.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads and improvement of about in Bridavanam Colony in KR Pura	1980000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/11/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/11/12	06/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
12		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0223	NA	Bridavanam Colony
SegmentNo	TotalLength	
52/S-W0223/S092647	284.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads and improvement of about in Bridavanam Colony in KR Pura	1980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/11/12	06/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0235	NA	Bridavanam Colony
SegmentNo	TotalLength	
52/S-W0235/S092803	34.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads and improvement of about in Bridavanam Colony in KR Pura	1980000	
Year	Type of Work	Other Work Type
2011 - 2012	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/11/12	06/12/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0434	NA	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0434/S092955	44.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0432	NA	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0432/S093438	138.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0423	2nd Crs	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0423/S093614	212.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0428	NA	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0428/S100728	129.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0420	Rama Anjaneya Lyt	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0420/S100903	92.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0416	5th Crs	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0416/S101028	95.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0419	NA	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0419/S101125	32.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0415	NA	Srinivasa colony
SegmentNo	TotalLength	
52/S-W0415/S101352	206.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Ajay		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of mettalled road in kathi viswanatha and Srinivasa layout	9980000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/12/AS/034
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/6/192/2009/10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0413	StreetName NA	Significant LandMark ITI Compound
SegmentNo 52/S-W0413/S101657	TotalLength 711.74	

ContractorDetails		
NameofContractor M. Ramesh	ContractorRegNo	Expenditure 0.00
PhoneNo 9448045901	EmailId	

Work Details		
NameOfWork providind improvement of road (cement concrete) and drain from ITI Compound of kr pura	Sanctioned Amount 2500000	Sanctioned Year
Year	Type of Work Others	Other Work Type
Tender	WorkDetails	Job No Work Code 204/09/N/G/E/D/FO/025
Work OrderNo EE/KPD/TND/NPW/06/17/93/08/09	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 2	Other Information	Name DINESH
Date of Inspection 30/06/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0481	Doddenakundi Main Rd	Harijana Colony
SegmentNo	TotalLength	
52/S-W0481/S102642	96.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C. Umalhankar		0.00
PhoneNo	EmailId	
9444586734		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drain at Harijana colony in ambedkar colony of KR Pura	800000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		204/08/1/W/E/R/IM/012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/119/07/08		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0450	Papayya Reddy Lyt, 15th Crs	V B Layout
SegmentNo	TotalLength	
52/S-W0450/S103723	132.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0446	Mani Lyt 5th Crs	V B Layout
SegmentNo	TotalLength	
52/S-W0446/S104321	10.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0488	NA	V B Layout
SegmentNo	TotalLength	
52/S-W0488/S104502	17.96	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0490	NA	V B Layout
SegmentNo	TotalLength	
52/S-W0490/S104635	17.78	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0495	Doddenakundi Industrial Rd	V B Layout
SegmentNo	TotalLength	
52/S-W0495/S104944	64.80	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0497	NA	V B Layout
SegmentNo	TotalLength	
52/S-W0497/S105203	58.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0463	Shetty Lyt, 1st Main Rd	V B Layout
SegmentNo	TotalLength	
52/S-W0463/S105434	18.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0448	Mani Lyt 6th Crs	V B layout
SegmentNo	TotalLength	
52/S-W0448/S105614	41.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0444	Mani Lyt 4th Crs	V B Layout
SegmentNo	TotalLength	
52/S-W0444/S110817	144.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0431	NA	V B Layout
SegmentNo	TotalLength	
52/S-W0431/S110952	82.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.L Kadegowda		0.00
PhoneNo	EmailId	
9845192849		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in VB layout (infront of urdu school) and kempalekkana layout (surrounding kote temple) in kr pura	9965000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		000/10/N/P/P/R/AS/0073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/05/189/09/10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
30/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0628	5th Crs	ITPL Main Road
SegmentNo	TotalLength	
52/S-W0628/S111332	179.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads of extention in KR Pura	3500000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		045/10/N/A/E/R/IM/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/2009/10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0593	6th Crs	ITPL Main Road
SegmentNo	TotalLength	
52/S-W0593/S111823	71.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads of extention in KR Pura	3500000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
Tender		045/10/N/A/E/R/IM/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/2009/10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0601	NA	ITPL Main Road
SegmentNo	TotalLength	
52/S-W0601/S112752	74.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads of extention in KR Pura	3500000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		045/10/N/A/E/R/IM/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/200 9/10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0595	5th Crs	ITPL Main Road
SegmentNo	TotalLength	
52/S-W0595/S112904	38.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads of extention in KR Pura	3500000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		045/10/N/A/E/R/IM/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/200 9/10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0636	StreetName 7th Crs	Significant LandMark ITPL Main Road
SegmentNo 52/S-W0636/S113024	TotalLength 124.17	

ContractorDetails		
NameofContractor K.R.I.D.L	ContractorRegNo	Expenditure 0.00
PhoneNo 9945520405	EmailId	

Work Details		
NameOfWork Improvement of roads of extention in KR Pura	Sanctioned Amount 3500000	Sanctioned Year
Year	Type of Work Others	Other Work Type
Tender	WorkDetails	Job No Work Code 045/10/N/A/E/R/IM/001
Work OrderNo EE/KPD/TND/NPW/18/01/02/200 9/10	Work Order Date 05/05/2009	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 3	Other Information	Name DINESH
Date of Inspection 01/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0015	NA	Grace Apt
SegmentNo	TotalLength	
52/S-W0015/S113240	68.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B. Raganath		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of roads and drain including forming roads in road motoroble condiation in KR pura	2148000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/CD/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/04/11/14/09/10	29/06/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0032	NA	Grace Apt
SegmentNo	TotalLength	
52/S-W0032/S114136	28.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
B. Raganath		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of roads and drain including formatting roads in road motoroble condition in KR pura	2148000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		045/10/M/G/E/12/CD/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/04/11/14/09/10	29/06/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0036	NA	Manjunatha Colony
SegmentNo	TotalLength	
52/S-W0036/S114609	220.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Shivakumar		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing improvement from manjunatha layout and sunshine layout of anandapura in kr pura	1500000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/023
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/19/79/2007/09	19/11/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
9		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0030	NA	Manjunatha Colony
SegmentNo	TotalLength	
52/S-W0030/S115021	259.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Shivakumar		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing improvement from manjunatha layout and sunshine layout of anandapura in kr pura	1500000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/023
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/19/79/2008/09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0038	NA	Manjunatha Colony
SegmentNo	TotalLength	
52/S-W0038/S115329	270.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Shivakumar		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing improvement from manjunatha layout and sunshine layout of anandapura in kr pura	1500000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/023
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/19/79/2008/09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
11		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0258	Ambedkar Nagar Slum	Ambedkar nagar colony
SegmentNo	TotalLength	
52/S-W0258/S115522	31.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9448443663		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Defined estimate for the work of providing improvements of roads and drains from kr pura	3000000	
Year	Type of Work	Other Work Type
	Others	CC Drain
Tender	WorkDetails	Job No Work Code
Tender		204/09/N/G/E/D/FO/022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/18/95/2008/09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0243	Chowdeshwari Temple Behind Rd	Ambedkar nagar colony
SegmentNo	TotalLength	
52/S-W0243/S120243	32.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9448443663		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Defined estimate for the work of providing improvements of roads and drains from kr pura	3000000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/18/95/2008/09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0253	NA	Ambedkar nagar colony
SegmentNo	TotalLength	
52/S-W0253/S120420	144.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9448443663		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Defined estimate for the work of providing improvements of roads and drains from kr pura	3000000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/18/95/2008/09		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0138	2nd Crs	G.P.H School
SegmentNo	TotalLength	
52/S-W0138/S120944	109.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G. Anthoni Swamy		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC drains in bhattarahalli village in kr pura	1985000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		052/11/000051
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/23/262/2011/12		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0599	NA	NH-4 Main road
SegmentNo	TotalLength	
52/S-W0599/S114119	62.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads of Extension in K.R.Pura	3500000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		045-10-N-A-E-R-IM-001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/2009-10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0500	StreetName 1st Crs	Significant LandMark kote vinayaka temple
SegmentNo 52/S-W0500/S25133	TotalLength 79.00	

ContractorDetails		
NameofContractor T.Venugopal	ContractorRegNo	Expenditure 0.00
PhoneNo	EmailId	

Work Details		
NameOfWork Ashphating improvements of Muniyappa layout in K.R.Pura Old extension	Sanctioned Amount 9974000	Sanctioned Year 2009-10
Year 2009 - 2010	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 000-10-N-P-P-R-AS-076
Work OrderNo 189	Work Order Date 04/12/2009	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name DINESH
Date of Inspection 02/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0502, W0439, W0461	2nd Crs, 2nd Crs, NA	Manjunatha reddy house
SegmentNo	TotalLength	
52/S-W0502/S25142	61.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.VENUGOPLA		0.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Ashphalting and improvements of roads in Muniyappa layout in K.R.Pura old extension	9974000	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000-10-N-P-P-R-AS-076
Work OrderNo	Work Order Date	Period of Extention
186	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0459, W0439, W0508	3rd Crs, 2nd Crs, 1st Main Rd	Ganesh house road
SegmentNo	TotalLength	
52/S-W0459/S25149	102.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.VENUGOPALA		10735000.00
PhoneNo	EmailId	

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvements of roads in Muniyappa layout in K.R.Pura old Extension	9974000	2009-10
Year	Type of Work	Other Work Type
2009 - 2010	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		000-10-N-P-P-R-AS-076
Work OrderNo	Work Order Date	Period of Extention
186	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		Dinesh
Date of Inspection	Remarks	
28/06/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0280	2nd Crs, Lakshmi Sagar Lyt	BEML
SegmentNo	TotalLength	
52/S-W0280/S030225	189.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0290	NA	BEML
SegmentNo	TotalLength	
52/S-W0290/S030455	38.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0292	3rd Crs Lakshmi Sagar Lyt	BEML
SegmentNo	TotalLength	
52/S-W0292/S030630	77.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0313	NA	BEML
SegmentNo	TotalLength	
52/S-W0313/S030833	64.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0278	Lakshmi Sagar Lyt, 1st Crs	Balance Road
SegmentNo	TotalLength	
52/S-W0278/S031415	32.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of balance roads in T C Palya village of K R Pura	1981000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/19/57/2014/15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0291	NA	Balance Road
SegmentNo	TotalLength	
52/S-W0291/S032025	116.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of balance roads in T C Palya village of K R Pura	1981000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/19/57/2014/ 15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0299	Maheshwari Nagar Main Rd	Balance Road
SegmentNo	TotalLength	
52/S-W0299/S032224	77.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of balance roads in T C Palya village of K R Pura	1981000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/1/19/57/2014/15	26/08/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0760	NA	Manjunatha Layout
SegmentNo	TotalLength	
52/S-W0760/S033417	74.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads in old manjunatha layout main road urbon culster layout in T C palya in K R Pura	1600000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/85/143/14	14/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0758	NA	Manjunatha Layout
SegmentNo	TotalLength	
52/S-W0758/S034120	75.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads in old manjunatha layout main road urbon culster layout in T C palya in K R Pura	1600000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/85/143/14	14/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0756	NA	Manjunatha Layout
SegmentNo	TotalLength	
52/S-W0756/S034322	77.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting od roads in old manjunatha layout main road urbon culster layout in T C palya in K R Pura	1600000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000004
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/85/143/14	14/05/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0348	NA	Sharavahi Layout
SegmentNo	TotalLength	
52/S-W0348/S045133	144.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in Sharavahi Layout at Bhattarahalli K R Pura	1285000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/30/188/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0371	Dr Ambekdar Govt Ashraya Colony Garudacharapalya	Sharavahi Layout
SegmentNo	TotalLength	
52/S-W0371/S051130	183.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in Sharavahi Layout at Bhattarahalli K R Pura	1285000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/30/188/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0003	NA	Mukthi Vinayaka
SegmentNo	TotalLength	
52/S-W0003/S051418	305.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of Scared heart layout main road & Mukthi Vinayaka Layout roads in T C Palya in K R Pura	2700000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/13/000025
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/452/2012/13	03/01/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
12		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0131	NA	Subhas Nagara
SegmentNo	TotalLength	
52/S-W0131/S052527	52.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st main and cross roads in Manjunatha Layout, subhas nagara, Mutton stall road T C palya and vinayaka layout bhattachahalli in K R Pura	3350000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/14/000021
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/242/2013/14	10/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0133	Vinayaka Lyt 4th Crs	Subhas Nagara
SegmentNo	TotalLength	
52/S-W0133/S053143	54.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st main and cross roads in Manjunatha Layout, subhas nagara, Mutton stall road T C palya and vinayaka layout bhattarahalli in K R Pura	3350000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000021
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/242/2013/14	10/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0144	3rd Crs	Subhas Nagara
SegmentNo	TotalLength	
52/S-W0144/S053305	77.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st main and cross roads in Manjunatha Layout, subhas nagara, Mutton stall road T C palya and vinayaka layout bhattachahalli in K R Pura	3350000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	0	052/14/000021
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/242/2013/14	10/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0129	NA	Subhas Nagara
SegmentNo	TotalLength	
52/S-W0129/S053437	62.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st main and cross roads in Manjunatha Layout, subhas nagara, Mutton stall road T C palya and vinayaka layout bhattarahalli in K R Pura	3350000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000021
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/242/2013/14	10/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0327	Lakshmi Sagar Lyt North Side, 2nd Crs	TC PALYA CHURCH
SegmentNo	TotalLength	
52/S-W0327/S040502	76.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	4000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	052-15-000016
Work OrderNo	Work Order Date	Period of Extention
22/2015-16	06/04/2015	480 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		Gurusiddappa Gokhale
Date of Inspection	Remarks	
08/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0325	NA	TC PALYA CHURCH
SegmentNo	TotalLength	
52/S-W0325/S041200	81.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	4000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	052-15-000016
Work OrderNo	Work Order Date	Period of Extention
22/2015-16	06/04/2015	480 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		Gurusiddappa Gokhale
Date of Inspection	Remarks	
08/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0076	NA	TC PALYA CHURCH
SegmentNo	TotalLength	
52/S-W0076/S041807	124.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	4000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	052-15-000016
Work OrderNo	Work Order Date	Period of Extention
22/2015-16	06/04/2015	480 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
20		Gurusiddappa Gokhale
Date of Inspection	Remarks	
08/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0065	Om Shakthi Lyt 5th Crs	TC PALYA CHURCH
SegmentNo	TotalLength	
52/S-W0065/S042152	70.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	4000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and drains in Secred heart layout and Basco Nagar in K.R.Pura ward No.52	052-15-000016
Work OrderNo	Work Order Date	Period of Extention
22/2015-16	06/04/2015	480 Days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		Gurusiddappa Gokhale
Date of Inspection	Remarks	
08/03/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0352	NA	Garrage
SegmentNo	TotalLength	
52/S-W0352/S010340	58.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venakatchapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphating of road in layout (back side pertol bunk) at bhattarahalli kr pura 52	1600000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphating	
Tender	WorkDetails	Job No Work Code
Tender	As Asphatling	052/12/000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/28/190/12/13/22/03/2012		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0356	NA	Garage
SegmentNo	TotalLength	
52/S-W0356/S011701	55.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Alphalting of roads in layout (back side of pertol bunk) of bhattarahalli	1600000	12
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/29/190/2012/2013	22/03/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0358	NA	Garage
SegmentNo	TotalLength	
52/S-W0358/S012738	61.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Alphalting of roads in layout (back side of pertol bunk) of bhattarahalli	1600000	12
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/29/190/2012/2013	22/03/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0364	Lakshmi Sagar Lyt, 5th Crs	Garage
SegmentNo	TotalLength	
52/S-W0364/S013008	73.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Alphalting of roads in layout (back side of pertol bunk) of bhattarahalli	1600000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/29/190/2012/2013	22/03/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
1		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0195	NA	Club House
SegmentNo	TotalLength	
52/S-W0195/S013614	538.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st,2nd,3rd cross roads of Anadapura cross road of club	4835000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/14/000033
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/243/2013/14	22/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0074	NA	Club House
SegmentNo	TotalLength	
52/S-W0074/S015029	116.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 1st,2nd,3rd cross roads of Anadapura cross road of club	4835000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/14/000033
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/243/2013/14	22/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0561	NA	OHT
SegmentNo	TotalLength	
52/S-W0561/S021112	840.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of cross roads of 1st main now extention pu college road	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	05213000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/85/21/13/14	13/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
20		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0542	1st Main Rd	OHT
SegmentNo	TotalLength	
52/S-W0542/S022342	96.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of cross roads of 1st main now extention pu college road	1900000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		05213000014
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/85/21/13/14	13/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0668	StreetName NA	Significant LandMark Borevel
SegmentNo 52/S-W0668/S023101	TotalLength 196.00	

ContractorDetails		
NameofContractor K.R.I.D.L	ContractorRegNo	Expenditure 0.00
PhoneNo 9945520405	EmailId	

Work Details		
NameOfWork Improvement and Asphaltting to roads at sr layout 9th cross to cimbrige college road	Sanctioned Amount 4900000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Asphalting	Other Work Type
Tender Tender	WorkDetails As Asphalting	Job No Work Code 052/13/000023
Work OrderNo EE/KPD/TND/NPW/454/12/13	Work Order Date 01/03/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 9	Other Information	Name DINESH
Date of Inspection 01/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0749	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0749/S031454	290.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
9		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0808	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0808/S032718	130.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0806	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0806/S032941	140.76	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0804	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0804/S033209	138.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0802	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0802/S033513	138.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0800	NA	RTO Office
SegmentNo	TotalLength	
52/S-W0800/S033711	142.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in banashakari layout to bhattarahalli in kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000011
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/32/18/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0207	NA	Garage
SegmentNo	TotalLength	
52/S-W0207/S034155	128.81	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in sairam ashray layout (Bank Colony) in T.C Palya kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000013
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/34/16/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
9		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0005	NA	Garage
SegmentNo	TotalLength	
52/S-W0005/S035010	270.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in sairam ashray layout (Bank Colony) in T.C Palya kr pura	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000013
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/34/16/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
10		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0492	NA	Sarvodaya School
SegmentNo	TotalLength	
52/S-W0492/S043650	68.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete road near sarvodaya school shetteppa road (1st cross) opp. road of mesjid and ramaiah layout cross roads and rain water drin	1950000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender	As Concrete	052/13/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/2012/13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0507	I T P L Main Rd	Sarvodaya School
SegmentNo	TotalLength	
52/S-W0507/S044200	60.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete road near sarvodaya school shetteppa road (1st cross) opp. road of mesjid and ramaiah layout cross roads and rain water drin	1950000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender	As Concrete	052/13/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/2012/13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0484	3rd Crs	Sarvodaya School
SegmentNo	TotalLength	
52/S-W0484/S044410	65.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete road near sarvodaya school shetteppa road (1st cross) opp. road of mesjid and ramaiah layout cross roads and rain water drin	1950000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	Concrete
Tender	WorkDetails	Job No Work Code
Tender	As Concrete	052/13/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/2012/13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0499	NA	Sarvodaya School
SegmentNo	TotalLength	
52/S-W0499/S044829	111.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete road near sarvodaya school shetteppa road (1st cross) opp. road of mesjid and ramaiah layout cross roads and rain water drin	1950000	
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
Tender	As Concrete	052/13/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/2012/13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0752	Vinayaka Nagar	Basavapura Main Road
SegmentNo	TotalLength	
52/S-W0752/S101121	74.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in pillappa layout to gayatri layout	1300000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/26/192/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0697	NA	Basavapura Main Road
SegmentNo	TotalLength	
52/S-W0697/S102128	102.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in pillappa layout to gayatri layout	1300000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/26/192/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0102	NA	Gada city college road
SegmentNo	TotalLength	
52/S-W0102/S102420	79.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in pillappa layout to gayatri layout	1300000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/26/192/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0100	NA	Gada city college road
SegmentNo	TotalLength	
52/S-W0100/S103609	60.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in pillappa layout to gayatri layout	1300000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/13/000013
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/34/16/2013/14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0093	15th Crs	Gada city college road
SegmentNo	TotalLength	
52/S-W0093/S103843	103.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in pillappa layout to gayatri layout	1300000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000012
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/26/192/12/13	22/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0330	NA	Indus valye School
SegmentNo	TotalLength	
52/S-W0330/S104928	81.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in puttappa layout srinivasa layout at bharatahalli	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/24//201/12 /13	25/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0341	NA	Indus valye School
SegmentNo	TotalLength	
52/S-W0341/S105627	159.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in puttappa layout srinivasa layout at bharatahalli	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/24//201/12 /13	25/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
5		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0343	NA	Indus valye School
SegmentNo	TotalLength	
52/S-W0343/S105829	143.72	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in puttappa layout srinivasa layout at bharatahalli	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/24//201/12 /13	25/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
8		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0345	S Krishnappa Lyt	Indus valye School
SegmentNo	TotalLength	
52/S-W0345/S110033	144.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in puttappa layout srinivasa layout at bharatahalli	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	As Asphalting	052/12/000010
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/05/24//201/12 /13	25/08/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
7		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0682	NA	Cambridge College
SegmentNo	TotalLength	
52/S-W0682/S112510	114.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Prasad		0.00
PhoneNo	EmailId	
9886625864		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of bhuvaneshwari layout 2nd, 7th and 8th cross of kr pura	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender		52/14/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/6/3/117/14/15	11/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0674	NA	Cambridge College
SegmentNo	TotalLength	
52/S-W0674/S113033	95.50	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K. Prasad		0.00
PhoneNo	EmailId	
9886625864		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of bhuvaneshwari layout 2nd, 7th and 8th cross of kr pura	1800000	
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender		52/14/000001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/6/3/117/14/15	11/06/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0764	NA	Ganapathi Temple
SegmentNo	TotalLength	
52/S-W0764/S122142	156.59	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in RMS colony(Back Side Ganapathi Temple Narayanapura)	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000009
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/200/25/08/12/13	14/05/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
4		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0707	NA	Ganapathi Temple
SegmentNo	TotalLength	
52/S-W0707/S022104	35.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in RMS colony(Back Side Ganapathi Temple Narayanapura)	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/12/000009
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/200/25/08/12/13	14/05/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
3		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0768	NA	Ganesha Temple
SegmentNo	TotalLength	
52/S-W0768/S022420	117.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in RMS colony(Back Side Ganapathi Temple Narayanapura)	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	0	052/12/000009
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/200/25/08/12/13	14/05/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0766	NA	Ganapathi Temple
SegmentNo	TotalLength	
52/S-W0766/S022950	225.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in RMS colony(Back Side Ganapathi Temple Narayanapura)	1995000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/12/000009
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/200/25/08/12/13	14/05/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
02/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0086	NA	Garden
SegmentNo	TotalLength	
52/S-W0086/S023451	134.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	
9448045901		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in krishnareddy, muniyappa road garden avenue bhattarahalli in K R Pura	1889000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000003
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/04/10/111/20 14/15	29/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
2		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0084	NA	Garden
SegmentNo	TotalLength	
52/S-W0084/S024126	247.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M. Ramesh		0.00
PhoneNo	EmailId	
9448045901		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in krishnareddy, muniyappa road garden avenue bhattarahalli in K R Pura	1889000	
Year	Type of Work	Other Work Type
2014 - 2015	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000003
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/04/10/111/20 14/15	29/10/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
12		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone MAHADEVAPURA	WardNo 52	WardName K R Pura
StreetID W0293	StreetName Maheshwari Nagar Opp Police Station Rd	Significant LandMark BEML
SegmentNo 52/S-W0293/S024642	TotalLength 121.37	

ContractorDetails		
NameofContractor K.R.I.D.L	ContractorRegNo	Expenditure 0.00
PhoneNo 9945520405	EmailId	

Work Details		
NameOfWork Improvements of roads and drains in Papanna Layout in K R Pura	Sanctioned Amount 4755200	Sanctioned Year
Year 2013 - 2014	Type of Work Others	Other Work Type
Tender Tender	WorkDetails	Job No Work Code 052/14/000030
Work OrderNo EE/KPD/TND/NPW/237/13/14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 4	Other Information	Name DINESH
Date of Inspection 01/07/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0284	NA	BEML
SegmentNo	TotalLength	
52/S-W0284/S025357	70.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0286	4th Crs, Maheshwari Nagar	BEML
SegmentNo	TotalLength	
52/S-W0286/S025533	25.31	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0295	NA	BEML
SegmentNo	TotalLength	
52/S-W0295/S025727	57.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in Papanna Layout in K R Pura	4755200	
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		DINESH
Date of Inspection	Remarks	
01/07/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0277	NA	Maheshwari Nagara
SegmentNo	TotalLength	
52/S-W0277/S051538	45.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and drains in Papanna layout iin K.R.Pura	47.55	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-14-000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/237/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0260	Ambedkar Nagar Slum	Ambedkar nagar colony
SegmentNo	TotalLength	
52/S-W0260/S052303	30.22	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
R. Srinivasa Reddy		0.00
PhoneNo	EmailId	
9448443663		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing improvements of roads and drains from kr pura	3000000	
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
		204/09/N/G/E/D/FO/022
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/06/18/95/2008/09	29/01/2008	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0136	NA	G.P.H School
SegmentNo	TotalLength	
52/S-W0136/S053202	137.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G. Anthoni Swamy		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of CC drains in bhattarahalli village in kr pura	1985000	
Year	Type of Work	Other Work Type
	Others	
Tender	WorkDetails	Job No Work Code
Tender		052/11/000051
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/23/262/2011/12	10/05/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0281	NA	Abedkar Nagar Slum
SegmentNo	TotalLength	
52/S-W0281/S053608	78.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements of roads and drains in papanna layout in KR Pura	4755000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		052/14/000030
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/237/13/14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0442	Own Use Rd	Sarvodaya School
SegmentNo	TotalLength	
52/S-W0442/S054012	49.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T. Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Construction of concrete road near sarvodaya school shetteppa road (1st cross) opp. road of mesjid and ramaiah layout cross roads and rain water drain	1950000	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		052/13/000016
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/66/555/2012/13	15/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0459	Shetty Lyt, 2nd Main Rd	Ramesh house
SegmentNo	TotalLength	
52/S-W0459/S054232	191.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in K.R.Pura	9974000	
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
		000-10-N-P-P-R-AS-076
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/NPW/14/2/186/19-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0438	Mani Lyt 2nd Crs	muniyappa Layout
SegmentNo	TotalLength	
52/S-W0438/S055256	44.24	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.Venugopal		0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in K.R.Pura	9974000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
		000-10-N-P-P-R-AS-037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/NPW/14/2/186/09-10	04/11/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0461	NA	Muniyappa layout
SegmentNo	TotalLength	
52/S-W0461/S055920	60.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
T.Venugopal	9343722590	0.00
PhoneNo	EmailId	
9343722590		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and improvement of roads in Muniyappa layout in K.R.Pura	9974000	
Year	Type of Work	Other Work Type
2012 - 2013	Asphalting	
Tender	WorkDetails	Job No Work Code
		000-10-N-P-P-R-AS-037
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/14/2/186/09-10	04/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0599	NA	Anjaneya temple road
SegmentNo	TotalLength	
52/S-W0599/S061432	62.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.R.I.D.L		0.00
PhoneNo	EmailId	
9945520405		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvement of roads of extention in KR Pura	3500000	
Year	Type of Work	Other Work Type
	Asphalting	
Tender	WorkDetails	Job No Work Code
		045/10/N/A/E/R/IM/001
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/18/01/02/2009/10	05/05/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		dinesh
Date of Inspection	Remarks	
07/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0007	NA	Garaj
SegmentNo	TotalLength	
52/S-W0007/S021616	449.39	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M Venkatachalapathi		0.00
PhoneNo	EmailId	
9611508999		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting of roads in Sairam Ashraya Layout (bank colony) in T.C Palya in K.r.Pura ward No. 52	1850000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		052-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW/17/34/16/13-14	22/06/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
W0425	NA	Sinivas colony
SegmentNo	TotalLength	
52/S-W0425/S022450	44.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S Ajay Enterprises (Ramaiah)		0.00
PhoneNo	EmailId	
9343751106		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting and Improvements of Metalled Roads in Kashi Vishwanatha and Srinivasa Layout in K.R.Pura Old Extension K.R.Pura Sub- Division	9980000	
Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	
Tender	WorkDetails	Job No Work Code
		000-10-N-P-P-R-AS-073
Work OrderNo	Work Order Date	Period of Extention
EE/KPD/TND/NPW//14/6/192/09- 10	07/12/2009	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
MAHADEVAPURA	52	K R Pura
StreetID	StreetName	Significant LandMark
I0159	NA	Shanthi Layout
SegmentNo	TotalLength	
52/S-I0159/S113428	171.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
1111111111		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to roads and RCC drains in K.R.Pura old extension in K.R.Pura ward no.52	4000000	2015-16
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to roads and RCC drains in K.R.Pura old extension in K.R.Pura ward no.52	052-15-000017
Work OrderNo	Work Order Date	Period of Extention
23/2015-16	06/04/2015	167 days
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

