



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0096	NA	GIDDAPPA BLOCK
SegmentNo	TotalLength	
60/S-W0096/S033403	171.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		484729.00
PhoneNo	EmailId	
9432516511		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO THE CROSS ROADS OF GIDDAPPA BLOCK	500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Road	
Tender	WorkDetails	Job No Work Code
Not a Tender		060-14-000041
Work OrderNo	Work Order Date	Period of Extention
EE\PN\TEND\WO\45\2014-15	10/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0217, W0219, W0146, W0227	NA, Chowdeshwari Temple Rd	Shri Ajeethnath Jain Shwetambar Temple
SegmentNo	TotalLength	
60/C-W0217/S044133	145.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HOMBEGOWDA		1836824.00
PhoneNo	EmailId	
9631651621		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING RCC DRAIN ALONG TANNARY MAIN ROAD	2000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		060-13-000011
Work OrderNo	Work Order Date	Period of Extention
EE\PN\TEND\WO\154\2013-14	19/12/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0130, W0128, W0237, W0134	NA, 1st Crs	RICHARDS PARK
SegmentNo	TotalLength	
60/C-W0130/S044956	211.86	




ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HOMBEGOWDA		958187.00
PhoneNo	EmailId	
9658425425		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTANANCE OF ROADS AND DRAINS	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	ROAD AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		060-14-000001
Work OrderNo	Work Order Date	Period of Extention
EE/PN/TEND/WO/467/2013-2014	04/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0079, W0055, W0062, W0173, W0021, W0017	Om Shakthi Lyt 4th Crs, NA, 8th Crs	bagaluru layout
SegmentNo	TotalLength	
60/C-W0079/S012736	127.40	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI R NITHIN		861705.00
PhoneNo	EmailId	
9853745473		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
INTIMATION OF WORK ORDER TO START THE WORK : PROVIDING CEMENT COCCRETE IN BAGALURU LAYOUT	950000	2010
Year	Type of Work	Other Work Type
2010 - 2011	Others	CEMENT CONCRETE
Tender	WorkDetails	Job No Work Code
Tender	CEMENT CONCRETE	050-10-N-W-B-R-FO-008
Work OrderNo	Work Order Date	Period of Extention
EE(PN)AE/WO/TEND/687/2010- 2011	06/01/2010	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0086	NA	pillannagarden
SegmentNo	TotalLength	
60/S-W0086/S031647	295.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		418031.00
PhoneNo	EmailId	
9766754895		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing cement concrete to the cross roads of pillanna garden	500000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	concrete
Tender	WorkDetails	Job No Work Code
Not a Tender	cement concrete	060-14-000040
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/TEND/WO/44/2014-2015	14/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0185, W0171, W0086, W0082, I0076, W0078, W0183, W	NA	PILLANNA GARDEN
SegmentNo	TotalLength	
60/C-W0185/S032718	210.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
A OM PRAKASH		114790.00
PhoneNo	EmailId	
9566476874		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVING SILT AND DEBRIS AT NEW BAGALURLAYOUT AND PILLANNA GARDEN	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Others	REMOVING SILTS AND DIBRIS
Tender	WorkDetails	Job No Work Code
Tender	REMOVING SLITS AND DEBRIS	060-12-000023
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/TEND/WO/25/2014-2015	20/02/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 60	WardName Sagayarapura
StreetID W0018, W0135, W0143, W0141, W0123, W0117	StreetName NA	Significant LandMark THOMAS TOWN
SegmentNo 60/C-W0018/S033826	TotalLength 111.01	

ContractorDetails		
NameofContractor T VEERENDRA PATIL	ContractorRegNo	Expenditure 1404951.00
PhoneNo 9767654337	EmailId	

Work Details		
NameOfWork CONSTRUCTION OF RCC DRAIN AT GHOSHAL STREET	Sanctioned Amount 1571559	Sanctioned Year 2012
Year 2012 - 2013	Type of Work Others	Other Work Type RCC DRAIN
Tender	WorkDetails CONSTRUCTION RCC DRAIN	Job No Work Code 060-12-000015
Work OrderNo EE/(PN)/TEND/WO/175/2012- 2013	Work Order Date 29/11/2012	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name maruthi
Date of Inspection 03/12/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 60	WardName Sagayarapura
StreetID W0142, W0239, W0235, W0233, W0237, W0231	StreetName NA	Significant LandMark JOHN ARMSTRONG ROAD
SegmentNo 60/C-W0142/S035001	TotalLength 778.40	

ContractorDetails		
NameofContractor HOMBEGOWDA	ContractorRegNo	Expenditure 1781305.00
PhoneNo 9864654637	EmailId	

Work Details		
NameOfWork PROVIDING ASPALTING TON VIVIANI ROAD AND JOHN ARMSTRONG ROAD	Sanctioned Amount 2000000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type ASPALTING
Tender Tender	WorkDetails ASPALTING	Job No Work Code 646-12-13
Work OrderNo EE(PN)/PE/PR/2013-2014	Work Order Date 24/01/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name maruthi
Date of Inspection 03/12/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 60	WardName Sagayarapura
StreetID W0030, I0161, W0163, W0062, W0070, W0218, W0072, W	StreetName NA	Significant LandMark PILLANNAGARDEN
SegmentNo 60/C-W0030/S044155	TotalLength 476.13	

ContractorDetails		
NameofContractor N B NAGARAJ	ContractorRegNo	Expenditure 1376897.00
PhoneNo 9745647454	EmailId	

Work Details		
NameOfWork PROVIDING CEMENT CONCRETE ROADS AT PILLANNA GARDEN	Sanctioned Amount 1534504	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type CEMENT CONCRETE
Tender Tender	WorkDetails CEMENT CONCRETE	Job No Work Code 060-12-000013
Work OrderNo EE/(N)/TEND/WO/231/2012-2013	Work Order Date 08/12/2015	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name maruthi
Date of Inspection 03/12/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0079, W0093, W0085, W0056, W0050, W0057, W0055	Om Shakthi Lyt 4th Crs, 15th Crs, NA	BAGALURU LAYOUT
SegmentNo	TotalLength	
60/C-W0079/S045026	90.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
TANUJA CONSTRUCTION		861336.00
PhoneNo	EmailId	
9877673778		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO 19TH MAIN NEW BAGALUR LAYOUT D BLOCK	950000	2010
Year	Type of Work	Other Work Type
2010 - 2011	Others	CEMENT CONCRETE
Tender	WorkDetails	Job No Work Code
Not a Tender	CEMENT CONCRETE	050-10-N-P-W-B-R-FO-014
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/AE/WO/TEND/109/2009- 2010	06/01/2010	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0070, W0218, I0161, W0163, W0173, W0072, W0216	NA	BAGALURU LAYOUT
SegmentNo	TotalLength	
60/C-W0070/S050000	314.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PUNEETH KUMAR		854050.00
PhoneNo	EmailId	
9776576545		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CEMENT CONCRETE TO 19TH MAIN NEW BAGALUR LAYOUT H BLOCK	950000	2010
Year	Type of Work	Other Work Type
2010 - 2011	Others	CEMENT CONCRETE
Tender	WorkDetails	Job No Work Code
Tender	CEMENT CONCRETE	050-10-N-P-W-B-R-FO-018
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/AE/WO/TEND/111/2010- 2011	06/01/2010	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0159, W0086	NA	PILLANNA GARDEN
SegmentNo	TotalLength	
60/C-W0159/S121551	30.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAKESH ANUGULA		1030608.00
PhoneNo	EmailId	
9847547574		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF RCC DRAIN AT PILLANNA GARDEN	1046931	2011
Year	Type of Work	Other Work Type
2010 - 2011	Others	RCC DRAIN
Tender	WorkDetails	Job No Work Code
Tender	RCC DRAIN	060-11-000002
Work OrderNo	Work Order Date	Period of Extention
EE/PN/TEND/WO/215/2011-2012	01/06/2011	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0142, W0211, W0239, W0235, W0233, W0237, W0227, W	NA	VIVAYANI ROAD
SegmentNo	TotalLength	
60/C-W0142/S123230	588.83	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		485890.00
PhoneNo	EmailId	
8895957589		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILTING OF DRAIN AND PROVIDING MISSING SLABS AND RECONSTRUCTION OF DAMAGE PORTION	500000	2014
Year	Type of Work	Other Work Type
2010 - 2011	Others	DESILTING DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender	DESILTING DRAIN	060-14-000042
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/TEND/WO/46/2014-2015	10/07/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0002, W0003, W0001, W0018, W0135, W0143, W0141	NA	SUNDAR HOSPITAL
SegmentNo	TotalLength	
60/C-W0002/S124315	52.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
J M DAS		896357.00
PhoneNo	EmailId	
9867768767		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AND FOTPATH AT SUNDAR HOSPITAL ROAD	942800	2012
Year	Type of Work	Other Work Type
2011 - 2012	Others	DRAIN ,FOOTPATH
Tender	WorkDetails	Job No Work Code
Tender	DRAIN FOOTPATH	060-11-000035
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/TEND/WO/807/2011- 2012	16/03/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone EAST	WardNo 60	WardName Sagayarapura
StreetID W0173, W0062, I0161, W0163, W0070, W0218, W0072, W	StreetName NA	Significant LandMark PILLANNA GARDEN
SegmentNo 60/C-W0173/S011011	TotalLength 889.03	

ContractorDetails		
NameofContractor HOMBE GOWDA	ContractorRegNo	Expenditure 1070614.00
PhoneNo 9857566787	EmailId	

Work Details		
NameOfWork PROVIDING CC TO CROSS ROADS OF PILLANNA GARDEN	Sanctioned Amount 1500000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work Others	Other Work Type CCDRAIN,ROAD CROSS
Tender Tender	WorkDetails CC DRAIN ,ROAD CROSS	Job No Work Code 060-13-000004
Work OrderNo EE/(PN)/JE/PR/62/2013-2014	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name maruthi
Date of Inspection 03/12/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition



Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
EAST	60	Sagayarapura
StreetID	StreetName	Significant LandMark
W0025, W0062, W0026	NA	BAGALUR LAYOUT
SegmentNo	TotalLength	
60/C-W0025/S012003	78.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
PUNEETH KUMAR		855784.00
PhoneNo	EmailId	
9787676756		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
INTIMATION OF WORK ORDER TO START THE WORK OF PROVIDING OF PROVIDING CEMENT CONCRETE 19TH MAIN BAGALUR LAYOUT G BLOCK	950000	2010
Year	Type of Work	Other Work Type
2010 - 2011	Others	
Tender	WorkDetails	Job No Work Code
Tender	CEMENT CONCRETE	050-10-N-P-W-B-R--F0-017
Work OrderNo	Work Order Date	Period of Extention
EE/(PN)/AE/WO/TEND/114/2009-2010	06/01/2010	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		maruthi
Date of Inspection	Remarks	
03/12/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition

