



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0080	NA	4TH CROSS ROAD TOWARDS SWIMMING POOL
SegmentNo	TotalLength	
68/S-W0080/S023805	327.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9845345559		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING MAHALAKSHMI LAYOUT AND SURROUNDINS IN WARD NO.68	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPT DRAIN WITH COVERING
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING MAHALAKSHMI LAYOUT AND SURROUNDINS IN WARD NO.68	068-15-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/309/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0082	NA	MICO LAYOUT
SegmentNo	TotalLength	
68/S-W0082/S024650	336.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9845345559		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING IN MICO LAYOUT AND SURROUNDINGS IN WARD NO.68	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPT DRAIN
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING IN MICO LAYOUT AND SURROUNDINGS IN WARD NO.68	068-15-000001
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/121/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0018	NA	3RD CROSS ROAD
SegmentNo	TotalLength	
68/S-W0018/S025446	268.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9845345559		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING IN MUNESHARA BLOCK AND SURROUNDINGS IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS WITH B.S.SLAB COVERING IN MUNESHARA BLOCK AND SURROUNDINGS IN WARD NO.68	068-15-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/122/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0207, W0160, W0166, W0201, W0162, W0164	NA	J.C.Nagara
SegmentNo	TotalLength	
68/C-W0207/S033001	154.52	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9845025446		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Providing flagging course with covering slab to 3rd to 6th cross in J.C.Nagara in ward no.68	1500000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	Flagging course
Tender	WorkDetails	Job No Work Code
Not a Tender	Providing flagging course with covering slab to 3rd to 6th cross in J.C.Nagara in ward no.68	068-14-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/350/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0152, W0150, W0201, W0146	StreetName NA	Significant LandMark J.C.NAGAR
SegmentNo 68/C-W0152/S033822	TotalLength 220.74	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9845025446	EmailId	

Work Details		
NameOfWork PROVIDING FLAGGING COURSE WITH COVERING SLAB TO 3RD MAIN AND 11TH MAIN ROAD IN J.C.NAGARA IN WARD NO.68	Sanctioned Amount 2500000	Sanctioned Year
Year 2013 - 2014	Type of Work Others	Other Work Type FLAGGING COURSE
Tender Not a Tender	WorkDetails PROVIDING FLAGGING COURSE WITH COVERING SLAB TO 3RD MAIN AND 11TH MAIN ROAD IN J.C.NAGARA IN WARD NO.68	Job No Work Code 068-14-000025
Work OrderNo EE/MLP/VO/PR/344/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0207, W0203, W0160	StreetName NA	Significant LandMark J.C.NAGAR
SegmentNo 68/C-W0207/S034313	TotalLength 125.59	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9845025446	EmailId	

Work Details		
NameOfWork PROVIDING FLAGGING COURSE WITH COVERING SLAB TO 3RD CROSS AND 15TH MAIN ROAD IN J.C.NAGARA IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2014
Year 2013 - 2014	Type of Work Others	Other Work Type FLAGGING COURSE
Tender Not a Tender	WorkDetails PROVIDING FLAGGING COURSE WITH COVERING SLAB TO 3RD CROSS AND 15TH MAIN ROAD IN J.C.NAGARA IN WARD NO.68	Job No Work Code 068-14-000024
Work OrderNo EE/MLP/VO/PR/351/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0104, W0129	NA	SOLLAPURADAMMA TEMPLE
SegmentNo	TotalLength	
68/C-W0104/S073831	129.68	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9878687990		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING FLAGGING COURSE WITH COVERING SLAB TO 1ST B CROSS AND 1ST MAIN	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Others	COVERING SLAB
Tender	WorkDetails	Job No Work Code
Not a Tender		068-14-000028
Work OrderNo	Work Order Date	Period of Extention
AEE/MLP/PR/348/2013-14	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
27/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0116, W0209	NA	GELEYARABALAGA
SegmentNo	TotalLength	
68/C-W0116/S023346	32.07	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO SSM SIDE AND DESILTING OF SWD IN GELEYARABALAGA IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO SSM SIDE AND DESILTING OF SWD IN GELEYARABALAGA IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/232/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0195	StreetName NA	Significant LandMark JC NAGAR
SegmentNo 68/S-W0195/S023906	TotalLength 34.58	

ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 6TH AND 7TH CROSS IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 6TH AND 7TH CROSS IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/232/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0099	NA	GELEYARABALAGA
SegmentNo	TotalLength	
68/S-W0099/S024434	62.21	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN GELEYARABALAGA IN WARD NO.68	99000	2012
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN IN GELEYARABALAGA IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/221/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0197	StreetName Vinayaka Lyt 1st Crs	Significant LandMark J C NAGAR
SegmentNo 68/S-W0197/S052320	TotalLength 19.32	

ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 2ND AND 3RD CROSS IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 2ND AND 3RD CROSS IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/224/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0197	Vinayaka Lyt 1st Crs	J.C.Nagar
SegmentNo	TotalLength	
68/S-W0197/S053127	52.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to ssm side wall and desilting of swd at J.C.Nagar 1st main between 2nd and 3rd cross in ward no.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	Improvements to ssm side wall and desilting of swd at J.C.Nagar 1st main between 2nd and 3rd cross in ward no.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/224/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0097, W0044	16th Crs, NA	Geleyarabalaga
SegmentNo	TotalLength	
68/C-W0097/S053659	50.53	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Maruthikumar GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath in 3rd cross (ch:15.00 to 30.00mtrs) Geleyarabalaga in ward no.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Improvements to footpath in 3rd cross (ch:15.00 to 30.00mtrs) Geleyarabalaga in ward no.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/je/pr/240/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0189	NA	J C NAGAR
SegmentNo	TotalLength	
68/S-W0189/S054237	3.70	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO SSM SIDE WALL AND DESILTING F SWD AT JCNAGAR 1ST MAIN NEAR 4TH CROSS IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO SSM SIDE WALL AND DESILTING F SWD AT JCNAGAR 1ST MAIN NEAR 4TH CROSS IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/238/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0191	StreetName NA	Significant LandMark J C NAGAR
SegmentNo 68/S-W0191/S054722	TotalLength 4.90	





ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGARA 1ST MAIN NEAR 3RD CROSS IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGARA 1ST MAIN NEAR 3RD CROSS IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/239/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0097, W0044, W0095	StreetName 16th Crs, NA, Om Shakthi Lyt 2nd Crs	Significant LandMark GELEYARABALAGA
SegmentNo 68/C-W0097/S055059	TotalLength 34.54	



ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH:45.00 TO 55.00M) GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH:45.00 TO 55.00M) GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/227/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0044, W0095	StreetName NA, Om Shakthi Lyt 2nd Crs	Significant LandMark GELEYARABALAGA
SegmentNo 68/C-W0044/S055531	TotalLength 35.24	

ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH30.00 TO 45.00m) GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH30.00 TO 45.00m) GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/228/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0195	NA	J C NAGAR
SegmentNo	TotalLength	
68/S-W0195/S060141	5.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 3RD AND 4TH CROSS IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 3RD AND 4TH CROSS IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/235/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0036	NA	GELEYARABALAGA
SegmentNo	TotalLength	
68/S-W0036/S060623	80.62	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH:15.00 TO 30.00) GELEYARABALAGA IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH IN 3RD CROSS (CH:15.00 TO 30.00) GELEYARABALAGA IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/226/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0193	Vinayaka Lyt 2nd Crs	J C NAGAR
SegmentNo	TotalLength	
68/S-W0193/S061057	3.90	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
Maruthikumar GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to ssm side wall and desilting of swd at JC Nagar 1st main in between 4th and 5th cross in ward no.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Improvements to ssm side wall and desilting of swd at JC Nagar 1st main in between 4th and 5th cross in ward no.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/233/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0056, W0099	NA	Geleyarabalaga
SegmentNo	TotalLength	
68/C-W0056/S061901	42.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath in 3rd cross (ch:0.00 to 15.00m) Geleyarabalaga in ward no.68 left side	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Improvements to footpath in 3rd cross (ch:0.00 to 15.00m) Geleyarabalaga in ward no.68 left side	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/230/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0062	StreetName NA	Significant LandMark BESIDE GAS GODOWN
SegmentNo 68/S-W0062/S062740	TotalLength 38.76	

ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN CUM FOOTPATH BESIDE GAS GODOWN IN AGB LAYOUT IN WARD NO.68 (CH:0.00 TO 17.00)	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO DRAIN CUM FOOTPATH BESIDE GAS GODOWN IN AGB LAYOUT IN WARD NO.68 (CH:0.00 TO 17.00)	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/225/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0181	StreetName Vinayaka Lyt 3rd Crs	Significant LandMark BESIDE GAS GODOWN
SegmentNo 68/S-W0181/S063215	TotalLength 5.45	

ContractorDetails		
NameofContractor MARUTHIKUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN CUM FOOTPATH BESIDE GAS GODOWN IN AGB LAYOUT IN WARD NO.68 (CH.17.00 TO 34.00MTR)	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO DRAIN CUM FOOTPATH BESIDE GAS GODOWN IN AGB LAYOUT IN WARD NO.68 (CH.17.00 TO 34.00MTR)	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/224/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		
Category	Photo	
Segment Start		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0015	StreetName NA	Significant LandMark SARASWATHIPURAM
SegmentNo 68/S-W0015/S063754	TotalLength 249.27	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN AND COVERING SLAB AT 1ST CROSS SARASWATHIPURA IN WARD NO.68	Sanctioned Amount 990000	Sanctioned Year 2013
Year 2013 - 2014	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO DRAIN AND COVERING SLAB AT 1ST CROSS SARASWATHIPURA IN WARD NO.68	Job No Work Code 068-13-000020
Work OrderNo EE/MLP/WO/JE/PR/515/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0111	NA	MAHALAKSHMIPURAM
SegmentNo	TotalLength	
68/S-W0111/S064737	118.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY WORKS IN WARD NO.68	2000000	2014
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	EMERGENCY WORKS IN WARD NO.68	068-14-000002
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/343/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpita
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0046	NA	Geleyarabalaga
SegmentNo	TotalLength	
68/S-W0046/S065350	80.38	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MARUTHIKUMAR GK		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to footpath in 3rd cross (ch:0.00 to 15.00m) Geleyarabalaga in ward no.68	99000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	Improvements to footpath in 3rd cross (ch:0.00 to 15.00m) Geleyarabalaga in ward no.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/229/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0038	NA	NEAR PARK
SegmentNo	TotalLength	
68/S-W0038/S012503	65.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RATHNA R		0.00
PhoneNo	EmailId	
0		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING S.S.RAILLING TO STEPS AT PARKS IN WARD NO.68	500000	2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	PROVIDING S.S.RAILLING TO STEPS AT PARKS IN WARD NO.68	068-16-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/29/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0023, W0025	NA	NANDINI LYT
SegmentNo	TotalLength	
68/S-W0023/S100120	171.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
YASANTH HK		0.00
PhoneNo	EmailId	
9956475648		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 9TH MAIN AND10TH MAIN ROADS GANESHA BLOCK AT MAHALAXMI LYT MAIIN ROAD	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-15-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/298/14-15	27/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0114, W0145, W0168, W0239, W0170	StreetName NA	Significant LandMark AMBEDKAR NAGAR
SegmentNo 68/C-W0114/S100609	TotalLength 155.82	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9934564758	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN AT 1ST MAIN 12TH AND 13TH CROSS INJ C NAGAR	Sanctioned Amount 1000000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 068-15-000026
Work OrderNo EE/MLP/TS/PR/123-14-15	Work Order Date 12/12/2014	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name revanna
Date of Inspection 03/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0027, W0022	NA	SARASWATHI PURA
SegmentNo	TotalLength	
68/C-W0027/S100940	192.46	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
MUTHAPPA A N		0.00
PhoneNo	EmailId	
9945673845		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS 6TH AND 7TH CROSS SARASWATHIPURAM MAHALAXMI LYT	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-15-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/244/14-15	12/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0269, W0174	NA	J C NAGARA
SegmentNo	TotalLength	
68/C-W0269/S101345	136.36	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945674568		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 9TH MAIN 6 7 AND 8TH CROSS ROAD IN J C NAGARA	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000036
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/133/14-15	12/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0176	NA	J C NAGARA
SegmentNo	TotalLength	
68/S-W0176/S101913	175.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956478364		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND 10TH MAIN J C NAGARA	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000033
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/130/14-15	12/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0029, W0022	NA	SAMUDAYA BHAVAN
SegmentNo	TotalLength	
68/C-W0029/S102135	198.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945673846		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 7TH CROSS SARASWATHIPURAM MAIN ROAD TO S S PURAM SAMUDAYA BHAVAN BETWEEN ROAD	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000075
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/420/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0109	NA	MAHALAXMI LYT
SegmentNo	TotalLength	
68/S-W0109/S102518	54.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V RAVIKUMAR		0.00
PhoneNo	EmailId	
9956473846		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 2ND C CROSS ROAD GELEYARABALAG AT MAHALAXMI LYT	600000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-15-000020
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/379/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0151, W0143, W0145	NA	J C NAGAR
SegmentNo	TotalLength	
68/S-W0151/S102902	223.85	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9957684657		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 11TH 12TH AND 13TH MAIN CROSS IN J C NAGAR	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000077
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/422/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0023	NA	GANESHA BLOCK
SegmentNo	TotalLength	
68/S-W0023/S103214	42.82	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 10TH MAIN IN GANESHA BLOCK	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000086
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/472/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
I0271	Ambedkar Nagar Slum	SARASWATHIPURAM MAIN ROAD
SegmentNo	TotalLength	
68/S-I0271/S044832	744.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
YOGESH J		0.00
PhoneNo	EmailId	
9844535318		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROAD IN DAMAGED PORTION IN WARD NO.68	600000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	PROVIDING CC ROAD IN DAMAGED PORTION IN WARD NO.68	068-14-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/289/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0201, W0211, W0167, W0152, I0271	StreetName NA, Ambedkar Nagar Slum	Significant LandMark MAHALAKSHMI LAYOUT
SegmentNo 68/S-W0201/S045635	TotalLength 81.52	

ContractorDetails		
NameofContractor G.K.MARUTHIKUMAR	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork MAINTENANCE OF WATER TANK IN MAHALAKSHMI LAYOUT IN WARD NO.68	Sanctioned Amount 100000	Sanctioned Year 2012
Year 2012 - 2013	Type of Work	Other Work Type
Tender	WorkDetails MAINTENANCE OF WATER TANK IN MAHALAKSHMI LAYOUT IN WARD NO.68	Job No Work Code 068-12-000039
Work OrderNo EE/MLP/WO/JE/PR/220/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name arpitha
Date of Inspection 20/01/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0116	NA	JC NAGAR AREA
SegmentNo	TotalLength	
68/S-W0116/S050417	379.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTENANCE OF WARD IN J.C.NAGAR AREA AND SURROUNDINGS IN WARD NO.68	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	MAINTENANCE OF WARD IN J.C.NAGAR AREA AND SURROUNDINGS IN WARD NO.68	068-14-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/342/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0080	NA	MAHALAKSHMI LAYOUT AREA
SegmentNo	TotalLength	
68/S-W0080/S052037	327.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
MAINTENANCE O WARD IN MAHALAKSHMILAYOUT AREA AND SURROUNDINGS IN WARD NO.68	1200000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	MAINTENANCE O WARD IN MAHALAKSHMILAYOUT AREA AND SURROUNDINGS IN WARD NO.68	068-14-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/341/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet



Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
I0117	NA	SRIRAMANAGAR
SegmentNo	TotalLength	
68/S-I0117/S052930	709.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF DEBRIES AT J.C.NAGARA MAHALAKSHMI LAYOUT AND SRIRAMANAGARA IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF DEBRIES AT J.C.NAGARA MAHALAKSHMI LAYOUT AND SRIRAMANAGARA IN WARD NO.68	068-15-000054
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/199/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
20/01/2017	Remarks
Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0201	NA	AMBEDKAR COLLEGE AND SURROUNDINGS
SegmentNo	TotalLength	
68/S-W0201/S054342	280.55	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (AMBEDKAR COLLEGE AND SURROUNDINGS)	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (AMBEDKAR COLLEGE AND SURROUNDINGS)	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/11/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0044	NA	MAHALAKSHMILAYOUT
SegmentNo	TotalLength	
68/S-W0044/S055445	115.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/15/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0054	NA	SRIRAMANAGARA AND SURROUNDINGS
SegmentNo	TotalLength	
68/S-W0054/S081040	235.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (SRIRAMANAGARA AND SURROUNDINGS)	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (SRIRAMANAGARA AND SURROUNDINGS)	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/13/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
I0271	Ambedkar Nagar Slum	J.C.NAGARA 60FEET ROAD AND SURROUNDINGS
SegmentNo	TotalLength	
68/S-I0271/S081802	744.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (J.C.NAGARA 60FEET ROAD SURROUNDINGS)	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (J.C.NAGARA 60FEET ROAD SURROUNDINGS)	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/10/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0207	NA	MICO LAYOUT SURROUNDINGS
SegmentNo	TotalLength	
68/S-W0207/S082438	419.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (MICO LAYOUT SURROUNDINGS)	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (MICO LAYOUT SURROUNDINGS)	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/12/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0093	15th Crs	GELEYARABALAGA LAYOUT
SegmentNo	TotalLength	
68/S-W0093/S082944	205.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (GELEYARABALAGA LAYOUT SURROUNDINGS)	199000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	REMOVAL OF SILT AND TRACTOR IN WARD NO.68 (GELEYARABALAGA LAYOUT SURROUNDINGS)	068-13-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/14/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0096	NA	mahalakshmi layout
SegmentNo	TotalLength	
68/S-W0096/S052705	125.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN 11TH CROSS MAHALAKSHMI LAYOUT IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMENTS TO DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN 11TH CROSS MAHALAKSHMI LAYOUT IN WARD NO.68	068-15-000053
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/198/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0237	NA	J.C.NAGARA
SegmentNo	TotalLength	
68/S-W0237/S053053	29.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO CONCRETE ROAD AT 11TH MAIN J.C.NAGAR IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO CONCRETE ROAD AT 11TH MAIN J.C.NAGAR IN WARD NO.68	068-15-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/131/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0007	NA	S.G.INTERNATIONAL SCHOOL
SegmentNo	TotalLength	
68/S-W0007/S054603	51.77	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO PARK OUR OPP S.G.INTERNATIONAL SCHOOL NEAR SWD IN WARD NO.68	1000000	
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO PARK OUR OPP S.G.INTERNATIONAL SCHOOL NEAR SWD IN WARD NO.68	068-15-000029
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/126/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0187	NA	J C NAGAR
SegmentNo	TotalLength	
68/S-W0187/S055036	207.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 5TH, 6TH, 7TH CROSS OF 1ST MAIN J.C.NAGARA IN WARD NO.68	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AT 5TH, 6TH, 7TH CROSS OF 1ST MAIN J.C.NAGARA IN WARD NO.68	068-15-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/134/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0169	NA	MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/S-W0169/S055603	97.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING NAME BOARDS IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	PROVIDING NAME BOARDS IN WARD NO.68	068-15-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/135/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0103	NA	MAHALAKSHMILAYOUT
SegmentNo	TotalLength	
68/S-W0103/S060011	284.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING KERB STONE IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	PROVIDING KERB STONE IN WARD NO.68	068-15-000043
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/188/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0108	Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	MAHALAKSHMIPURAM
SegmentNo	TotalLength	
68/S-W0108/S123204	137.84	



ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CHAINLINK FENCING FOR STORM WATER DRAIN IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CHAIN LINK FENCING
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING CHAINLINK FENCING FOR STORM WATER DRAIN IN WARD NO.68	068-17-000005
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/255/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0176	NA	10TH MAIN
SegmentNo	TotalLength	
68/S-W0176/S124749	468.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HARISH RAM MURTHY		0.00
PhoneNo	EmailId	
9060795906		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
RECONSTRUCTION OF SECONDARY DRAIN AT J.C.NAGARA IN WARD NO.13	1000000	
Year	Type of Work	Other Work Type
2013 - 2014	Others	RECONSTRUCTION
Tender	WorkDetails	Job No Work Code
Tender	RECONSTRUCTION OF SECONDARY DRAIN AT J.C.NAGARA IN WARD NO.13	R-068-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/298/2009-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
23/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0080	NA	Mahalakshmi layout
SegmentNo	TotalLength	
68/S-W0080/S020438	420.23	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 2nd, 3rd, 4th 8th & surrounding at Mahalakshmi layout in ward no.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting to 2nd, 3rd, 4th 8th & surrounding at Mahalakshmi layout in ward no.68	068-16-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/332/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
23/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0088	NA	J.C.Nagara
SegmentNo	TotalLength	
68/S-W0088/S021215	266.26	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to opp Jayadurga choultry road Ambedkar college and other J.C.Nagara in ward no.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting to opp Jayadurga choultry road Ambedkar college and other J.C.Nagara in ward no.68	068-16-000029
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/331/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
21/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0109	NA	AGB LAYOUT
SegmentNo	TotalLength	
68/S-W0109/S022544	214.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
ASPHALTING TO BAD ROADS AT GELEYARA BALAGA & ATHMEYAGELEYARABALAGA IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	ASPHALTING TO BAD ROADS AT GELEYARA BALAGA & ATHMEYAGELEYARABALAGA IN WARD NO.68	068-16-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/333/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
23/01/2017	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0034	NA	Samudhaya bhavana road
SegmentNo	TotalLength	
68/S-W0034/S023405	592.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDI		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to ALF road and 2nd main (Samudaya bhavana road) & surrounding at Saraswathipuram in ward no.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting to ALF road and 2nd main (Samudaya bhavana road) & surrounding at Saraswathipuram in ward no.68	068-16-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/329/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
23/01/2017	

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0174	NA	Sathyanarayana layout
SegmentNo	TotalLength	
68/S-W0174/S023928	423.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Asphalting to 3rd cross Sathyanarayana layout and Sathyanarayana layout main road (bethal College road) J.C.Nagara in ward no.68	2000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
Not a Tender	Asphalting to 3rd cross Sathyanarayana layout and Sathyanarayana layout main road (bethal College road) J.C.Nagara in ward no.68	068-16-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/330/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
5		Arpitha
Date of Inspection	Remarks	
19/01/2017		

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0056	NA	Sivakumaraswamy park
SegmentNo	TotalLength	
68/S-W0056/S043349	316.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.G.RAMU	PWD	0.00
PhoneNo	EmailId	
9035160456		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING COVERING SLAB RAIN WATER HARVESTING AND OTHER CIVIL WORKS IN PARKS IN WARD NO.68	15	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING COVERING SLAB RAIN WATER HARVESTING AND OTHER CIVIL WORKS IN PARKS IN WARD NO.68	068-14-000011
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/330/2013-14	28/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0084	NA	SUB DIVISION OFFICE
SegmentNo	TotalLength	
68/S-W0084/S053747	140.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9035160456		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMETNS TO DRAIN AT 6TH AND 7TH CROSS MAHALAKSHMI LAYOUT AND SURROUNDINGS IN WARD NO.68	10	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	Improvements of drain
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMETNS TO DRAIN AT 6TH AND 7TH CROSS MAHALAKSHMI LAYOUT AND SURROUNDINGS IN WARD NO.68	068-15-000039
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/PR/136/2014-15	12/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	
Date of Inspection	Name
12/02/2016	yadukrishna
Remarks	
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
I0005	NA	Circular road
SegmentNo	TotalLength	
68/S-I0005/S055803	155.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9035160456		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DEVELOPMENT IN ALF BORDER ROAD (BEHIND BESCOM OFFICE) IN WARD NO.68	20	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	DEVELOPMENT OF ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender	DEVELOPMENT IN ALF BORDER ROAD (BEHIND BESCOM OFFICE) IN WARD NO.68	068-15-000047
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/192/2014-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0092	StreetName NA	Significant LandMark DRY WASTE COLLECTION CENTRE
SegmentNo 68/S-W0092/S111928	TotalLength 227.17	

ContractorDetails		
NameofContractor V.RAVIKUMAR	ContractorRegNo	Expenditure 0.00
PhoneNo 0	EmailId	

Work Details		
NameOfWork PROVIDING CHAIN LINK FENCING TO DRY WASTE COLLECTION IN MAHALAKSHMIPURAM IN WARD NO.68	Sanctioned Amount 400000	Sanctioned Year 2014
Year 2014 - 2015	Type of Work	Other Work Type
Tender	WorkDetails PROVIDING CHAIN LINK FENCING TO DRY WASTE COLLECTION IN MAHALAKSHMIPURAM IN WARD NO.68	Job No Work Code 068-15-000009
Work OrderNo EE/MLP/WO/JE/PR/253/2014-15	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
20/01/2017	Remarks
Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0024, W0059	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	GANESHA BLOCK
SegmentNo	TotalLength	
68/C-W0024/S123949	133.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9916616207		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN GANESHA BLOCK IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN IN GANESHA BLOCK IN WARD NO.68	068-15-000052
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/197/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0076	NA	swimming pool road
SegmentNo	TotalLength	
68/S-W0076/S092430	313.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING ASPHALTING TO MAIN ROAD AND CROSS ROADS NEAR SWIMMING POOL ROADS IN WARD NO.68	4900000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	PROVIDING ASPHALTING TO MAIN ROAD AND CROSS ROADS NEAR SWIMMING POOL ROADS IN WARD NO.68	068-14-000021
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/307/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0152, W0150, W0201, W0146, W0063, I0117, W0061, W	NA, Om Shakthi Lyt 6th Crs, Om Shakthi Lyt 7th Crs	MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/C-W0152/S014905	212.47	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DRILLING OF BOREWELL IN WARD NO.68	2500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	DRILLING BOREWELL
Tender	WorkDetails	Job No Work Code
Not a Tender	DRILLING OF BOREWELL IN WARD NO.68	068-15-000004
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/0184/2013- 14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0137	NA	60feet road
SegmentNo	TotalLength	
68/S-W0137/S021317	66.63	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHIKUMAR		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN 60FEET ROAD END ROAD IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Others	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN IN 60FEET ROAD END ROAD IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/222/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0189	NA	J.C.NAGAR
SegmentNo	TotalLength	
68/S-W0189/S021916	104.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
G.K.MARUTHI		0.00
PhoneNo	EmailId	
9060849233		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMETNS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN NEAR 6TH CROSS IN WARD NO.68	99000	2013
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN IN 60FEET ROAD END ROAD IN WARD NO.68	068-13-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/236/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0189	StreetName NA	Significant LandMark J.C.NAGARA
SegmentNo 68/S-W0189/S022349	TotalLength 104.06	

ContractorDetails		
NameofContractor MARUTHIKUMAR G.K	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 5TH CROSS IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGAR 1ST MAIN BETWEEN 5TH CROSS IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/237/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0163	StreetName NA	Significant LandMark 5TH AND 6TH CROSS
SegmentNo 68/S-W0163/S022725	TotalLength 41.64	

ContractorDetails		
NameofContractor MARUTHI KUMAR GK	ContractorRegNo	Expenditure 0.00
PhoneNo 9060849233	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGARA 1ST MAIN IN BETWEEN 5TH AND 6TH CROSS IN WARD NO.68	Sanctioned Amount 99000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work	Other Work Type
Tender	WorkDetails IMPROVEMENTS TO SSM SIDE WALL AND DESILTING OF SWD AT J.C.NAGARA 1ST MAIN IN BETWEEN 5TH AND 6TH CROSS IN WARD NO.68	Job No Work Code 068-13-000006
Work OrderNo EE/MLP/WO/JE/PR/231/2013-14	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0015	NA	J.C.Nagar
SegmentNo	TotalLength	
68/S-W0015/S112536	249.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
HARISH RAM MURTHY		0.00
PhoneNo	EmailId	
9060795905		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
RECONSTRUCTION SECONDARY DRAIN AT J.C.NAGARA IN WARD NO.13	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	DRAIN WORKS
Tender	WorkDetails	Job No Work Code
Tender	RECONSTRUCTION SECONDARY DRAIN AT J.C.NAGARA IN WARD NO.13	R-068-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/298/2009-10		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0103, W0034, W0017, W0022, W0021, W0019, W0029, W	NA, 8th Crs	MAHALAKSHMIPURA
SegmentNo	TotalLength	
68/C-W0103/S113614	478.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
WARD MAINTENANCE IN WARD NO.68	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
Not a Tender	WARD MAINTENANCE IN WARD NO.68	068-15-000025
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/462/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0044	StreetName NA	Significant LandMark J.C.Nagara
SegmentNo 68/S-W0044/S111951	TotalLength 115.79	

ContractorDetails		
NameofContractor KRISHNEGOWDA	ContractorRegNo	Expenditure 0.00
PhoneNo 9845003091	EmailId	

Work Details		
NameOfWork Construction of concrete road in J.C.Nagara in ward no.68	Sanctioned Amount 800000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work	Other Work Type
Tender Tender	WorkDetails Construction of concrete road in J.C.Nagara in ward no.68	Job No Work Code 068-16-000006
Work OrderNo EE/MLP/WO/JE/PR/18/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name arpitha
Date of Inspection 19/01/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0058, W0115, W0056, W0111, W0054	NA	DIALYSIS CENTER
SegmentNo	TotalLength	
68/C-W0058/S112821	104.66	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
K.C.PRASHANTH		0.00
PhoneNo	EmailId	
0		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DIALYSIS CENTER IN WARD NO.68	4000000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DIALYSIS CENTER IN WARD NO.68	068-15-000065
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/156/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
23/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0130, W0161, W0179, W0167, W0136, W0173, W0052, W	NA, Om Shakthi Lyt 3rd Crs, 16th Crs, Subhash Chandra Bose Lyt, Vinayaka Lyt 3rd Crs	Mahalakshmpuram
SegmentNo	TotalLength	
68/C-W0130/S012204	683.13	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
EMERGENCY GRANT IN WARD NO.68	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	EMERGENCY GRANT IN WARD NO.68	068-15-000013
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/461/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
21/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0181	Vinayaka Lyt 3rd Crs	SATHYANARAYANA LAYOUT
SegmentNo	TotalLength	
68/S-W0181/S013059	282.54	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
RAISING MASONRY DRAIN IN SATHYANARAYANA LAYOUT IN WARD NO.68	1500000	
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	RAISING MASONRY DRAIN IN SATHYANARAYANA LAYOUT IN WARD NO.68	068-15-000073
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/418/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
23/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0116	1st Main Jc Nagar	temo
SegmentNo	TotalLength	
68/S-W0116/S114715	379.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
pradeep		0.00
PhoneNo	EmailId	
8456215412		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
	20	
Year	Type of Work	Other Work Type
2010 - 2011	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-11-000001
Work OrderNo	Work Order Date	Period of Extention
ae\mplest\09\11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	20/07/2010	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0187	5th Crs, J C Nagar	temple
SegmentNo	TotalLength	
68/S-W0187/S115057	207.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
rakesh		0.00
PhoneNo	EmailId	
9030109050		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		87452-58632-00000008
Work OrderNo	Work Order Date	Period of Extention
ae\m\ples\12\11		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	18/01/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0116, W0181, W0189, W0191, W0193, W0195, W0207, W	1st Main Jc Nagar, 7th Crs, J C Nagar, 4th Crs, J C Nagar, 3rd Crs, J C Nagar, 2nd Crs, J C Nagar, 1	park
SegmentNo	TotalLength	
68/C-W0116/S115522	1453.43	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
tharun		0.00
PhoneNo	EmailId	
9456321877		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2011 - 2012	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		9854-58621-00000005
Work OrderNo	Work Order Date	Period of Extention
aee/mlp/r\est/95		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	26/04/2011	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0207, W0219, W0201, W0203, W0146, W0128, W0217, W	3rd Crs, 4th A Crs J C Nagar, 3rd Main Rd, 1st Main Rd, 5th Main Rd, 5th Crs, 6th Crs, 7th Crs, 3rd	park
SegmentNo	TotalLength	
68/C-W0207/S120056	2150.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
vijay		0.00
PhoneNo	EmailId	
9456524168		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		8542-6521-0000005
Work OrderNo	Work Order Date	Period of Extention
ae\mlp\eds\edx		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	16/11/2011	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0069	7th Main Rd	junction
SegmentNo	TotalLength	
68/S-W0069/S120741	405.64	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
jana		0.00
PhoneNo	EmailId	
8654126541		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	100000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	852-520-0000050
Work OrderNo	Work Order Date	Period of Extention
aee\mplrds		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	14/12/2011	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0008	8th Crs Ganesha Block	temp
SegmentNo	TotalLength	
68/S-W0008/S122003	396.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sashe		0.00
PhoneNo	EmailId	
9455542204		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		852-521-00006
Work OrderNo	Work Order Date	Period of Extention
ae\mlp\rfd\rd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	17/04/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0022	NA	jun
SegmentNo	TotalLength	
68/S-W0022/S122415	316.17	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sharma		0.00
PhoneNo	EmailId	
9556644112		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		6521-521-00000050
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\rt dx\led		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	16/05/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0027	6th Crs	temp
SegmentNo	TotalLength	
68/S-W0027/S123040	225.02	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
chiru		0.00
PhoneNo	EmailId	
9888465323		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		854-985-00000050
Work OrderNo	Work Order Date	Period of Extention
aee\mpl\reds\eds		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	19/03/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0021	5th Crs Saraswathi Puram	temp
SegmentNo	TotalLength	
68/S-W0021/S123234	229.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sashe		0.00
PhoneNo	EmailId	
9455542204		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender		852-521-00006
Work OrderNo	Work Order Date	Period of Extention
AEE\MLP\RFD\RD		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	19/07/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0029	7th Crs	temp
SegmentNo	TotalLength	
68/S-W0029/S123444	218.99	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ram sandeep		0.00
PhoneNo	EmailId	
9654145652		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	85-521-000000050
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\kjhg\l		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	13/07/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0019	4th Crs Saraswathi Puram	temp
SegmentNo	TotalLength	
68/S-W0019/S123704	198.45	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
rajee		0.00
PhoneNo	EmailId	
9456858574		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		8542-852-000006
Work OrderNo	Work Order Date	Period of Extention
aee\mip\rd\		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	16/07/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0103	4th Crs G Balaga	temp
SegmentNo	TotalLength	
68/S-W0103/S025626	284.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
satya		0.00
PhoneNo	EmailId	
9456245541		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		852-98-00000090
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\rdx\tgf		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	15/08/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0107	3rd Crs	temp
SegmentNo	TotalLength	
68/S-W0107/S030317	215.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
raveendra		0.00
PhoneNo	EmailId	
9066536516		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		85-5821-000000020
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\gfgfvc\gfv		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	18/07/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0034	1st Amain Rd Gelayarabalaga	temp
SegmentNo	TotalLength	
68/S-W0034/S031110	592.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ravi		0.00
PhoneNo	EmailId	
9000500020		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	9652-451-00000020
Work OrderNo	Work Order Date	Period of Extention
ae\mlp\gfd\res		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	13/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0024	Ganesha Block 2nd Crs	temp
SegmentNo	TotalLength	
68/S-W0024/S032240	214.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
santosh		0.00
PhoneNo	EmailId	
8456123963		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		98542-98542-000000050
Work OrderNo	Work Order Date	Period of Extention
aee\mpl\red\dx		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	14/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0059	NA	temp
SegmentNo	TotalLength	
68/S-W0059/S034015	68.35	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
srihari		0.00
PhoneNo	EmailId	
9703867182		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	100000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	050544-541-0000080
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\trfd\rfd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	13/06/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0020	Ganesha Block 3rd Crs	park
SegmentNo	TotalLength	
68/S-W0020/S034438	130.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sri hari rao		0.00
PhoneNo	EmailId	
9455412525		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		854-41-00040
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\rtfd\rd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	23/02/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0028	Ganesha Block 1st Crs	park
SegmentNo	TotalLength	
68/S-W0028/S034620	135.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
raju		0.00
PhoneNo	EmailId	
8463521455		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	852-789-000550
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\rfd\gfc		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	17/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0067	1st Main Rd	junction
SegmentNo	TotalLength	
68/S-W0067/S034736	586.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
babji		0.00
PhoneNo	EmailId	
8456151452		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	412-4145-00050
Work OrderNo	Work Order Date	Period of Extention
aee\mpl\red\redx		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	11/04/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0128	5th Main Rd	temp
SegmentNo	TotalLength	
68/S-W0128/S035004	377.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
raghu		0.00
PhoneNo	EmailId	
9654155241		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
		9852-452-000090
Work OrderNo	Work Order Date	Period of Extention
ae\mlp\tfrc\fdc		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	19/01/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Footpath Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0195	1st Main, J C Nagar	jun
SegmentNo	TotalLength	
68/S-W0195/S035137	67.15	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
maneendra		0.00
PhoneNo	EmailId	
9050064048		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		8961-74514-000090
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\gftf\gtf		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	15/05/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0183	4th Crs	temp
SegmentNo	TotalLength	
68/S-W0183/S035438	189.14	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
naresh		0.00
PhoneNo	EmailId	
9436542412		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		5415-45214-000080
Work OrderNo	Work Order Date	Period of Extention
aee\mpl\trfc\ytg		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	12/07/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0161	8th Crs	temp
SegmentNo	TotalLength	
68/S-W0161/S035811	260.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
datthu		0.00
PhoneNo	EmailId	
9777373864		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
Tender		52-789-000090
Work OrderNo	Work Order Date	Period of Extention
aee\mpl\fcx\fd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	24/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0157	9th Crs	temp
SegmentNo	TotalLength	
68/S-W0157/S041228	259.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
roopa		0.00
PhoneNo	EmailId	
9562452114		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		8745-88562-000080
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\gvfc\ffd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	17/05/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0153	10th Crs	park
SegmentNo	TotalLength	
68/S-W0153/S041439	225.03	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
arvind		0.00
PhoneNo	EmailId	
9665365166		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		9621-78621-00002120
Work OrderNo	Work Order Date	Period of Extention
ee\mlp\tgvf\rd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	24/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0097	5th Crs Rd	temp
SegmentNo	TotalLength	
68/S-W0097/S044630	204.92	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
raju		0.00
PhoneNo	EmailId	
8452152145		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		74128-85621-0000090
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\rd\rfrfd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	20/03/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0095	6th Crs Rd	temp
SegmentNo	TotalLength	
68/S-W0095/S044752	205.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
ravee		0.00
PhoneNo	EmailId	
9654121232		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
Tender		5423-8621-0000060
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\ltdx\tgfc		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	12/06/2013	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0117	12th Crs	park
SegmentNo	TotalLength	
68/S-W0117/S044928	709.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
pava		0.00
PhoneNo	EmailId	
8456123635		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		541235-46321-0000050
Work OrderNo	Work Order Date	Period of Extention
aee\mplpygfc\gtfc		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	21/03/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revana
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0093	7th Crs	temp
SegmentNo	TotalLength	
68/S-W0093/S045058	205.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
kiran		0.00
PhoneNo	EmailId	
8451236543		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		5842584-8521-00090
Work OrderNo	Work Order Date	Period of Extention
aee\mlptgtgtgfc		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	12/12/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
2		revanna
Date of Inspection	Remarks	
19/02/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Footpath Condition	
Footpath Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0044	1st Crs Rd	temp
SegmentNo	TotalLength	
68/S-W0044/S045313	115.79	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
teje		0.00
PhoneNo	EmailId	
9635241456		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	5621-546214-000090
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\gfd\tfrd		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	15/08/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0091	8th Crs G Balaga	temp
SegmentNo	TotalLength	
68/S-W0091/S045420	251.42	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
sudeer		0.00
PhoneNo	EmailId	
9123456415		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain maintance	200000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	542541-456214-0000909
Work OrderNo	Work Order Date	Period of Extention
aee\mplpytgvyg		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	12/04/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0056	3rd Main G Balaga	temp
SegmentNo	TotalLength	
68/S-W0056/S045528	316.04	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
krishna		0.00
PhoneNo	EmailId	
9456123415		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
drain main	100000	2012
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender	0	74125-4521-00050
Work OrderNo	Work Order Date	Period of Extention
aee\mlp\tgfd\hgv		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
	16/10/2012	Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		mah
Date of Inspection	Remarks	
30/01/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0176, W0253, I0006, W0249, W0241, W0211, W0261, W	NA, Mahadevapura Village Rd, Ambedkar Nagar Slum, Chowdeshwari Temple Behind Rd, Maheshwaramma Templ	J.C.NAGARA
SegmentNo	TotalLength	
68/C-W0176/S013214	594.84	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
OFFICE		0.00
PhoneNo	Emailld	
9845918909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF J.C.NAGARA IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS TO FOOTPATH AND DRAIN,
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF J.C.NAGARA IN WARD NO.68	068-15-0000102
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/10202015-16	06/12/2012	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0168	NA	J.C.NAGARA
SegmentNo	TotalLength	
68/S-W0168/S015855	313.69	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SFGDS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF JC.NAGARA IN WARD NO.68		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF JC.NAGARA IN WARD NO.68	068-15-000102
Work OrderNo	Work Order Date	Period of Extention
000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0176, W0253, I0006, W0241, W0247, W0174, W0251	StreetName NA, 4th Crs, Maheshwaramma Temple Behind Rd	Significant LandMark J C NAGARA
SegmentNo 68/C-W0176/S020623	TotalLength 277.60	

ContractorDetails		
NameofContractor SFGDS	ContractorRegNo	Expenditure 0.00
PhoneNo 9845198909	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF JC.NAGARA IN WARD NO.68	Sanctioned Amount 10000000	Sanctioned Year 2015
Year 2015 - 2016	Type of Work Others	Other Work Type IMPROVEMENTS DRAIN & FOOTHPATH
Tender	WorkDetails IMPROVEMENTS TO FOOTPATH AND DRAINS TO 9TH, 10TH, 6TH A MAIN ROAD AND 8TH CROSS ROADS OF JC.NAGARA IN WARD NO.68	Job No Work Code 068-15-000102
Work OrderNo 000	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0028	NA	GANESHA BLOCK
SegmentNo	TotalLength	
68/S-W0028/S021559	135.05	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0024	NA	GANESHA BLOCK
SegmentNo	TotalLength	
68/S-W0024/S022045	214.32	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0020	NA	GANESHA BLOCK 3RD CROSS
SegmentNo	TotalLength	
68/S-W0020/S022430	130.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0016	NA	GANESHA BLOCK 5TH CROSS
SegmentNo	TotalLength	
68/S-W0016/S022704	224.74	


ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68		
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0023	NA	10TH MAIN
SegmentNo	TotalLength	
68/S-W0023/S022948	172.48	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68		
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0049	NA	2ND MAIN ROAD
SegmentNo	TotalLength	
68/S-W0049/S023145	115.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
AFAS		0.00
PhoneNo	EmailId	
9845198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68		2015
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 2ND 3RD 4TH 10TH AND 10TH CROSS MAIN ROADS AND 1ST, 2ND, 3RD AND 8TH CROSS ROADS IN GANESHA BLOCK IN WARD NO.68	068-15-000101
Work OrderNo	Work Order Date	Period of Extention
0000		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0025	NA	1ST CROSS
SegmentNo	TotalLength	
68/S-W0025/S023442	175.61	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SDFAKJ		0.00
PhoneNo	EmailId	
9945198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	FOOTPATH AND DRAIN
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	068-15-000103
Work OrderNo	Work Order Date	Period of Extention
00		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0223	NA	2ND CROSS
SegmentNo	TotalLength	
68/S-W0223/S024002	156.16	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SDFAKJ		0.00
PhoneNo	EmailId	
9945198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	10000000	
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	068-15-000103
Work OrderNo	Work Order Date	Period of Extention
00		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
13/02/2016		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet


Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0209	NA	2ND MAIN ROAD
SegmentNo	TotalLength	
68/S-W0209/S024314	149.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SDFAKJ		0.00
PhoneNo	EmailId	
9945198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68		
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	068-15-000103
Work OrderNo	Work Order Date	Period of Extention
00		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0142	NA	3RD MAIN ROAD MICO LAYOUT
SegmentNo	TotalLength	
68/S-W0142/S024549	145.44	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SDFAKJ		0.00
PhoneNo	EmailId	
9945198909		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	10000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO FOOTPATH AND DRAINS TO 1ST, 2ND, 3RD, 4TH MAIN ROAD IN MICO LAYOUT IN WARD NO.68	068-15-000103
Work OrderNo	Work Order Date	Period of Extention
00		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
12/02/2016	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0233	NA	J.C.Nagara
SegmentNo	TotalLength	
68/S-W0233/S065204	48.28	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING COVERING SLAB AND FLAGGING COURSE IN J.C.NAGARA AREA AND SURROUNDINGS IN WARD NO.68	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	
Tender	WorkDetails	Job No Work Code
	PROVIDING COVERING SLAB AND FLAGGING COURSE IN J.C.NAGARA AREA AND SURROUNDINGS IN WARD NO.68	068-14-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/269/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
I0079	Om Shakthi Lyt 4th Crs	Swimming pool
SegmentNo	TotalLength	
68/S-I0079/S011858	360.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.68 MAHALAKSHMIPURAM	5000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.68 MAHALAKSHMIPURAM	068-16-000018
Work OrderNo	Work Order Date	Period of Extension
EE/MLP/WO/JE/PR/33/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0077, W0088, W0075, W0071, W0082, W0073, W0094, W	StreetName NA, Om Shakthi Lyt 4th Crs	Significant LandMark Mahalakshmi Layout
SegmentNo 68/C-W0077/S012834	TotalLength 1148.24	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.68 MAHALAKSHMIPURAM	Sanctioned Amount 5000000	Sanctioned Year 2016
Year 2015 - 2016	Type of Work	Other Work Type
Tender	WorkDetails DEVELOPMENT AND IMPROVEMENTS TO ROADS AND DRAINS IN MAIN ROAD AND CROSS ROADS OF WARD NO.68 MAHALAKSHMIPURAM	Job No Work Code 068-16-000018
Work OrderNo EE/MLP/WO/JE/PR/033/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0097, W0007, W0332, W0034, I0005	16th Crs, NA	1st Cross behind S.G.International school
SegmentNo	TotalLength	
68/C-W0097/S095153	82.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND ROADS 1ST CROSS ROAD S S PURAM IN WARD NO.68	1500000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN AND ROADS 1ST CROSS ROAD S S PURAM IN WARD NO.68	068-15-000032
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/129/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0082	NA	ganesha block
SegmentNo	TotalLength	
68/S-W0082/S103224	336.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AND CC ROAD AT GANESHA BLOCK AND SURROUNDINGS IN WARD NO.68		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN WITH B.S.SLAB COVERING AND CC ROAD AT GANESHA BLOCK AND SURROUNDINGS IN WARD NO.68	068-15-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/162/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0095	Om Shakthi Lyt 2nd Crs	j c nagar
SegmentNo	TotalLength	
68/S-W0095/S103757	205.65	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN J.C.NAGARA AREA IN WARD NO.68		
Year	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN IN J.C.NAGARA AREA IN WARD NO.68	068-13-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/579/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0109	NA	Athmiya Geleyarabalaga
SegmentNo	TotalLength	
68/S-W0109/S055226	214.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN 2ND A CROSS AND SURROUNDING IN ATHMIYA GELEYARABALAGA IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN IN 2ND A CROSS AND SURROUNDING IN ATHMIYA GELEYARABALAGA IN WARD NO.68	068-17-000038
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/347/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0076	NA	2nd cross
SegmentNo	TotalLength	
68/S-W0076/S060048	313.67	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH OPP BUS STAND AND NEAR SWIMMING POOL 2ND CROSS AND SURROUNDING IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN AND FOOTPATH OPP BUS STAND AND NEAR SWIMMING POOL 2ND CROSS AND SURROUNDING IN WARD NO.68	068-17-000036
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/346/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0103	NA	Mahalakshmilayout
SegmentNo	TotalLength	
68/S-W0103/S070755	284.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CLEANING OF THE DEBRIES AND SILT IN WARD NO.68	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	CLEANING OF THE DEBRIES AND SILT IN WARD NO.68	068-16-000024
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/180/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
6		Arpitha CP
Date of Inspection	Remarks	
09/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0109	NA	ASWAR HOSPITAL
SegmentNo	TotalLength	
68/S-W0109/S033950	126.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9945364758		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN 8TH CROSS 1ST D CROBLOCK AND SURROUNDINGSSS MUNESHWARA	2000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-145-000048
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/193/14-15	22/12/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0046, W0036, W0107, W0042	NA, Subhash Chandra Bose Lyt	MAHALAXMI LYT
SegmentNo	TotalLength	
68/C-W0046/S034331	195.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
V RAVI KUMAR		0.00
PhoneNo	EmailId	
9967456745		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 3RD CROSS GELEYARABALAGAAT MAHALAXMI LYT	600000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		06-15-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/254/14-15	17/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0082	NA	MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/S-W0082/S021149	336.91	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
SRI.BALARAJU Y		0.00
PhoneNo	EmailId	
9008735737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING HAND RAILS TO STEPS BEHIND MAHALAKSHMI LAYOUT CLUB IN MAHALAKSHMI LAYOUT IN WARD NO.68	500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	HAND RAILS
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING HAND RAILS TO STEPS BEHIND MAHALAKSHMI LAYOUT CLUB IN MAHALAKSHMI LAYOUT IN WARD NO.68	068-15-000023
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/437/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0015	NA	ALF QUARTERS
SegmentNo	TotalLength	
68/S-W0015/S021713	249.27	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
BALARAJU Y		0.00
PhoneNo	EmailId	
9008735737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CHILDREN PLAY EQUIPMENTS AND CHAIN LINK FENCING TO ALF QUARTERS IN WARD NO.68	500000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	CHAIN LINK FENCING
Tender	WorkDetails	Job No Work Code
Tender	PROVIDING CHILDREN PLAY EQUIPMENTS AND CHAIN LINK FENCING TO ALF QUARTERS IN WARD NO.68	068-15-000024
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/438/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
I0271	Ambedkar Nagar Slum	MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/S-I0271/S022207	744.88	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
BALARAJU Y		0.00
PhoneNo	EmailId	
9008735737		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO PARK IN WARD NO.68	1000000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS TO PARK
Tender	WorkDetails	Job No Work Code
Tender	IMPROVEMENTS TO PARK IN WARD NO.68	068-15-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/436/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0020, W0016, W0088, W0086, W0071, W0077, W0081, W	NA, 14th Crs	Mahalakshmi layout
SegmentNo	TotalLength	
68/S-W0020/S073302	318.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRISHNEGOWDA		0.00
PhoneNo	EmailId	
0		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CC ROADS PATCH WORKS IN MAHALAKSHMIPURAM WARD NO.68	1000000	2016
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	CC ROADS PATCH WORKS IN MAHALAKSHMIPURAM WARD NO.68	068-16-000003
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/43/2015-16		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0207	NA	JAYADURGA KALYANA MANTAPA
SegmentNo	TotalLength	
68/S-W0207/S014538	419.00	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN JAYADURGA KALYANA MANTAPA ROADS IN J.C.NAGARA IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN JAYADURGA KALYANA MANTAPA ROADS IN J.C.NAGARA IN WARD NO.68	068-16-000040
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/132/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0179	NA	J.C.NAGARA
SegmentNo	TotalLength	
68/S-W0179/S074211	258.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 6TH A CROSS AND 4TH AND 5TH CROSS (SATHYANARAYANA KALYANA MANTAPA DOWN ROADS) IN J.C.NAGARA IN WARD NO.68	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AT 6TH A CROSS AND 4TH AND 5TH CROSS (SATHYANARAYANA KALYANA MANTAPA DOWN ROADS) IN J.C.NAGARA IN WARD NO.68	068-15-000076
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/421/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
19/01/2017	Remarks
Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0128	NA	J.C.Nagara
SegmentNo	TotalLength	
68/S-W0128/S073750	377.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
m/s kridl		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain in J.C.Nagara in ward no.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	Improvements to drain in J.C.Nagara in ward no.68	068-16-000038
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/je/pr130/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0008	NA	Saraswathipuram
SegmentNo	TotalLength	
68/S-W0008/S080115	396.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain 8th cross Saraswathipuram in ward no.68	1000000	
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	Improvements to drain 8th cross Saraswathipuram in ward no.68	068-16-000039
Work OrderNo	Work Order Date	Period of Extention
ee/mlp/wo/je/pr/131/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	 
Drain Condition	 



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0034	NA	7TH CROSS J.C.NAGARA
SegmentNo	TotalLength	
68/S-W0034/S040120	592.86	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9886046507		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
Improvements to drain at 7th cross J.C.Nagara in ward no.68	1900000	2014
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
		068-15-000035
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/32/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		yadukrishna
Date of Inspection	Remarks	
12/02/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0185, W0130, W0179, W0187, W0183, W0171, W0128, W	NA, Vinayaka Lyt 3rd Crs	1ST MAIN J.C.NAGARA
SegmentNo	TotalLength	
68/C-W0185/S043700	170.51	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
N.VENKATAREDDY		0.00
PhoneNo	EmailId	
9845641836		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING FLAGGING COURSE 1ST MAIN ROAD SURROUNDINGS IN WARD NO.68	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	FLAGGING COURSE	068-14-000012
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/268/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0048	NA	behind vasavi temple
SegmentNo	TotalLength	
68/S-W0048/S084828	62.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT SWD AT 10TH AND 11TH CROSS BEHIND VASAVI TEMPLE MAHALAKSHMI LAYOUT IN WARD NO.68	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS TO DRAIN AT SWD AT 10TH AND 11TH CROSS BEHIND VASAVI TEMPLE MAHALAKSHMI LAYOUT IN WARD NO.68	068-15-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/124/20214-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0144	StreetName 3rd Crs	Significant LandMark GANESHA BLOCK
SegmentNo 68/S-W0144/S085255	TotalLength 111.74	

ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN GANESHA BLOCK ROADS IN WARD NO.68	Sanctioned Amount 1500000	Sanctioned Year 2015
Year 2014 - 2015	Type of Work	Other Work Type
Tender	WorkDetails	Job No Work Code 068-15-000031
Work OrderNo EE/MLP/WO/JE/PR/128/2014-15	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No

Field Inspection Details		
Number of Trees 0	Other Information	Name arpitha
Date of Inspection 20/01/2017	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0126	NA	SRIRAMANAGARA
SegmentNo	TotalLength	
68/S-W0126/S085605	121.58	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN IN SRIRAMANAGARA IN WARD NO.68	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
		068-15-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/127/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0131	NA	5TH CROSS MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/S-W0131/S090203	106.46	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 2ND, 3RD AND 5TH CROSS AT MAHALAKSHMI LAYOUT IN WARD NO.68	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
		068-15-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/125/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0227	NA	Opposite to Sandeep Bar
SegmentNo	TotalLength	
68/S-W0227/S110813	132.94	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROAD OPPOSITE TO SANDEEP BAR AND CHAIN LINK FENCING IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING CC ROAD OPPOSITE TO SANDEEP BAR AND CHAIN LINK FENCING IN WARD NO.68	068-17-000017
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/268/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
I0117	NA	Athmiya geleyarabalaga
SegmentNo	TotalLength	
68/S-I0117/S055808	709.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AND FOOTPATH TO ATHMIYA GELEYARA BALAGA IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2015 - 2016	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN AND FOOTPATH TO ATHMIYA GELEYARA BALAGA IN WARD NO.68	068-17-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/345/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0114	NA	J.C.NAGARA
SegmentNo	TotalLength	
68/S-W0114/S060121	81.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS BETWEEN 11TH TO 12TH CROSS ROADS IN J.C.NAGARA IN WARD NO.68	1900000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS BETWEEN 11TH TO 12TH CROSS ROADS IN J.C.NAGARA IN WARD NO.68	068-17-000030
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/335/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0052, W0097, W0056, W0093, W0099, W0095	StreetName NA, 16th Crs, 15th Crs, Om Shakthi Lyt 2nd Crs	Significant LandMark GELEYARABALAGA
SegmentNo 68/C-W0052/S060814	TotalLength 301.29	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAIN 7TH AND 8TH CROSS IN ATHMIYA GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type IMPROVEMENTS
Tender Not a Tender	WorkDetails IMPROVEMENTS TO DRAIN 7TH AND 8TH CROSS IN ATHMIYA GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-17-000039
Work OrderNo EE/MLP/WO/JE/PR/339/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0052, W0097, W0044, W0034, W0046, W0036, W0056, W	StreetName NA, 16th Crs	Significant LandMark AGB LAYOUT
SegmentNo 68/C-W0052/S051018	TotalLength 475.05	

ContractorDetails		
NameofContractor M/s kridl	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork IMPROVEMENTS AND ASPHALTING TO 4TH, 5TH CROSS IN AGB LAYOUT IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type IMPROVEMENS AND ASPHALT
Tender Not a Tender	WorkDetails IMPROVEMENTS AND ASPHALTING TO 4TH, 5TH CROSS IN AGB LAYOUT IN WARD NO.68	Job No Work Code 068-17-000020
Work OrderNo EE/MLP/WO/JE/PR272/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0002	NA	GANESHA BLOCK 8TH B CROSS
SegmentNo	TotalLength	
68/S-W0002/S052309	259.56	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 8TH MAIN ROAD IN GANESHA BLOCK IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS AND ASPHALT
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS AND ASPHALTING TO 8TH MAIN ROAD IN GANESHA BLOCK IN WARD NO.68	068-17-000015
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/267/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
19/01/2017	Remarks
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0151, W0114, W0153	NA	11TH CROSS AND 10TH CROSS J.C NAGAR
SegmentNo	TotalLength	
68/C-W0151/S052913	288.06	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 11TH CROSS ROAD IN J.C.NAGARA IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS AND ASPHALTING
Tender	WorkDetails	Job No Work Code
	IMPROVEMENTS AND ASPHALTING TO 11TH CROSS ROAD IN J.C.NAGARA IN WARD NO.68	068-17-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/270/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0041, W0016, W0018, W0067, W0059	Om Shakthi Lyt, 9th Crs, NA, 13th Crs, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	GANESHA BLOCK 5TH CROSS
SegmentNo	TotalLength	
68/C-W0041/S053411	429.87	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING AT 5TH CROSS IN GANESHA BLOCK IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS AND ASPHALTING
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS AND ASPHALTING AT 5TH CROSS IN GANESHA BLOCK IN WARD NO.68	068-17-000008
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/264/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
19/01/2017	Remarks
Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0039, W0004, W0008, W0002, W0006, W0043	NA	GANESHA BLOCK 5TH MAIN
SegmentNo	TotalLength	
68/C-W0039/S054041	190.18	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 5TH MAIN AND 6TH MAIN ROAD IN GANESHA BLOCK IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS AND ASPHALT
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS AND ASPHALTING TO 5TH MAIN AND 6TH MAIN ROAD IN GANESHA BLOCK IN WARD NO.68	068-17-000016
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/268/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0219, W0217, W0215, W0211, W0213	StreetName Chowdeshwari Temple Rd, NA	Significant LandMark PIPELINE PARK
SegmentNo 68/C-W0219/S054705	TotalLength 247.29	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork PROVIDING CHAIN LINK FENCING IN PIPELINE PARK AND OTHER IMPROVEMENTS WORKS IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type CHAIN LINK FENCING
Tender Not a Tender	WorkDetails PROVIDING CHAIN LINK FENCING IN PIPELINE PARK AND OTHER IMPROVEMENTS WORKS IN WARD NO.68	Job No Work Code 068-17-000004
Work OrderNo EE/MLP/WO/JE/PR/254/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0038	NA	NEAR TEMPLE GAS GODOWN UP ROAD
SegmentNo	TotalLength	
68/S-W0038/S055928	65.75	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING CC ROAD IN GAS GOWDOWN UP IN MUNESHWARA BLOCK 10TH CROSS IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	CC ROAD
Tender	WorkDetails	Job No Work Code
Not a Tender	PROVIDING CC ROAD IN GAS GOWDOWN UP IN MUNESHWARA BLOCK 10TH CROSS IN WARD NO.68	068-17-000019
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/271/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0018	NA	4TH CROSS
SegmentNo	TotalLength	
68/S-W0018/S060419	268.99	





ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS AND ASPHALTING TO 4TH CROSS GANESHA BLOCK IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	IMPROVEMENTS AND ASPHALTING
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS AND ASPHALTING TO 4TH CROSS GANESHA BLOCK IN WARD NO.68	068-17-000006
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/263/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0118, W0151, W0143, W0114, W0259, I0271, W0257, W	StreetName NA, Ambedkar Nagar Slum	Significant LandMark J C NAGARA
SegmentNo 68/C-W0118/S061138	TotalLength 421.74	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork APPLYING PAINTING TO KERBS REPLACING OF DAMAGED KERBS AND OTHER IMPROVEMENTS WORKS IN J.C.NAGARA IN WARD NO.68	Sanctioned Amount 1000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type KERB PAINTING AND REPLACING DAMAGED KERB
Tender Not a Tender	WorkDetails APPLYING PAINTING TO KERBS REPLACING OF DAMAGED KERBS AND OTHER IMPROVEMENTS WORKS IN J.C.NAGARA IN WARD NO.68	Job No Work Code 068-17-000012
Work OrderNo EE/MLP/WO/JE/PR/257/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
19/01/2017	Remarks
Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0118, W0143, W0114, I0271, W0257, W0145	NA, Ambedkar Nagar Slum	GANESHA BLOCK
SegmentNo	TotalLength	
68/C-W0118/S061552	207.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
APPLYING PAINTING TO KERBS AND REPLACING OF DAMAGED KERBS AND OTHER IMPROVEMENTS WORKS IN GANESHA BLOCK IN WARD NO.68	1000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	PAINTING TO KERBS AND REPLACING OF DAMAGED KERBS
Tender	WorkDetails	Job No Work Code
Not a Tender	APPLYING PAINTING TO KERBS AND REPLACING OF DAMAGED KERBS AND OTHER IMPROVEMENTS WORKS IN GANESHA BLOCK IN WARD NO.68	068-17-000014
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/261/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0068, W0127	NA	SRIRAMNAGAR
SegmentNo	TotalLength	
68/S-W0068/S103953	162.30	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475869		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 5TH MAIN SRIRAMNAGAR 2ND CROSS MUNESWARA BLOCK AND 5TH CROSS LEFT SIDE MAHALAXMI LYT	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000060
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/476/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0014, W0015, W0017	NA	SARASWATHIPURAM
SegmentNo	TotalLength	
68/C-W0014/S104334	125.19	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT 2ND CROSS	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000088
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/474/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0207	NA	SATHYANARAYA LYT
SegmentNo	TotalLength	
68/S-W0207/S104628	27.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956474858		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT 3RD CROSS SATHYANARAYANA LYT	2000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000087
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/473/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0025	NA	MAHABALESWARA TEMPLE
SegmentNo	TotalLength	
68/S-W0025/S104943	91.97	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956473846		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT9TH MAIN IN GANESHA BLOCK	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000085
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/471/14-5	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0261, W0255	NA, Mahadevapura Village Rd	J C NAGAR
SegmentNo	TotalLength	
68/S-W0261/S105217	131.12	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9967584657		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN AT 6TH CROSS AND 4TH AND 5TH CROSS IN J C NAGAR	1500000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000076
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/421/14-15	27/02/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0173	NA	J C NAGAR
SegmentNo	TotalLength	
68/S-W0173/S105454	110.41	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAIN AT 6TH CROSS J C NAGAR	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000091
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/477/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0077, W0090, W0088	NA	GOVT SCHOOL
SegmentNo	TotalLength	
68/C-W0077/S105857	232.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475647		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT 9TH CROSS GOVT SCHOOL ROAD MAHALAXMI LYT	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000089
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/475/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0041, W0018, W0059	Om Shakthi Lyt, 9th Crs, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd	MAHALAXMI LYT
SegmentNo	TotalLength	
68/C-W0041/S110250	213.71	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
YASHANTH HK		0.00
PhoneNo	EmailId	
9946573865		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AT 2ND 3RD AND 4TH CROSS ROAD GANESHA BLOCK AT MHALAXMI MAIN ROAD	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-15-000015
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/297/14-15	27/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		
Category	Photo	
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0207, W0219, W0203, W0146, W0128	NA, Chowdeshwari Temple Rd	C A SITE
SegmentNo	TotalLength	
68/C-W0207/S110557	206.95	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475867		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT 4TH MAIN TO SATHYANARAYANA LYT AND MICO LYT AND SURROUNDINGS	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000092
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/478/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0179, W0132, W0136, W0134	NA, 1st Crs	J C NAGAR
SegmentNo	TotalLength	
68/C-W0179/S110900	195.98	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9956475647		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS OF DRAINS AT5TH CROSS	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-15-000093
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/479/14-15	30/03/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0090	NA	MAHALAXMI LYT
SegmentNo	TotalLength	
68/S-W0090/S111107	117.81	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
YASHANTH HK		0.00
PhoneNo	EmailId	
9956785678		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
CONSTRUCTION OF CULVERTS AND IMPROVEMENTS TO DRAIN IN MAHALAXMI LYT	1000000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Others	CULVERTS AND DRAIN
Tender	WorkDetails	Job No Work Code
Tender		068-15-000010
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/TS/PR/296/14-15	27/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0039	NA	7th main of Ganesha Block
SegmentNo	TotalLength	
68/S-W0039/S034442	115.60	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH COVERING SLAB AT 7TH MAIN OF GANESHA BLOCK IN WARD NO.68	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	IMPROVEMENTS TO DRAIN
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAIN WITH COVERING SLAB AT 7TH MAIN OF GANESHA BLOCK IN WARD NO.68	068-13-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/523/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0179	NA	5TH CROSS
SegmentNo	TotalLength	
68/S-W0179/S085724	258.09	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DESILT AND IMPROVEMENTS TO FOOTPATH IN WARD NO.68	1000000	2013
Year	Type of Work	Other Work Type
2013 - 2014	Others	IMPROVEMENTS TO FOOTPATH
Tender	WorkDetails	Job No Work Code
	DESILT AND IMPROVEMENTS TO FOOTPATH IN WARD NO.68	068-13-000037
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/577/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0104, W0129	NA	sollapuradama temple
SegmentNo	TotalLength	
68/C-W0104/S065735	113.20	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9542682288		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
providing flagging course with covering slab to 1st b cross and 1st main	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-14-000028
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/348/13-14	03/03/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0037, W0029, W0031, W0022	StreetName NA	Significant LandMark SARASWTHIPURAM
SegmentNo 68/S-W0037/S070835	TotalLength 153.68	


ContractorDetails		
NameofContractor KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9666927137	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRIAN WITH COVERING SLAB AT SARASWATHIPURAM	Sanctioned Amount 2000000	Sanctioned Year 2013
Year 2012 - 2013	Type of Work Drain Maintenance	Other Work Type
Tender Not a Tender	WorkDetails	Job No Work Code 068-13-000033
Work OrderNo EE/MLP/WO/JE/PR/581/12-13	Work Order Date 16/03/2013	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved Yes

Field Inspection Details		
Number of Trees 0	Other Information	Name revanna
Date of Inspection 03/09/2015	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0036, W0103, W0042	NA	GELEYARA BALAGA
SegmentNo	TotalLength	
68/S-W0036/S071602	145.73	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
RAVIKUMAR V		0.00
PhoneNo	EmailId	
9030657417		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING COVERING SLAB AND FLAGGING COURSE IN GELETARA BALAGA	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-14-000009
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/259/13-14	10/02/2014	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0005	NA	AGB LAYOUT
SegmentNo	TotalLength	
68/S-W0005/S072246	64.29	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9663235469		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN WITH COVERING SLAB AT AGB LAYOUT	2000000	2013
Year	Type of Work	Other Work Type
2012 - 2013	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Not a Tender		068-13-000034
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/580/12-13	16/03/2013	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		revanna
Date of Inspection	Remarks	
03/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0062	NA	GELEYARA BALAGA
SegmentNo	TotalLength	
68/S-W0062/S072829	92.34	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
C MAHESH		0.00
PhoneNo	EmailId	
9542503388		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DAIN WIYH COVERING SLAB AT 3RD MAIN	1250000	2015
Year	Type of Work	Other Work Type
2014 - 2015	Drain Maintenance	
Tender	WorkDetails	Job No Work Code
Tender		068-15-000016
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/243/14-15	12/01/2015	
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		Yes

Field Inspection Details		
Number of Trees	Other Information	Name
Date of Inspection	Remarks	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshimpura
StreetID	StreetName	Significant LandMark
W0221	NA	pipeline
SegmentNo	TotalLength	
68/S-W0221/S100307	99.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAIN 3RD CROSS AND PIPELINE IN J.C.NAGARA WARD NO.68	1000000	2014-15
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
		068-15-000050
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/195/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0130	NA	MAHALAKSHMI LAYOUT
SegmentNo	TotalLength	
68/S-W0130/S100649	149.10	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
H.N.SHIVASHANKAR		0.00
PhoneNo	EmailId	
9620699722		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
REPLACEMENT OF SANITARY LANE IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015		
Tender	WorkDetails	Job No Work Code
		068-14-000018
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/68/2014-15		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0094	NA	BUS STAND
SegmentNo	TotalLength	
68/S-W0094/S123009	310.01	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENS AND SIFTING REINSTALL BUS STAND AT MAHALAKSHMI LAYOUT MAIN ROAD IN WARD NO.68	1000000	2014
Year	Type of Work	Other Work Type
2014 - 2015	Others	IMPROVEMENTS
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENS AND SIFTING REINSTALL BUS STAND AT MAHALAKSHMI LAYOUT MAIN ROAD IN WARD NO.68	068-14-000026
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/PR/353/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
20/01/2017	

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0031	NA	2ND CROSS
SegmentNo	TotalLength	
68/S-W0031/S043938	107.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
DEVELOPMENT OF CONCRETE DRAIN AND COVERNG SLAB AT 2ND CROSS MUNESHWARA BLOCK IN WARD NO.68	990000	2013
Year	Type of Work	Other Work Type
2012 - 2013		
Tender	WorkDetails	Job No Work Code
	DEVELOPMENT OF CONCRETE DRAIN AND COVERNG SLAB AT 2ND CROSS MUNESHWARA BLOCK IN WARD NO.68	068-13-000022
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/AE/WO/517/2012-13		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	arpitha
20/01/2017	Remarks
Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0020	NA	GANESHA BLOCK
SegmentNo	TotalLength	
68/S-W0020/S044401	130.08	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
PROVIDING COVERING SLAB TO 5TH CROSS GANESHA BLOCK IN WARD NO.68	500000	2014
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	PROVIDING COVERING SLAB TO 5TH CROSS GANESHA BLOCK IN WARD NO.68	068-14-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/347/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshnipura
StreetID	StreetName	Significant LandMark
W0048	NA	mahalakshmi layout main road
SegmentNo	TotalLength	
68/S-W0048/S022252	62.74	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements to footpath in mahalakshmilayout main road in ward no.68	1000000	2014
Year	Type of Work	Other Work Type
2013 - 2014		
Tender	WorkDetails	Job No Work Code
	FOOTPATH	068-14-000027
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/347/2013-14		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
20/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmipura
StreetID	StreetName	Significant LandMark
W0111	NA	IPP HOSPITAL
SegmentNo	TotalLength	
68/S-W0111/S064238	320.11	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
improvements to park and civil works for dialysies ceter at ipp hospital in ward no.68	3000000	2016
Year	Type of Work	Other Work Type
2015 - 2016		
Tender	WorkDetails	Job No Work Code
	improvements to park and civil works for dialysies ceter at ipp hospital in ward no.68	068-16-000033
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/334/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmpura
StreetID W0058, W0056, W0111, W0054	StreetName NA	Significant LandMark IPP HOSPITAL
SegmentNo 68/C-W0058/S064524	TotalLength 141.28	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork CONSTRUCTIO NOF LIFT PIT AND OTHT E IMPROVEMENT WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type
Tender Not a Tender	WorkDetails CONSTRUCTIO NOF LIFT PIT AND OTHT E IMPROVEMENT WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-17-000001
Work OrderNo EE/MLP/WO/JE/PR/309/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0058	StreetName NA	Significant LandMark IPP HOSPITAL
SegmentNo 68/S-W0058/S064828	TotalLength 99.71	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork CONSTRUCTIO NOF HANDCAP RAMP AND OTHTE IMPROVEMENT WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 1000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type
Tender Not a Tender	WorkDetails CONSTRUCTIO NOF HANDCAP RAMP AND OTHTE IMPROVEMENT WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-17-000002
Work OrderNo EE/MLP/WO/JE/PR/310/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0054	StreetName NA	Significant LandMark IPP HOSPITAL
SegmentNo 68/S-W0054/S065400	TotalLength 235.13	

ContractorDetails		
NameofContractor M/S KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork PRIVIDING EXTERNAL FOR EXTERNAL WALL AND OTHER IMPROVEMENTS WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type
Tender Not a Tender	WorkDetails PRIVIDING EXTERNAL FOR EXTERNAL WALL AND OTHER IMPROVEMENTS WORKS IN THE PREMISES OF DIALYSIS CENTER IN GELEYARABALAGA IN WARD NO.68	Job No Work Code 068-17-000003
Work OrderNo EE/MLP/WO/JE/PR/311/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0114	NA	13th cross
SegmentNo	TotalLength	
68/S-W0114/S052129	81.89	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/S KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS AND CULVERTS IN 13TH CROSS LEFT SIDE ADJACNET TO 60FEET ROAD IN WARD NO.68	1000000	2016
Year	Type of Work	Other Work Type
2016 - 2017		
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS AND CULVERTS IN 13TH CROSS LEFT SIDE ADJACNET TO 60FEET ROAD IN WARD NO.68	068-17-000031
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/336/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0006	NA	11TH MAIN JC NAGAR
SegmentNo	TotalLength	
68/S-W0006/S052720	125.49	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO DRAINS IN 11TH MAIN IN J.C.NAGARA IN WARD NO.68	1000000	2016
Year	Type of Work	Other Work Type
2016 - 2017		
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO DRAINS IN 11TH MAIN IN J.C.NAGARA IN WARD NO.68	068-17-000033
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/338/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone	WardNo	WardName
WEST	68	Mahalakshmpura
StreetID	StreetName	Significant LandMark
W0215, W0213, W0217	NA	PIPELINE ROAD
SegmentNo	TotalLength	
68/C-W0215/S053129	165.70	

ContractorDetails		
NameofContractor	ContractorRegNo	Expenditure
M/s KRIDL		0.00
PhoneNo	EmailId	
9900333496		

Work Details		
NameOfWork	Sanctioned Amount	Sanctioned Year
IMPROVEMENTS TO PIPELINE ROAD ND SURROUNDING DRAINS IN WARD NO.68	2000000	2016
Year	Type of Work	Other Work Type
2016 - 2017	Others	
Tender	WorkDetails	Job No Work Code
Not a Tender	IMPROVEMENTS TO PIPELINE ROAD ND SURROUNDING DRAINS IN WARD NO.68	068-17-000025
Work OrderNo	Work Order Date	Period of Extention
EE/MLP/WO/JE/PR/343/2016-17		
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved
		No

Field Inspection Details		
Number of Trees	Other Information	Name
0		arpitha
Date of Inspection	Remarks	
19/01/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Zone WEST	WardNo 68	WardName Mahalakshmipura
StreetID W0052, W0093, W0044, W0034, W0095, W0097, W0007	StreetName NA, 15th Crs, Om Shakthi Lyt 2nd Crs, 16th Crs	Significant LandMark AGB LAYOUT
SegmentNo 68/C-W0052/S053533	TotalLength 593.23	

ContractorDetails		
NameofContractor M/s KRIDL	ContractorRegNo	Expenditure 0.00
PhoneNo 9900333496	EmailId	

Work Details		
NameOfWork IMPROVEMENTS TO DRAINS AND CULVERTS IN 5TH AND 6TH CROSS AGB LAYOUT IN WARD NO.68	Sanctioned Amount 2000000	Sanctioned Year 2016
Year 2016 - 2017	Type of Work Others	Other Work Type
Tender Not a Tender	WorkDetails IMPROVEMENTS TO DRAINS AND CULVERTS IN 5TH AND 6TH CROSS AGB LAYOUT IN WARD NO.68	Job No Work Code 068-17-000026
Work OrderNo EE/MLP/WO/JE/PR/344/2016-17	Work Order Date	Period of Extention
Defect Liability Period From	Defect Liability Period To	Multiple Road Involved No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
BRUHAT BANGALORE MAHANAGARA PALIKE
ENGINEERING DEPARTMENT
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
19/01/2017	

Category	Photo
Drain Condition	