



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0049, W0076, W0119, W0445, W0001, W0125, W0105, W	NA, Shetty Lyt, 4th Main Rd, Veera Anjaneya Temple Rd, 16th Crs	SRIGANDHANAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0049/S021851	373.94	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SHANKAR NAIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586758		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
DESTILING OF DRAINS IN MAIN AND CROSS ROADS	1200000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/95/13-14	05/08/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0345, W0328, W0347, W0336, W0338, W0381	S Krishnappa Lyt, R H B Colony, 4th Crs, R H B Colony 2nd Main Rd, R H B Colony, 6th Crs, NA	ganesha temple
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0345/S053148	170.40	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SUGGAPPA KEMPARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9972851320		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF RCC DRAIN IN 4TH CROSS GAJANANANAGARA	1990000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/93/13-14	05/08/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0172, W0229, W0164, W0221	NA	SANJEEVANI NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0172/S032737	201.73	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
M.D.GNANENDRA MURTHY		495612.00
<b>PhoneNo</b>	<b>EmailId</b>	
9986020978		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN & PLACING COVERING SLABS IN CROOS ROADS OF SANJIVINAGARA	500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000017
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/DD/VO/372/2012-13	22/02/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
14/10/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0266, W0183, W0185, W0179, W0264	NA	PETROL BUNK
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0266/S042554	216.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9968596859		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ROAD AND ASPHALTING	1260000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-14-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/28/14-15	04/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0162, W0191	NA	GOODWILL SHOOL
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0162/S042937	52.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9978986743		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND FOOTPATH	1990000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-14-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/25/14-15	04/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0376, W0372, W0370	7th Crs Lakshmi Sagar Lyt, NA	GAJANANA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/S-W0376/S043247	193.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967586958		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ROAD AND ASPHALTING	1765000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-14-000001
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/30/14-15	04/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0118, W0147, W0137, W0098, W0139	NA	SHIVANANDA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0118/S043549	116.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9967483684		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN AND FOOTPATH	1995000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-14-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/24/14-15	04/06/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0424, W0443, W0435, W0439	NA, Garudachar Palya Main Rd	HOYSALA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0424/S121536	201.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
IMPANA CONSTRUCTION		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9182734498		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF CONCRETE DRAIN ON 13TH CROSS LEFT SIDE	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/31/13-14	05/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju.
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0040, W0042, W0033, W0025, W0036, W0023, W0038	NA	MARUTHI NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0040/S122317	175.03	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
HARSHA CONSTRUCTIONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8892340098		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN IN MARUTHI NAGARA 3RD CR5OSS	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/DD/VO/155/12-13	10/10/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		tk
<b>Date of Inspection</b>	<b>Remarks</b>	
05/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0362	NA	GAJANANA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/S-W0362/S122859	108.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRIDHAR C		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9834009271		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF SLAB CULVERT AND DRAIN TO THE CROSS IN GAJANANA NAGARA	976000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-11-000058
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/VO/93/11-12	25/07/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0343	NA	LAKSMAN NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/S-W0343/S123407	81.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T T VASANTH KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9288374658		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF CONCRETE ROAD TO 1ST CROSS	1975000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/WO/26/12-13	28/08/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0311, W0365, W0155, W0361, W0163, W0151, W0363, W	NA, Chikka Muniswammappa Lyt, 2nd Crs, Chikka Muniswammappa Lyt, 1st Crs, R H B Colcny 1st Main Rd,	LAKSHMAN NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0311/S124947	167.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S MANJUNATH		0.00
<b>PhoneNo</b>	<b>Emailld</b>	
9088902314		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND FOOTPATH IN LAKSHMANNAGARA	1375000	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Others	DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000023
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/DD/WO/128/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> DASARAHALLI	<b>WardNo</b> 71	<b>WardName</b> Hegganahalli
<b>StreetID</b> W0424, W0443, W0428, W0435, W0439	<b>StreetName</b> NA, Garudachar Palya Main Rd	<b>Significant LandMark</b> hoysala nagara
<b>SegmentNo</b> 71/C-W0424/S125846	<b>TotalLength</b> 204.19	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SUGGAPPA KEMAPARAJU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9812300984	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> CONSTRUCTION OF CONCRETE DRAIN ON 13TH CROSS	<b>Sanctioned Amount</b> 1450000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 071-13-000023
<b>Work OrderNo</b> EE/DD/WO/94/13-14	<b>Work Order Date</b> 05/08/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> nagaraju
<b>Date of Inspection</b> 06/09/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0189, W0195, W0187, W0183, W0179, W0201, W0185, W	NA, Vinayaka Lyt 3rd Crs	OMSAKTHI TEMPLE ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0189/S010823	191.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
S NIKHIL AND NISHAL CONSTRUCTION		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9822300987		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF RCC DRAIN ON OMSAKTHI TEMPLE ROAD	1990000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000018
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/130/13-14	04/09/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> DASARAHALLI	<b>WardNo</b> 71	<b>WardName</b> Hegganahalli
<b>StreetID</b> W0189, W0195, W0187, W0183, W0179, W0201, W0185, W	<b>StreetName</b> NA, Vinayaka Lyt 3rd Crs	<b>Significant LandMark</b> OMSAKTHI TEMPLE
<b>SegmentNo</b> 71/C-W0189/S011255	<b>TotalLength</b> 227.69	

<b>ContractorDetails</b>		
<b>NameofContractor</b> S NIKHIL AND NISHAL CONSTRUCTION	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9981120922	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> CONSTRUCTION OF RCC DRAIN	<b>Sanctioned Amount</b> 1995000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 071-13-000017
<b>Work OrderNo</b> EE/DD/WO/131/13-14	<b>Work Order Date</b> 04/09/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> nagaraju
<b>Date of Inspection</b> 06/09/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0377, W0373, W0375, W0174, W0371	V S T Opposite, 5th Crs, East Park Reje Lyt, 6th Crs, Muthkurappa Lyt, NA, Dr Ambekdar Govt Ashraya	LAKSHMANNAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0377/S011835	83.40	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SHANKER NAIK		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9877230198		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAIN AND FOOTPATH	1000000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	DRAIN AND FOOTPATH
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/DD/VO/25/12-13	25/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0162	NA	SANJEEVININAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/S-W0162/S012255	49.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SHIVA PRAKASH B M		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8879001276		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN IN 10TH CROSS	540000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/DD/WO/123/12-13	22/10/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0167, W0118, W0147, W0139	NA	POOJAMMA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0167/S012801	99.95	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K NAGARAJ		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8899071625		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN	1160000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/WO/127/12-13	29/09/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0430, W0428, W0453, W0447, W0434, W0422, W0432, W	Nagappa Lyt, NA, 6th Crs, Shetty Lyt, 3rd Main Rd, Rama Anjaneya Lyt, 1st Crs, Garudachar Palya Main	VIGNESWARA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0430/S013749	185.20	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B SHIVASHANKER		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8897667801		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAINS TO CROSS ROADS	995000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-11-000048
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/WO/91/11-12	20/07/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0178, W0103	NA	MUNESWARA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0178/S014126	66.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B SHIVASHANKER		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9880127654		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO DRAINS TO CROSS ROADS	920000	2011
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2011 - 2012	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-11-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/WO/88/11-12	20/07/2011	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0322, W0208, W0306, W0212, W0218, W0210, W0326, W	R H B Colony, 2nd Crs, NA, Chikkanna Lyt 5th Crs, 1st Crs, Maheshwari Nagar Ambedkar Rd	SANJEEVINI NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0322/S014504	193.40	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KP HEMESHAPPA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980223871		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN AND FOOTPATH	1870000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-12-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/DZ/EE/HG/WO/47/12-13	13/08/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
06/09/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0089	NA	HOYASALANAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/S-W0089/S050216	77.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
IMPANA CONSTRUCTIONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9978675867		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF CONCRETE DRAIN ON 15TH CROSS RIGHT SIDE OF HOYASALANAGARA	1160000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/30/13-14	05/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
19/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0012, W0009	NA	heganahalli
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0012/S050246	46.12	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
NAGARAJU		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
8899008899		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
construction of road and drain on right side	1950000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Others	drain & road
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-13-000015
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/282/12-13	07/12/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
19/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0015, W0026, W0022, W0017	NA	HEGGANAHALLI
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0015/S050809	68.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
TECHNICAL MANAGER		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7788990990		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ROAD AND DRAIN ON 6 TH CROSS	1995000	2012
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2012 - 2013	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender		071-13-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/281/12-13	07/12/2012	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
19/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0435, W0443, W0445, W0439	NA, Garudachar Palya Main Rd, Shetty Lyt, 4th Main Rd	HOYASALA NAGARA 2ND MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0435/S031040	156.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B T RAVI KUMAR		1467824.00
<b>PhoneNo</b>	<b>EmailId</b>	
7353903103		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION IF CONCRETE DRAIN IN 14TH CROSS LEFT SIDE OF HOYASALA NAGARA	1550000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	CONCRETE DRAIN WORK	071-13-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/137/13-14	26/09/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraj
<b>Date of Inspection</b>	<b>Remarks</b>	
13/03/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> DASARAHALLI	<b>WardNo</b> 71	<b>WardName</b> Hegganahalli
<b>StreetID</b> W0193, W0276, W0285, W0268	<b>StreetName</b> Vinayaka Lyt 2nd Crs, NA	<b>Significant LandMark</b> Omshakthi Temple
<b>SegmentNo</b> 71/C-W0193/S012241	<b>TotalLength</b> 66.91	

<b>ContractorDetails</b>		
<b>NameofContractor</b> RAMACHANDRAIAH	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448736905	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of roads and drains beside Omshakthi temple in ward no.71	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 071-16-000005
<b>Work OrderNo</b> EE/DD/WO/48/15-16	<b>Work Order Date</b> 24/03/2016	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> Balagangadharaiah K G
<b>Date of Inspection</b> 08/07/2016	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0257, W0182, W0261	NA	SANJEEVINI NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0257/S120540	211.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
IMPANA CONSTRUCTIONS		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9833759011		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF DRAIN IN 10TH CROSS ROAD OF SANJEEVINI NAGARA	1995000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Drain Maintenance	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/32/13-14	05/07/2013	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
27/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> DASARAHALLI	<b>WardNo</b> 71	<b>WardName</b> Hegganahalli
<b>StreetID</b> W0428, W0435, W0445, W0439	<b>StreetName</b> NA, Shetty Lyt, 4th Main Rd	<b>Significant LandMark</b> HOYSALA NAGAR
<b>SegmentNo</b> 71/C-W0428/S121137	<b>TotalLength</b> 144.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b> IMPANA CONSTRUCTIONS	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9927485690	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> CONSTRUCTION OF CONCRETYE DRAIN ON 14TH CROSS RIGHT SIDE	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Drain Maintenance	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 071-13-000025
<b>Work OrderNo</b> EE/DD/WO/123/13-14	<b>Work Order Date</b> 26/08/2013	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> nagaraju
<b>Date of Inspection</b> 27/08/2015	<b>Remarks</b>	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0424, W0443, W0422, W0395, W0433	NA, Garudachar Palya Main Rd, Rama Anjaneya Lyt, 1st Crs	HOYSALA NAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0424/S113531	328.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B MOHAN KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9968768596		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ROAD AND ASPHALTING TO CROSS ROADS OF HOYASALANAGARA 15TH 16TH CROSS ROAD	1995000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000033
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/D/WO/243/13-14	06/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
27/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0103, W0120	NA	GAJANANAGARA
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0103/S114203	123.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B MOHAN KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9978695869		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OFROAD AND ASPHALTING TO 4TH AND 5TH CROSS ROADS OF GAJANANA NAGARA	1990000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000031
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/241/13-14	06/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> DASARAHALLI	<b>WardNo</b> 71	<b>WardName</b> Hegganahalli
<b>StreetID</b> W0114, W0111, W0098, W0115, W0117	<b>StreetName</b> NA	<b>Significant LandMark</b> GAJANANANNAGARA
<b>SegmentNo</b> 71/C-W0114/S114832	<b>TotalLength</b> 97.00	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B MOHAN KUMAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9967586958	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> RE CONSTRUCTION OF BAD STRETCHES ON 1ST MAIN ROAD	<b>Sanctioned Amount</b> 1995000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b>	<b>Job No Work Code</b> 071-13-000030
<b>Work OrderNo</b> EE/DD/WO/240/13-14	<b>Work Order Date</b> 06/02/2014	<b>Period of Extention</b>
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b> 0	<b>Other Information</b>	<b>Name</b> nagaraju
<b>Date of Inspection</b> 26/08/2015	<b>Remarks</b>	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
DASARAHALLI	71	Hegganahalli
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0424, W0443, W0435, W0445, W0439	NA, Garudachar Palya Main Rd, Shetty Lyt, 4th Main Rd	hoysalanagara
<b>SegmentNo</b>	<b>TotalLength</b>	
71/C-W0424/S114752	328.80	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B MOHAN KUMAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
7829583223		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
CONSTRUCTION OF ROAD AND ASPHALTING	1995000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		071-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/DD/WO/242/13-14	06/02/2014	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		nagaraju
<b>Date of Inspection</b>	<b>Remarks</b>	
26/08/2015		





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	

