



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0087	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0087/S024625	83.93	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>Emailld</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0081	14th Crs	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0081/S024818	62.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0270	<b>StreetName</b> 2nd A Crs, Maheshwari Nagar	<b>Significant LandMark</b> ANJANEYA LAYOUT
<b>SegmentNo</b> 9/S-W0270/S025231	<b>TotalLength</b> 262.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri. B. Chandrashekar, #28, Thindlu Anjaneyaswamy Layout, 1St Main, Vidyaranyaपुरa (Post),	<b>ContractorRegNo</b>	<b>Expenditure</b> 1978351.00
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	<b>Job No Work Code</b> 009-15-000007
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/243/2014-15	<b>Work Order Date</b> 24/01/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 15/05/2015	<b>Defect Liability Period To</b> 14/05/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
23/09/2015	completed	

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0268	<b>StreetName</b> NA	<b>Significant LandMark</b> anjaneya layout
<b>SegmentNo</b> 9/S-W0268/S032447	<b>TotalLength</b> 126.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri. B. Chandrashekar, #28, Thindlu Anjaneyaswamy Layout, 1St Main, Vidyaranyaपुरa (Post),	<b>ContractorRegNo</b>	<b>Expenditure</b> 1978351.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b> Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	<b>Job No Work Code</b> 009-15-000007
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/243/2014- 15	<b>Work Order Date</b> 24/01/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 15/05/2015	<b>Defect Liability Period To</b> 14/05/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 23/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0256	Ambedkar Nagar Slum	ANJANEYA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0256/S032716	25.79	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Chandrashekar, #28, Thindlu Anjaneyaswamy Layout, 1St Main, Vidyaranyaपुरa (Post),		1978351.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Anjaneya Layout & Siddalingeshwara Layout Roads In Ward No 09	009-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/243/2014- 15	24/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
23/09/2015	completed

Category	Photo
Drain Condition	
Drain Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0494	NA	INDIAN EXPRESSES LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0494/S114358	118.67	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		934804.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	009-11-000094
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/71/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0731	NA	INDIAN EXPRESS LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0731/S115711	31.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		934804.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	009-11-000094
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/71/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Suresh
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0733	NA	INDIAN EXPRESSES LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0733/S120458	33.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		934804.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	009-11-000094
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/71/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Suresh
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0737	NA	INDIAN EXPRESSES LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0737/S120717	68.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		934804.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements To Metaling & Asphalting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	009-11-000094
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/71/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 28/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0400	NA	INDIAN EXPRESSES LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0400/S121356	50.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		934804.00
<b>PhoneNo</b>	<b>EmailId</b>	
9348040088		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements To Metaling & Asphalting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Metaling & Asphalting At Virupakshapura Maramma temple To Indian Express Layout Road In Ward No 09	009-11-000094
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/71/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 28/09/2015	Remarks completed

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0214	NA	BASAVASAMITHI
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0214/S122249	108.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Girish Contractor, #227, 32 A Cross, 7Th Block, Jayanagar, Bangalore- 560082		1566633.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improements To Roads And Drains In Basavasamithi Road In Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improements To Roads And Drains
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improements To Roads And Drains In Basavasamithi Road In Ward No 09	009-15-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/296/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/04/2015	24/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0192	NA	BASAVASAMITHI
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0192/S123018	40.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Girish Contractor, #227, 32 A Cross, 7Th Block, Jayanagar, Bangalore- 560082		1566633.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improements To Roads And Drains In Basavasamithi Road In Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improements To Roads And Drains
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improements To Roads And Drains In Basavasamithi Road In Ward No 09	009-15-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/296/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/04/2015	24/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0391, W0196	NA	BASAVASAMITHI
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0391/S123815	34.75	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Girish Contractor, #227, 32 A Cross, 7Th Block, Jayanagar, Bangalore- 560082		1566633.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improements To Roads And Drains In Basavasamithi Road In Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improements To Roads And Drains
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improements To Roads And Drains In Basavasamithi Road In Ward No 09	009-15-000025
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/296/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/04/2015	24/04/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0485	NA	veerabhadraswamy temple road
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0485/S125947	141.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Girish Contractor, #227, 32 A Cross, 7Th Block, Jayanagar, Bangalore- 560082		1991711.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of concrete roads in thindlu veerabhadraswamy temple road in ward no 09	1900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Construction of concrete roads in thindlu veerabhadraswamy temple road in ward no 09	009-15-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/298/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/04/2015	24/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0310	Chikkanna Lyt 4th Crs	veerabhadraswamy temple road
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0310/S010808	159.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Girish Contractor, #227, 32 A Cross, 7Th Block, Jayanagar, Bangalore- 560082		1991711.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of concrete roads in thindlu veerabhadraswamy temple road in ward no 09	1900000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Construction of concrete roads in thindlu veerabhadraswamy temple road in ward no 09	009-15-000026
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/298/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/04/2015	24/04/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0709	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0709/S020255	139.71	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2073154.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	009-15-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/34/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0709, W0715	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0709/S020900	161.52	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2073154.00
<b>PhoneNo</b>	<b>Emailld</b>	
9886888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	009-15-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/34/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0717, W0721, W0719, W0723	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0717/S021438	188.36	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2073154.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886888882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	009-15-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/34/2015-16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0717	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0717/S022010	132.25	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2073154.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Dhanalakshmi Layout Balance roads in Ward No 09	009-15-000036
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/34/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0428	NA	SRI. M V LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0428/S022641	310.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2075140.00
<b>PhoneNo</b>	<b>EmailId</b>	
9886888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to Sri M. V. Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to Sri M. V. Layout Balance roads in Ward No 09	009-15-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/31/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0386	Doddamuniswammppa Lyt, 2nd Crs	SRI. M V LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0386/S023555	139.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2075140.00
<b>PhoneNo</b>	<b>EmailId</b>	
9884888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to Sri M. V. Layout Balance roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to Sri M. V. Layout Balance roads in Ward No 09	009-15-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/31/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0376, W0388, W0382	7th Crs Lakshmi Sagar Lyt, Doddamuniswammppa Lyt, 3rd Crs, Doddamuniswammppa Lyt, 1st Crs	ANAND LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0376/S024003	42.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2076590.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to anand layout balance roads in ward no 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to anand layout balance roads in ward no 09	009-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/38/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	20/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
24/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0372	NA	ANAND LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0372/S024908	320.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2076590.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to anand layout balance roads in ward no 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to anand layout balance roads in ward no 09	009-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/38/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0370	NA	ANAND LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0370/S025145	314.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2076590.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to anand layout balance roads in ward no 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to anand layout balance roads in ward no 09	009-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/38/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0603	NA	ANAND LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0603/S025521	56.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Bettahalasur(P), Bangalore North, Bangalore		2076590.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to anand layout balance roads in ward no 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to anand layout balance roads in ward no 09	009-15-000038
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/38/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/09/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
24/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0321, W0485, W0158	<b>StreetName</b> NA	<b>Significant LandMark</b> THINDLU VILLAGE
<b>SegmentNo</b> 9/C-W0321/S124059	<b>TotalLength</b> 96.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2091149.00
<b>Work Details</b>		
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO-09	2000000	2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO- 09	<b>Job No Work Code</b> 009-15-000028
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/297/2014- 15	<b>Work Order Date</b> 06/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 26/05/2015	<b>Defect Liability Period To</b> 25/05/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0545	NA	THINDLU VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0545/S124830	32.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75		2091149.00
<b>Work Details</b>		
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO- 09	009-15-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/297/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/05/2015	25/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0547	1st Crs	THINDLU VILLAGE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0547/S125049	26.30	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75		2091149.00
<b>Work Details</b>	<b>EmailId</b>	
<b>PhoneNo</b>		
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO- 09	009-15-000028
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/297/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/05/2015	25/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0743, W0635, W0470, W0472, W0745, W0747, W0715, W	<b>StreetName</b> 2nd Main Rd, 8th Crs, 2nd Crs, 3rd Crs, NA, 4th Crs	<b>Significant LandMark</b> Virupakshapura
<b>SegmentNo</b> 9/C-W0743/S082630	<b>TotalLength</b> 404.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SURENDRA B.T	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9880706343	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to roads at Virupakshapura and surrounding areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka	<b>Sanctioned Amount</b> 3000000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to roads at Virupakshapura and surrounding areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	<b>Job No Work Code</b> 009-16-000004
<b>Work OrderNo</b> BBMP/EE/BTP/WO/120/2016-17	<b>Work Order Date</b> 31/08/2016	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 31/08/2016	<b>Defect Liability Period To</b> 30/08/2017	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
6	JANARDHAN
Date of Inspection	Remarks
28/10/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0673	NA	Kempe gowda nagara colony
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0673/S043202	210.09	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL BANGALORE		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9449863065		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Estimate for Improvements to roads and Drains at Kempe gowda nagara colony in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zo	1442000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Estimate for Improvements to roads and Drains at Kempe gowda nagara colony in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	009-16-000055
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/BTP/WO/93/2016-17	05/08/2016	180 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
05/08/2016	01/08/2017	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	JANARDHAN
Date of Inspection	Remarks
29/10/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0316	<b>StreetName</b> Chikkanna Lyt 2nd Crs	<b>Significant LandMark</b> THINDLU VILLAGE
<b>SegmentNo</b> 9/S-W0316/S015811	<b>TotalLength</b> 100.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2091149.00
<b>Work Details</b>		
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO-09	2000000	2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO- 09	<b>Job No Work Code</b> 009-15-000028
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/297/2014- 15	<b>Work Order Date</b> 06/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 26/05/2015	<b>Defect Liability Period To</b> 25/05/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Suresh
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0539, W0529, W0527	<b>StreetName</b> NA	<b>Significant LandMark</b> THINDLU VILLAGE
<b>SegmentNo</b> 9/C-W0539/S020057	<b>TotalLength</b> 23.08	



<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2091149.00
<b>Work Details</b>		
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO-09	2000000	2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Others	<b>Other Work Type</b> IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO ROADS AND DRAINS IN THINDLU VILLAGE ROAD IN WARD NO- 09	<b>Job No Work Code</b> 009-15-000028
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/297/2014- 15	<b>Work Order Date</b> 06/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 26/05/2015	<b>Defect Liability Period To</b> 25/05/2016	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0190	NA	ICHS LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0190/S020646	203.45	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		1345686.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ICHS LAYOUT ROADS IN WARD NO-09	1300000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ICHS LAYOUT ROADS IN WARD NO- 09	009-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/72/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	complete	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0194	NA	ICHS LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0194/S021502	216.43	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		1345686.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ICHS LAYOUT ROADS IN WARD NO-09	1300000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ICHS LAYOUT ROADS IN WARD NO- 09	009-14-000006
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/72/2015- 16	06/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0229	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/S-W0229/S022054	<b>TotalLength</b> 247.31	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2597626.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Job No Work Code</b> 009-15-000021
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/322/2014- 15	<b>Work Order Date</b> 23/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 20/05/2015	<b>Defect Liability Period To</b> 19/05/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0158	NA	Thindlu GKV road
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0158/S062042	150.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Jayaprakash T		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980377722		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of cement concrete Balance roads at Thindlu and Surrounding area in ward no. 09 in Vidyaranyaपुरa sub division.	2000000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		009-16-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/BTP/WO/335/2016-17		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
1		janardhan
<b>Date of Inspection</b>	<b>Remarks</b>	
29/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0501	NA	Construction of cement concrete Balance roads at T
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0501/S063915	21.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Jayaprakash T		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980377722		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Construction of cement concrete Balance roads at Thindlu and Surrounding area in ward no. 09 in Vidyaranyaपुरa sub division.	2000000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		009-16-000019
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
BBMP/EE/BTP/WO/335/2016-17		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		janardhan
<b>Date of Inspection</b>	<b>Remarks</b>	
29/12/2016		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0056, W0058, W0062, W0159, W0070, W0066, W0074, W	<b>StreetName</b> NA, Chowdeshwari Temple Behind Rd, 60 Feet Main Rd	<b>Significant LandMark</b> Balaji Layout Main road
<b>SegmentNo</b> 9/C-W0056/S101832	<b>TotalLength</b> 287.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b> H S NATRAJ	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448474325	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to Balaji Layout Main road in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to Balaji Layout Main road in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-13-000027
<b>Work OrderNo</b> EE/BTP/BBMP/E- TND/WO/500/2013-14	<b>Work Order Date</b> 14/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 30/05/2014	<b>Defect Liability Period To</b> 29/05/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
14	
Date of Inspection	Name
29/12/2016	SURESH
	Remarks
	COMPLETED

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0237, W0118, W0069, W0241, W0130, W0261, W0128, W	<b>StreetName</b> NA	<b>Significant LandMark</b> Durga Layout Main road and Cross Roads
<b>SegmentNo</b> 9/C-W0237/S102801	<b>TotalLength</b> 698.41	

<b>ContractorDetails</b>		
<b>NameofContractor</b> H S NATARAJ	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448474325	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to Durga Layout Main road and Cross Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2013
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to Durga Layout Main road and Cross Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-13-000026
<b>Work OrderNo</b> EE/BTP/BBMP/E- TND/WO/159/2013-14	<b>Work Order Date</b> 09/10/2013	<b>Period of Extention</b> 60 DAY
<b>Defect Liability Period From</b> 30/05/2014	<b>Defect Liability Period To</b> 29/05/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
14	Name
Date of Inspection	Remarks
29/12/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0153, W0088, W0352, W0151, I0463	<b>StreetName</b> NA, Shetty Lyt, 1st Main Rd	<b>Significant LandMark</b> SRI NANDI LAYOUT
<b>SegmentNo</b> 9/C-W0153/S072605	<b>TotalLength</b> 106.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1981441.13
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Job No Work Code</b> 009-14-000038
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/449/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/03/2014	<b>Defect Liability Period To</b> 27/03/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0153, W0088, W0090, W0151	<b>StreetName</b> NA	<b>Significant LandMark</b> SRI NANDI LAYOUT
<b>SegmentNo</b> 9/C-W0153/S073200	<b>TotalLength</b> 146.86	



<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1981441.13
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Job No Work Code</b> 009-14-000038
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/449/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/03/2014	<b>Defect Liability Period To</b> 27/03/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0615	NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0615/S073656	143.78	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0629	1st Crs	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0629/S074546	182.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0294	<b>StreetName</b> NA	<b>Significant LandMark</b> HANUMAN LAYOUT
<b>SegmentNo</b> 9/S-W0294/S074156	<b>TotalLength</b> 234.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1981378.44
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ESTIMATE FOR IMPROVEMENTS AND ASPALTING TO LAKESHORE GARDEN, APC, HANUMAN LAYOUT IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> ESTIMATE FOR IMPROVEMENTS AND ASPALTING TO LAKESHORE GARDEN, APC, HANUMAN LAYOUT IN WARD NO 09	<b>Job No Work Code</b> 009-14-000043
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/454/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 29/03/2014	<b>Defect Liability Period To</b> 28/03/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0621	NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0621/S074830	27.98	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0625	Pattanduru Agrahara Rd	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0625/S075046	101.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0627	NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0627/S075304	92.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0294, W0300, W0308, W0485, W0481	<b>StreetName</b> NA, 4th Crs Lakshmi Sagar Lyt, Doddenakundi Main Rd	<b>Significant LandMark</b> HANUMAN LAYOUT
<b>SegmentNo</b> 9/C-W0294/S075440	<b>TotalLength</b> 240.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1981378.44
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> ESTIMATE FOR IMPROVEMENTS AND ASPALTING TO LAKESHORE GARDEN, APC, HANUMAN LAYOUT IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> ESTIMATE FOR IMPROVEMENTS AND ASPALTING TO LAKESHORE GARDEN, APC, HANUMAN LAYOUT IN WARD NO 09	<b>Job No Work Code</b> 009-14-000043
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/454/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0631	NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0631/S075543	84.61	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		2973022.00
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO CANARA BANK LAYOUT ROADS IN WARD NO.09	009-14-000040
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/451/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0149	NA	VAISHNAVI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0149/S075938	117.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		990587.58
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPALTING TO VAISHNAVI LAYOUT ROAD IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPALTING TO VAISHNAVI LAYOUT ROAD IN WARD NO 09	009-14-000037
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/448/2013-14	21/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0137, W0106, I0469, W0153, W0149, I0463	NA, 3rd Crs, Shetty Lyt, 1st Main Rd	VAISHNAVI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0137/S080923	56.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		1981378.44
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPALTING TO VAISHNAVI LAYOUT ROAD IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPALTING TO VAISHNAVI LAYOUT ROAD IN WARD NO 09	009-14-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/454/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0343	<b>StreetName</b> NA	<b>Significant LandMark</b> BEL LAYOUT
<b>SegmentNo</b> 9/S-W0343/S081923	<b>TotalLength</b> 230.83	



<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1783141.74
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO BALANCE BEL LAYOUT ROADS (1ST TO 5th BLOCK) IN WARD NO 09	<b>Sanctioned Amount</b> 1800000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO BALANCE BEL LAYOUT ROADS (1ST TO 5th BLOCK) IN WARD NO 09	<b>Job No Work Code</b> 009-14-000036
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/447/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 29/03/2014	<b>Defect Liability Period To</b> 28/03/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 29/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0341	<b>StreetName</b> NA	<b>Significant LandMark</b> BEL LAYOUT
<b>SegmentNo</b> 9/S-W0341/S083320	<b>TotalLength</b> 231.33	



<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1783141.74
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO BALANCE BEL LAYOUT ROADS (1ST TO 5th BLOCK) IN WARD NO 09	<b>Sanctioned Amount</b> 1800000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO BALANCE BEL LAYOUT ROADS (1ST TO 5th BLOCK) IN WARD NO 09	<b>Job No Work Code</b> 009-14-000036
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/447/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 29/03/2014	<b>Defect Liability Period To</b> 28/03/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 29/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0179	NA	NIT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0179/S114354	162.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		2028150.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	009-14-000048
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/226/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2015	27/02/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
23/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0092	<b>StreetName</b> NA	<b>Significant LandMark</b> NIT LAYOUT
<b>SegmentNo</b> 9/S-W0092/S121806	<b>TotalLength</b> 41.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97	<b>ContractorRegNo</b>	<b>Expenditure</b> 2028150.00
<b>Work Details</b>		
<b>WorkID</b> 8888888888	<b>EmailId</b>	
<b>NameOfWork</b> Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	<b>Job No Work Code</b> 009-14-000048
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/226/2014- 15	<b>Work Order Date</b> 14/01/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/02/2015	<b>Defect Liability Period To</b> 27/02/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
23/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0181	Vinayaka Lyt 3rd Crs	NIT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0181/S122152	160.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		2028150.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	009-14-000048
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/226/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2015	27/02/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
23/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0191, W0181, W0173, W0187, W0179, W0096	<b>StreetName</b> NA, Vinayaka Lyt 3rd Crs	<b>Significant LandMark</b> NIT LAYOUT
<b>SegmentNo</b> 9/C-W0191/S122445	<b>TotalLength</b> 163.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b> Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97	<b>ContractorRegNo</b>	<b>Expenditure</b> 2028150.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and asphaltting to NIT Layout 7Th, 8Th Cross And Other Roads Near Park in Ward No 09	<b>Job No Work Code</b> 009-14-000048
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/226/2014- 15	<b>Work Order Date</b> 14/01/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/02/2015	<b>Defect Liability Period To</b> 27/02/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
23/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0177	NA	HMT 5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0177/S122827	196.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		2015446.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements and asphaltting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	009-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/224/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0185	NA	HMT 5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0185/S123329	182.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		2015446.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements and asphaltting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	009-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/224/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0177, W0072, W0185	NA	HMT 5TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0177/S123702	69.96	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		2015446.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements and asphaltting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to HMT 5Th Block Roads in Ward No 09	009-14-000044
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/224/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0032	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0032/S124252	171.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		1500009.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	009-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/225/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0065	Om Shakthi Lyt 5th Crs	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0065/S124908	110.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		1500009.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	009-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/225/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0067	13th Crs	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0067/S125336	133.15	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. C. Shivaraj, Contractor, Nanjundeshwara Nilaya, Durgadevi Layout, Vidyaranyaपुरa, Bangalore- 97		1500009.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to BEL 6Th Block Roads in Ward No 09	009-14-000039
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/225/2014- 15	14/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/02/2015	25/02/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0361	Chikka Muniswammappa Lyt, 1st Crs	MES School Road
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0361/S125829	151.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2593838.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Drain and asphalting To MES School Road in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Drain and asphalting To MES School Road in Ward No 09	009-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/317/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0170	NA	MES SCHOOL ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0170/S010527	428.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2593838.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements To Drain and asphalting To MES School Road in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	Improvements To Drain and asphalting
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements To Drain and asphalting To MES School Road in Ward No 09	009-15-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/317/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0198	NA	THINDLU LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0198/S013350	323.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2593840.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	009-15-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/321/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/04/2015	19/04/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0367	NA	THINDLU LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0367/S013843	139.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2593840.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	009-15-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/321/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/04/2015	19/04/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
23/09/2015	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0365	Chikka Muniswammappa Lyt, 2nd Crs	THINDLU LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0365/S014052	142.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2593840.00
<b>PhoneNo</b>	<b>EmailId</b>	
9884885889		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	009-15-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/321/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/04/2015	19/04/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 23/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0363	R H B Colony 1st Main Rd	THINDLU LAKE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0363/S014247	153.51	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2593840.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Defence Layout And BEL Layout Main Roads And Cross Roads in Ward No 09	009-15-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/321/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/04/2015	19/04/2016	No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 23/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0243	Chowdeshwari Temple Behind Rd	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0243/S014744	123.26	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2061491.00
<b>PhoneNo</b>	<b>EmailId</b>	
9884888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Sapthagiri Layout roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Sapthagiri Layout roads in Ward No 09	009-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/320/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0253	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0253/S020131	120.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2061491.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Saphthagiri Layout roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Saphthagiri Layout roads in Ward No 09	009-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/320/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0259	Ambedkar Nagar Slum	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0259/S020512	119.19	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2061491.00
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Saphthagiri Layout roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Saphthagiri Layout roads in Ward No 09	009-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/320/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	Yes

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0242, W0267	NA, Maheshwari Nagar Ambedkar Rd	SAPTHGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0242/S022330	61.38	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. B. umesh, Contractor, #385, Bettahalasur(P), Bangalore North, Bangalore		2061491.00
<b>PhoneNo</b>	<b>EmailId</b>	
9884888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to Sapthagiri Layout roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to Sapthagiri Layout roads in Ward No 09	009-15-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/320/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/04/2015	23/04/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0083	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0083/S022815	187.07	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0071	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0071/S023749	180.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
25/05/2015	24/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0077	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0077/S024128	114.43	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphalting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0079	Om Shakthi Lyt 4th Crs	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0079/S024430	103.17	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. M Srinivasa Murthy, Contractor, #17, (Opp) Jyothi Gas Godown, 6Th Cross, Kurubarahalli, Bangalo		2075516.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and asphaltting to H M T Layout 6Th And 7Th Block roads in Ward No 09	009-15-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/319/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
15/05/2015	14/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0155, W0106, W0153, I0098, W0169, W0329, W0175, W	<b>StreetName</b> NA, Lakshmi Sagar Lyt North Side, 1st Crs	<b>Significant LandMark</b> Vaishnavi Layout and Surrounding Areas
<b>SegmentNo</b> 9/C-W0155/S022433	<b>TotalLength</b> 412.06	
<b>ContractorDetails</b>		
<b>NameofContractor</b> P VIJAY BABU	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9845025446	<b>EmailId</b>	
<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to Roads at Vaishnavi Layout and Surrounding Areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahank	<b>Sanctioned Amount</b> 3500000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to Roads at Vaishnavi Layout and Surrounding Areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zoneMODIFIED WORK ORDER	<b>Job No Work Code</b> 009-16-000008
<b>Work OrderNo</b> BBMP/ EE/BTP/WO/124/2016-17	<b>Work Order Date</b> 20/09/2016	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 26/09/2016	<b>Defect Liability Period To</b> 25/09/2017	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
9	JANARDHAN
Date of Inspection	Remarks
28/01/2017	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0019, W0009, W0017	NA	Defence layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0019/S035522	279.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
R.HARISH		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9242881054		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement to Defence layout Roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2015 - 2016	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement to Defence layout Roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-14-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/70/2015- 16	05/05/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
05/05/2015	04/05/2016	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
15	Name
Date of Inspection	Remarks
25/07/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0317, W0154, W0485, W0315, W0332, W0553, W0551, W	<b>StreetName</b> NA, R H B Colony, 4th Crs, I T P L Main Rd, Doddenakundi Industrial Rd	<b>Significant LandMark</b> Thindlu Village
<b>SegmentNo</b> 9/C-W0317/S042922	<b>TotalLength</b> 564.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B.CHANDRASHEKAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9980496926	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of Concrete roads and Asphalt in Thindlu Village in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Construction of Concrete roads and Asphalt in Thindlu Village in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-15-000009
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/51/2014- 15	<b>Work Order Date</b> 27/04/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 27/04/2015	<b>Defect Liability Period To</b> 26/04/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		SURESH
Date of Inspection	Remarks	
25/07/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0270, W0449, W0268, W0429, W0431, W0220, W0427, W	2nd A Crs, Maheshwari Nagar, 3rd Crs, NA, Shetty Lyt, 4th Main Rd, Ambedkar Nagar Slum	Anjaneya layout & Siddalingeshwara layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0270/S044822	533.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri. B. Chandrashekar, #28, Thindlu Anjaneyaswamy Layout, 1St Main, Vidyaranyaपुरa (Post),		1978351.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and Asphaltting to Anjaneya layout & Siddalingeshwara layout roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahan	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and Asphaltting to Anjaneya layout & Siddalingeshwara layout roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-15-000007
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/243/2014- 15	24/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/01/2015	23/01/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
6	Name
Date of Inspection	Remarks
25/07/2016	Completed

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0155, W0108, W0106, W0153, I0098, W0090, W0137, I	NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Shetty Lyt, 1st Main Rd, 3rd Crs	Balaji Srinidhi & Ganesh layout roads
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0155/S051218	633.97	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
B.CHANDRASHEKAR		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9980496926		

Work Details		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements and Asphaltting to Balaji Srinidhi & Ganesh layout roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements and Asphaltting to Balaji Srinidhi & Ganesh layout roads in wards no 9 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-15-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/242/2014- 15	24/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
24/01/2015	23/01/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
14	SURESH
Date of Inspection	Remarks
25/07/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaapura
<b>StreetID</b> W0231	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/S-W0231/S013943	<b>TotalLength</b> 199.54	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2597626.00

<b>WorkID</b> 8888888888	<b>EmailId</b>
-----------------------------	----------------

<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Job No Work Code</b> 009-15-000021
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/322/2014- 15	<b>Work Order Date</b> 23/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 20/05/2015	<b>Defect Liability Period To</b> 19/05/2016	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0255, W0233, W0263, W0245, W0136	<b>StreetName</b> Mahadevapura Village Rd, NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/C-W0255/S014342	<b>TotalLength</b> 204.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2597626.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Job No Work Code</b> 009-15-000021
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/322/2014- 15	<b>Work Order Date</b> 23/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 20/05/2015	<b>Defect Liability Period To</b> 19/05/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0186	NA	BEL layout 5th Block near coffee day
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0186/S014645	361.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
K.N. Prabhakar M/S P.N.R. construction, contractor, No 2, V.B. residence 1st cross 2nd stage B.H.E.I		1535889.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to BEL Layout roads in ward No 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements to BEL Layout roads in ward No 09	009-14-000009
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/335/2013-14	13/02/2014	60 days
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh devathraj
<b>Date of Inspection</b>	<b>Remarks</b>	
25/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0245	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/S-W0245/S050612	<b>TotalLength</b> 56.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2597626.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Job No Work Code</b> 009-15-000021
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/322/2014- 15	<b>Work Order Date</b> 23/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 20/05/2015	<b>Defect Liability Period To</b> 19/05/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet


<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0255	Mahadevapura Village Rd	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0255/S050921	38.33	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75		2597626.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	009-15-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/322/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
26/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0263	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0263/S051247	152.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75		2597626.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	2500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	009-15-000021
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/322/2014- 15	23/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0251	<b>StreetName</b> Maheshwaramma Temple Behind Rd	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/S-W0251/S051759	<b>TotalLength</b> 24.90	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,CONTRACTOR, #385, BETTAHALASUR (P), BANGALORE NORTH, BANGALORE-75	<b>ContractorRegNo</b>	<b>Expenditure</b> 2597626.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT MAIN ROAD AND CROSS ROADS IN WARD NO-09	<b>Job No Work Code</b> 009-15-000021
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/322/2014- 15	<b>Work Order Date</b> 23/02/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 20/05/2015	<b>Defect Liability Period To</b> 19/05/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Drain Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0446, W0671, W0481, W0450, W0444, W0294, W0483, W	<b>StreetName</b> Mani Lyt 5th Crs, NA, Doddenakundi Main Rd, Papayya Reddy Lyt, 15th Crs, Mani Lyt 4th Crs, Mani Lyt	<b>Significant LandMark</b> ACP Layout, Lakeshore Garden and Hanuman layout
<b>SegmentNo</b> 9/C-W0446/S105106	<b>TotalLength</b> 1164.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B B UMESHA	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886213563	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to Road at ACP Layout, Lakeshore Garden and Hanuman layout in ward no 09 in (Vidyaranayapura) Vidyaranayapura Sub-Divisi	<b>Sanctioned Amount</b> 3000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to Road at ACP Layout, Lakeshore Garden and Hanuman layout in ward no 09 in (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-16-000002
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/220/2015- 16	<b>Work Order Date</b> 16/02/2016	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 16/02/2016	<b>Defect Liability Period To</b> 15/02/2017	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
47		T.Janardhan
Date of Inspection	Remarks	
21/06/2016	completed	
Category	Photo	
Drain Condition		
Drain Condition		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0425, W0244	NA	Thindlu surrounding
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0425/S072539	150.16	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T. Gopinathreddy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845654827		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
construction of concrete roads in Thindlu surrounding area in ward no 09 of Vidyaranyaपुरa sub division	2500000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
		009-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/174/2015-16		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
7		madhavrao
<b>Date of Inspection</b>	<b>Remarks</b>	
06/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranya
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0328, W0495	R H B Colony, 4th Crs, Doddenakundi Industrial Rd	Thindlu vidyaranya main road
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0328/S073054	38.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T. Gopinathreddy		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9845654827		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
construction of concrete roads in Thindlu surrounding area in ward no 09 of Vidyaranya sub division	2500000	2014-15
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		009-15-000022
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/174/2015- 16		
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
		No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
2		madhvrao
<b>Date of Inspection</b>	<b>Remarks</b>	
06/02/2017		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0392	2nd Crs	Anandh Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0392/S035512	144.82	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	1958936.42	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014- 15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0585	1st Crs	Doddamuniswamappa Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0585/S044027	63.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphalting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	2000000	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement and asphalting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014- 15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0398	4th Crs	Doddamuniswamappa Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0398/S044357	86.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	2000000	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014-15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0406	NA	Doddamuniswamappa Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0406/S044654	123.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphalting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	2000000	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014- 15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0408	NA	Doddamuniswamappa Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0408/S045145	306.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	2000000	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphaltting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement and asphaltting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014- 15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0400	NA	Doddamuniswamappa Layout
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0400/S045359	50.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
Sri Madhusudhan #830,5th Block BEL Layout Vidhyaranyaपुरa Banagalore 97		1957674.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b>		
1234567891		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvement and asphalting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	2000000	2014-2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvement and asphalting to siddhi vinayaka & Sir M V Layout roads in Ward no 09	009-15-000004
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/201/2014- 15	08/01/2015	60
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
23/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0022	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0022/S051245	223.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1538931.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 1ST AND 2ND CROSS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 1ST AND 2ND CROSS IN WARD NO 09	009-14-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/338/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0016	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0016/S052129	376.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1538931.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 1ST AND 2ND CROSS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 1ST AND 2ND CROSS IN WARD NO 09	009-14-000012
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/338/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0203, W0072, W0185	NA	NTI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0203/S052409	160.08	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1025146.00
<b>WorkNo</b>	<b>EmailId</b>	
7777777777		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO NTI LAYOUT ROADS IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO NTI LAYOUT ROADS IN WARD NO 09	009-14-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/334/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0203, W0064	NA	NTI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0203/S053137	91.52	

ContractorDetails		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1025146.00
<b>WorkNo</b>	<b>EmailId</b>	
7777777777		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO NTI LAYOUT ROADS IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO NTI LAYOUT ROADS IN WARD NO 09	009-14-000008
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/334/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

Field Inspection Details		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0203	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0203/S053446	183.91	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1537718.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	009-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/337/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0060	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0060/S054941	160.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1537718.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	009-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/337/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0064, W0185	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0064/S060755	48.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1537718.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	009-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/337/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	comps	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0020	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0020/S060956	156.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1537718.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO HMT LAYOUT 6TH AND 7TH CROSS ROADS IN WARD NO 09	009-14-000011
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/337/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0537	NA	TELECOM LAYOUT MAIN ROAD
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0537/S061413	67.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		2038370.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	009-14-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/330/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0452, W0691	NA	TELECOM LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0452/S061928	121.60	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		2038370.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	009-14-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/330/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		Suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0697, W0701, W0452	NA	TELECOM LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0697/S063650	72.50	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		2038370.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	009-14-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/330/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0695, W0675, W0697, W0448	NA, Mani Lyt 6th Crs	TELECOM LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0695/S063938	228.03	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		2038370.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO TELECOM LAYOUT MAIN ROAD IN WARD NO 09	009-14-000002
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/330/2013-14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0887	NA	CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0887/S064230	67.49	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		1536030.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	009-14-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/340/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 29/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0885	<b>StreetName</b> NA	<b>Significant LandMark</b> CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT
<b>SegmentNo</b> 9/S-W0885/S065025	<b>TotalLength</b> 81.83	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 1536030.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000014
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/340/2013- 14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/02/2014	<b>Defect Liability Period To</b> 27/02/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0883	<b>StreetName</b> NA	<b>Significant LandMark</b> CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT
<b>SegmentNo</b> 9/S-W0883/S065352	<b>TotalLength</b> 98.55	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 1536030.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000014
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/340/2013- 14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/02/2014	<b>Defect Liability Period To</b> 27/02/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 29/09/2015	Remarks completed
Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0885, W0883, W0887, W0586	<b>StreetName</b> NA	<b>Significant LandMark</b> CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT
<b>SegmentNo</b> 9/C-W0885/S065703	<b>TotalLength</b> 169.39	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR	<b>ContractorRegNo</b>	<b>Expenditure</b> 1536030.00
<b>Work Details</b>		
8888888888		
<b>NameOfWork</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 1500000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS TO CHIKKA VENKATAPPA AND MUNIBYRAPPA LAYOUT ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000014
<b>Work OrderNo</b> EE/BTP/BBMP/E-PTM/340/2013- 14	<b>Work Order Date</b> 13/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 28/02/2014	<b>Defect Liability Period To</b> 27/02/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0647	1st Main Rd, Pattandur Agrah	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0647/S070222	157.77	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		1025085.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	009-14-000003
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/331/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0647, W0643	1st Main Rd, Pattandur Agrah, NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0647/S070933	50.59	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		1025085.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	009-14-000003
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/331/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0153, W0169, W0094	<b>StreetName</b> NA	<b>Significant LandMark</b> SEI NANDI LAYOUT
<b>SegmentNo</b> 9/C-W0153/S071937	<b>TotalLength</b> 102.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1981441.13
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO ROADS TO ROADS AT SRINIDHI LAYOUT AND BALAJI LAYOUT IN WARD NO 09	<b>Job No Work Code</b> 009-14-000038
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/449/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 02/03/2014	<b>Defect Liability Period To</b> 27/03/2015	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
29/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0623	NA	CANARA BANK LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0623/S072128	125.10	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		1025085.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	1000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO CANARA BANK LAYOUT MAIN ROADS IN WARD NO 09	009-14-000003
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/331/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
29/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0122	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT Layout 2nd Block 6th Cross
<b>SegmentNo</b> 9/S-W0122/S052533	<b>TotalLength</b> 302.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b> T.K.SHANKARAPPA	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9964440879	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements to drains at HMT Layout 2nd Block 6th Cross and surrounding in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements to drains at HMT Layout 2nd Block 6th Cross and surrounding in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-16-000014
<b>Work OrderNo</b> EE/BTP/BBMP/E-PET/60/2016-17	<b>Work Order Date</b> 29/06/2016	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 29/06/2016	<b>Defect Liability Period To</b> 28/06/2017	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
15		JANARDHAN
Date of Inspection	Remarks	
06/08/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0905, W0584, W0895	NA	Puttananjappa layout 5th main I F of Shiva temple
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0905/S055437	87.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
T.K.SHANKARAPPA		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9964440879		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Roads and drain at Puttananjappa layout 5th main I F of Shiva temple in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Ye	1500000	2016
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2016 - 2017	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	Improvements to Roads and drain at Puttananjappa layout 5th main I F of Shiva temple in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-16-000020
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PET/59/2016- 17	29/06/2016	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2016	28/06/2017	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	JANARDHAN
Date of Inspection	Remarks
06/08/2016	completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0244	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0244/S101124	77.46	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	2072580	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	009-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/37/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
26/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0279	Ambedkar Nagar Slum	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0279/S104552	243.19	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	2072580	
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	009-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/37/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0415	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0415/S105144	77.67	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2072580.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		


<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	009-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/37/ 2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0423	2nd Crs	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0423/S105734	93.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	009-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/37/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/06/2015	25/06/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0273	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0273/S111125	88.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2074020.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	009-15-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/33/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	28/07/2016	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0239	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0239/S111626	193.59	


<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2074020.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	009-15-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/33/2015- 16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	29/06/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0150	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0150/S112003	160.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2074020.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	009-15-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/33/2015- 16	22/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
02/07/2015	28/06/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0148, W0283, W0279	NA, Ambedkar Nagar Slum	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0148/S112443	158.97	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2074020.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 1ST. 2ND 3RD AND 4TH CROSS ROADS IN WARD NO-09	009-15-000042
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/33/2015- 16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	28/06/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0242, W0425, W0244	NA	SAPTHAGIRI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0242/S113553	100.30	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE		2000000.00
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SAPTHAGIRI LAYOUT 5TH, 6TH, 7TH AND 8TH CROSS ROADS IN WARD NO-0	009-15-000043
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/37/2015- 16	22/04/2015	
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	28/06/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0395	NA	LG ENCLAVE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0395/S112912	240.84	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		977806.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO LG ENCLAVE ROADS IN WARD NO-09	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO LG ENCLAVE ROADS IN WARD NO-09	EE/BTP/BBMP/E-PMT/199/2014- 15
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/199/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0236	2nd Main Rd	LG ENCLAVE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0236/S114213	56.74	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		977806.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO LG ENCLAVE ROADS IN WARD NO-09	1000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO LG ENCLAVE ROADS IN WARD NO-09	EE/BTP/BBMP/E-PMT/199/2014- 15
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/199/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Drain Condition	
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0226	NA	SIDDALINGESHWARA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0226/S114446	50.62	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MADHUSUDHAN, NO 830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958860.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	009-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/327/2014- 15	25/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0260	<b>StreetName</b> Ambedkar Nagar Slum	<b>Significant LandMark</b> ANJANEYA LAYOUT
<b>SegmentNo</b> 9/S-W0260/S114540	<b>TotalLength</b> 264.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE	<b>ContractorRegNo</b>	<b>Expenditure</b> 2070577.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-15-000040
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/36/2015- 16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 29/06/2015	<b>Defect Liability Period To</b> 28/06/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0232	NA	SIDDALINGESHWARA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0232/S115042	54.29	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MADHUSUDHAN, NO 830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958860.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	009-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/327/2014- 15	25/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0429	<b>StreetName</b> NA	<b>Significant LandMark</b> ANJANEYA LAYOUT
<b>SegmentNo</b> 9/S-W0429/S115121	<b>TotalLength</b> 136.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE	<b>ContractorRegNo</b>	<b>Expenditure</b> 2070577.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-15-000040
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/36/2015- 16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 29/06/2015	<b>Defect Liability Period To</b> 28/06/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0431	<b>StreetName</b> NA	<b>Significant LandMark</b> ANJANEYA LAYOUT
<b>SegmentNo</b> 9/S-W0431/S115354	<b>TotalLength</b> 132.85	



<b>ContractorDetails</b>		
<b>NameofContractor</b> SRI. B.B.UMESH,BETTAHALASU R (P), BANGALORE NORTH, BANGALORE	<b>ContractorRegNo</b>	<b>Expenditure</b> 2070577.20
<b>PhoneNo</b>	<b>EmailId</b>	
<b>Work Details</b> 8888888888		

<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO ANJANEYA LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-15-000040
<b>Work OrderNo</b> EE/BTP/BBMP/E-PMT/36/2015- 16	<b>Work Order Date</b> 22/04/2015	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 29/06/2015	<b>Defect Liability Period To</b> 28/06/2016	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed a

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0264	NA	SIDDALINGESHWARA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0264/S115419	118.24	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MADHUSUDHAN, NO 830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958860.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	009-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/327/2014- 15	25/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0427	NA	SIDDALINGESHWARA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0427/S122117	138.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MADHUSUDHAN, NO 830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958860.00
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015		
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	009-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/327/2014- 15	25/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
26/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0248	NA	SIDDALINGESHWARA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0248/S122531	386.39	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MADHUSUDHAN, NO 830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958860.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO SIDDALINGESHWARA LAYOUT BALANCE ROADS IN WARD NO-09	009-15-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/327/2014- 15	25/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
26/09/2015	completed	

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0373, W0208, W0204, W0214, W0216, W0200, W0387	East Park Reje Lyt, NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Mani Lyt 1st Main	VENKATASWAMAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0373/S122819	181.93	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SMT. SHANTHA KUMARI, NO199, 4TH CROSS, SSA ROAD, KUNTHI GRAMA, A BLOCK, C N HALLI, R T NAGARA POST,		881553.71
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROAD FROM VENKATASWAMAPPA LAYOUT TO GNANESHWARI LAYOUT MAIN ROAD IN WARD NO-09	950000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ROAD FROM VENKATASWAMAPPA LAYOUT TO GNANESHWARI LAYOUT MAIN ROAD IN WARD NO-09	009-11-000059
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/08 (16723)/WO/17/2014-15	06/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	28/06/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0407, W0409, W0220	Mani Lyt 2nd Main Rd, NA	VENKATASWAMAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0407/S123916	137.67	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SMT. SHANTHA KUMARI, NO199, 4TH CROSS, SSA ROAD, KUNTHI GRAMA, A BLOCK, C N HALLI, R T NAGARA POST,		881553.71
<b>Work Details</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROAD FROM VENKATASWAMAPPA LAYOUT TO GNANESHWARI LAYOUT MAIN ROAD IN WARD NO-09	950000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ROAD FROM VENKATASWAMAPPA LAYOUT TO GNANESHWARI LAYOUT MAIN ROAD IN WARD NO-09	009-11-000059
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/08 (16723)/WO/17/2014-15	06/04/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/06/2015	28/06/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
	Suresh
Date of Inspection	Remarks
28/09/2015	completed

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0480	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0480/S011055	162.66	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958066.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	009-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/202/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
28/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0478	NA	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0478/S011448	160.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958066.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender		009-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/202/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0474	4th Crs	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0474/S011627	168.01	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958066.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	009-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/202/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0468	1st Crs	DHANALAKSHMI LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0468/S011808	190.21	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1958066.00
<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO DHANALAKSHMI LAYOUT ROADS IN WARD NO-09	009-15-000005
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/202/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0030	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0030/S014920	213.04	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1467952.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-15-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/203/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0028	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0028/S015358	104.42	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1467952.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-15-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/203/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0057	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0057/S015631	227.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. MURUDHARAN R, CONTRACTOR, #830, 5TH BLOCK, BEL LAYOUT, VIDYARANYAPURA, BANGALORE-97		1467952.00
<b>Work Details</b>		
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO BEL 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-15-000014
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/203/2014- 15	08/01/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
20/05/2015	19/05/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0171	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0171/S020137	53.32	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. SHIVANNA, CONTRACTOR, #182, 4TH MAIN, S RAMAIAH ENCLAVE, HESARAGATTA MAIN ROAD, BANGALORE- 75		20092817.00
<b>Work Details</b>		
<b>PhoneNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO ROADS AND DRAINS IN GANESHA TEMPLE ROAD IN WARD NO- 09	2000000	2015
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Others	IMPROVEMENTS TO ROADS AND DRAINS
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO ROADS AND DRAINS IN GANESHA TEMPLE ROAD IN WARD NO-09	009-15-000027
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/295/2014- 15	06/02/2015	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
26/05/2015	25/05/2016	No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Segment End



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0340	Mariyappa Lyt	BULLET KRISHNAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0340/S021145	200.18	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. H S NATRAJ, CONTRACTOR, #505, 54TH CROSS, 3RD BLOCK, RAJAJINAGAR, BANGALORE-10		1572001.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	009-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/153/2013- 14	09/10/2013	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/11/2013	29/11/2014	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0541	NA	BULLET KRISHNAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0541/S021821	127.35	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. H S NATRAJ, CONTRACTOR, #505, 54TH CROSS, 3RD BLOCK, RAJAJINAGAR, BANGALORE-10		1572001.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	009-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/153/2013- 14	09/10/2013	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/11/2013	29/11/2014	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0543	NA	BULLET KRISHNAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0543/S023355	125.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. H S NATRAJ, CONTRACTOR, #505, 54TH CROSS, 3RD BLOCK, RAJAJINAGAR, BANGALORE-10		1572001.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	009-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/153/2013- 14	09/10/2013	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/11/2013	29/11/2014	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0332, W0549	NA	BULLET KRISHNAPPA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0332/S023823	74.20	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI. H S NATRAJ, CONTRACTOR, #505, 54TH CROSS, 3RD BLOCK, RAJAJINAGAR, BANGALORE-10		1572001.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	1500000	2013
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS BULLET KRISHNAPPA LAYOUT MAIN ROAD IN WARD NO-09	009-13-000032
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PTM/153/2013- 14	09/10/2013	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/11/2013	29/11/2014	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0073	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0073/S034036	174.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE,B.H.E.L LAYOUT, RAJARA		1539517.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/336/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0233, W0132, W0142, W0136	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/C-W0233/S033903	<b>TotalLength</b> 91.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,	<b>ContractorRegNo</b>	<b>Expenditure</b> 1998395.80
<b>PhoneNo</b> 0836888882	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000056
<b>Work OrderNo</b> EE/BTP/BBMP/KRIDL/VO/33/20 14-15	<b>Work Order Date</b> 03/07/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 30/08/2014	<b>Defect Liability Period To</b> 29/08/2015	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 26/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0075	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0075/S034919	120.26	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE,B.H.E.L LAYOUT, RAJARA		1539517.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/336/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0233, W0142, W0235	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0233/S034946	28.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		1998395.80
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	009-14-000056
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/KRIDL/VO/33/20 14-15	03/07/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/08/2014	29/08/2015	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0085, W0073, W0075, W0069	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0085/S035134	92.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE,B.H.E.L LAYOUT, RAJARA		1539517.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/336/2013-14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0148, W0152, W0142, W0235	<b>StreetName</b> NA	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/C-W0148/S035344	<b>TotalLength</b> 199.06	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,	<b>ContractorRegNo</b>	<b>Expenditure</b> 1998395.80
<b>PhoneNo</b> 9886888882	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b>	<b>WorkDetails</b> IMPROVEMENTS AND ASPALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000056
<b>Work OrderNo</b> EE/BTP/BBMP/KRIDL/VO/33/20 14-15	<b>Work Order Date</b> 03/07/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 30/08/2014	<b>Defect Liability Period To</b> 29/08/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0085, W0069, W0028	NA	BEL 6TH BLOCK
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0085/S035421	109.56	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE,B.H.E.L LAYOUT, RAJARA		1539517.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO BEL LAYOUT 6TH BLOCK BALANCE ROADS IN WARD NO-09	009-14-000010
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/336/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
27/03/2014	26/03/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0152, W0239, W0235	NA	HMT LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0152/S035703	36.30	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		1998395.80
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	009-14-000056
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/KRIDL/VO/33/20 14-15	03/07/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/08/2014	29/08/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0152, W0106, W0242, W0387, W0239	<b>StreetName</b> NA, Mani Lyt 1st Main Rd	<b>Significant LandMark</b> HMT LAYOUT
<b>SegmentNo</b> 9/C-W0152/S040024	<b>TotalLength</b> 41.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,	<b>ContractorRegNo</b>	<b>Expenditure</b> 1998395.80
<b>PhoneNo</b> 9846888882	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO HMT LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000056
<b>Work OrderNo</b> EE/BTP/BBMP/KRIDL/VO/33/20 14-15	<b>Work Order Date</b> 03/07/2014	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 30/08/2014	<b>Defect Liability Period To</b> 29/08/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
26/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0582	NA	VIDYARANYAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0582/S035810	62.75	




<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		997067.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	950000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	009-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/342/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0580	Whitefield Rd	VIDYARANYAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0580/S040404	91.51	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		997067.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	950000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	009-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/342/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0578	NA	VIDYARANYAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0578/S041950	95.81	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		997067.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	950000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	009-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/342/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0375, W0222, W0230, W0218, W0389, W0387	<b>StreetName</b> 6th Crs, Muthkurappa Lyt, NA, V S T Opposite, 4th Crs, Mani Lyt 1st Main Rd	<b>Significant LandMark</b> NANJAPPA CIRCLE
<b>SegmentNo</b> 9/C-W0375/S041425	<b>TotalLength</b> 251.68	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,	<b>ContractorRegNo</b>	<b>Expenditure</b> 3999768.00
<b>PhoneNo</b> 9998888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO ROAD FROM NANJAPPA CIRCLE DWARAKA CHOWLTRY TO SAPTAGIRI LAYOUT (KEB OFFICE) IN ROAD IN WARD NO.09	<b>Sanctioned Amount</b> 4000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO ROAD FROM NANJAPPA CIRCLE DWARAKA CHOWLTRY TO SAPTAGIRI LAYOUT (KEB OFFICE) IN ROAD IN WARD NO.09	<b>Job No Work Code</b> 009-14-000032
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/444/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 30/08/2014	<b>Defect Liability Period To</b> 29/08/2015	<b>Multiple Road Involved</b> No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 28/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0873, W0879, W0574, I0194	Renuka Lyt, NA	VIDYARANYAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0873/S042157	49.85	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		997067.00
<b>WorkID</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	950000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	009-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/342/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	Yes

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0905, I0194, W0584	NA	VIDYARANYAPURA
<b>SegmentNo</b>	<b>TotalLength</b>	
9/C-W0905/S042445	203.14	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA, M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJAR		997067.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	950000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO VIDYARANYAPURA AREA ROADS IN WARD NO 09	009-14-000024
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/342/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
26/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0869	NA	RENUKA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0869/S043656	325.13	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1542066.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	009-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/339/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2015	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0695	NA	KEMPEGOWDA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0695/S044001	166.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2971234.00
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	009-14-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/452/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaapura
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0867	NA	RENUKA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0867/S044437	116.72	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1542066.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	009-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/339/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0697, W0452, W0691, W0699	<b>StreetName</b> NA	<b>Significant LandMark</b> KEMPEGOWDA NAGAR
<b>SegmentNo</b> 9/C-W0697/S044825	<b>TotalLength</b> 49.19	



<b>ContractorDetails</b>		
<b>NameofContractor</b> KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,	<b>ContractorRegNo</b>	<b>Expenditure</b> 2971234.00
<b>PhoneNo</b> 0836888882	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	<b>Sanctioned Amount</b> 3000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2013 - 2014	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	<b>Job No Work Code</b> 009-14-000041
<b>Work OrderNo</b> EE/BTP/KRIDL/WO/452/2013-14	<b>Work Order Date</b> 21/02/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 28/02/2014	<b>Defect Liability Period To</b> 27/02/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
28/09/2015	completed

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0871	NA	RENUKA TEMPLE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0871/S044851	198.12	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
SRI.K.N.PRABHAKARA,M/s. P.N.R. CONSTRUCTION CONTRACTOR, 1st CROSS, 2nd STAGE, B.H.E.L LAYOUT, RAJARA		1542066.00
<b>WorkNo</b>	<b>EmailId</b>	
8888888888		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	1500000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Road	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS TO RENUKAMBA TEMPLE ROADS IN WARD NO 09	009-14-000013
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/E-PMT/339/2013- 14	13/02/2014	60 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
30/05/2014	29/05/2015	No

<b>Field Inspection Details</b>		
<b>Number of Trees</b>	<b>Other Information</b>	<b>Name</b>
0		suresh
<b>Date of Inspection</b>	<b>Remarks</b>	
28/09/2015	completed	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Category	Photo
Road Condition	
Segment End	
Segment Start	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0697	NA	KEMPEGOWDA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0697/S045109	39.02	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2971234.00
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	009-14-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/452/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0691	NA	KEMPEGOWDA NAGAR
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0691/S045440	174.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2971234.00
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Tender	IMPROVEMENTS AND ASPHALTING TO ROAD FROM TENNIS VILLAGE TO KEMPEGOWDA MAIN ROAD IN WARD NO.09	009-14-000041
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/452/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
28/02/2014	27/02/2015	No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	Name
Date of Inspection	Remarks
28/09/2015	completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0120, W0122, W0233, W0118, W0227, W0069	<b>StreetName</b> NA	<b>Significant LandMark</b> BEL LAYOUT
<b>SegmentNo</b> 9/C-W0120/S045414	<b>TotalLength</b> 305.47	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 1698799.00
<b>PhoneNo</b> 8888888888	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> IMPROVEMENTS AND ASPHALTING TO BEL LAYOUT AND NTI LAYOUT BALANCE ROADS IN WARD NO 09	<b>Sanctioned Amount</b> 1700000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Road	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> IMPROVEMENTS AND ASPHALTING TO BEL LAYOUT AND NTI LAYOUT BALANCE ROADS IN WARD NO 09	<b>Job No Work Code</b> 009-14-000057
<b>Work OrderNo</b> EE/BTP/BBMP/KRIDL/WO/34/20 14-15	<b>Work Order Date</b> 03/07/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 30/08/2014	<b>Defect Liability Period To</b> 29/08/2015	<b>Multiple Road Involved</b> No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0467	4th Crs	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0467/S051022	44.64	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
21/02/2014	20/02/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	

Category	Photo
Road Condition	
Segment End	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0459	Shetty Lyt, 2nd Main Rd	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0459/S052124	44.44	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>EmailId</b>	
9988888888		
<b>Work Details</b>		

<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	
Category	Photo	
Road Condition		
Segment End		



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0439	NA	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0439/S052629	64.87	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0437	NA	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0437/S053612	219.88	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>Emailld</b>	
9884889882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
22/03/2014	28/03/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 28/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0441	NA	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0441/S054233	43.05	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>EmailId</b>	
9884889882		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		suresh
Date of Inspection	Remarks	
28/09/2015	completed	

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0080	NA	VEERANNA LAYOUT
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0080/S055142	227.94	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KARNATAKA RURAL INFRASTRUCTURE DEVELOPMENT LIMITED,		2972079.93
<b>PhoneNo</b>	<b>EmailId</b>	
0088888888		
<b>Work Details</b>		


<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	3000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2013 - 2014	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	IMPROVEMENTS AND ASPHALTING TO ROAD VEERANNA AND SADASHIVAPPA LAYOUT ROADS IN WARD NO.09	009-14-000049
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/KRIDL/WO/459/2013-14	21/02/2014	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
29/03/2014	28/03/2015	No





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees 0	Other Information Name suresh
Date of Inspection 28/09/2015	Remarks completed

Category	Photo
Road Condition	
Segment End	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b>	<b>WardNo</b>	<b>WardName</b>
YELAHANKA	9	Vidyaranyaपुरa
<b>StreetID</b>	<b>StreetName</b>	<b>Significant LandMark</b>
W0242	NA	THINDLU CIRCLE
<b>SegmentNo</b>	<b>TotalLength</b>	
9/S-W0242/S081721	291.22	

<b>ContractorDetails</b>		
<b>NameofContractor</b>	<b>ContractorRegNo</b>	<b>Expenditure</b>
KRIDL		0.00
<b>PhoneNo</b>	<b>EmailId</b>	
9900377845		

<b>Work Details</b>		
<b>NameOfWork</b>	<b>Sanctioned Amount</b>	<b>Sanctioned Year</b>
Improvements to Footpath in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	2000000	2014
<b>Year</b>	<b>Type of Work</b>	<b>Other Work Type</b>
2014 - 2015	Asphalting	
<b>Tender</b>	<b>WorkDetails</b>	<b>Job No Work Code</b>
Not a Tender	Improvements to Footpath in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-14-000069
<b>Work OrderNo</b>	<b>Work Order Date</b>	<b>Period of Extention</b>
EE/BTP/BBMP/KRIDL/WO/79/2014-15	14/08/2015	90 DAYS
<b>Defect Liability Period From</b>	<b>Defect Liability Period To</b>	<b>Multiple Road Involved</b>
14/08/2015	13/08/2016	Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
2	SURESH
Date of Inspection	Remarks
24/08/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaapura
<b>StreetID</b> W0332, W0553, W0551, W0549, W0543, W0541	<b>StreetName</b> NA	<b>Significant LandMark</b> THINDLU ROAD
<b>SegmentNo</b> 9/C-W0332/S082841	<b>TotalLength</b> 336.70	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9900377845	<b>EmailId</b>	



<b>Work Details</b>		
<b>NameOfWork</b> Improvements to Roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 2000000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> Improvements to Roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-14-000061
<b>Work OrderNo</b> EE/BTP/BBMP/KRIDL/WO/83/20 14-15	<b>Work Order Date</b> 14/08/2014	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 14/08/2014	<b>Defect Liability Period To</b> 13/08/2015	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
4	Name
Date of Inspection	Remarks
24/08/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaapura
<b>StreetID</b> W0011, W0012, W0047, W0014, W0045, W0043	<b>StreetName</b> NA	<b>Significant LandMark</b> Narsipura
<b>SegmentNo</b> 9/C-W0011/S110326	<b>TotalLength</b> 64.34	

<b>ContractorDetails</b>		
<b>NameofContractor</b> SHARATH .S	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9538768015	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Construction of cement concreted narrow roads at Narsipura in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 1000000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Construction of cement concreted narrow roads at Narsipura in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-16-000018
<b>Work OrderNo</b> EE/BTP/BBMP/E- PMT/WO/302/2015-16	<b>Work Order Date</b> 23/03/2016	<b>Period of Extention</b> 90DAYS
<b>Defect Liability Period From</b> 22/03/2016	<b>Defect Liability Period To</b> 22/03/2017	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	JANARDHAN
Date of Inspection	Remarks
01/09/2016	COMPLETED

Category	Photo
Road Condition	
Road Condition	





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0426, W0579, W0601, W0430, W0362, W0428, W0344, W	<b>StreetName</b> Gosale Rd, 5th Crs, NA, Nagappa Lyt, 2nd Crs, Sathya Lyt, Mariyappa Lyt	<b>Significant LandMark</b> virupakshapura and sir mv layout
<b>SegmentNo</b> 9/C-W0426/S111047	<b>TotalLength</b> 867.63	


<b>ContractorDetails</b>		
<b>NameofContractor</b> ASWATHNARAYANA	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9448034435	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and asphalting to virupakshapura and sir mv layout main road and cross roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Divisi	<b>Sanctioned Amount</b> 2500000	<b>Sanctioned Year</b> 2014
<b>Year</b> 2014 - 2015	<b>Type of Work</b> Asphalting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and asphalting to virupakshapura and sir mv layout main road and cross roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-15-000023
<b>Work OrderNo</b> EE/BTP/BBMP/E- PMT/WO/293/2014-15	<b>Work Order Date</b> 05/02/2015	<b>Period of Extention</b> 60DAYS
<b>Defect Liability Period From</b> 05/02/2015	<b>Defect Liability Period To</b> 04/02/2016	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
15		SURESH
Date of Inspection	Remarks	
01/09/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0665, W0436, W0663, W0659, W0657, W0633, W0639, W	<b>StreetName</b> NA, Mani Lyt 1st Crs, 1st Main Rd, Pattandur Agrah, 5th Crs, 8th Crs, 6th Crs Gramatana, Narayanaswa	<b>Significant LandMark</b> canara bank layout
<b>SegmentNo</b> 9/C-W0665/S084855	<b>TotalLength</b> 63.53	

<b>ContractorDetails</b>		
<b>NameofContractor</b> B B UMESHA	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9886213563	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to roads at canara bank layout in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 4900000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to roads at canara bank layout in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-16-000001
<b>Work OrderNo</b> BBMP/EE/BTP/WO/104/2016-17	<b>Work Order Date</b> 09/08/2016	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 09/08/2016	<b>Defect Liability Period To</b> 08/08/2017	<b>Multiple Road Involved</b> Yes



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
0		JANARDHAN
Date of Inspection	Remarks	
14/09/2016	COMPLETED	

Category	Photo
Road Condition	
Road Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0881, W0576, W0917, W0915, W0919, W0913, W0602, W	<b>StreetName</b> NA, 1st Crs, 1st Main Rd	<b>Significant LandMark</b> Deshaband nagar and Surrounding Roads
<b>SegmentNo</b> 9/C-W0881/S090728	<b>TotalLength</b> 475.92	

<b>ContractorDetails</b>		
<b>NameofContractor</b> M SRIVIVASA MURTHY	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9845132243	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to roads drains and construction of culverts at Deshaband nagar puttanjinappa layout & Krishna temple area in Ward no 09 (	<b>Sanctioned Amount</b> 4500000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to roads drains and construction of culverts at Deshaband nagar puttanjinappa layout & Krishna temple area in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	<b>Job No Work Code</b> 009-16-000009
<b>Work OrderNo</b> BBMP/EE/BTP/WO/105/2016-17	<b>Work Order Date</b> 18/08/2016	<b>Period of Extention</b> 60 DAYS
<b>Defect Liability Period From</b> 18/08/2016	<b>Defect Liability Period To</b> 17/08/2017	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
0	JANARDHAN
Date of Inspection	Remarks
14/09/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0579, W0418, W0370, W0577, W0583, W0591, W0595	<b>StreetName</b> 5th Crs, 7th Crs Gramatana, NA, 3rd Crs	<b>Significant LandMark</b> Sri M V LAYOUT 5TH Cross
<b>SegmentNo</b> 9/C-W0579/S095012	<b>TotalLength</b> 271.57	

<b>ContractorDetails</b>		
<b>NameofContractor</b> R.MADHUSUDHAN	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9019996726	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to Sri M V LAYOUT 5TH Cross and other Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka zone	<b>Sanctioned Amount</b> 100000	<b>Sanctioned Year</b> 2015
<b>Year</b> 2015 - 2016	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to Sri M V LAYOUT 5TH Cross and other Roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	<b>Job No Work Code</b> 009-16-000016
<b>Work OrderNo</b> BBMP/EE/BTP/WO/343/2015-16	<b>Work Order Date</b> 30/03/2016	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 30/03/2016	<b>Defect Liability Period To</b> 29/03/2017	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
12	
Date of Inspection	Name
10/12/2016	MADHAVA RAO
	Remarks
	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Drain Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0438, W0469, W0444, W0461, W0294, W0479, W0471, W	<b>StreetName</b> Mani Lyt 2nd Crs, 3rd Crs, Mani Lyt 4th Crs, NA, 1st Crs, Doddenakundi Main Rd	<b>Significant LandMark</b> Anjaneya Swamy layout balance roads
<b>SegmentNo</b> 9/C-W0438/S100220	<b>TotalLength</b> 925.48	

<b>ContractorDetails</b>		
<b>NameofContractor</b> R.MADHUSUDHAN	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9019996726	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to road at Anjaneya Swamy layout balance roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub- Division Yelahanka z	<b>Sanctioned Amount</b> 3000000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Tender	<b>WorkDetails</b> Improvements and Asphaltting to road at Anjaneya Swamy layout balance roads in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	<b>Job No Work Code</b> 009-16-000003
<b>Work OrderNo</b> BBMP/EE/BTP/WO/126/2016-17	<b>Work Order Date</b> 21/09/2016	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 21/09/2016	<b>Defect Liability Period To</b> 20/09/2017	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details	
Number of Trees	Other Information
15	JANARDHAN
Date of Inspection	Remarks
10/12/2016	COMPLETED

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Drain Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

<b>Zone</b> YELAHANKA	<b>WardNo</b> 9	<b>WardName</b> Vidyaranyaपुरa
<b>StreetID</b> W0531, W0292	<b>StreetName</b> NA, 3rd Crs Lakshmi Sagar Lyt	<b>Significant LandMark</b> Veeranna layout & thindul surroundings
<b>SegmentNo</b> 9/S-W0531/S100930	<b>TotalLength</b> 144.89	

<b>ContractorDetails</b>		
<b>NameofContractor</b> KRIDL BANGALORE	<b>ContractorRegNo</b>	<b>Expenditure</b> 0.00
<b>PhoneNo</b> 9449863065	<b>EmailId</b>	

<b>Work Details</b>		
<b>NameOfWork</b> Improvements and Asphaltting to Veeranna layout Goutam book store road and thindul surroundings in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-	<b>Sanctioned Amount</b> 100000	<b>Sanctioned Year</b> 2016
<b>Year</b> 2016 - 2017	<b>Type of Work</b> Asphaltting	<b>Other Work Type</b>
<b>Tender</b> Not a Tender	<b>WorkDetails</b> Improvements and Asphaltting to Veeranna layout Goutam book store road and thindul surroundings in ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	<b>Job No Work Code</b> 009-16-000031
<b>Work OrderNo</b> BBMP/EE/BTP/WO/67/2016-17	<b>Work Order Date</b> 11/07/2016	<b>Period of Extention</b> 90 DAYS
<b>Defect Liability Period From</b> 11/07/2016	<b>Defect Liability Period To</b> 10/07/2017	<b>Multiple Road Involved</b> Yes





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Field Inspection Details		
Number of Trees	Other Information	Name
12		MADHAVA RAO
Date of Inspection	Remarks	
10/12/2016	COMPLETED	

Category	Photo
Drain Condition	
Drain Condition	



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition

