



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                   |                    |                             |
|-------------------|--------------------|-----------------------------|
| <b>Zone</b>       | <b>WardNo</b>      | <b>WardName</b>             |
| WEST              | 99                 | Rajajinagar                 |
| <b>StreetID</b>   | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0111             | 12th Main Rd       | RTO                         |
| <b>SegmentNo</b>  | <b>TotalLength</b> |                             |
| 99/S-W0111/S11977 | 981.00             |                             |

| ContractorDetails       |                        |                    |
|-------------------------|------------------------|--------------------|
| <b>NameofContractor</b> | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| kridl                   | 2222                   | 3700000.00         |
| <b>PhoneNo</b>          | <b>EmailId</b>         |                    |
|                         |                        |                    |

| Work Details                                  |                                   |                               |
|---|-----------------------------------|-------------------------------|
| <b>NameOfWork</b>                             | <b>Sanctioned Amount</b>          | <b>Sanctioned Year</b>        |
| Improvement to drains and footpath at 12 main | 4000000                           | 2010-2011                     |
| <b>Year</b>                                   | <b>Type of Work</b>               | <b>Other Work Type</b>        |
| 2012 - 2013                                   | Footpath Layering                 |                               |
| <b>Tender</b>                                 | <b>WorkDetails</b>                | <b>Job No Work Code</b>       |
| Not a Tender                                  |                                   | 099-11-000036                 |
| <b>Work OrderNo</b>                           | <b>Work Order Date</b>            | <b>Period of Extention</b>    |
| 2222  | 01/01/2011                        | 90                            |
| <b>Defect Liability Period From</b>           | <b>Defect Liability Period To</b> | <b>Multiple Road Involved</b> |
| 01/06/2012                                    | 01/06/2014                        | No                            |

| Field Inspection Details  |                          |              |
|---------------------------|--------------------------|--------------|
| <b>Number of Trees</b>    | <b>Other Information</b> | <b>Name</b>  |
| 0                         |                          | H shivakumar |
| <b>Date of Inspection</b> | <b>Remarks</b>           |              |
| 09/12/2015                | completed                |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Segment End     |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet



|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0166, W0007, W0051,<br>W0133, W0131, W0013,<br>W0121, W | 41st Crs, 11th Main Rd, 42nd<br>Crs 4th Block Rajajinagara,<br>3rd Main Rd, NA, 10th Main<br>Rd 41st Crs Raja | Andhra bank                 |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0166/S015254                                       | 390.90  |                             |

|                               |                        |                    |
|-------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>      |                        |                    |
| <b>NameofContractor</b>       | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavnagar<br>bangalore |                        | 2893445.00         |
| <b>PhoneNo</b>                | <b>EmailId</b>         |                    |
| 1234567890                    |                        |                    |

|   |  |                               |
|---|--|-------------------------------|
| <b>Work Details</b>   |  |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drain<br>andfootpath at 41st crossfrom<br>W.O.C.road to dr.Rajkumar<br>road, 2nd block,Rajajinagar in<br>ward no-99 | 3000000  | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012   | Others   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender  | Improvements to drain<br>andfootpath at 41st crossfrom<br>W.O.C.road to dr.Rajkumar road,<br>2nd block,Rajajinagar in ward no-<br>99 | 099-11-000036                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/197/2011-12  | 04/11/2011   | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 06/11/2011  | 05/02/2012   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |  |         |
|--------------------------|--|---------|
| Number of Trees          | Other Information  | Name    |
| 10                       |  | Farjana |
| Date of Inspection       | Remarks  |         |
| 18/12/2014               | complete   |         |
| Category                 | Photo  |         |
| Drain Condition          |   |         |
| Drain Condition          |  |         |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |  |
|--|---|--|
| <b>Zone</b><br>WEST  | <b>WardNo</b><br>99   | <b>WardName</b><br>Rajajinagar                     |
| <b>StreetID</b><br>W0108, W0109, W0092,<br>W0094, W0111, W0096 | <b>StreetName</b><br>35th Crs, 17th Main Rd, 21st<br>Crs, 22nd Crs, 12th Main Rd,<br>36th Crs | <b>Significant LandMark</b><br>State bank of india |
| <b>SegmentNo</b><br>99/C-W0108/S112620                         | <b>TotalLength</b><br>268.60  |  |

|  |                        |                                  |
|--|------------------------|----------------------------------|
| <b>ContractorDetails</b>                                   |                        |                                  |
| <b>NameofContractor</b><br>KRIDL Madavanagara<br>Bangalore | <b>ContractorRegNo</b> | <b>Expenditure</b><br>4205411.00 |
| <b>PhoneNo</b><br>1234567890                               | <b>EmailId</b>         |                                  |

|  |   |  |
|--|---|--|
| <b>Work Details</b>  |   |  |
| <b>NameOfWork</b><br>Improvements to drains and<br>foot path at 12th main road,2nd<br>block, Rajajinagar in ward no-<br>99 | <b>Sanctioned Amount</b><br>4500000   | <b>Sanctioned Year</b><br>2011           |
| <b>Year</b><br>2011 - 2012   | <b>Type of Work</b><br>Others   | <b>Other Work Type</b>                   |
| <b>Tender</b><br>Not a Tender  | <b>WorkDetails</b><br>Improvements to drains and foot<br>path at 12th main road,2nd block,<br>Rajajinagar in ward no-99 | <b>Job No Work Code</b><br>099-11-000033 |
| <b>Work OrderNo</b><br>EE/RNR/WO NO/193/11-12  | <b>Work Order Date</b><br>04/11/2011  | <b>Period of Extention</b><br>90days     |
| <b>Defect Liability Period From</b><br>06/11/2011  | <b>Defect Liability<br/>Period To</b><br>05/03/2012   | <b>Multiple Road Involved</b><br>No      |

|   |                          |                             |
|---|--------------------------|-----------------------------|
| <b>Field Inspection Details</b>         |                          |                             |
| <b>Number of Trees</b><br>0             | <b>Other Information</b> | <b>Name</b><br>H shivakumar |
| <b>Date of Inspection</b><br>09/12/2015 | <b>Remarks</b>           |                             |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Segment End    |       |
| Segment Start  |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                                   |                             |
|---------------------|-----------------------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>                     | <b>WardName</b>             |
| WEST                | 99                                | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>                 | <b>Significant LandMark</b> |
| W0046, W0079, W0048 | 1st Main Rd, 5th Crs, 2nd Main Rd | Ganesh temple               |
| <b>SegmentNo</b>    | <b>TotalLength</b>                |                             |
| 99/C-W0046/S113945  | 260.98                            |                             |

|                             |                        |                    |
|-----------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>    |                        |                    |
| <b>NameofContractor</b>     | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar Bangalore |                        | 987947.00          |
| <b>PhoneNo</b>              | <b>EmailId</b>         |                    |
| 1234567890                  |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains andCulverts aat1st and 2nd phase Manjunathnagar from WOC service road to dead end road in ward no-99 | 1000000   | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Not a Tender  | Improvements to drains andCulverts aat1st and 2nd phase Manjunathnagar from WOC service road to dead end road in ward no-99 | 099-12-000054                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/226/12-13  | 22/12/2012  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 23/12/2012  | 22/02/2013  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
|                          | H shivakumar      |
| Date of Inspection       | Remarks           |
| 09/12/2015               | completed         |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Segment End     |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0108, W0066, W0138,<br>M0093, W0128, W0064,<br>W0130, W | 35th Crs, 34th A Crs, Dr<br>Rajkumar Rd (link Rd), 32nd<br>Crs, 7th Crs, 33rd Crs, 34th<br>Crs, 10th Main Rd, | Andhra bank                 |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0108/S120323                                       | 699.94  |                             |

|                                |                        |                    |
|--------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>       |                        |                    |
| <b>NameofContractor</b>        | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar<br>Bangalore |                        | 4170032.00         |
| <b>PhoneNo</b>                 | <b>EmailId</b>         |                    |
| 1234567890                     |                        |                    |

|  |   |                               |
|--|---|-------------------------------|
| <b>Work Details</b>  |   |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>foot path at Dr; Rajakumar<br>road,2nd block, Rajajinagar in<br>ward no-99 | 4500000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Not a Tender   | Improvements to drains and foot<br>path at Dr; Rajakumar road,2nd<br>block, Rajajinagar in ward no-99 | 099-12-000038                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/191/11-12   | 04/11/2011  | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 06/11/2011   | 05/03/2012  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        |                   |
| Date of Inspection       | Name              |
| 09/12/2015               | H shivakumar      |
|                          | Remarks           |
|                          | completed         |

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0124, W0116, W0122,<br>W0098, W0106, W0100,<br>W0114, W | 31st Crs, NA, 30th Crs, 23rd<br>Crs, 26th Crs, 24th Crs, 28th<br>Crs, 27th Crs, 21st Crs, 29th<br>Crs, 22nd C | City hospital               |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0124/S010354                                       | 437.72  |                             |

|                                 |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>        |                        |                    |
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL madavanagara<br>bangalore |                        | 3788083.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

|  |   |                               |
|--|---|-------------------------------|
| <b>Work Details</b>  |   |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvents to drains and foot<br>path at 19th main road dr modi<br>road to 32nd cross 2nd block<br>Rajajinagar in ward no-99 | 4000000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012  | Others  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender   | Improvents to drains and foot<br>path at 19th main road dr modi<br>road to 32nd cross 2nd block<br>Improvents to drains and foot<br>path at 19th main road dr modi<br>road to 32nd cross 2nd block<br>Rajajinagar in ward no-99 | 099-11-000035                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/196/2011-12   | 04/11/2011  | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 06/11/2011   | 05/03/2012  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
| Date of Inspection       | Remarks           |
| 09/12/2015               | completed         |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0166, W0241, W0152,<br>W0134, W0107, W0111,<br>W0126, W | 41st Crs, 17th Main Rd, NA,<br>12th Main Rd, 32nd Crs, 12th<br>Main 3rd Block Rajaji Nagar,<br>11th Main Rd | E.S.I Hospital              |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0166/S012433                                       | 651.99  |                             |

| ContractorDetails               |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL madavanagara<br>bangalore |                        | 4817606.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

| Work Details  |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>footpath at 17th main road 2nd<br>block Rajajinagar | 5000000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Others  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | improvements to drains and<br>footpath at 17th main road 2nd<br>block Rajajinagar Bangalore | 099-11-000034                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/195/2011-12  | 04/11/2011  | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 06/11/2011  | 05/03/2012  | Yes                           |

| Field Inspection Details  |                          |             |
|---------------------------|--------------------------|-------------|
| <b>Number of Trees</b>    | <b>Other Information</b> | <b>Name</b> |
| 4                         |                          | Farjana.M   |
| <b>Date of Inspection</b> | <b>Remarks</b>           |             |
| 18/12/2014                | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Footpath Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                                     |                             |
|----------------------------|-------------------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                       | <b>WardName</b>             |
| WEST                       | 99                                  | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                   | <b>Significant LandMark</b> |
| W0004, W0026, W0029, W0025 | NA, 2nd Main Rd, 12th Crs, 11th Crs | bangalore one               |
| <b>SegmentNo</b>           | <b>TotalLength</b>                  |                             |
| 99/C-W0004/S015703         | 146.06                              |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>                                |                        |                    |
| <b>NameofContractor</b>                                 | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| K V Vittal no 77 DCF muddinapalya B.E.L layout bangalor |                        | 892845.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| 934461899   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at 6th cross, maruthi layout in ward no 99 | 1000000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and culverts at 6th cross, maruthi layout in ward no.99 | 099-11-000011                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/14/2011-12  | 03/05/2011   | 60 days                       |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 01/06/2011   | 31/07/2011   | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 4                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | Complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0004, W0011       | NA, 6th Crs        | navya colleg                |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/C-W0004/S020916 | 146.59             |                             |

| ContractorDetails   |                        |                    |
|---|------------------------|--------------------|
| <b>NameofContractor</b>                                       | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| K V Vittal no 77 DCF<br>muddinapalya B.E.L layout<br>bangalor |                        | 892845.00          |
| <b>PhoneNo</b>  | <b>Emailld</b>         |                    |
| 99467968  |                        |                    |

| Work Details  |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 6th cross maruthy<br>layout in ward no-99 | 1000000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Others  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and<br>culverts at 6th cross maruthy<br>layout in ward no-99 | 099-11-000011                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/14/2011-12   | 03/05/2011  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 01/06/2011  | 31/07/2011  | No                            |

| Field Inspection Details  |                          |              |
|---------------------------|--------------------------|--------------|
| <b>Number of Trees</b>    | <b>Other Information</b> | <b>Name</b>  |
| 4                         |                          | H.Shivakumar |
| <b>Date of Inspection</b> | <b>Remarks</b>           |              |
| 18/12/2014                | Complete                 |              |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |  |
|--|---|--|
| <b>Zone</b><br>WEST                    | <b>WardNo</b><br>99                         | <b>WardName</b><br>Rajajinagar             |
| <b>StreetID</b><br>W0114, W0107        | <b>StreetName</b><br>28th Crs, 17th Main Rd | <b>Significant LandMark</b><br>KLE Society |
| <b>SegmentNo</b><br>99/C-W0114/S023932 | <b>TotalLength</b><br>109.42                |  |

|   |                        |                                  |
|---|------------------------|----------------------------------|
| <b>ContractorDetails</b>                                  |                        |                                  |
| <b>NameofContractor</b><br>KRIDL Madavanagar<br>Bangalore | <b>ContractorRegNo</b> | <b>Expenditure</b><br>1808582.00 |
| <b>PhoneNo</b><br>1234567890                              | <b>EmailId</b>         |                                  |

|  |   |  |
|--|---|--|
| <b>Work Details</b>  |   |  |
| <b>NameOfWork</b><br>Providing asphaltting to 21st<br>cross to28th cross in2nd block<br>rajajinagar in ward no- 99 | <b>Sanctioned Amount</b><br>2000000   | <b>Sanctioned Year</b><br>2012           |
| <b>Year</b><br>2012 - 2013   | <b>Type of Work</b><br>Asphaltting  | <b>Other Work Type</b>                   |
| <b>Tender</b><br>Tender  | <b>WorkDetails</b><br>Providing asphaltting to 21st cross<br>to28th cross in2nd block<br>rajajinagar in ward no- 99 | <b>Job No Work Code</b><br>099-12-000039 |
| <b>Work OrderNo</b><br>EE/RNR/WO NO/243/12-13  | <b>Work Order Date</b><br>07/01/2012  | <b>Period of Extention</b><br>90days     |
| <b>Defect Liability Period From</b><br>08/01/2012  | <b>Defect Liability<br/>Period To</b><br>07/03/2012   | <b>Multiple Road Involved</b><br>Yes     |

|   |                            |                          |
|---|----------------------------|--------------------------|
| <b>Field Inspection Details</b>         |                            |                          |
| <b>Number of Trees</b><br>4             | <b>Other Information</b>   | <b>Name</b><br>Farjana.M |
| <b>Date of Inspection</b><br>18/12/2014 | <b>Remarks</b><br>complete |                          |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |
| Road Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0105, W0110       | NA, 27th Crs       | KLE Society                 |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/C-W0105/S025224 | 117.51             |                             |

|                                |                        |                    |
|--------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>       |                        |                    |
| <b>NameofContractor</b>        | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar<br>Bangalore |                        | 1808582.00         |
| <b>PhoneNo</b>                 | <b>EmailId</b>         |                    |
| 1234567890                     |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Providing asphaltting to 21st<br>cross to28th cross in2nd block<br>rajajinagar in ward no- 99 | 2000000   | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Asphaltting   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Providing asphaltting to 21st cross<br>to28th cross in2nd block<br>rajajinagar in ward no- 99 | 099-12-000039                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/243/12-13  | 07/01/2012  | 90 days                       |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 08/01/2012  | 07/03/2012  | Yes                           |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 4                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |
| Segment End    |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                              |                             |
|---------------------|------------------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>                | <b>WardName</b>             |
| WEST                | 99                           | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>            | <b>Significant LandMark</b> |
| W0106, W0104, W0100 | 26th Crs, 25th Crs, 24th Crs | KLE Society                 |
| <b>SegmentNo</b>    | <b>TotalLength</b>           |                             |
| 99/S-W0106/S025817  | 406.33                       |                             |

|                                |                        |                    |
|--------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>       |                        |                    |
| <b>NameofContractor</b>        | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar<br>Bangalore |                        | 1808582.00         |
| <b>PhoneNo</b>                 | <b>EmailId</b>         |                    |
| 1234567890                     |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Providing asphaltting to 21st cross to28th cross in2nd block rajajinagar in ward no- 99 | 2000000   | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Asphaltting   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Providing asphaltting to 21st cross to28th cross in2nd block rajajinagar in ward no- 99 | 099-12-000039                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/243/12-13  | 07/01/2012  | 90 days                       |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
|   |   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 2                               |                          | Farjana. M  |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |
| Road Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0124, W0118       | 31st Crs, 29th Crs | Bbmp complex                |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/S-W0124/S031706 | 172.89             |                             |

|                                 |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>        |                        |                    |
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL madavanagara<br>Bangalore |                        | 1811193.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

|   |  |                               |
|---|--|-------------------------------|
| <b>Work Details</b>   |  |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Providng asphaltng to 32<br>cross and 37 cross to 40th<br>cross in 2nd block rajajinagar<br>in ward no 99 | 2000000  | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013   | Asphalting   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender  | Providng asphaltng to 32 cross<br>and 37 cross to 40th cross in 2nd<br>block rajajinagar in ward no-99 | 099-12-000040                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/242/12-13  | 07/01/2012   | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 08/01/2012  | 07/03/2012   | Yes                           |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 5                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | Complete                 |             |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0122              | 30th Crs           | Bbmp complex                |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/S-W0122/S033415 | 84.38              |                             |

|                                 |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>        |                        |                    |
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL madavanagara<br>Bangalore |                        | 1811193.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Providing asphaltting to 29th<br>cross to 32 cross 37 cross to<br>40th cross in 2nd block<br>rajainagar in ward no 99 | 2000000   | 2013                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2013 - 2014   | Asphaltting   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Providing asphaltting to 29th<br>cross to 32 cross 37 cross to 40th<br>cross in 2nd block rajainagar in<br>ward no-99 | 099-12-000040                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/242/12-13  | 07/01/2012  | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
|   |   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 5                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | Complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition








ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                      |                             |
|--------------------|----------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>        | <b>WardName</b>             |
| WEST               | 99                   | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0072, W0077       | 3rd Main Rd, 6th Crs | Shipasir school             |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/C-W0072/S112618 | 100.41               |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Praveen no.6, 4th B main road Kalyangara, nagarabhavi main road, Bangalore |                        | 182905.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and covering slab at 4th cross from to 3rd main, 2nd phase ,manjunathnagara in ward no-99 | 200000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and covering slab at 4th cross from to 3rd main, 2nd phase ,manjunathnagara in ward no-99 | 099-11-000001/10              |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/109/11-12   | 16/08/2011   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 18/08/2011   | 03/10/2011   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 0                        |                   | H shivakumar |
| Date of Inspection       | Remarks           |              |
| 09/12/2015               | completed         |              |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Segment End     |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |  |                             |
|---------------------|--|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>                                | <b>WardName</b>             |
| WEST                | 99   | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>                            | <b>Significant LandMark</b> |
| W0166, W0053, W0135 | 41st Crs, 2nd Main Rd 4th Block Rajajinagara | Andhra bank                 |
| <b>SegmentNo</b>    | <b>TotalLength</b>                           |                             |
| 99/C-W0166/S114118  | 133.65                                       |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>                                  |                        |                    |
| <b>NameofContractor</b>                                   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Rajesh 3rd stage, 3rd block, Basaveshvarnagar Bangalore |                        | 1382746.00         |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| 9344615890  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at 2nd main road 2nd block rajajinagar in ward no-99 from 36th cross to 41 cross | 1999000  | 2012                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and culverts at 2nd main road 2nd block rajajinagar in ward no-99 from 36th cross to 41 cross | 099-12-000016                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/128/12-13   | 16/10/2012   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 17/10/2012   | 16/12/2012   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 2                               |                          | Farjana. M  |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |  |                             |
|--|--|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>  | <b>WardName</b>             |
| WEST   | 99   | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0134, W0158, W0115,<br>W0127, W0123, W0125,<br>W0154, W | NA, 37th Crs, 2nd B Main Rd,<br>35th Main Rd, 2nd Crs, 2nd A<br>Main Rd, 38th Crs, 39th Crs,<br>40th Crs | ESI Hospital                |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/S-W0134/S115929                                       | 895.67   |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Kumar Constructions #18th A<br>505 4th main 2nd stage<br>Mahalakshmipuram<br>Bangalore |                        | 1802112.00         |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| providing asphalting to 10th.<br>11th B and P and T road and<br>main road and cross road 2nd<br>block rajajinagar Bangalore | 1950000   | 2010                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2010 - 2011   | Asphalting  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | providing asphalting to 10th. 11th<br>B and P and T road and main<br>road and cross road 2nd block<br>rajajinagar Bangalore | 099/10/000005                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/340/2009-10  | 19/02/2010  | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 10/09/2014  |   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |            |
|--------------------------|-------------------|------------|
| Number of Trees          | Other Information | Name       |
| 6                        |                   | Farjana. M |
| Date of Inspection       | Remarks           |            |
| 18/12/2014               | complete          |            |

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0162, W0158, W0164,<br>W0160, W0113, W0133,<br>W0131, W | 39th Crs, 37th Crs, 40th Crs,<br>38th Crs, 11th Main Rd, 3rd<br>Main Rd, NA, 4th Crs, 1st<br>Main Rd, 6th Mai | Shipasir school             |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0162/S123513                                       | 820.57  |                             |

| ContractorDetails               |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagara<br>bangalore |                        | 2796225.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

| Work Details   |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing asphalting to road in<br>2nd phase Manjunatha nagar<br>in ward no-99 | 3000000  | 2013                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014  | Asphalting   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | providing asphalting to road in<br>2nd phase Manjunatha nagar in<br>ward no-99 | 099-13-000032                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/349/12-13   | 06/03/2013   | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 07/03/2013   | 06/06/2013   | No                            |

| Field Inspection Details  |                          |             |
|---------------------------|--------------------------|-------------|
| <b>Number of Trees</b>    | <b>Other Information</b> | <b>Name</b> |
| 2                         |                          | Farjana. M  |
| <b>Date of Inspection</b> | <b>Remarks</b>           |             |
| 22/12/2014                | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |  |                             |
|--|--|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>  | <b>WardName</b>             |
| WEST   | 99   | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0053, W0058, W0060,<br>W0072, W0057, W0055,<br>W0059, W | 11th Crs, 6th Main Rd, 3rd<br>Main Rd, 10th Crs, 8th Crs,<br>9th Crs, NA, 7th Crs, 6th Crs,<br>5th Crs | Royal school                |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/C-W0053/S011321                                       | 732.21   |                             |

|                                  |                        |                    |
|----------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>         |                        |                    |
| <b>NameofContractor</b>          | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagagar<br>bangalore |                        | 2751938.00         |
| <b>PhoneNo</b>                   | <b>Emailld</b>         |                    |
| 1234567890                       |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing asphalting to road in<br>2nd phase Manjunatha nagar<br>in ward no-99 (from 40th cross<br>to 9th cross) | 3000000  | 2013                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014  | Asphalting   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | providing asphalting to road in<br>2nd phase Manjunatha nagar in<br>ward no-99 (from 40th cross to<br>9th cross) | 099-13-000033                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/353/12-13   | 06/03/2013   | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 07/03/2013   | 06/06/2013   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
| Date of Inspection       | Remarks           |
| 09/12/2015               | completed         |

| Category       | Photo  |
|----------------|--|
| Road Condition |   |
| Segment End    |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                                    |                             |
|----------------------------|------------------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                      | <b>WardName</b>             |
| WEST                       | 99                                 | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                  | <b>Significant LandMark</b> |
| W0053, W0058, W0060, W0072 | 11th Crs, 6th Main Rd, 3rd Main Rd | Royal school                |
| <b>SegmentNo</b>           | <b>TotalLength</b>                 |                             |
| 99/C-W0053/S012503         | 109.31                             |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Narayana, #41, 7th A Main, 2nd block, 3rd stage, Basaveshwaranagara, Bangalore |                        | 454891.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains at 9th cross 2nd phase Manjunathnagar in ward no-99 | 500000   | 2012                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains at 9th cross 2nd phase Manjunathnagar in ward no-99 | 099-12-000024                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/193/12-13   | 15/12/2012   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 16/12/2012   | 15/02/2013   | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 0                               |                          | H shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 09/12/2015                      | completed                |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Segment End    |       |
| Segment Start  |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |   |                             |
|--|---|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>   | <b>WardName</b>             |
| WEST   | 99  | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0072, W0045, W0062,<br>W0058, W0060, W0049,<br>W0053, W | 3rd Main Rd, 13th Crs, 2nd<br>Crs, 6th Main Rd, 12th Crs,<br>11th Crs, 4th Crs, 1st Main<br>Rd, 39th Crs, 37t | Royal school                |
| <b>SegmentNo</b>   | <b>TotalLength</b>  |                             |
| 99/C-W0072/S111646                                       | 803.85  |                             |

|                                 |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>        |                        |                    |
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagara<br>bangalore |                        | 2796225.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing asphalting to road in<br>2nd phase Manjunatha nagar<br>in ward no-99 ( 1st main and<br>10th cross to13th cross ) | 3000000  | 2013                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014  | Asphalting   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | providing asphalting to road in<br>2nd phase Manjunatha nagar in<br>ward no-99 ( 1st main and 10th<br>cross to13th cross ) | 099-13-000032                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/349/12-13   | 06/03/2013   | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 07/03/2013   | 06/06/2013   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |           |
|--------------------------|-------------------|-----------|
| Number of Trees          | Other Information | Name      |
| 2                        |                   | Farjana.M |
| Date of Inspection       | Remarks           |           |
| 18/12/2014               | Complete          |           |

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                                       |                             |
|---------------------|---------------------------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>                         | <b>WardName</b>             |
| WEST                | 99                                    | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>                     | <b>Significant LandMark</b> |
| W0058, W0060, W0057 | 6th Main Rd, 3rd Main Rd,<br>10th Crs | Royal school                |
| <b>SegmentNo</b>    | <b>TotalLength</b>                    |                             |
| 99/C-W0058/S013510  | 110.94                                |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| B.N.Naveena kumar,#22, 1st<br>cross,MR line, Akkipet,<br>Bangalore |                        | 440165.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| 924467899  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains at 8th<br>cross 2nd phase<br>Manjunathnagar in ward no-99<br>from 40feet road to 3rd main | 500000   | 2012                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains at 8th<br>cross 2nd phase Manjunathnagar<br>in ward no-99 from 40feet road to<br>3rd main | 099-12-000023                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/192/12-13   | 15/12/2012   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 16/12/2012   | 15/02/2013   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
|                          | H shivakumar      |
| Date of Inspection       | Remarks           |
| 09/12/2015               | completed         |

| Category       | Photo  |
|----------------|--|
| Road Condition |   |
| Segment End    |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                      |                             |
|--------------------|----------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>        | <b>WardName</b>             |
| WEST               | 99                   | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0084, W0055       | 6th Main Rd, 8th Crs | axis bank atm               |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/C-W0084/S021828 | 151.25               |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Kirana.y #124/A, 5th main road 3rd stage, 2nd block basaveshwaranagar Bangalore |                        | 722269.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| <b>Work Details</b><br>1234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at 4th main 2nd phase manjunathnagar in ward no-99 from Thimmaiah road to 8th cross | 800000  | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and culverts at 4th main 2nd phase manjunathnagar in ward no-99 from Thimmaiah road to 8th cross | 099-12-000019                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/136/12-13  | 31/10/2012  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 02/11/2012  | 01/01/2013  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |  |            |
|--------------------------|--|------------|
| Number of Trees          | Other Information  | Name       |
| 4                        |  | Farjana. M |
| Date of Inspection       | Remarks  |            |
| 18/12/2014               | complete   |            |
| Category                 | Photo  |            |
| Drain Condition          |   |            |
| Drain Condition          |  |            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |  |                             |
|----------------------------|--|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                          | <b>WardName</b>             |
| WEST                       | 99                                     | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                      | <b>Significant LandMark</b> |
| W0026, W0036, W0040, W0035 | 2nd Main Rd, 1st Crs, 15th Main Rd, NA | Play ground                 |
| <b>SegmentNo</b>           | <b>TotalLength</b>                     |                             |
| 99/C-W0026/S024723         | 101.99                                 |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Kirana.y #124/A, 5th main road 3rd stage, 2nd block basaveshwaranagar Bangalore |                        | 448439.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| <b>Work Details</b>   |                        |                    |
| 1234567890  |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at 15th cross Gayathri layout in ward no-99 | 600000  | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and culverts at 15th cross Gayathri layout in ward no-99 | 099-12-000018                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/137/12-13  | 31/10/2012  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 02/11/2012  | 01/01/2013  | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 4                               |                          | Farjana. M  |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                                      |                                      |                             |
|--------------------------------------|--------------------------------------|-----------------------------|
| <b>Zone</b>                          | <b>WardNo</b>                        | <b>WardName</b>             |
| WEST                                 | 99                                   | Rajajinagar                 |
| <b>StreetID</b>                      | <b>StreetName</b>                    | <b>Significant LandMark</b> |
| W0101, W0054, W0069,<br>W0087, W0093 | NA, 4th Main Rd, 8th Crs, 1st<br>Crs | bbmp play ground            |
| <b>SegmentNo</b>                     | <b>TotalLength</b>                   |                             |
| 99/C-W0101/S030440                   | 252.60                               |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| S.N.Enterprises, no.41,1st<br>main road 1st phase<br>Ramachand, Bangalore<br>rapura |                        | 703506.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| <b>Work Details</b>   |                        |                    |
| 1234567890  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 4th main road 1st<br>phase Manjunathnagar in<br>ward no-99 | 780000   | 2012                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and<br>culverts at 4th main road 1st<br>phase Manjunathnagar in ward<br>no-99 | 099-12-000020                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/139/12-13   | 05/11/2012   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 06/11/2012   | 05/01/2013   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 1                               |                          | Farjana. M  |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|   |   |                             |
|---|---|-----------------------------|
| <b>Zone</b>                                 | <b>WardNo</b>   | <b>WardName</b>             |
| WEST  | 99  | Rajajinagar                 |
| <b>StreetID</b>                             | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0091, W0058, W0072,<br>W0070, W0068, W0066 | 4th Crs, 6th Main Rd, 3rd<br>Main Rd, 2nd Main Rd, 1st<br>Main Rd, NA | Shipashree school           |
| <b>SegmentNo</b>                            | <b>TotalLength</b>  |                             |
| 99/C-W0091/S032623                          | 96.44   |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Praveen no.6, 4th B main<br>road Kalyangara,<br>nagarabhavi main road,<br>Bangalore |                        | 182905.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| <b>Work Details</b>   |                        |                    |
| 1234567890  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>covering slab at 4th cross from<br>40feet road to 3rd main, 2nd<br>phase ,manjunathnagara in<br>ward no-99 | 200000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and<br>covering slab at 4th cross from<br>40feet road to 3rd main, 2nd<br>phase ,manjunathnagara in ward<br>no-99 | 099-11-000001/10              |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/109/11-12   | 16/08/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 19/08/2011   | 03/10/2011   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 0                        |                   | H.Shivakumar |
| Date of Inspection       | Remarks           |              |
| 18/12/2014               | complete          |              |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                                      |                             |
|----------------------------|--------------------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                        | <b>WardName</b>             |
| WEST                       | 99                                   | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                    | <b>Significant LandMark</b> |
| W0021, W0017, W0015, W0025 | 10th Crs, 9th Crs, 8th Crs, 11th Crs | Bangalore one               |
| <b>SegmentNo</b>           | <b>TotalLength</b>                   |                             |
| 99/C-W0021/S013411         | 209.30                               |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Narayana,No.42,7th A Main, 2nd block,3rd Stage, Shivanagar,Bangalore |                        | 645955.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| 934467899  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at 8th and 9th cross in Adarsha layout in ward no-99 | 100000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and culverts at 8th and 9th cross in Adarsha layout in ward no-99 | 107-11-000012                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/32/10-11  | 23/03/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 26/03/2011   | 24/05/2011   | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 2                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                                       |                             |
|---------------------|---------------------------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>                         | <b>WardName</b>             |
| WEST                | 99                                    | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>                     | <b>Significant LandMark</b> |
| W0058, W0060, W0057 | 6th Main Rd, 3rd Main Rd,<br>10th Crs | Royal School                |
| <b>SegmentNo</b>    | <b>TotalLength</b>                    |                             |
| 99/C-W0058/S021228  | 108.76                                |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| K.V.Vittal,No.77,DCF,<br>mudhinapaly B.E.L Layout,<br>Bangalore |                        | 454971.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| 934567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>covering slab at 10th cross<br>from 40feet road to 3rd main<br>,2nd phase Manjunathnagar<br>in ward no-99 | 500000  | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and<br>covering slab at 10th cross from<br>40feet road to 3rd main ,2nd<br>phase Manjunathnagar in ward<br>no-99 | 99-11-000018                  |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/12/11-12   | 30/05/2011  |                               |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 01/06/2011  | 31/07/2011  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 0                        |                   | H shivakumar |
| Date of Inspection       | Remarks           |              |
| 09/12/2015               | completed         |              |

| Category       | Photo  |
|----------------|--|
| Road Condition |   |
| Segment End    |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|   |   |                             |
|---|---|-----------------------------|
| <b>Zone</b>   | <b>WardNo</b>   | <b>WardName</b>             |
| WEST  | 99  | Rajajinagar                 |
| <b>StreetID</b>                                       | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0084, W0082, W0076,<br>W0055, W0074, W0090,<br>W0080 | 6th Main Rd, 5th Main Rd,<br>3rd B Main Rd, 8th Crs, 3rd A<br>Main Rd, Manjunath Nagar<br>Rd, 4th Main Rd | Nagager college             |
| <b>SegmentNo</b>                                      | <b>TotalLength</b>  |                             |
| 99/C-W0084/S024416                                    | 158.68  |                             |

| ContractorDetails   |                        |                    |
|---|------------------------|--------------------|
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| G. Balamurugana No.240, 1st<br>main road 3rd cross 3 stage<br>Manjunathanagar Bangalore |                        | 645344.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| 934461899   |                        |                    |

| Work Details  |  |                               |
|---|--|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 8th cross from<br>1st main to 3rd main 2nd<br>phase Manjunathnagar in<br>ward no-99 | 100000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012   | Drain Maintenance  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and<br>culverts at 8th cross from 1st<br>main to 3rd main 2nd phase<br>Manjunathnagar in ward no-99 | 099-11-000024                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/15/10-11   | 15/03/2011   |                               |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 18/03/2011  | 15/05/2011   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 2                        |                   | H.Shivakumar |
| Date of Inspection       | Remarks           |              |
| 18/12/2014               | complete          |              |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|   |   |                             |
|---|---|-----------------------------|
| <b>Zone</b>   | <b>WardNo</b>   | <b>WardName</b>             |
| WEST  | 99  | Rajajinagar                 |
| <b>StreetID</b>                                       | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0115, W0125, W0154,<br>W0129, W0146, W0119,<br>W0148 | 2nd B Main Rd, NA, 35th<br>Main Rd, 2nd Crs, 34th B<br>Crs, 2nd A Main Rd | ESI Hospital                |
| <b>SegmentNo</b>                                      | <b>TotalLength</b>  |                             |
| 99/C-W0115/S030516                                    | 235.96  |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Thimmaiah .b, no 347,<br>Basaveshwaranagar, Bhovi<br>colony Bangalore |                        | 640666.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| 1024567800  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing cement concrete<br>roads drains and culverts at<br>juganahalli village in ward no-<br>99 | 100000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Road   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | providing cement concrete roads<br>drains and culverts at juganahalli<br>village in ward no-99 | 099-11-000008                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/166/11-12   | 13/10/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 14/10/2011   | 12/12/2011   | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 3                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                                      |   |                             |
|--------------------------------------|---|-----------------------------|
| <b>Zone</b>                          | <b>WardNo</b>   | <b>WardName</b>             |
| WEST                                 | 99  | Rajajinagar                 |
| <b>StreetID</b>                      | <b>StreetName</b>   | <b>Significant LandMark</b> |
| W0015, W0013, W0029,<br>W0025, W0021 | 8th Crs, 7th Crs Rajajinagar,<br>12th Crs, 11th Crs, 10th Crs | state bank of india         |
| <b>SegmentNo</b>                     | <b>TotalLength</b>  |                             |
| 99/C-W0015/S110443                   | 250.19  |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Narayana,No.42,7th A<br>Main, 2nd block,3rd Stage,<br>Shivanagar,Bangalore |                        | 647798.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| 9344618990   |                        |                    |

|  |   |                               |
|--|---|-------------------------------|
| <b>Work Details</b>  |   |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 7th and 10th A<br>cross in Adarsha layout in ward<br>no-99 | 1000000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and<br>culverts at 7th and 10th A cross<br>in Adarsha layout in ward no-99 | 099-11-000013                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/22/10-11  | 21/03/2011  |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 24/03/2011   | 22/05/2011  | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 2                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                              |                             |
|--------------------|------------------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>                | <b>WardName</b>             |
| WEST               | 99                           | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>            | <b>Significant LandMark</b> |
| W0007, W0009       | 4th Crs, 5th Crs Rajajinagar | Navya college               |
| <b>SegmentNo</b>   | <b>TotalLength</b>           |                             |
| 99/S-W0007/S114519 | 277.75                       |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Sri, Manjunath enterpreses<br>518/A,15th main,<br>Manjunathnagar Bangalore |                        | 1022228.00         |
| <b>PhoneNo</b>   | <b>Emailld</b>         |                    |
| 9234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 4th and 5th cross<br>maruthi layout in ward no-99 | 1500000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains and<br>culverts at 4th and 5th cross<br>maruthi layout in ward no-99 | 099-11-000010                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/19/10-11   | 18/03/2011  |                               |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 21/03/2011  | 18/06/2011  | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 4                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |  |                             |
|----------------------------|--|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                          | <b>WardName</b>             |
| WEST                       | 99                                     | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                      | <b>Significant LandMark</b> |
| W0158, W0160, W0162, W0164 | 37th Crs, 38th Crs, 39th Crs, 40th Crs | Govt first grade college    |
| <b>SegmentNo</b>           | <b>TotalLength</b>                     |                             |
| 99/S-W0158/S013434         | 504.76                                 |                             |

|                             |                        |                    |
|-----------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>    |                        |                    |
| <b>NameofContractor</b>     | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar bangalore |                        | 1811193.00         |
| <b>PhoneNo</b>              | <b>EmailId</b>         |                    |
| 1234567890                  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing asphaltting to 29th cross to 37th cross to 40th cross in 2nd block Rajajinagar in ward no-99 | 2000000  | 2013                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014  | Asphaltting  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | providing asphaltting to 29th cross to 37th cross to 40th cross in 2nd block Rajajinagar in ward no-99 | 099-12-000040                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/242/2011-12   | 07/01/2013   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 08/01/2013   | 07/03/2013   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 5                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | Complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                      |                             |
|----------------------------|----------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>        | <b>WardName</b>             |
| WEST                       | 99                   | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0034, W0037, W0036, W0039 | 2nd Crs, NA, 1st Crs | playground                  |
| <b>SegmentNo</b>           | <b>TotalLength</b>   |                             |
| 99/C-W0034/S115841         | 173.61               |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Benaka enterprises, no 680, 13th main road 3rd block 3rd stage Basveshwaranagar, Bangalore |                        | 1352778.00         |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
|  |                        |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| providing CC road and improvements to culverts at 1st A cross and 2nd cross indiranagara slum in ward no-99 | 1500000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Others  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | providing CC road and improvements to culverts at 1st A cross and 2nd cross indiranagara slum in ward no-99 | 099-11-000059                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/150/11-12  | 29/09/2011  | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 30/09/2011  | 27/12/2011  | No                            |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
| Date of Inspection       | Remarks           |
| 18/12/2014               | complete          |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |  |                               |
|--|--|-------------------------------|
| <b>Zone</b>  | <b>WardNo</b>  | <b>WardName</b>               |
| WEST   | 99   | Rajajinagar                   |
| <b>StreetID</b>  | <b>StreetName</b>  | <b>Significant LandMark</b>   |
| W0091, W0072, W0070,<br>W0068, W0066, W0058,<br>W0085, W   | 4th Crs, 3rd Main Rd, 2nd<br>Main Rd, 1st Main Rd, NA,<br>6th Main Rd, 5th Crs, 6th Crs,<br>7th Crs, 8th Crs,    | Shipashree scholl             |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                               |
| 99/C-W0091/S121030   | 615.34   |                               |
| <b>ContractorDetails</b>   |  |                               |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b>   | <b>Expenditure</b>            |
| KRIDL Madavanagagar<br>bangalore   |  | 2751938.00                    |
| <b>PhoneNo</b>   | <b>EmailId</b>   |                               |
| 1234567890   |  |                               |
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing asphalting to road in<br>2nd phase Manjunatha nagar<br>in ward no-99 (from 40th cross<br>to 9th cross) | 3000000  | 2013                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014  | Asphalting   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | providing asphalting to road in<br>2nd phase Manjunatha nagar in<br>ward no-99 (from 40th cross to<br>9th cross) | 099-13-000033                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/353/12-13   | 06/03/2013   | 90days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 07/03/2013   | 06/06/2013   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |           |
|--------------------------|-------------------|-----------|
| Number of Trees          | Other Information | Name      |
| 7                        |                   | Farzana.M |
| Date of Inspection       | Remarks           |           |
| 18/12/2014               | complete          |           |

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                      |                             |
|----------------------------|----------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>        | <b>WardName</b>             |
| WEST                       | 99                   | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0059, W0060, W0072, W0061 | 9th Crs, 3rd Main Rd | Royal school                |
| <b>SegmentNo</b>           | <b>TotalLength</b>   |                             |
| 99/C-W0059/S121845         | 108.34               |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Narayana, #41, 7th A Main, 2nd block, 3rd stage, Basaveshwaranagara, Bangalore |                        | 454891.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains at 9th cross 2nd phase Manjunathnagar in ward no-99 from | 500000  | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains at 9th cross 2nd phase Manjunathnagar in ward no-99 from | 099-12-000024                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/193/12-13  | 15/12/2012  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 16/12/2012  | 15/02/2013  | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 2                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                                       |                             |
|----------------------------|---------------------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                         | <b>WardName</b>             |
| WEST                       | 99                                    | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                     | <b>Significant LandMark</b> |
| W0058, W0064, W0060, W0069 | 6th Main Rd, NA, 3rd Main Rd, 8th Crs | royal school                |
| <b>SegmentNo</b>           | <b>TotalLength</b>                    |                             |
| 99/C-W0058/S122532         | 106.36                                |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>                                     |                        |                    |
| <b>NameofContractor</b>                                      | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| B.N.Naveena kumar,#22, 1st cross,MR line, Akkipet, Bangalore |                        | 440165.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| 934461899  |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>Work Details</b>   |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Improvements to drains at 8th cross 2nd phase Manjunathnagar in ward no-99 from 40feet road to 3rd main | 500000  | 2012                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Improvements to drains at 8th cross 2nd phase Manjunathnagar in ward no-99 from 40feet road to 3rd main | 099-12-000023                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/192/12-13  | 15/12/2012  | 60days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability Period To</b>   | <b>Multiple Road Involved</b> |
| 16/12/2012  | 15/02/2013  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |            |
|--------------------------|-------------------|------------|
| Number of Trees          | Other Information | Name       |
| 2                        |                   | Farjana. M |
| Date of Inspection       | Remarks           |            |
| 18/12/2014               | complete          |            |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                       |                             |
|---------------------|-----------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>         | <b>WardName</b>             |
| WEST                | 99                    | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>     | <b>Significant LandMark</b> |
| W0018, W0037, W0016 | 9th Crs, NA, 10th Crs | Bright algan school         |
| <b>SegmentNo</b>    | <b>TotalLength</b>    |                             |
| 99/C-W0018/S124208  | 230.60                |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>                                       |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| K.Anada,no 970,9th main road 7th cross Prakashnagar, Bangalore |                        | 1723375.00         |
| <b>PhoneNo</b>   | <b>Emailld</b>         |                    |
| 994567890  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing CC road and improvements to drains at 9th and 10th cross indiranagara slum in ward no-99 | 2000000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | providing CC road and improvements to drains at 9th and 10th cross indiranagara slum in ward no-99 | 099-11-000063                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/148/11-12   | 29/09/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 30/09/2011   | 27/12/2011   | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 0                               |                          | Farjana. M  |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo  |
|-----------------|--|
| Drain Condition |    |
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                                   |                             |
|----------------------------|-----------------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>                     | <b>WardName</b>             |
| WEST                       | 99                                | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>                 | <b>Significant LandMark</b> |
| W0043, W0022, W0037, W0020 | 7th Main Rd, 7th Crs, NA, 8th Crs | Bright algan school         |
| <b>SegmentNo</b>           | <b>TotalLength</b>                |                             |
| 99/C-W0043/S125852         | 218.89                            |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Benaka enterprises, no 680, 13th main road 3rd block 3rd stage Basveshwaranagar, Bangalore |                        | 1467342.00         |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing CC road and improvements to drains culverts at 7th and 8th cross indiranagara slum in ward no-99 | 1800000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | providing CC road and improvements to drains culverts at 7th and 8th cross indiranagara slum in ward no-99 | 099-11-000062                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/152/11-12   | 29/09/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 30/09/2011   | 27/12/2011   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |            |
|--------------------------|-------------------|------------|
| Number of Trees          | Other Information | Name       |
| 0                        |                   | Farjana. M |
| Date of Inspection       | Remarks           |            |
| 18/12/2014               | complete          |            |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition



BANGALORE MAHANAGARA PALIKE



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                      |                             |
|---------------------|----------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>        | <b>WardName</b>             |
| WEST                | 99                   | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0032, W0037, W0030 | 3rd Crs, NA, 4th Crs | play ground                 |
| <b>SegmentNo</b>    | <b>TotalLength</b>   |                             |
| 99/C-W0032/S011641  | 190.03               |                             |

|   |   |                               |
|---|---|-------------------------------|
| <b>ContractorDetails</b>  |   |                               |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b>  | <b>Expenditure</b>            |
| Benaka enterprises<br>no.680,13th main road, 3rd<br>block,3rd stage,<br>Basaveshwarnagara,<br>Bangalore                     |   | 1353796.00                    |
| <b>Work Details</b>   | <b>EmailId</b>  |                               |
| 1234567890  |   |                               |
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| providing CC road and<br>improvements to drains and<br>culverts at 3rd and 4th cross<br>indiranagara slum in ward no-<br>99 | 1500000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2012 - 2013   | Others  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | providing CC road and<br>improvements to drains and<br>culverts at 3rd and 4th cross<br>indiranagara slum in ward no-99 | 099-11-000060                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/151/11-12  | 29/09/2011  |                               |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 30/09/2011  | 27/12/2011  | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
| Date of Inspection       | Remarks           |
| 18/12/2014               | Complete          |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Road Condition



Segment End



Segment Start



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                     |                      |                             |
|---------------------|----------------------|-----------------------------|
| <b>Zone</b>         | <b>WardNo</b>        | <b>WardName</b>             |
| WEST                | 99                   | Rajajinagar                 |
| <b>StreetID</b>     | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0028, W0037, W0024 | 5th Crs, NA, 6th Crs | Bright algan scholl         |
| <b>SegmentNo</b>    | <b>TotalLength</b>   |                             |
| 99/C-W0028/S013006  | 204.92               |                             |


|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>                                       |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| K.Anada,no 970,9th main road 7th cross Prakashnagar, Bangalore |                        | 1539308.00         |
| <b>PhoneNo</b>   | <b>Emailld</b>         |                    |
| 99/C-W0028/S013006   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing CC road and improvements to drains and culverts at 5th and 6th cross indiranagara slum in ward no-99 | 1700000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | providing CC road and improvements to drains and culverts at 5th and 6th cross indiranagara slum in ward no-99 | 099-11-000061                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/149/11-12   | 29/09/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 30/09/2011   | 27/12/2011   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 0                        |                   | H.Shivakumar |
| Date of Inspection       | Remarks           |              |
| 18/12/2014               | complete          |              |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0014, W0037       | 11th Crs, NA       | Stste bank of india         |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/C-W0014/S014446 | 120.34             |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Lokesh.C,NO.72, 5th main,<br>bovicolony,<br>Basaveshwarnagara<br>Bangalore |                        | 904880.00          |
| <b>PhoneNo</b>   | <b>Emailld</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| providing CC road and<br>improvements to drains and<br>culverts at 11th cross<br>indiranagara slum in ward no-<br>99 | 1000000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | providing CC road and<br>improvements to drains and<br>culverts at 11th cross<br>indiranagara slum in ward no-99 | 099-11-000064                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/155/11-12   | 01/10/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 03/10/2011   | 31/12/2011   | No                            |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |             |
|--------------------------|-------------------|-------------|
| Number of Trees          | Other Information | Name        |
| 0                        |                   | H.Shivkumar |
| Date of Inspection       | Remarks           |             |
| 18/12/2014               | complete          |             |

| Category        | Photo  |
|-----------------|--|
| Drain Condition |   |
| Drain Condition |  |





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Road Condition



Road Condition





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

Road Condition



Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                                      |   |                             |
|--------------------------------------|---|-----------------------------|
| <b>Zone</b>                          | <b>WardNo</b>   | <b>WardName</b>             |
| WEST                                 | 99  | Rajajinagar                 |
| <b>StreetID</b>                      | <b>StreetName</b>                                       | <b>Significant LandMark</b> |
| W0162, W0158, W0121,<br>W0164, W0160 | 39th Crs, 37th Crs, 10th Main<br>Rd, 40th Crs, 38th Crs | Govt pu 1st grade college   |
| <b>SegmentNo</b>                     | <b>TotalLength</b>                                      |                             |
| 99/C-W0162/S023733                   | 161.58  |                             |

|                                 |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>        |                        |                    |
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagara<br>bangalore |                        | 1909718.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>footpath at 10th main road from<br>36th cross to 41st<br>cross,Rajajinagar in ward no-<br>99 | 2000000  | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Others   |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | Improvements to drains and<br>footpath at 10th main road from<br>36th cross to 41st<br>cross,Rajajinagar in ward no-99 | 099-11-000039                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/198/11-12   | 04/11/2011   |                               |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 06/11/2011   | 05/02/2012   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 5                        |                   | H.Shivakumar |
| Date of Inspection       | Remarks           |              |
| 18/12/2014               | complete          |              |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Footpath Condition



Footpath Condition



BANGALORE MAHANAGARA PALIKE





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Footpath Condition



Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                            |                          |                             |
|----------------------------|--------------------------|-----------------------------|
| <b>Zone</b>                | <b>WardNo</b>            | <b>WardName</b>             |
| WEST                       | 99                       | Rajajinagar                 |
| <b>StreetID</b>            | <b>StreetName</b>        | <b>Significant LandMark</b> |
| W0050, W0081, W0087, W0093 | 3rd Main Rd, NA, 1st Crs | BBMP play ground            |
| <b>SegmentNo</b>           | <b>TotalLength</b>       |                             |
| 99/C-W0050/S122053         | 216.29                   |                             |

|                                |                        |                    |
|--------------------------------|------------------------|--------------------|
| <b>ContractorDetails</b>       |                        |                    |
| <b>NameofContractor</b>        | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagar<br>Bangalore |                        | 1825530.00         |
| <b>PhoneNo</b>                 | <b>EmailId</b>         |                    |
| 1234567890                     |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>Work Details</b>  |  |                               |
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and culverts at3rd main and 2nd phase Manjunatha nagar from WOC road to 8th cross in ward no-99 | 2000000  | 2012                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2012 - 2013  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender   | Improvements to drains and culverts at3rd main and 2nd phase Manjunatha nagar from WOC road to 8th cross in ward no-99 | 099-12-000052                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/225/12-13   | 22/12/2012   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability Period To</b>  | <b>Multiple Road Involved</b> |
| 23/12/2012   | 22/02/2013   | No                            |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |
|--------------------------|-------------------|
| Number of Trees          | Other Information |
| 0                        | Name              |
| Date of Inspection       | Remarks           |
| 09/12/2015               | completed         |

| Category       | Photo  |
|----------------|--|
| Road Condition |   |
| Segment End    |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|  |  |                             |
|--|--|-----------------------------|
| <b>Zone</b>  | <b>WardNo</b>  | <b>WardName</b>             |
| WEST   | 99   | Rajajinagar                 |
| <b>StreetID</b>  | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0078, W0056, W0058,<br>W0072, W0070, W0068,<br>W0066, W | NA, 5th Main Rd, 6th Main<br>Rd, 3rd Main Rd, 2nd Main<br>Rd, 1st Main Rd, 4th Main<br>Rd, 12th Crs, 8th Crs | shilpashree school          |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/C-W0078/S011739                                       | 1156.70  |                             |

| ContractorDetails               |                        |                    |
|---------------------------------|------------------------|--------------------|
| <b>NameofContractor</b>         | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| KRIDL Madavanagara<br>Bangalore |                        | 5007942.00         |
| <b>PhoneNo</b>                  | <b>EmailId</b>         |                    |
| 1234567890                      |                        |                    |

| Work Details  |  |                               |
|---|--|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Providing Asphaltting to 1st<br>phase Manjunathnagar in ward<br>no-99 | 5500000  | 2013                          |
| <b>Year</b>   | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2013 - 2014   | Asphaltting  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Not a Tender  | Providing Asphaltting to 1st phase<br>Manjunathnagar in ward no-99 | 099-13-000031                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/354/10-11  | 06/03/2013   |                               |
| <b>Defect Liability Period From</b>                                   | <b>Defect Liability<br/>Period To</b>                              | <b>Multiple Road Involved</b> |
| 07/03/2013  | 06/07/2013   | No                            |

| Field Inspection Details  |                          |             |
|---------------------------|--------------------------|-------------|
| <b>Number of Trees</b>    | <b>Other Information</b> | <b>Name</b> |
| 4                         |                          | Farjana. M  |
| <b>Date of Inspection</b> | <b>Remarks</b>           |             |
| 18/12/2014                | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category       | Photo |
|----------------|-------|
| Road Condition |       |
| Road Condition |       |
| Road Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0012, W0037       | 12th Crs, NA       | State bank                  |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/C-W0012/S013857 | 140.53             |                             |

|  |                        |                    |
|--|------------------------|--------------------|
| <b>ContractorDetails</b>   |                        |                    |
| <b>NameofContractor</b>  | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| T.Rajesh, no.147,3rd stage,<br>3rd block Sanegoravanahally<br>Basaveshwaranagar<br>Bangalore |                        | 901583.00          |
| <b>PhoneNo</b>   | <b>EmailId</b>         |                    |
| <b>Work Details</b>  |                        |                    |
| 1234567890   |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Providing cement concrete<br>road and improvement to<br>drains and culverts 12th cross<br>indranagar slum in ward no-99 | 1000000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Road  |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Providing cement concrete road<br>and improvement to drains and<br>culverts 12th cross indranagar<br>slum in ward no-99 | 099-11-000065                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/218/12-13  | 08/11/2011  |                               |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 10/11/2011  | 08/01/2012  | No                            |

|                                 |                          |             |
|---------------------------------|--------------------------|-------------|
| <b>Field Inspection Details</b> |                          |             |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b> |
| 2                               |                          | Farjana.M   |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |             |
| 18/12/2014                      | complete                 |             |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|   |   |  |
|---|---|--|
| <b>Zone</b><br>WEST   | <b>WardNo</b><br>99   | <b>WardName</b><br>Rajajinagar                 |
| <b>StreetID</b><br>W0059, W0053, W0072,<br>W0071, W0045, W0061,<br>W0057, W | <b>StreetName</b><br>9th Crs, 11th Crs, 3rd Main<br>Rd, 7th Crs, 13th Crs, 10th<br>Crs, 8th Crs, 12th Crs | <b>Significant LandMark</b><br>Nagager college |
| <b>SegmentNo</b><br>99/C-W0059/S025107                                      | <b>TotalLength</b><br>226.86  |  |

|   |                        |                                  |
|---|------------------------|----------------------------------|
| <b>ContractorDetails</b>  |                        |                                  |
| <b>NameofContractor</b><br>R.R Prasad no.154, 19th<br>cross road 3rd block 4th<br>stage Basveshwaranagar<br>Bangalore | <b>ContractorRegNo</b> | <b>Expenditure</b><br>1033447.00 |
| <b>PhoneNo</b>  | <b>Emailld</b>         |                                  |

|   |  |  |
|---|--|--|
| <b>Work Details</b><br>1234567890   |  |  |
| <b>NameOfWork</b><br>Improvements to drains and<br>culverts at3rd main from<br>Thimmaiah road to 9th cross<br>2nd phase Manjunathnagar in<br>ward no-99 | <b>Sanctioned Amount</b><br>1150000  | <b>Sanctioned Year</b><br>2011           |
| <b>Year</b><br>2011 - 2012  | <b>Type of Work</b><br>Drain Maintenance   | <b>Other Work Type</b>                   |
| <b>Tender</b><br>Tender   | <b>WorkDetails</b><br>Improvements to drains and<br>culverts at3rd main from<br>Thimmaiah road to 9th cross 2nd<br>phase Manjunathnagar in ward<br>no-99 | <b>Job No Work Code</b><br>099-11-000023 |
| <b>Work OrderNo</b><br>EE/RNR/WO NO/28/10-11  | <b>Work Order Date</b><br>21/03/2011   | <b>Period of Extention</b>               |
| <b>Defect Liability Period From</b><br>24/03/2011   | <b>Defect Liability<br/>Period To</b><br>22/05/2011  | <b>Multiple Road Involved</b><br>No      |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Field Inspection Details |                   |              |
|--------------------------|-------------------|--------------|
| Number of Trees          | Other Information | Name         |
| 2                        |                   | H.Shivakumar |
| Date of Inspection       | Remarks           |              |
| 18/12/2014               | complete          |              |

| Category        | Photo |
|-----------------|-------|
| Drain Condition |       |
| Drain Condition |       |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Drain Condition



Segment End



Segment Start







ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                      |                             |
|--------------------|----------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>        | <b>WardName</b>             |
| WEST               | 99                   | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>    | <b>Significant LandMark</b> |
| W0046, W0079       | 1st Main Rd, 5th Crs | Ganesha temple              |
| <b>SegmentNo</b>   | <b>TotalLength</b>   |                             |
| 99/C-W0046/S030028 | 125.74               |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>  |                        |                    |
| <b>NameofContractor</b>   | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Bhujanageshwara<br>Enterprises no.155, 35th<br>cross 2nd block Rajajinagar<br>Bangalore |                        | 457858.00          |
| <b>PhoneNo</b>  | <b>EmailId</b>         |                    |
| <b>Work Details</b>   |                        |                    |
| 1234567890  |                        |                    |

|  |  |                               |
|--|--|-------------------------------|
| <b>NameOfWork</b>  | <b>Sanctioned Amount</b>   | <b>Sanctioned Year</b>        |
| Improvements to drains and<br>culverts at 1st main 1st phase<br>Manjunathnagar in ward no-99 | 500000   | 2011                          |
| <b>Year</b>  | <b>Type of Work</b>  | <b>Other Work Type</b>        |
| 2011 - 2012  | Drain Maintenance  |                               |
| <b>Tender</b>  | <b>WorkDetails</b>   | <b>Job No Work Code</b>       |
| Tender   | Improvements to drains and<br>culverts at 1st main 1st phase<br>Manjunathnagar in ward no-99 | 099-11-000015                 |
| <b>Work OrderNo</b>  | <b>Work Order Date</b>   | <b>Period of Extention</b>    |
| EE/RNR/WO NO/07/11-12  | 23/05/2011   | 60days                        |
| <b>Defect Liability Period From</b>  | <b>Defect Liability<br/>Period To</b>  | <b>Multiple Road Involved</b> |
| 25/04/2011   | 23/07/2011   | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 4                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

| Category        | Photo  |
|-----------------|--|
| Drain Condition |    |
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start





ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

|                    |                    |                             |
|--------------------|--------------------|-----------------------------|
| <b>Zone</b>        | <b>WardNo</b>      | <b>WardName</b>             |
| WEST               | 99                 | Rajajinagar                 |
| <b>StreetID</b>    | <b>StreetName</b>  | <b>Significant LandMark</b> |
| W0005              | 3rd Crs            | Navya college               |
| <b>SegmentNo</b>   | <b>TotalLength</b> |                             |
| 99/S-W0005/S032215 | 175.60             |                             |

|   |                        |                    |
|---|------------------------|--------------------|
| <b>ContractorDetails</b>                      |                        |                    |
| <b>NameofContractor</b>                       | <b>ContractorRegNo</b> | <b>Expenditure</b> |
| Ajay<br>kumar,no.33,balajinagar,Ban<br>galore |                        | 983895.00          |
| <b>PhoneNo</b>                                | <b>Emailld</b>         |                    |
| 984567890                                     |                        |                    |
| <b>Work Details</b>                           |                        |                    |

|   |   |                               |
|---|---|-------------------------------|
| <b>NameOfWork</b>   | <b>Sanctioned Amount</b>  | <b>Sanctioned Year</b>        |
| Providing rcc box type drains<br>and covering slab at 3rd cross<br>LIC colony in ward no-99 | 1500000   | 2011                          |
| <b>Year</b>   | <b>Type of Work</b>   | <b>Other Work Type</b>        |
| 2011 - 2012   | Drain Maintenance   |                               |
| <b>Tender</b>   | <b>WorkDetails</b>  | <b>Job No Work Code</b>       |
| Tender  | Providing rcc box type drains<br>and covering slab at 3rd cross<br>LIC colony in ward no-99 | 099-11-000009                 |
| <b>Work OrderNo</b>   | <b>Work Order Date</b>  | <b>Period of Extention</b>    |
| EE/RNR/WO NO/33/10-11   | 23/03/2011  | 90days                        |
| <b>Defect Liability Period From</b>   | <b>Defect Liability<br/>Period To</b>   | <b>Multiple Road Involved</b> |
| 26/03/2011  | 23/06/2011  | No                            |

|                                 |                          |              |
|---------------------------------|--------------------------|--------------|
| <b>Field Inspection Details</b> |                          |              |
| <b>Number of Trees</b>          | <b>Other Information</b> | <b>Name</b>  |
| 4                               |                          | H.Shivakumar |
| <b>Date of Inspection</b>       | <b>Remarks</b>           |              |
| 18/12/2014                      | complete                 |              |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
BRUHAT BANGALORE MAHANAGARA PALIKE  
ENGINEERING DEPARTMENT  
Road History Data Sheet

| Category        | Photo  |
|-----------------|--|
| Drain Condition |    |
| Drain Condition |   |
| Drain Condition |  |



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ  
**BRUHAT BANGALORE MAHANAGARA PALIKE**  
**ENGINEERING DEPARTMENT**  
**Road History Data Sheet**

Segment End



Segment Start

